

DEKRA's commission No. : PKOL(W)/LODZ/60584/26/07/02
commission/ damage No. : 24/003790
Date of commission: 02-07-2026

DEKRA Poland - Headquarters
02-673 Warszawa, ul. Konstruktorska 12A

Client :

PKO Leasing SA
Świętokrzyska 36
00-116 Warszawa

Expert:

Kacper Sosnowski (WSP)
DEKRA Polska - współpraca O/Warszawa
Andrzej Sosnowski
DEKRA Polska - Centrala

NOTE:

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

Vehicle data

Group of objects (Eurotax)	cars
EC code (Eurotax)	0139963
Manufacturer	MERCEDES-BENZ
Model	CLA [C 118] 19-23
Type / version	AMG CLA 45 S 4-Matic 8G-DCT
Body type	sedan
Number of doors / seats	4/5
Curb weight [kg]	1679
Gross vehicle weight [kg]	2175
Wheelbase 1/2	2729
Engine type	spark ignition
Pollution reduction system	GPF
Engine capacity [ccm]	1991
Engine Power [hp/kW]	421/310
Gearbox	automatic
Registration /record No.	ZS643SV
VIN / serial number	W1K1183541N192885
Date of first registration	21-12-2020
Date of next. tech. test	30-12-2026
Year of manufacture	2020
Readout [km]	73 639 (read)
Body color / type of coating	gray/double-layered, metallized

Tyres

axle	Wheel	Manufacturer, type	Size	Measured profile
Front	right	PIRELLI, SOTTOZERO WINTER 240 SERIE II	255/35 19 96V	4,5 mm
	left	PIRELLI, SOTTOZERO WINTER 240 SERIE II	255/35 19 96V	5,0 mm
back	right	PIRELLI, SOTTOZERO WINTER 240 SERIE II	255/35 19 96V	5,0 mm
	left	PIRELLI, SOTTOZERO WINTER 240 SERIE II	255/35 19 96V	5,0 mm

Standard equipment by Eurotax

- | | |
|--|---|
| 1. Alarm | 32. Other |
| 2. Alcantara upholstery, Textile upholstery | 33. Other |
| 3. Automatic Emergency Call | 34. Other |
| 4. Automatic climate control | 35. Other |
| 5. Bord entertainment: other accessories, Radio | 36. Other |
| 6. Brake Assist | 37. Other |
| 7. Cruise control | 38. Other |
| 8. DAB radio | 39. Other |
| 9. Diminished spare wheel | 40. Other |
| 10. Door mirrors autodimming, Rear-view mirror autodimming | 41. Other |
| 11. Door mirrors electrically foldable | 42. Other |
| 12. Driver airbag, Passenger airbag | 43. Other |
| 13. Driver knee airbag | 44. Other |
| 14. Exterior design: other | 45. Other |
| 15. Exterior design: other | 46. Other |
| 16. Exterior design: other, Interior: other | 47. Other |
| 17. Floor mat | 48. Other |
| 18. Head airbags front, Head airbags rear | 49. Other |
| 19. Interior lights: other accessories | 50. Park Assistant, Park Distance Control front, Park Distance Control rear |
| 20. Interior lights: other accessories, Other | 51. Pre-Crash System, Seats: other |
| 21. Interior: other | 52. Rain sensor |
| 22. Interior: other | 53. Rear bench/seats foldable |
| 23. LED front dim light | 54. Rear view camera |
| 24. Lane control assistant | 55. Selectable driveline characteristics |
| 25. Leather steering wheel, Sports steering wheel | 56. Side airbag driver and passenger |
| 26. Light Alloy wheels 19" | 57. Sport seats front |
| 27. Metal finish | 58. Sport suspension |
| 28. Mobile Tire System | 59. Steering: other |
| 29. Multi functional steering wheel | 60. Storage facilities in general |
| 30. Navigation system | 61. Tyre pressure control (RDC) |
| 31. On board monitor | 62. Uni-Lackierung |

Dealer's equipment (selected items)

1. 360 view camera -
Kamery ułatwiające parkowanie 360
2. Armrest (s) rear, Automatic headlight elevation control, Cornering Headlights, Driver seat electrically adjustable, Electric tailgate, Glass tilt/slide sunroof electric, Heated seat driver, Heated seat passenger, Keyless go, LED front dim light, Lumbar adjust driver, Lumbar adjust passenger, Memory seat, On board monitor, Other, Passenger seat electrically adjustable, Soundsystem -
Fotel pasażera regulowany elektrycznie z pamięcią położenia
Fotele przednie podgrzewane
Dach szklany panoramiczny
Fotel kierowcy regulowany elektrycznie z pamięcią położenia
Listwy progowe Mercedes-Benz, podświetlane
Fotele przednie z 4 stopniową regulacją łędźwi
Lampy przednie MULTIBEAM LED - Inteligentny system świateł drogowych
Wyświetlacz IC 10,25 cali
Pakiet KEYLESS-GO
Podłokietnik kanapy tylnej
Listwy progowe drzwi, podświetlane
System nagłośnienia, rozszerzony
3. Bord communication: other, iPod Interface, Mobile phone preparation -
Apple CarPlay
Android Auto

- 4. Distance control, Pre-Crash System -
System PRE-SAFE
System aktywnej kontroli odległości - DISTRONIC
- 5. Exterior design: other, Heat reflecting windows, Tinted rear windows -
Szyby przyciemniane z funkcją termoizolacji
Elementy nadwozia w kolorze czarnym o wysokim połysku (lusterka, listwy)
- 6. Exterior design: other, Rear spoiler, Tinted rear windows -
- 7. Keyless go -
- 8. Other -
- 9. Soundsystem -

Base value of the vehicle

Base value of the vehicle by Eurotax (net) -

Corrections

First registration

Equipment

Tyres

Other

Current market situation -
Uszkodzenia, stan, weryfikacja serwisowa -

Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 07-2026 POL) with regard to technical and market parameters affecting the value of the vehicle.

Basic print without information about the vehicle's value - due to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 13-07-2026

DEKRA's expert:
Kacper Sosnowski (WSP)
Andrzej Sosnowski

Document issued electronically valid without signature.

Measurement of thickness of the vehicle lacquer coating


No. of controlled item	Controlled item	Measured range of thickness of the lacquer coat [μm]
1	Front cover	to 150
2	Front left fender	to 150
3	Left front pillar	to 150
4	Front left door	to 150
5	Roof	to 150
6	Left middle pillar	to 150
7	Right side sill	to 150
8	Left rear door	to 150
9	Rear left fender	to 150
10	Cover/lid	to 150
11	Right rear fender	to 150
12	Right rear door	to 150
13	Right middle pillar	to 150
14	Right side sill	to 150
15	Front right door	to 150
16	Right front pillar	to 150
17	Front right fender	to 150

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

During the inspection the registration proof of the vehicle was presented and its photo was taken and enclosed to the expertise.

During the inspection the service book was presented and its number is given below:
elektroniczna

Information concerning the origin of the vehicle

Lack of reliable data.

Anti-theft protection - immobilizer

- as a result of the inspection of the vehicle found no malfunctions of the immobilizer in the extent possible to determine during the inspection of the vehicle in the non- workshop conditions.

Anti-theft protection - other:

not found

Additional comments on the car:

Not applicable.

Test drive

Test drive of the vehicle was conducted. Test drive in the full extent is not possible. Comment below:
ograniczenia placowe

Checking of the correctness and / or construction of identification / serial numbers of the object:

Not tested

Verification of the accuracy of the object data, including year of production, and other.

Not conducted - adopted according to the documents presented and indicated sources.

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.
- The evaluation has been carried out basing on delivered documentation and organoleptic examination of

the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the assessed object.

- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

Comments to the commission - regarding valuation

Kluczyki

TAK

2

Expert comments - regarding valuation

Rysy na samochodzie. Brak kompresora zestawu naprawczego. Przegląd B wymagany od 254dni. Brak zaślepek w tylnej kanapie. Nieprawidłowe działanie przycisków konsoli tunelu środkowego. Odpryski na szybie czołowej.

Rzeczoznawca dokonał oględzin pojazdu w warunkach parkingowych, co mogło ograniczyć pełną ocenę jego stanu technicznego. Dodatkowo, jeżeli jazda próbna została przeprowadzona (informacje w treści raportu), to wykonano ją w warunkach parkingowych, z niewielką prędkością, co może nie odzwierciedlać pełnych warunków eksploatacyjnych. Istnieje możliwość, że w innych okolicznościach ujawnią się dodatkowe uszkodzenia lub usterki, których nie można było wykryć podczas obecnych oględzin. Zalecamy zatem skorzystanie z możliwości oględzin pojazdu we własnym zakresie lub w Autoryzowanej Stacji Obsługi danej marki, co pozwoli na pełniejszą weryfikację stanu technicznego pojazdu przed udziałem w aukcji."

Restrictive disclaimer - regarding valuation

Nie weryfikowano szczegółowo stanu układu napędowego, zawieszenia, kierowniczego, hamulcowego oraz wydechowego. Ocena została wykonana bez użycia podnośnika i specjalistycznego sprzętu diagnostycznego, nie dokonywano demontażu osłon i innych elementów. Ocena określa ogólny stan pojazdu na dzień oględzin w miejscu jego udostępnienia, nie może być zatem traktowana jako kompleksowa ocena stanu technicznego. Specyfikacja wg. programu operacyjnego w zakresie wyposażenia standardowego i dodatkowego nie gwarantuje zgodności ze stanem faktycznym w zakresie możliwym do ustalenia przez rzeczoznawcę podczas oględzin pojazdu.

Pomiar grubości powłoki lakierowej wykonano w miejscach możliwych do ich wykonania pomiary nie gwarantują oryginalności poszczególnych elementów poddanych ocenie.

- W Ocenie/Raporcie uwzględniono niesprawności, uszkodzenia, braki itp., które były możliwe do stwierdzenia organoleptycznego, w warunkach oględzin (z uwzględnieniem: stanu czystości pojazdu, warunków atmosferycznych, oświetlenia itd.) oraz bez weryfikacji serwisowej, bez dostępu do spodu pojazdu, bez specjalistycznego sprzętu diagnostycznego (w tym bez diagnostyki komputerowej), bez jazdy próbnej wykonanej w warunkach drogowych z obciążeniem.
- W ramach Oceny/Raportu nie weryfikowano odczytanego stanu drogomierza z zapisami w urządzeniach elektronicznych pojazdu.
- Rzeczoznawca nie bierze na siebie odpowiedzialności za wady ukryte (prawne i fizyczne) oraz ewentualne skutki wynikające z dalszego użytkowania przedmiotu oceny, a także za skutki wykorzystania samej oceny.

- Podane przedziały grubości powłoki lakierowej, dotyczą punktów pomiarowych. Nie mogą być traktowane jako gwarancja, że grubość powłoki lakierowej w innych punktach nie wykracza poza te przedziały.
- Zawarte w niniejszej Ocenie/Raporcie informacje (w tym dotyczące wyposażenia) służą jedynie ogólnym celom informacyjnym. Ocena/Raport nie może być zatem traktowana jako oferta w rozumieniu przepisów Kodeksu Cywilnego oraz opisu towaru ani zapewnienia w rozumieniu art. 4 Ustawy z dnia 27 lipca 2002 roku o szczególnych warunkach sprzedaży konsumenckiej.
- Niniejsza Ocena/Raport nie jest szczegółową oceną stanu technicznego.

Ocenę/Raport wykonano w kierunku ujawnienia uszkodzeń nieakceptowanych z punktu widzenia właściwego przewodnika zwrotu pojazdu lub innych ustaleń ze Zleceniodawcą. Tym samym Ocena/Raport może nie ujmować typowych zużyć i uszkodzeń eksploatacyjnych.

PHOTOGRAPHIC DOCUMENTATION



Photo 1.

Przekątna przednia lewa



Photo 2.

Przód

PHOTOGRAPHIC DOCUMENTATION



Photo 3.

Przekątna przednia prawa



Photo 4.

Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 5.

Bok prawy z tyłu



Photo 6.

Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 7.

Tył



Photo 8.

Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 9.

Bok lewy z tyłu



Photo 10.

Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 11.

Próg lewy (widok od przodu)



Photo 12.

Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



Photo 13.
Spód pojazdu przód



Photo 14.
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION



Photo 15.

Tarcza hamulcowa przednia prawa



Photo 16.

Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 17.

Tarcza hamulcowa tylna lewa



Photo 18.

Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 19.
Bagażnik



Photo 20.
Komora silnika

PHOTOGRAPHIC DOCUMENTATION



Photo 21.
Numer identyfikacyjny



Photo 22.
Tabliczka znamionowa

PHOTOGRAPHIC DOCUMENTATION



Photo 23.

Zestaw wskaźników - przebieg




Photo 24.

Zestaw wskaźników - serwis

PHOTOGRAPHIC DOCUMENTATION



Photo 25.

Widok przez otwarte drzwi przednie lewe



Photo 26.

Kierownica z lewej strony

PHOTOGRAPHIC DOCUMENTATION



Photo 27.

Widok przez otwarte drzwi tylne lewe



Photo 28.

Widok z tylnej kanapy na deskę rozdź.

PHOTOGRAPHIC DOCUMENTATION



Photo 29.

Konsola środkowa



Photo 30.

Tunel środkowy

PHOTOGRAPHIC DOCUMENTATION**Photo 31.**

Kierownica (na wprost)

**Photo 32.**

Dowód rej. Str. 1

PHOTOGRAPHIC DOCUMENTATION



Photo 33.

Książka serwisowa – dane




Photo 34.

Książka serwisowa – ostatni przegląd

[illegible]The image shows the front cover of a Mercedes-Benz CLA instruction manual. The cover is primarily black with a large, vibrant photograph of a silver Mercedes-Benz CLA driving on a city street at night. The background of the photo is filled with colorful, blurred lights from buildings and other vehicles, creating a sense of motion. Below the photograph, the word "CLA" is printed in a large, white, sans-serif font. Underneath "CLA", the words "Instrukcja obsługi" are written in a smaller, white, sans-serif font. At the bottom left, the "Mercedes-Benz" logo is visible. At the bottom right, there is a large, white, circular emblem containing the Mercedes-Benz three-pointed star logo. The manual is resting on a dark, textured surface, possibly a car seat, with a red strap visible in the lower right corner.

DEKRA Polska Sp. z o.o.
02-673 Warszawa, ul. Konstruktorska 12A
www.dekra.pl

PHOTOGRAPHIC DOCUMENTATION



Photo 37.

Zestaw naprawczy koła



Photo 38.

Kluczyki

PHOTOGRAPHIC DOCUMENTATION



Photo 39.

Zdjęcie do protokołu



Photo 40.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 41.

Zdjęcie do protokołu



Photo 42.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION




Photo 43.

Zdjęcie do protokołu



Photo 44.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 45.

Kratka/zaślepka halogenu L - Rysa/odprysk 1



Photo 46.

Pokrywa komory silnika - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 47.

Szyba czołowa - zdjęcie poglądowe 1




Photo 48.

Szyba czołowa - Pęknięcie/rozerwanie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 49.

Zderzak - Rysa/odprysk 1



Photo 50.

Zderzak - Rysa/odprysk 2

PHOTOGRAPHIC DOCUMENTATION



Photo 51.

Zderzak - Pęknięcie/rozerwanie 1



Photo 52.

Felga aluminiowa przednia P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 53.

Drzwi przednie P - Rysa/odprysk 1



Photo 54.

Drzwi przednie P - Rysa/odprysk 2

PHOTOGRAPHIC DOCUMENTATION



Photo 55.

Drzwi tylne P - Rysa/odprysk 1




Photo 56.

Drzwi tylne P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 57.

Błotnik tylny P / Ściana boczna P - zdjęcie poglądowe 1



Photo 58.

Błotnik tylny P / Ściana boczna P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 59.

Felga aluminiowa tylna P - Rysa/odprysk 1



Photo 60.

Opona tylna P - Pęknięcie/rozerwanie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 61.

Pokrywy bagażnika - Rysa/odprysk 1



Photo 62.

Pokrywy bagażnika - Rysa/odprysk 2

PHOTOGRAPHIC DOCUMENTATION



Photo 63.

Błotnik tylny L / Ściana boczna L - Wgniecenie/odkształcenie 1



Photo 64.

Felga aluminiowa tylna L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 65.

Drzwi przed L - Rysa/odprysk 1




Photo 66.

Słupek środkowy L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 67.

Fotel prz. praw. - Inne 1




Photo 68.

Kanapa tyl. - Inne 1