

DEKRA's commission No. : PKOL(W)/LODZ/69918/26/07/28
commission/ damage No. : 25/054498
Date of commission: 28-07-2026

DEKRA Poland - Headquarters
02-673 Warszawa, ul. Konstruktorska 12A

Client :

PKO Leasing SA
Świętokrzyska 36
00-116 Warszawa

Expert:

Kacper Sosnowski (WSP)
DEKRA Polska - współpraca O/Warszawa
Andrzej Sosnowski
DEKRA Polska - Centrala

NOTE:

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

Vehicle data

Group of objects (Eurotax)	cars
EC code (Eurotax)	0145364
Manufacturer	VOLKSWAGEN
Model	Arteon Shooting Brake 20-24
Type / version	Arteon 2.0 TSI Elegance DSG
Body type	KOM
Number of doors / seats	5/5
Curb weight [kg]	1578
Gross vehicle weight [kg]	2170
Wheelbase 1/2	2836
Engine type	spark ignition
Pollution reduction system	GPF
Engine capacity [ccm]	1984
Engine Power [hp/kW]	190/140
Gearbox	automatic
Registration /record No.	DB1675M
VIN / serial number	WVWZZZ3HZNK003690
Date of first registration	27-07-2022
Date of next. tech. test	17-07-2027
Year of manufacture	2022 (year has been verified with the manufacturer's base)
Readout [km]	101 342 (read)
Body color / type of coating	white/double-layered, metallized

Tyres

axle	Wheel	Manufacturer, type	Size	Measured profile
Front	right	CONTINENTAL, ECOCONTACT 6	245/45 18 96W	4,0 mm
	left	CONTINENTAL, ECOCONTACT 6	245/45 18 96W	4,0 mm
back	right	CONTINENTAL, ECOCONTACT 6	245/45 18 96W	2,0 mm
	left	CONTINENTAL, ECOCONTACT 6	245/45 18 96W	2,0 mm

Standard equipment by Eurotax

- | | |
|---|--|
| 1. Antilock-Brake-System (ABS), Brake Assist, ESP (Electronical Stabilizing Program), Other, Traction control | 29. Leather gearshifter/switch, Leather steering wheel, Multi functional steering wheel, Steering wheel with gear-switches |
| 2. Armrest (s) front, Storage facilities in general | 30. Leather upholstery, Velours upholstery |
| 3. Automated High-beam assist | 31. Light Alloy wheels 18'', Self sealing mobility tyre |
| 4. Automatic climate control | 32. Lumbar adjust driver electric, Lumbar adjust passenger electric, Sport seats front |
| 5. Automatic dimlight activation, Follow me home | 33. Metal finish |
| 6. Automatic headlight elevation control, LED Daytime running lights, LED front dim light | 34. Mirror: others |
| 7. Bord communication: other | 35. On board computer |
| 8. Child seat fixation | 36. Other |
| 9. DAB radio | 37. Other |
| 10. Door mirrors autodimming, Door mirrors electrically foldable | 38. Other |
| 11. Driver airbag, Driver knee airbag, Head airbags front, Passenger airbag, Side airbag driver, Side airbag driver and passenger | 39. Other |
| 12. Electric parking brake | 40. Other |
| 13. Electric tailgate | 41. Other |
| 14. Exterior design: other | 42. Other |
| 15. Exterior design: other | 43. Park Distance Control front, Park Distance Control rear |
| 16. Extra power outlet | 44. Pre-Crash System |
| 17. Floor mat | 45. Radio |
| 18. Gniazdo USB-C, obsługuje iPod/iPhone | 46. Rain sensor |
| 19. Gwarancja 2 lata | 47. Rear-view mirror autodimming |
| 20. Hatch/skibag in rear bench, Rear seat-backs foldable in two separate parts | 48. Servotronic |
| 21. Heated seat driver, Heated seat passenger | 49. Soundsystem |
| 22. Interior lights: other accessories | 50. Start/Stop system |
| 23. Interior lights: other accessories | 51. Tempomat aktywny z automatyczną regulacją odległości ACC (do 210 km/h) |
| 24. Interior: other | 52. Tyre pressure control (RDC) |
| 25. Interior: other, Other | 53. Uni-Lackierung |
| 26. Keyless go | 54. Vehicle immobilizer |
| 27. LED rear lights, Side indicators | 55. Windscreen wash-nozzle heated |
| 28. Lane control assistant, Traffic jam assist | |

Dealer's equipment (selected items)

1. Rear view camera -

Base value of the vehicle

Base value of the vehicle by Eurotax (net) -

CorrectionsFirst registration

MileageEquipmentTyresOther

Regularity of service review -
Earlier repairs -
Braki uszkodzenia, weryfikacja serwisowa. -


Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 08-2026 POL) with regard to technical and market parameters affecting the value of the vehicle.

Basic print without information about the vehicle's value - duey to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 04-08-2026

DEKRA's expert:
Kacper Sosnowski (WSP)
Andrzej Sosnowski

Document issued electronically valid without signature.

Measurement of thickness of the vehicle lacquer coating


No. of controlled item	Controlled item	Measured range of thickness of the lacquer coat [μm]
1	Front cover	150 - 300
2	Front left fender	150 - 300
3	Left front pillar	150 - 300
4	Front left door	150 - 300
5	Roof	150 - 300
6	Left middle pillar	150 - 200
7	Right side sill	150 - 300
8	Left rear door	150 - 300
9	Rear left fender	150 - 300
10	Cover/lid	150 - 300
11	Right rear fender	150 - 300
12	Right rear door	150 - 300
13	Right middle pillar	150 - 200
14	Right side sill	150 - 300
15	Front right door	150 - 300
16	Right front pillar	150 - 300
17	Front right fender	150 - 300

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

During the inspection the registration proof of the vehicle was presented and its photo was taken and enclosed to the expertise.

During the inspection the service book was presented and its number is given below:
elektroniczna

Information concerning the origin of the vehicle

Lack of reliable data.

Anti-theft protection - immobilizer

- as a result of the inspection of the vehicle found no malfunctions of the immobilizer in the extent possible to determine during the inspection of the vehicle in the non- workshop conditions.

Anti-theft protection - other:

not found

Additional comments on the car:

Not applicable.

Test drive

Test drive of the vehicle was conducted. Test drive in the full extent is not possible. Comment below:
ograniczenia placowe

Checking of the correctness and / or construction of identification / serial numbers of the object:

Not tested

Verification of the accuracy of the object data, including year of production, and other.

Not conducted - adopted according to the documents presented and indicated sources.

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.
- The evaluation has been carried out basing on delivered documentation and organoleptic examination of

page 5/44

the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the assessed object.

- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

Comments to the commission - regarding valuation

Kluczyki

TAK

1

Expert comments - regarding valuation

Ruchomy lewy reflektor. Rysy na samochodzie. Wymagany przegląd od 12200km i wymagana wymiana oleju od 11400km. Widoczne wady lakiernicze. Odpryski na szybie czołowej.

Rzeczoznawca dokonał oględzin pojazdu w warunkach parkingowych, co mogło ograniczyć pełną ocenę jego stanu technicznego. Dodatkowo, jeżeli jazda próbna została przeprowadzona (informacje w treści raportu), to wykonano ją w warunkach parkingowych, z niewielką prędkością, co może nie odzwierciedlać pełnych warunków eksploatacyjnych. Istnieje możliwość, że w innych okolicznościach ujawnią się dodatkowe uszkodzenia lub usterki, których nie można było wykryć podczas obecnych oględzin. Zalecamy zatem skorzystanie z możliwości oględzin pojazdu we własnym zakresie lub w Autoryzowanej Stacji Obsługi danej marki, co pozwoli na pełniejszą weryfikację stanu technicznego pojazdu przed udziałem w aukcji."

Restrictive disclaimer - regarding valuation

Nie weryfikowano szczegółowo stanu układu napędowego, zawieszenia, kierowniczego, hamulcowego oraz wydechowego. Ocena została wykonana bez użycia podnośnika i specjalistycznego sprzętu diagnostycznego, nie dokonywano demontażu osłon i innych elementów. Ocena określa ogólny stan pojazdu na dzień oględzin w miejscu jego udostępnienia, nie może być zatem traktowana jako kompleksowa ocena stanu technicznego. Specyfikacja wg. programu operacyjnego w zakresie wyposażenia standardowego i dodatkowego nie gwarantuje zgodności ze stanem faktycznym w zakresie możliwym do ustalenia przez rzeczoznawcę podczas oględzin pojazdu.

Pomiar grubości powłoki lakierowej wykonano w miejscach możliwych do ich wykonania pomiary nie gwarantują oryginalności poszczególnych elementów poddanych ocenie.

- W Ocenie/Raporcie uwzględniono niesprawności, uszkodzenia, braki itp., które były możliwe do stwierdzenia organoleptycznego, w warunkach oględzin (z uwzględnieniem: stanu czystości pojazdu, warunków atmosferycznych, oświetlenia itd.) oraz bez weryfikacji serwisowej, bez dostępu do spodu pojazdu, bez specjalistycznego sprzętu diagnostycznego (w tym bez diagnostyki komputerowej), bez jazdy próbnej wykonanej w warunkach drogowych z obciążeniem.
- W ramach Oceny/Raportu nie weryfikowano odczytanego stanu drogomierza z zapisami w urządzeniach elektronicznych pojazdu.
- Rzeczoznawca nie bierze na siebie odpowiedzialności za wady ukryte (prawne i fizyczne) oraz ewentualne skutki wynikające z dalszego użytkowania przedmiotu oceny, a także za skutki wykorzystania samej oceny.
- Podane przedziały grubości powłoki lakierowej, dotyczą punktów pomiarowych. Nie mogą być traktowane jako gwarancja, że grubość powłoki lakierowej w innych punktach nie wykracza poza te przedziały.

- Zawarte w niniejszej Ocenie/Raporcie informacje (w tym dotyczące wyposażenia) służą jedynie ogólnym celom informacyjnym. Ocena/Raport nie może być zatem traktowana jako oferta w rozumieniu przepisów Kodeksu Cywilnego oraz opisu towaru ani zapewnienia w rozumieniu art. 4 Ustawy z dnia 27 lipca 2002 roku o szczególnych warunkach sprzedaży konsumenckiej.
- Niniejsza Ocena/Raport nie jest szczegółową oceną stanu technicznego.

Ocenę/Raport wykonano w kierunku ujawnienia uszkodzeń nieakceptowanych z punktu widzenia właściwego przewodnika zwrotu pojazdu lub innych ustaleń ze Zleceniodawcą. Tym samym Ocena/Raport może nie ujmować typowych zużyć i uszkodzeń eksploatacyjnych.

PHOTOGRAPHIC DOCUMENTATION



Photo 1.
Przekątna przednia lewa



Photo 2.
Przód

PHOTOGRAPHIC DOCUMENTATION



Photo 3.

Przekątna przednia prawa



Photo 4.

Bok prawy z przodu

A side profile view of a white Volvo SUV, likely a XC60, parked in a garage. The car is positioned diagonally, showing its rear and side. It features a silver door handle, a fuel filler door, and a multi-spoke alloy wheel. The background shows a concrete floor and a white wall with a door.

A rear three-quarter view of a white Volkswagen Arteon parked in a well-lit, clean garage. The car's design features a sleek, aerodynamic profile with a large, dark rear window and a subtle spoiler. The rear lights are illuminated, showing a red and white pattern. The Volkswagen logo and 'ARTEON' badge are visible on the trunk. The license plate reads 'DB 1675M'. The car is parked on a light-colored floor, and a metal drainage grate is visible in the foreground.

DEKRA Polska Sp. z o.o.
02-673 Warszawa, ul. Konstruktorska 12A
www.dekra.pl

PHOTOGRAPHIC DOCUMENTATION



Photo 7.

Tył



Photo 8.

Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 9.

Bok lewy z tyłu



Photo 10.

Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 11.
Próg lewy (widok od przodu)



Photo 12.
Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



Photo 13.
Spód pojazdu przód



Photo 14.
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION




Photo 15.

Tarcza hamulcowa przednia prawa




Photo 16.

Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 17.

Tarcza hamulcowa tylna lewa



Photo 18.

Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 19.
Bagażnik



Photo 20.
Komora silnika

PHOTOGRAPHIC DOCUMENTATION



Photo 21.
Numer identyfikacyjny




Photo 22.
Tabliczka znamionowa

PHOTOGRAPHIC DOCUMENTATION



Photo 23.

Zestaw wskaźników - przebieg



Photo 24.

Zestaw wskaźników - serwis

PHOTOGRAPHIC DOCUMENTATION



Photo 25.

Widok przez otwarte drzwi przednie lewe



Photo 26.

Kierownica z lewej strony

PHOTOGRAPHIC DOCUMENTATION



Photo 27.

Widok przez otwarte drzwi tylne lewe




Photo 28.

Widok z tylnej kanapy na deskę rozdz.

PHOTOGRAPHIC DOCUMENTATION



Photo 29.
Konsola środkowa



Photo 30.
Tunel środkowy


PHOTOGRAPHIC DOCUMENTATION



Photo 31.
Kierownica (na wprost)



Photo 32.
Dowód rej. Str. 1

PHOTOGRAPHIC DOCUMENTATION**Photo 33.**


Książka serwisowa – dane

**Photo 34.**

Książka serwisowa – ostatni przegląd

PHOTOGRAPHIC DOCUMENTATION**Photo 35.**

Dow. Rej. Str. 2

**Photo 36.**

Instrukcje

PHOTOGRAPHIC DOCUMENTATION



Photo 37.

Kluczyki



Photo 38.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 39.
Zdjęcie do protokołu



Photo 40.
Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 41.

Krata zderzaka prz. - zdjęcie poglądowe 1



Photo 42.

Krata zderzaka prz. - Pęknięcie/rozerwanie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 43.

Pokrywa komory silnika - Rysa/odprysk 1



Photo 44.

Pokrywa komory silnika - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 45.

Pokrywa komory silnika - Wgniecenie/odkształcenie 2



Photo 46.

Pokrywa komory silnika() - Wgniecenie/odkształcenie 3

PHOTOGRAPHIC DOCUMENTATION



Photo 47.

Spoiler zderzaka przedniego - Rysa/odprysk 1




Photo 48.

Uszczelka/listwa szyby czołowej - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 49.

Zderzak - Rysa/odprysk 1



Photo 50.

Zderzak - Rysa/odprysk 2

PHOTOGRAPHIC DOCUMENTATION



Photo 51.

Zderzak() - Rysa/odprysk 3



Photo 52.

Zderzak - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 53.

Zderzak - Pęknięcie/rozerwanie 1



Photo 54.

Felga aluminiowa przednia P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 55.

Nadkole przednie P - Pęknięcie/rozerwanie 1



Photo 56.

Drzwi tylne P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 57.

Próg P - Wgniecenie/odkształcenie 1



Photo 58.

Felga aluminiowa tylna P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION




Photo 59.

Felga aluminiowa tylna P - Inne 1



Photo 60.

Opona tylna P - Pęknięcie/rozerwanie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 61.

Zderzak tylny - Rysa/odprysk 1



Photo 62.

Zderzak tylny - Rysa/odprysk 2

PHOTOGRAPHIC DOCUMENTATION



Photo 63.

Dach - Wgniecenie/odkształcenie 1



Photo 64.

Felga aluminiowa tylna L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 65.

Opona tylna L - Pęknięcie/rozerwanie 1



Photo 66.

Drzwi przed L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 67.

Drzwi tylne L - Rysa/odprysk 1



Photo 68.

Felga Aluminiowa przednia L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION




Photo 69.

Felga Aluminiowa przednia L - Inne 1



Photo 70.

Gałka dźwigni zmiany biegów - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 71.

Fotel prz. lew. - Inne 1



Photo 72.

Podsufitka - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 73.

Wykładzina(y) słupka przedniego P - Inne 1