

DEKRA's commission No. : PKOL(W)/LODZ/69897/25/09/17
commission/ damage No. : 24/041894
Date of commission: 17-09-2025

DEKRA Poland - Headquarters
02-673 Warszawa, ul. Konstruktorska 12A

Client :

PKO Leasing SA
Świętokrzyska 36
00-116 Warszawa

Expert:

Kacper Sosnowski (NEW)
DEKRA Polska - współpraca O/Warszawa
Andrzej Sosnowski
DEKRA Polska - Centrala

NOTE:

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

Vehicle data

Group of objects (Eurotax)	cars
EC code (Eurotax)	0151129
Manufacturer	KIA
Model	EV6 21-25
Type / version	EV6 77.4kWh Plus
Body type	hatchback
Number of doors / seats	5/5
Curb weight [kg]	1910
Gross vehicle weight [kg]	2425
Wheelbase 1/2	2900
Engine type	elektryczny
Pollution reduction system	-
Engine capacity [ccm]	0
Engine Power [hp/kW]	229/168
Gearbox	automatic
Registration /record No.	WR057GU
VIN / serial number	KNAC381AFN5038883
Date of first registration	21-06-2022
Date of next. tech. test	20-06-2027
Year of manufacture	2022 (year has been verified with the manufacturer's base)
Readout [km]	77 456 (read)
Body color / type of coating	granatowy/double-layered, pearly

Tyres

axle	Wheel	Manufacturer, type	Size	Measured profile
Front	right	YOKOHAMA, ADVAN DB V552	255/45 20 105Y	6,0 mm
	left	YOKOHAMA, ADVAN DB V552	255/45 20 105Y	6,0 mm
back	right	YOKOHAMA, ADVAN DB V552	255/45 20 105Y	5,5 mm
	left	YOKOHAMA, ADVAN DB V552	255/45 20 105Y	5,5 mm

Standard equipment by Eurotax

- | | |
|--|--|
| 1. Active Emergency Brake Assist, Intersection Assist | 52. Luggage compartment cover |
| 2. Active speed sign recognition | 53. Metallic paint |
| 3. Adaptive Cruise Control | 54. Mirror: others, Side indicators |
| 4. Adaptive Cruise Control, Lane control assistant | 55. Mobile Tire System |
| 5. Android Auto, Apple CarPlay, Navigation system, On board monitor, Rear view camera | 56. Nakładki na pedały „standard” |
| 6. Antilock-Brake-System (ABS) | 57. On board monitor |
| 7. Armrest (s) front | 58. Other |
| 8. Artificial leather upholstery | 59. Other |
| 9. Automated High-beam assist | 60. Other |
| 10. Automatic Emergency Call | 61. Other |
| 11. Automatic climate control | 62. Other |
| 12. Automatic dimlight activation | 63. Other |
| 13. Blind spot warning | 64. Other |
| 14. Blind spot warning | 65. Other |
| 15. Bord climate: other | 66. Other |
| 16. Bord entertainment: other accessories | 67. Other |
| 17. Bord entertainment: other accessories, DAB radio, mp3 Player, Radio | 68. Other |
| 18. Central airbag driver and passenger | 69. Other |
| 19. Child lock electric | 70. Other, Seatbelts vertically adjustable front, Seatbelts vertically adjustable rear |
| 20. Child seat fixation | 71. Oświetlenie wnętrza oraz bagażników LED |
| 21. Collision Warning System, Curve trace assistant | 72. Panel sterowania układem klimatyzacji i systemem multimedialnym z funkcją „zmiennej klawiatury ” |
| 22. Dodatkowy bagażnik z przodu | 73. Park Distance Control front, Park Distance Control rear |
| 23. Door mirror with memory, Driver seat electrically adjustable, Lumbar adjust driver electric, Lumbar adjust passenger electric, Memory seat, Passenger seat electrically adjustable | 74. Pedestrian Emergency Brake Assist, Power assisted brakes |
| 24. Door mirror(s) electrically adjustable in general, Door mirrors heated | 75. Podświetlenie kameralne wnętrza |
| 25. Door mirrors electrically foldable | 76. Power windows front, Power windows rear |
| 26. Driver airbag, Head airbags front, Passenger airbag, Side airbag driver, Side airbag driver and passenger | 77. Pre-Crash System |
| 27. Driver conditioning monitoring | 78. Quick charging function |
| 28. Driver-information-system, Other | 79. Quick charging function |
| 29. Driver-information-system, Other | 80. Quick charging function |
| 30. ESP (Electronical Stabilizing Program) | 81. Rain sensor |
| 31. Elementy stylistyczne dolnej części zderzaka przedniego i tylnego | 82. Rear bench foldable in two separate parts |
| 32. Energy recovery system | 83. Rear seat heating |
| 33. Exterior design: other | 84. Rear spoiler |
| 34. Exterior design: other | 85. Rear-view mirror autodimming |
| 35. Exterior design: other | 86. Remote controlled central locking |
| 36. Exterior design: other | 87. Seatbelt pretensioner front |
| 37. Extra power outlet | 88. Seatbelts vertically adjustable front |
| 38. Gwarancja | 89. Seats: other |
| 39. Heat reflecting windows | 90. Selectable driveline characteristics |
| 40. Heated seat driver, Heated seat passenger | 91. Servotronic |
| 41. Hill holder | 92. Sport suspension |
| 42. Interior decoration: other, Textile upholstery | 93. Steering wheel heated |

- | | |
|---|--|
| 43. Interior: other | 94. Storage facilities in general |
| 44. Intersection Assist | 95. Tinted rear windows |
| 45. Keyless go | 96. Traffic jam assist |
| 46. Kia Live - usługi cyfrowe dla kierowcy(ruch drogowy, pogoda, ceny paliw, parkingi, stacje łado) | 97. USB in |
| 47. LED Daytime running lights | 98. Vehicle immobilizer |
| 48. LED front dim light | 99. Ventilated front seat |
| 49. LED rear lights | 100. Windows: other |
| 50. Leather steering wheel | 101. Zakrzywiony ekran wysokiej rozdzielczości |
| 51. Light Alloy wheels 20" | 102. {Asystent utrzymania pasa ruchu} |

Dealer's equipment (selected items)

1. Heated seat driver, Heated seat passenger, Other, Rear seat heating, Ventilated front seat -
- Fotele tylne, ogrzewane
- Fotele przednie wentylowane
- Klamki zewnętrzne automatyczne easy entry
- Panel sterowania dotykowy
- Pokrywa bagażnika elektryczna
2. Metallic paint -

Base value of the vehicle

Base value of the vehicle by Eurotax (net) -

Corrections

First registration

Mileage

Equipment

Tyres

Other

Regularity of service review -

Uszkodzenia, stan -


Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 09-2025 POL) with regard to technical and market parameters affecting the value of the vehicle.

Basic print without information about the vehicle's value - due to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 01-10-2025

DEKRA's expert:
Kacper Sosnowski (NEW)
Andrzej Sosnowski

Document issued electronically valid without signature.

Measurement of thickness of the vehicle lacquer coating


No. of controlled item	Controlled item	Measured range of thickness of the lacquer coat [μm]
1	Front cover	to 150
2	Front left fender	to 150
3	Left front pillar	to 150
4	Front left door	to 150
5	Roof	to 150
6	Left middle pillar	to 150
7	Right side sill	to 150
8	Left rear door	to 150
9	Rear left fender	to 150
10	Cover/lid	to 150
11	Right rear fender	to 150
12	Right rear door	to 150
13	Right middle pillar	to 150
14	Right side sill	to 150
15	Front right door	to 150
16	Right front pillar	to 150
17	Front right fender	to 150

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

During the inspection the registration proof of the vehicle was presented and its photo was taken and enclosed to the expertise.

During the inspection the service book was presented and its number is given below:
elektroniczna

Information concerning the origin of the vehicle

Lack of reliable data.

Anti-theft protection - immobilizer

- as a result of the inspection of the vehicle found no malfunctions of the immobilizer in the extent possible to determine during the inspection of the vehicle in the non- workshop conditions.

Anti-theft protection - other:

not found

Additional comments on the car:

Not applicable.

Test drive

Test drive of the vehicle was conducted. Test drive in the full extent is not possible. Comment below:
ograniczenia placowe

Checking of the correctness and / or construction of identification / serial numbers of the object:

Not tested

Verification of the accuracy of the object data, including year of production, and other.

Not conducted - adopted according to the documents presented and indicated sources.

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.
- The evaluation has been carried out basing on delivered documentation and organoleptic examination of

page 6/46

the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the assessed object.

- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

Comments to the commission - regarding valuation

Kluczyki

TAK

2

Expert comments - regarding valuation

Informacja konieczny przegląd od 3862km. Rysy na samochodzie. Pojazd elektryczny

Rzeczoznawca dokonał oględzin pojazdu w warunkach parkingowych, co mogło ograniczyć pełną ocenę jego stanu technicznego. Dodatkowo, jeżeli jazda próbna została przeprowadzona (informacje w treści raportu), to wykonano ją w warunkach parkingowych, z niewielką prędkością, co może nie odzwierciedlać pełnych warunków eksploatacyjnych. Istnieje możliwość, że w innych okolicznościach ujawnią się dodatkowe uszkodzenia lub usterki, których nie można było wykryć podczas obecnych oględzin. Zalecamy zatem skorzystanie z możliwości oględzin pojazdu we własnym zakresie lub w Autoryzowanej Stacji Obsługi danej marki, co pozwoli na pełniejszą weryfikację stanu technicznego pojazdu przed udziałem w aukcji."

Restrictive disclaimer - regarding valuation

Nie weryfikowano szczegółowo stanu układu napędowego, zawieszenia, kierowniczego, hamulcowego oraz wydechowego. Ocena została wykonana bez użycia podnośnika i specjalistycznego sprzętu diagnostycznego, nie dokonywano demontażu osłon i innych elementów. Ocena określa ogólny stan pojazdu na dzień oględzin w miejscu jego udostępnienia, nie może być zatem traktowana jako kompleksowa ocena stanu technicznego. Specyfikacja wg. programu operacyjnego w zakresie wyposażenia standardowego i dodatkowego nie gwarantuje zgodności ze stanem faktycznym w zakresie możliwym do ustalenia przez rzeczoznawcę podczas oględzin pojazdu.

Pomiar grubości powłoki lakierowej wykonano w miejscach możliwych do ich wykonania pomiary nie gwarantują oryginalności poszczególnych elementów poddanych ocenie.

- W Ocenie/Raporcie uwzględniono niesprawności, uszkodzenia, braki itp., które były możliwe do stwierdzenia organoleptycznego, w warunkach oględzin (z uwzględnieniem: stanu czystości pojazdu, warunków atmosferycznych, oświetlenia itd.) oraz bez weryfikacji serwisowej, bez dostępu do spodu pojazdu, bez specjalistycznego sprzętu diagnostycznego (w tym bez diagnostyki komputerowej), bez jazdy próbnej wykonanej w warunkach drogowych z obciążeniem.
- W ramach Oceny/Raportu nie weryfikowano odczytanego stanu drogomierza z zapisami w urządzeniach elektronicznych pojazdu.
- Rzeczoznawca nie bierze na siebie odpowiedzialności za wady ukryte (prawne i fizyczne) oraz ewentualne skutki wynikające z dalszego użytkowania przedmiotu oceny, a także za skutki wykorzystania samej oceny.
- Podane przedziały grubości powłoki lakierowej, dotyczą punktów pomiarowych. Nie mogą być traktowane jako gwarancja, że grubość powłoki lakierowej w innych punktach nie wykracza poza te przedziały.

- Zawarte w niniejszej Ocenie/Raporcie informacje (w tym dotyczące wyposażenia) służą jedynie ogólnym celom informacyjnym. Ocena/Raport nie może być zatem traktowana jako oferta w rozumieniu przepisów Kodeksu Cywilnego oraz opisu towaru ani zapewnienia w rozumieniu art. 4 Ustawy z dnia 27 lipca 2002 roku o szczególnych warunkach sprzedaży konsumenckiej.
- Niniejsza Ocena/Raport nie jest szczegółową oceną stanu technicznego.

Ocenę/Raport wykonano w kierunku ujawnienia uszkodzeń nieakceptowanych z punktu widzenia właściwego przewodnika zwrotu pojazdu lub innych ustaleń ze Zleceniodawcą. Tym samym Ocena/Raport może nie ujmować typowych zużyć i uszkodzeń eksploatacyjnych.

PHOTOGRAPHIC DOCUMENTATION



Photo 1.
Przekątna przednia lewa



Photo 2.
Przód

PHOTOGRAPHIC DOCUMENTATION



Photo 3.

Przekątna przednia prawa



Photo 4.

Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 5.
Bok prawy z tyłu



Photo 6.
Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 7.

Tył



Photo 8.

Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 9.

Bok lewy z tyłu



Photo 10.

Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 11.

Próg lewy (widok od przodu)



Photo 12.

Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



Photo 13.
Spód pojazdu przód



Photo 14.
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION



Photo 15.

Tarcza hamulcowa przednia prawa



Photo 16.

Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 17.

Tarcza hamulcowa tylna lewa



Photo 18.

Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 19.
Bagażnik



Photo 20.
Koło zapasowe

PHOTOGRAPHIC DOCUMENTATION




Photo 21.
Komora silnika



Photo 22.
Numer identyfikacyjny

PHOTOGRAPHIC DOCUMENTATION




Photo 23.

Tabliczka znamionowa



Photo 24.

Zestaw wskaźników - przebieg

PHOTOGRAPHIC DOCUMENTATION



Photo 25.

Widok przez otwarte drzwi przednie lewe



Photo 26.

Kierownica z lewej strony

PHOTOGRAPHIC DOCUMENTATION



Photo 27.

Widok przez otwarte drzwi tylne lewe



Photo 28.

Widok z tylnej kanapy na deskę rozd.

PHOTOGRAPHIC DOCUMENTATION



Photo 29.
Konsola środkowa




Photo 30.
Tunel środkowy

PHOTOGRAPHIC DOCUMENTATION




Photo 31.
Kierownica (na wprost)



Photo 32.
Dowód rej. Str. 1

PHOTOGRAPHIC DOCUMENTATION**Photo 33.**

Dow. Rej. Str.2 i klucze

**Photo 34.**

Książka serwisowa – dane

PHOTOGRAPHIC DOCUMENTATION




Photo 35.

Książka serwisowa – ostatni przegląd



Photo 36.

Przewód ładowania baterii trakcyjnej

PHOTOGRAPHIC DOCUMENTATION



Photo 37.
Instrukcje




Photo 38.
Zestaw naprawczy koła

PHOTOGRAPHIC DOCUMENTATION



Photo 39.

Zdjęcie do protokołu



Photo 40.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 41.

Zdjęcie do protokołu



Photo 42.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 43.

Zdjęcie do protokołu



Photo 44.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 45.

Pokrywa komory silnika - Rysa/odprysk 1



Photo 46.

Pokrywa komory silnika - Rysa/odprysk 2

PHOTOGRAPHIC DOCUMENTATION



Photo 47.

Zderzak - Rysa/odprysk 1



Photo 48.

Listwa błotnika przedniego P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 49.

Drzwi przednie P - Rysa/odprysk 1



Photo 50.

Drzwi przednie P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 51.

Drzwi tylne P - Rysa/odprysk 1



Photo 52.

Drzwi tylne P - Rysa/odprysk 2

PHOTOGRAPHIC DOCUMENTATION



Photo 53.

Drzwi tylne P - Wgniecenie/odkształcenie 1



Photo 54.

Łotnik tylny P / Ściana boczna P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 55.

Pokrywy bagażnika - Rysa/odprysk 1



Photo 56.

Pokrywy bagażnika - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 57.

Zderzak tylny - Rysa/odprysk 1



Photo 58.

Zderzak tylny - Rysa/odprysk 2

PHOTOGRAPHIC DOCUMENTATION




Photo 59.

Zderzak tylny() - Rysa/odprysk 3



Photo 60.

Dach - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 61.

Dach - Wgniecenie/odkształcenie 2



Photo 62.

Łotnik tylny L / Ściana boczna L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 63.

Błotnik tylny L / Ściana boczna L - Wgniecenie/odkształcenie 1



Photo 64.

Drzwi przed L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 65.

Drzwi przed L - Wgniecenie/odkształcenie 1



Photo 66.

Drzwi tylne L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 67.

Klamka drzwi prz L - Rysa/odprysk 1



Photo 68.

Klamka drzwi tyl L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 69.

Lusterko zew L - Rysa/odprysk 1



Photo 70.

Słupek środkowy L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 71.

Felga Alumiowa przednia L - Rysa/odprysk 1



Photo 72.

Konsola tunelu śr. - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 73.

Fotel prz. praw. - Rysa/odprysk 1



Photo 74.

Wykładzina(y) słupka przedniego L - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 75.

Wykładzina pokrywy tylnej - Rysa/odprysk 1