

DEKRA's commission No. : PKOL(W)/LODZ/36359/25/05/20
commission/ damage No. : 23/016289
Date of commission: 20-05-2025

DEKRA Poland - Headquarters
02-673 Warszawa, ul. Konstruktorska 12A

Client :

PKO Leasing SA
Świętokrzyska 36
00-116 Warszawa

Expert:

Kacper Sosnowski (NEW)
DEKRA Polska - współpraca O/Warszawa
Paweł Szwabowicz
DEKRA Polska - O. Lubin

NOTE:

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

Vehicle data

Group of objects (Eurotax)	jeeps
EC code (Eurotax)	0129395
Manufacturer	LAND ROVER
Model	Range Rover Sport 17-22
Type / version	Range Rover S 5.0 V8 S/C AB Dynamic
Body type	KOM
Number of doors / seats	5/5
Curb weight [kg]	2525
Gross vehicle weight [kg]	3100
Wheelbase 1/2	2923
Engine type	spark ignition
Pollution reduction system	three-way catalytic converter
Emission standard	EURO 6
Engine capacity [ccm]	4999
Engine Power [hp/kW]	525/386
Gearbox	automatic 8- gear
Registration /record No.	NO709AP
VIN / serial number	SALWA2BE0NA227484
Date of first registration	16-02-2022
Date of next. tech. test	12-02-2027
Year of manufacture	2022 (year has been verified with the manufacturer's base)
Readout [km]	71 333 (read)
Body color / type of coating	white/2-warstwowy metalik

Tyres

axle	Wheel	Manufacturer, type	Size	Measured profile
Front	right	PIRELLI, SCORPION ZERO ALLSEASON	275/45 21 110Y	4,0 mm
	left	PIRELLI, SCORPION ZERO ALLSEASON	275/45 21 110Y	4,0 mm
back	right	PIRELLI, SCORPION ZERO ALLSEASON	275/45 21 110Y	5,0 mm

left PIRELLI, SCORPION ZERO 275/45 21 110Y
ALLSEASON

5,0 mm

Standard equipment by Eurotax

- | | |
|---|---|
| 1. Accoustic windows, Windows: other | 43. Keyless go |
| 2. Air suspension, Electronic controlled suspension | 44. Lane control assistant |
| 3. Air suspension, Electronic controlled suspension | 45. Leather steering wheel |
| 4. Alarm | 46. Light Allow wheels over 21'' |
| 5. Android Auto | 47. Limited slip differential in general, Limited slip differential: other, Reducing gear |
| 6. Apple CarPlay | 48. Luggage compartment cover |
| 7. Armrest (s) rear | 49. Maska z aluminium |
| 8. Automated High-beam assist, LED front dim light | 50. Mobile Tire System |
| 9. Automatic dimlight activation, Rain sensor | 51. Navigation system |
| 10. Automatic limited slip differential, Limited slip differential: other | 52. On board monitor |
| 11. Blind spot warning, Other | 53. On board monitor |
| 12. Bluetooth interface, Hands-free system | 54. Other |
| 13. Bord entertainment: other accessories, CD-player, Radio | 55. Other |
| 14. Brak odtwarzacza CD/DVD | 56. Other |
| 15. Brak pakietu dla palących | 57. Other |
| 16. Brake Assist | 58. Other |
| 17. Child seat fixation | 59. Other |
| 18. Cooler box | 60. Other |
| 19. Cruise control | 61. Oznaczenie Autobiography |
| 20. DAB radio | 62. Oznaczenie P525 |
| 21. Daytime running lights | 63. Oznaczenie SPORT (napis w kolorze czarnym) |
| 22. Door mirrors autodimming, Door mirrors electrically foldable, Floor lighting, Side indicators | 64. Park Distance Control front, Park Distance Control rear |
| 23. Driver airbag, Head airbags front, Passenger airbag, Side airbag driver, Side airbag driver and passenger | 65. Park Distance Control front, Park Distance Control rear |
| 24. Driver seat height adjustable, Leather upholstery, Memory seat, Passenger seat height adjustable | 66. Pokrywa silnik |
| 25. Dualzone automatic climate control | 67. Power steering |
| 26. Electric tailgate | 68. Power windows front, Power windows rear |
| 27. Electronic controlled suspension | 69. Rear Cross Traffic Alert |
| 28. Exterior design: other | 70. Rear seat-backs foldable in two separate parts |
| 29. Exterior design: other | 71. Rear view camera |
| 30. Exterior design: other | 72. Rear-view mirror autodimming |
| 31. Floor mat | 73. Remote controlled central locking |
| 32. Fog lamps | 74. Roof: other |
| 33. Headlamp wash | 75. Selectable driveline characteristics, Steering: other |
| 34. Heated seat driver, Heated seat passenger, Rear seat heating, Ventilated front seat, Ventilated rear seat | 76. Steering wheel electrically adjustable |
| 35. Hill descent control | 77. Steering wheel with gear-switches |
| 36. Hill holder | 78. Sunblind rear side door manual |
| 37. Interior decoration: other | 79. Traffic sign recognition |
| 38. Interior lights: other accessories | 80. Tyre pressure control (RDC) |
| 39. Interior: other | 81. Vehicle immobilizer |
| 40. Interior: other | 82. Windows: other |
| 41. Interior: other | 83. Windscreen heating |
| 42. Internet access | 84. {Kontrola stabilności przyczepy} |

Dealer's equipment (selected items)

1. Glass tilt/slide sunroof electric -
2. Metallic paint -
3. Steering wheel heated -
4. Tinted rear windows -
5. Towbar removable -

Base value of the vehicle

Base value of the vehicle by Eurotax (net) -

Corrections

First registration

Mileage

Equipment

Other

State of the vehicle -
Earlier repairs -
Braki i uszkodzenia -


Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 05-2025 POL) with regard to technical and market parameters affecting the value of the vehicle.

Basic print without information about the vehicle's value - duey to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 28-05-2025

DEKRA's expert:
Kacper Sosnowski (NEW)
Paweł Szwabowicz

Document issued electronically valid without signature.

Measurement of thickness of the vehicle lacquer coating


No. of controlled item	Controlled item	Measured range of thickness of the lacquer coat [µm]
1	Front cover	150 - 300
2	Left front fender	150 - 300
3	Left front pillar	to 150
4	Left front wall	150 - 300
5	Roof	to 150
6	Left middle pillar	150 - 200
7	Left side sill	150 - 200
8	Left rear wall	150 - 300
9	Left side wall	150 - 300
11	Side right wall	150 - 300
12	Rear right door	150 - 300
13	Middle right pillar	150 - 200
14	Front right door	150 - 300
15	Right side sill	150 - 200
16	Right front pillar	to 150
17	Right front fender	150 - 300

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

During the inspection the registration proof of the vehicle was presented and its photo was taken and enclosed to the expertise.

During the inspection the service book of the vehicle was not provided.

Information concerning the origin of the vehicle

The vehicle purchased domestically from an authorized representative of the brand.

Additional comments on the car:

Not applicable.

Test drive

Test drive of the vehicle was conducted. Test drive in the full extent is not possible. Comment below:
Warunki parkingowe

Checking of the correctness and / or construction of identification / serial numbers of the object:

Not tested

Verification of the accuracy of the object data, including year of production, and other.

Not conducted - adopted according to the documents presented and indicated sources.

Anti-theft protection

Immobiliser

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.
- The evaluation has been carried out basing on delivered documentation and organoleptic examination of the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the assessed object.
- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

Comments to the commission - regarding valuation**Kluczyki**

TAK

2

Expert comments - regarding valuation

Rysy na samochodzie. Pojazd posiada hak. Informacja o wymaganym. Odpryski na szybie czołowej.

Restrictive disclaimer - regarding valuation

- W Ocenie/Raporcie uwzględniono niesprawności, uszkodzenia, braki itp., które były możliwe do stwierdzenia organoleptycznego, w warunkach oględzin (z uwzględnieniem: stanu czystości pojazdu, warunków atmosferycznych, oświetlenia itd.) oraz bez weryfikacji serwisowej, bez dostępu do spodu pojazdu, bez specjalistycznego sprzętu diagnostycznego (w tym bez diagnostyki komputerowej), bez jazdy próbnej wykonanej w warunkach drogowych z obciążeniem.
- W ramach Oceny/Raportu nie weryfikowano odczytanego stanu drogomierza z zapisami w urządzeniach elektronicznych pojazdu.
- Rzeczoznawca nie bierze na siebie odpowiedzialności za wady ukryte (prawne i fizyczne) oraz ewentualne skutki wynikające z dalszego użytkowania przedmiotu oceny, a także za skutki wykorzystania samej oceny.
- Podane przedziały grubości powłoki lakierowej, dotyczą punktów pomiarowych. Nie mogą być traktowane jako gwarancja, że grubość powłoki lakierowej w innych punktach nie wykracza poza te przedziały.
- Zawarte w niniejszej Ocenie/Raporcie informacje (w tym dotyczące wyposażenia) służą jedynie ogólnym celom informacyjnym. Ocena/Raport nie może być zatem traktowana jako oferta w rozumieniu przepisów Kodeksu Cywilnego oraz opisu towaru ani zapewnienia w rozumieniu art. 4 Ustawy z dnia 27 lipca 2002 roku o szczególnych warunkach sprzedaży konsumenckiej.
- Niniejsza Ocena/Raport nie jest szczegółową oceną stanu technicznego.

Ocenę/Raport wykonano w kierunku ujawnienia uszkodzeń nieakceptowanych z punktu widzenia właściwego przewodnika zwrotu pojazdu lub innych ustaleń ze Zleceniodawcą. Tym samym Ocena/Raport może nie ujmować typowych zużyć i uszkodzeń eksploatacyjnych.

PHOTOGRAPHIC DOCUMENTATION



Photo 1.
Przekątna przednia lewa



Photo 2.
Przód

PHOTOGRAPHIC DOCUMENTATION



Photo 3.

Przekątna przednia prawa



Photo 4.

Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 5.
Bok prawy z tyłu



Photo 6.
Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 7.

Tył



Photo 8.

Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 9.

Bok lewy z tyłu



Photo 10.

Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 11.

Próg lewy (widok od przodu)



Photo 12.

Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



Photo 13.
Spód pojazdu przód



Photo 14.
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION



Photo 15.

Tarcza hamulcowa przednia prawa



Photo 16.

Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 17.

Tarcza hamulcowa tylna lewa



Photo 18.

Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 19.
Bagażnik



Photo 20.
Koło zapasowe

PHOTOGRAPHIC DOCUMENTATION



Photo 21.
Komora silnika



Photo 22.
Numer identyfikacyjny

PHOTOGRAPHIC DOCUMENTATION




Photo 23.

Tabliczka znamionowa



Photo 24.

Zestaw wskaźników - przebieg

PHOTOGRAPHIC DOCUMENTATION



Photo 25.

Widok przez otwarte drzwi przednie lewe



Photo 26.

Kierownica z lewej strony

PHOTOGRAPHIC DOCUMENTATION



Photo 27.

Widok przez otwarte drzwi tylne lewe



Photo 28.

Widok z tylnej kanapy na deskę rozd.

PHOTOGRAPHIC DOCUMENTATION



Photo 29.
Konsola środkowa



Photo 30.
Tunel środkowy

PHOTOGRAPHIC DOCUMENTATION**Photo 31.**

Kierownica (na wprost)

**Photo 32.**

Dowód rej. Str. 1

PHOTOGRAPHIC DOCUMENTATION



Photo 33.

Dow. Rej. Str.2 i klucze



Photo 34.

Instrukcje

PHOTOGRAPHIC DOCUMENTATION



Photo 35.

Zdjęcie do protokołu



Photo 36.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 37.

Zdjęcie do protokołu



Photo 38.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION




Photo 39.

Zdjęcie do protokołu



Photo 40.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 41.

Zdjęcie do protokołu



Photo 42.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 43.

Zdjęcie do protokołu



Photo 44.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 45.

Zdjęcie do protokołu



Photo 46.

Pokrywa komory silnika - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 47.

Spoiler zderzaka przedniego - Rysa/odprysk 1



Photo 48.

Spoiler zderzaka przedniego - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 49.

Wykładzina pokrywy komory silnika - Pęknięcie/rozerwanie 1



Photo 50.

Zderzak - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 51.

Zderzak - Rysa/odprysk 2



Photo 52.

Zderzak - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 53.

Zderzak - Pęknięcie/rozerwanie 1



Photo 54.

Zderzak przedni cz P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 55.

Drzwi przednie P - Rysa/odprysk 1



Photo 56.

Drzwi tylne P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 57.

Lusterko zew P - Rysa/odprysk 1



Photo 58.

Zderzak tylny - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 59.

Drzwi przed L - Rysa/odprysk 1



Photo 60.

Drzwi przed L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 61.

Drzwi tylne L - Rysa/odprysk 1



Photo 62.

Łotnik przedni L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 63.

Podłokietnik środkowy przedni - Inne 1



Photo 64.

Podsufitka - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 65.

Podsufitka - Inne 2