

DEKRA's commission No. : PKOL(W)/LODZ/01243/26/01/08
commission/ damage No. : 24/005231
Date of commission: 08-01-2026

DEKRA Poland - Headquarters
02-673 Warszawa, ul. Konstruktorska 12A

Client :

PKO Leasing SA
Świętokrzyska 36
00-116 Warszawa

Expert:

Kacper Sosnowski (NEW)
DEKRA Polska - współpraca O/Warszawa
Andrzej Sosnowski
DEKRA Polska - Centrala

NOTE:

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

Vehicle data

Group of objects (Eurotax)	cars
EC code (Eurotax)	0145220
Manufacturer	TOYOTA
Model	Corolla TS Kombi 18-22
Type / version	Corolla 1.8 Hybrid GPF Comfort
Body type	KOM
Number of doors / seats	5/5
Curb weight [kg]	1387
Gross vehicle weight [kg]	1835
Wheelbase 1/2	2700
Engine type	spark ignition
Pollution reduction system	GPF
Engine capacity [ccm]	1798
Engine Power [hp/kW]	98/72
Gearbox	automatic
Registration /record No.	WU7596R
VIN / serial number	SB1Z93BE20E337364
Date of first registration	28-11-2022
Date of next. tech. test	28-11-2025
Year of manufacture	2022 (year has been verified with the manufacturer's base)
Readout [km]	164 751 (read)
Body color / type of coating	brązowy/double-layered, metallized

Tyres

axle	Wheel	Manufacturer, type	Size	Measured profile
Front	right	IMPERIAL, SNOWDRAGON HP	205/55 16 91V	3,5 mm
	left	IMPERIAL, SNOWDRAGON HP	205/55 16 91V	3,0 mm
back	right	IMPERIAL, SNOWDRAGON HP	205/55 16 91V	4,0 mm
	left	IMPERIAL, SNOWDRAGON HP	205/55 16 91V	4,0 mm

Standard equipment by Eurotax

- | | |
|--|---|
| 1. Adaptive Cruise Control | 44. LED front dim light |
| 2. Additional gauges | 45. LED rear lights |
| 3. Android Auto, Apple CarPlay | 46. Lane control assistant |
| 4. Antilock-Brake-System (ABS) | 47. Lane control assistant |
| 5. Armrest (s) front | 48. Leather gearshifter/switch |
| 6. Armrest (s) rear | 49. Leather steering wheel |
| 7. Automated High-beam assist | 50. Light Alloy wheels 16" |
| 8. Automatic Emergency Call | 51. Luggage compartment cover |
| 9. Automatic antenna/ window-antenna | 52. Luggage:other |
| 10. Automatic climate control | 53. Mobile Tire System |
| 11. Automatic dimlight activation | 54. Multi functional steering wheel |
| 12. Bluetooth interface | 55. On board computer |
| 13. Bord climate: other | 56. On board monitor |
| 14. Bord communication: other | 57. Other |
| 15. Bord entertainment: other accessories | 58. Other |
| 16. Bumpers: other, Exterior design: other | 59. Other |
| 17. Child lock manually | 60. Other |
| 18. Child seat fixation | 61. Other |
| 19. Cornering Headlights | 62. Other |
| 20. Distribution of braking force electronically | 63. Other |
| 21. Door mirror(s) electrically adjustable in general | 64. Passenger seat height adjustable |
| 22. Door mirrors heated | 65. Power assisted brakes |
| 23. Driver airbag, Passenger airbag | 66. Power windows front, Power windows rear |
| 24. Driver knee airbag | 67. Pre-Crash System |
| 25. Driver seat height adjustable | 68. Radio |
| 26. ESP (Electronical Stabilizing Program) | 69. Radio |
| 27. ESP (Electronical Stabilizing Program), Traction control | 70. Rear bench foldable in two separate parts |
| 28. Exterior lighting: other | 71. Rear bench foldable in two separate parts |
| 29. Extra power outlet | 72. Rear spoiler |
| 30. Extra power outlet | 73. Rear view camera |
| 31. Floor mat | 74. Remote controlled central locking |
| 32. Fog lamps | 75. Rev counter |
| 33. Head airbags front | 76. Roof railing |
| 34. Hill holder | 77. Seats: other |
| 35. Interior decoration: other | 78. Side airbag driver and passenger |
| 36. Interior decoration: other | 79. Steering wheel electrically adjustable |
| 37. Interior lights: other accessories | 80. Textile upholstery |
| 38. Interior lights: other accessories | 81. Traffic sign recognition |
| 39. Interior: other | 82. Tyre pressure control (RDC) |
| 40. Interior: other | 83. USB in |
| 41. Interior: other | 84. Uni-Lackierung |
| 42. Keyless go | 85. Vehicle immobilizer |
| 43. LED Daytime running lights | |

Dealer's equipment (selected items)

- | | |
|-------------------------------------|---|
| 1. Metallic paint | - |
| 2. Park Distance Control rear | - |

Base value of the vehicle

Base value of the vehicle by Eurotax (net) -

CorrectionsFirst registrationMileageEquipmentTyresOther

The validity of the technical examination -
State of the vehicle -
Braki, uszkodzenia stan -


Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 01-2026 POL) with regard to technical and market parameters affecting the value of the vehicle.

Basic print without information about the vehicle's value - duey to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 20-01-2026

DEKRA's expert:
Kacper Sosnowski (NEW)
Andrzej Sosnowski

Document issued electronically valid without signature.

Measurement of thickness of the vehicle lacquer coating


No. of controlled item	Controlled item	Measured range of thickness of the lacquer coat [μm]
1	Front cover	to 150
2	Front left fender	to 150
3	Left front pillar	to 150
4	Front left door	to 150
5	Roof	to 150
6	Left middle pillar	to 150
7	Right side sill	to 150
8	Left rear door	to 150
9	Rear left fender	to 150
11	Right rear fender	to 150
12	Right rear door	to 150
13	Right middle pillar	to 150
14	Right side sill	to 150
15	Front right door	to 150
16	Right front pillar	to 150
17	Front right fender	to 150

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

During the inspection the registration proof of the vehicle was presented and its photo was taken and enclosed to the expertise.

During the inspection the service book of the vehicle was not provided.

Information concerning the origin of the vehicle

Lack of reliable data.

Anti-theft protection - immobilizer

- as a result of the inspection of the vehicle found no malfunctions of the immobilizer in the extent possible to determine during the inspection of the vehicle in the non- workshop conditions.

Anti-theft protection - other:

not found

Additional comments on the car:

Not applicable.

Test drive

Test drive of the vehicle was conducted. Test drive in the full extent is not possible. Comment below:
ograniczenia placowe

Checking of the correctness and / or construction of identification / serial numbers of the object:

Not tested

Verification of the accuracy of the object data, including year of production, and other.

Not conducted - adopted according to the documents presented and indicated sources.

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.
- The evaluation has been carried out basing on delivered documentation and organoleptic examination of the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the

page 5/38

assessed object.

- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

Comments to the commission - regarding valuation

Kluczyki

TAK

2

Expert comments - regarding valuation

Braki aktualnych badań technicznych. Rysy na samochodzie. Odpryski na szybie czołowej.

Rzeczoznawca dokonał oględzin pojazdu w warunkach parkingowych, co mogło ograniczyć pełną ocenę jego stanu technicznego. Dodatkowo, jeżeli jazda próbna została przeprowadzona (informacje w treści raportu), to wykonano ją w warunkach parkingowych, z niewielką prędkością, co może nie odzwierciedlać pełnych warunków eksploatacyjnych. Istnieje możliwość, że w innych okolicznościach ujawnią się dodatkowe uszkodzenia lub usterki, których nie można było wykryć podczas obecnych oględzin. Zalecamy zatem skorzystanie z możliwości oględzin pojazdu we własnym zakresie lub w Autoryzowanej Stacji Obsługi danej marki, co pozwoli na pełniejszą weryfikację stanu technicznego pojazdu przed udziałem w aukcji."

Restrictive disclaimer - regarding valuation

Nie weryfikowano szczegółowo stanu układu napędowego, zawieszenia, kierowniczego, hamulcowego oraz wydechowego. Ocena została wykonana bez użycia podnośnika i specjalistycznego sprzętu diagnostycznego, nie dokonywano demontażu osłon i innych elementów. Ocena określa ogólny stan pojazdu na dzień oględzin w miejscu jego udostępnienia, nie może być zatem traktowana jako kompleksowa ocena stanu technicznego. Specyfikacja wg. programu operacyjnego w zakresie wyposażenia standardowego i dodatkowego nie gwarantuje zgodności ze stanem faktycznym w zakresie możliwym do ustalenia przez rzeczoznawcę podczas oględzin pojazdu.

Pomiar grubości powłoki lakierowej wykonano w miejscach możliwych do ich wykonania pomiary nie gwarantują oryginalności poszczególnych elementów poddanych ocenie.

- W Ocenie/Raporcie uwzględniono niesprawności, uszkodzenia, braki itp., które były możliwe do stwierdzenia organoleptycznego, w warunkach oględzin (z uwzględnieniem: stanu czystości pojazdu, warunków atmosferycznych, oświetlenia itd.) oraz bez weryfikacji serwisowej, bez dostępu do spodu pojazdu, bez specjalistycznego sprzętu diagnostycznego (w tym bez diagnostyki komputerowej), bez jazdy próbnej wykonanej w warunkach drogowych z obciążeniem.
- W ramach Oceny/Raporstu nie weryfikowano odczytanego stanu drogomierza z zapisami w urządzeniach elektronicznych pojazdu.
- Rzeczoznawca nie bierze na siebie odpowiedzialności za wady ukryte (prawne i fizyczne) oraz ewentualne skutki wynikające z dalszego użytkowania przedmiotu oceny, a także za skutki wykorzystania samej oceny.
- Podane przedziały grubości powłoki lakierowej, dotyczą punktów pomiarowych. Nie mogą być traktowane jako gwarancja, że grubość powłoki lakierowej w innych punktach nie wykracza poza te przedziały.

- Zawarte w niniejszej Ocenie/Raporcie informacje (w tym dotyczące wyposażenia) służą jedynie ogólnym celom informacyjnym. Ocena/Raport nie może być zatem traktowana jako oferta w rozumieniu przepisów Kodeksu Cywilnego oraz opisu towaru ani zapewnienia w rozumieniu art. 4 Ustawy z dnia 27 lipca 2002 roku o szczególnych warunkach sprzedaży konsumenckiej.
- Niniejsza Ocena/Raport nie jest szczegółową oceną stanu technicznego.

Ocenę/Raport wykonano w kierunku ujawnienia uszkodzeń nieakceptowanych z punktu widzenia właściwego przewodnika zwrotu pojazdu lub innych ustaleń ze Zleceniodawcą. Tym samym Ocena/Raport może nie ujmować typowych zużyć i uszkodzeń eksploatacyjnych.

PHOTOGRAPHIC DOCUMENTATION



Photo 1.
Przekątna przednia lewa



Photo 2.
Przód

PHOTOGRAPHIC DOCUMENTATION



Photo 3.

Przekątna przednia prawa



Photo 4.

Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 5.
Bok prawy z tyłu



Photo 6.
Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 7.

Tył



Photo 8.

Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 9.

Bok lewy z tyłu




Photo 10.

Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 11.

Próg lewy (widok od przodu)



Photo 12.

Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



Photo 13.
Spód pojazdu przód



Photo 14.
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION



Photo 15.

Tarcza hamulcowa przednia prawa



Photo 16.

Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 17.

Tarcza hamulcowa tylna lewa



Photo 18.

Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 19.
Bagażnik



Photo 20.
Koło zapasowe

PHOTOGRAPHIC DOCUMENTATION



Photo 21.
Komora silnika



Photo 22.
Numer identyfikacyjny

PHOTOGRAPHIC DOCUMENTATION




Photo 23.

Tabliczka znamionowa



Photo 24.

Zestaw wskaźników - przebieg

PHOTOGRAPHIC DOCUMENTATION



Photo 25.

Widok przez otwarte drzwi przednie lewe



Photo 26.

Kierownica z lewej strony

PHOTOGRAPHIC DOCUMENTATION



Photo 27.

Widok przez otwarte drzwi tylne lewe



Photo 28.

Widok z tylnej kanapy na deskę rozd.

PHOTOGRAPHIC DOCUMENTATION



Photo 29.

Konsola środkowa



Photo 30.

Tunel środkowy

PHOTOGRAPHIC DOCUMENTATION



Photo 31.

Kierownica (na wprost)



Photo 32.

Dowód rej. Str. 1

PHOTOGRAPHIC DOCUMENTATION



Photo 33.

Dow. Rej. Str.2 i klucze




Photo 34.

Instrukcje

PHOTOGRAPHIC DOCUMENTATION



Photo 35.
Zestaw naprawczy koła



Photo 36.
Pokrywa komory silnika - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 37.

Pokrywa komory silnika - Wgniecenie/odkształcenie 1



Photo 38.

Spoiler zderzaka przedniego - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 39.

Spoiler zderzaka przedniego - Wgniecenie/odkształcenie 1



Photo 40.

Zderzak - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 41.

Zderzak - Rysa/odprysk 2



Photo 42.

Drzwi przednie P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 43.

Drzwi tylne P - zdjęcie poglądowe 1




Photo 44.

Drzwi tylne P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 45.

Błotnik tylny P / Ściana boczna P - Wgniecenie/odkształcenie 1



Photo 46.

Pokrywy bagażnika - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 47.

Pokrywy bagażnika - Wgniecenie/odkształcenie 2



Photo 48.

Szyba tylna - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 49.

Zderzak tylny - Rysa/odprysk 1



Photo 50.

Zderzak tylny - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 51.

Dach - Wgniecenie/odkształcenie 1



Photo 52.

Ścianka tylna L / Ścianka boczna L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION




Photo 53.

Drzwi przed L - Wgniecenie/odkształcenie 1




Photo 54.

Drzwi tylne L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION




Photo 55.

Drzwi tylne L - Wgniecenie/odkształcenie 2




Photo 56.

Fotel prz. lew. - Inne 1

PHOTOGRAPHIC DOCUMENTATION




Photo 57.

Fotel prz. praw. - Inne 1



Photo 58.

Kanapa tyl. - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 59.
Kanapa tyl. - Inne 2



Photo 60.
Tapicerka drzwi przednich L - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 61.

Tapicerka drzwi tylnych L - Inne 1