

DEKRA's commission No. : PKOL(W)/LODZ/93766/25/12/01
commission/ damage No. : 22/032363
Date of commission: 01-12-2025

DEKRA Poland - Headquarters
02-673 Warszawa, ul. Konstruktorska 12A

Client :

PKO Leasing SA
Świętokrzyska 36
00-116 Warszawa

Expert:

Kacper Sosnowski (NEW)
DEKRA Polska - współpraca O/Warszawa
Bartłomiej Chodakowski (NEW)
DEKRA Polska - współpraca O/Wrocław

NOTE:

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

Vehicle data

Group of objects (Eurotax)	cars
EC code (Eurotax)	0152626
Manufacturer	BMW
Model	Seria 4 Coupe [G22/G82] 20-24
Type / version	M4 Competition M xDrive sport-aut
Body type	CPE
Number of doors / seats	2/4
Curb weight [kg]	1775
Gross vehicle weight [kg]	2205
Wheelbase 1/2	2857
Engine type	spark ignition
Pollution reduction system	GPF
Engine capacity [ccm]	2993
Engine Power [hp/kW]	510/375
Gearbox	automatic 8- gear
Registration /record No.	WU0435R
VIN / serial number	WBS41AZ090CK70598
Date of first registration	25-10-2022
Date of next. tech. test	25-10-2027
Year of manufacture	2022 (year has been verified with the manufacturer's base)
Readout [km]	69 344 (read)
Body color / type of coating	black/METALIK

Tyres

axle	Wheel	Manufacturer, type	Size	Measured profile
Front	right	MICHELIN, PILOT SPORT 4S	275/35 19 100Y	4,5 mm
	left	MICHELIN, PILOT SPORT 4S	275/35 19 100Y	4,5 mm
back	right	MICHELIN, PILOT SPORT 4S	285/30 20 99Y	3,5 mm
	left	MICHELIN, PILOT SPORT 4S	285/30 20 99Y	3,5 mm

Standard equipment by Eurotax

- | | |
|--|---|
| 1. Active speed sign recognition, Traffic sign recognition | 46. Interior decoration: other |
| 2. Additional gauges, Bluetooth interface, Digital instruments, Internet access, Navigation system, On board monitor, Radio, Touchscreen monitor, USB in, Voice control for audiosystem, Voice control for navigation system | 47. Interior lights: other accessories |
| 3. Additional gauges, Bord communication: other | 48. Interior lights: other accessories |
| 4. Airbag: other | 49. Interior lights: other accessories, Storage facilities in general |
| 5. Airbag: other, Head airbags front, Head airbags rear | 50. Interior: other |
| 6. Alarm | 51. Interior: other |
| 7. Android Auto, Apple CarPlay | 52. Keyless Engine start, Keyless go |
| 8. Antilock-Brake-System (ABS) | 53. LED front dim light, LED rear lights |
| 9. Armrest (s) front | 54. Lane control assistant |
| 10. Armrest (s) rear | 55. Leather steering wheel, Multi functional steering wheel, Sports steering wheel |
| 11. Automatic climate control | 56. Leather upholstery |
| 12. Bluetooth interface, Hands-free system, USB in | 57. Light Alloy wheels 19'', Light Alloy wheels 20'' |
| 13. Bord communication: other | 58. Lumbar adjust driver electric, Lumbar adjust passenger electric |
| 14. Bord communication: other | 59. Metallic paint |
| 15. Bord communication: other | 60. Mobile Tire System |
| 16. Bord communication: other | 61. Other |
| 17. Bord communication: other | 62. Other |
| 18. Brake Assist, Collision Warning System, Pedestrian Emergency Brake Assist | 63. Other |
| 19. Chassis: other | 64. Other |
| 20. Child seat fixation | 65. Other |
| 21. Collision Warning System, Other | 66. Other |
| 22. Colored glass | 67. Other |
| 23. Cruise control | 68. Other |
| 24. DAB radio | 69. Other |
| 25. Door mirrors autodimming, Door mirrors electrically foldable, Other, Rear-view mirror autodimming | 70. Park Assistant, Park Distance Control front, Park Distance Control rear, Rear view camera |
| 26. Driver airbag, Head airbags front, Head airbags rear, Passenger airbag, Side airbag driver and passenger, Side airbags rear | 71. Rain sensor |
| 27. Driver seat electrically adjustable, Memory seat, Passenger seat electrically adjustable | 72. Rear seat-backs foldable in two separate parts |
| 28. ESP (Electronical Stabilizing Program), Traction control | 73. Remote controlled central locking |
| 29. Electronic controlled suspension, Sport suspension | 74. Roof: other |
| 30. Exterior design: other | 75. Selectable central differential characteristics |
| 31. Exterior design: other | 76. Selectable driveline characteristics |
| 32. Exterior design: other | 77. Servotronic |
| 33. Exterior design: other | 78. Soundsystem |
| 34. Exterior design: other | 79. Sport seats front |
| 35. Exterior design: other | 80. Steering wheel manually adjustable |
| 36. Exterior design: other | 81. Steering: other |
| 37. Exterior design: other | 82. Storage facilities in general |
| 38. Exterior design: other | 83. Telematic |
| 39. Exterior design: other | 84. Telematic |

- | | |
|---|---------------------------------|
| 40. Exterior lighting: other | 85. Traction control |
| 41. Extra power outlet | 86. Tyre pressure control (RDC) |
| 42. Floor mat | 87. USB in |
| 43. Follow me home | 88. Vehicle immobilizer |
| 44. Follow me home | 89. Wheel bolt locks |
| 45. Heated seat driver, Heated seat passenger | |

Dealer's equipment (selected items)

- | | | |
|---|-------|---|
| 1. Adaptive light | | - |
| 2. Digital key, Keyless entry, Keyless go | | - |
| 3. Electric tailgate | | - |
| 4. Head-Up Display | | - |
| 5. Mobile phone | | - |
| 6. Other | | - |

Base value of the vehicle

Base value of the vehicle by Eurotax (net) -

Corrections

First registration

Mileage

Equipment

Tyres

Above figure was estimated on the basis of price quotations of used cars on the Polish market taking into account the technical and market parameters affecting the value of the vehicle.

Basic print without information about the vehicle's value - due to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 12-12-2025

DEKRA's expert:
Kacper Sosnowski (NEW)
Bartłomiej Chodakowski (NEW)

Document issued electronically valid without signature.

Measurement of thickness of the vehicle lacquer coating



No. of controlled item	Controlled item	Measured range of thickness of the lacquer coat [μm]
1	Front cover	150 - 300
2	Front left fender	150 - 300
3	Left front pillar	150 - 300
4	Front left door	to 150
5	Roof	150 - 2000
6	Left middle pillar	to 150
7	Right side sill	to 150
9	Rear left fender	to 150
10	Cover/lid	to 150
11	Right rear fender	to 150
13	Right middle pillar	to 150
14	Right side sill	to 150
15	Front right door	to 150
16	Right front pillar	150 - 300
17	Front right fender	150 - 300

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

During the inspection the registration proof of the vehicle was presented and its photo was taken and enclosed to the expertise.

During the inspection the service book was presented and its number is given below:

Elektroniczna

Information concerning the origin of the vehicle

The vehicle purchased domestically from an authorized representative of the brand.

Anti-theft protection - immobilizer

- as a result of the inspection of the vehicle found no malfunctions of the immobilizer in the extent possible to determine during the inspection of the vehicle in the non- workshop conditions.

Anti-theft protection - other:

not found

Additional comments on the car:

Not applicable.

Test drive

Test drive of the vehicle was conducted. Test drive in the full extent is not possible. Comment below:

Warunki parkingowe

Checking of the correctness and / or construction of identification / serial numbers of the object:

Not tested

Verification of the accuracy of the object data, including year of production, and other.

Not conducted - adopted according to the documents presented and indicated sources.

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.
- The evaluation has been carried out basing on delivered documentation and organoleptic examination of

the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the assessed object.

- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

Comments to the commission - regarding valuation

Kluczyki

TAK

2

Expert comments - regarding valuation

Niesprawne przyciski funkcyjne w jednym z kluczyków, grot prawidłowy. Pojazd oklejony folią. Pomiar lakieru wykonany na folii, elementy: pokrywa przednia, dach, słupki przedni lewy/prawy, błotnik przedni lewy/prawy. Rysy na samochodzie. Odpryski na szybie czołowej. Reflektory oklejone folią. Lampy tylne oklejone folią.

Restrictive disclaimer - regarding valuation

- W Ocenie/Raporcie uwzględniono niesprawności, uszkodzenia, braki itp., które były możliwe do stwierdzenia organoleptycznego, w warunkach oględzin (z uwzględnieniem: stanu czystości pojazdu, warunków atmosferycznych, oświetlenia itd.) oraz bez weryfikacji serwisowej, bez dostępu do spodu pojazdu, bez specjalistycznego sprzętu diagnostycznego (w tym bez diagnostyki komputerowej), bez jazdy próbnej wykonanej w warunkach drogowych z obciążeniem.
- W ramach Oceny/Raporu nie weryfikowano odczytanego stanu drogomierza z zapisami w urządzeniach elektronicznych pojazdu.
- Rzeczoznawca nie bierze na siebie odpowiedzialności za wady ukryte (prawne i fizyczne) oraz ewentualne skutki wynikające z dalszego użytkowania przedmiotu oceny, a także za skutki wykorzystania samej oceny.
- Podane przedziały grubości powłoki lakierowej, dotyczą punktów pomiarowych. Nie mogą być traktowane jako gwarancja, że grubość powłoki lakierowej w innych punktach nie wykracza poza te przedziały.
- Zawarte w niniejszej Ocenie/Raporcie informacje (w tym dotyczące wyposażenia) służą jedynie ogólnym celom informacyjnym. Ocena/Raport nie może być zatem traktowana jako oferta w rozumieniu przepisów Kodeksu Cywilnego oraz opisu towaru ani zapewnienia w rozumieniu art. 4 Ustawy z dnia 27 lipca 2002 roku o szczególnych warunkach sprzedaży konsumenckiej.
- Niniejsza Ocena/Raport nie jest szczegółową oceną stanu technicznego.

Ocenę/Raport wykonano w kierunku ujawnienia uszkodzeń nieakceptowanych z punktu widzenia właściwego przewodnika zwrotu pojazdu lub innych ustaleń ze Zleceniodawcą. Tym samym Ocena/Raport może nie ujmować typowych zużyć i uszkodzeń eksploatacyjnych.

PHOTOGRAPHIC DOCUMENTATION



Photo 1.

Przekątna przednia lewa



Photo 2.

Przód

PHOTOGRAPHIC DOCUMENTATION



Photo 3.

Przekątna przednia prawa



Photo 4.

Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 5.
Bok prawy z tyłu



Photo 6.
Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 7.

Tył



Photo 8.

Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 9.

Bok lewy z tyłu



Photo 10.

Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 11.

Próg lewy (widok od przodu)



Photo 12.

Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



Photo 13.
Spód pojazdu przód



Photo 14.
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION



Photo 15.

Tarcza hamulcowa przednia prawa



Photo 16.

Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 17.

Tarcza hamulcowa tylna lewa



Photo 18.

Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION




Photo 19.
Bagażnik



Photo 20.
Koło zapasowe

PHOTOGRAPHIC DOCUMENTATION



Photo 21.
Komora silnika



Photo 22.
Numer identyfikacyjny

PHOTOGRAPHIC DOCUMENTATION



Photo 23.

Tabliczka znamionowa



Photo 24.

Zestaw wskaźników - przebieg

PHOTOGRAPHIC DOCUMENTATION



Photo 25.

Widok przez otwarte drzwi przednie lewe



Photo 26.

Kierownica z lewej strony

PHOTOGRAPHIC DOCUMENTATION



Photo 27.

Widok przez otwarte drzwi tylne lewe



Photo 28.

Widok z tylnej kanapy na deskę rozdz.

PHOTOGRAPHIC DOCUMENTATION



Photo 29.
Konsola środkowa



Photo 30.
Tunel środkowy

PHOTOGRAPHIC DOCUMENTATION



Photo 31.
Kierownica (na wprost)



Photo 32.
Dowód rej. Str. 1

PHOTOGRAPHIC DOCUMENTATION



Photo 33.

Dow. Rej. Str.2 i klucze




Photo 34.

Książka serwisowa – dane

PHOTOGRAPHIC DOCUMENTATION



Photo 35.

Książka serwisowa – ostatni przegląd



Photo 36.

Zestaw naprawczy koła

PHOTOGRAPHIC DOCUMENTATION



Photo 37.
Zdjęcie do protokołu



Photo 38.
Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 39.

Zdjęcie do protokołu



Photo 40.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 41.

Zdjęcie do protokołu




Photo 42.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 43.

Zdjęcie do protokołu



Photo 44.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 45.

Zdjęcie do protokołu



Photo 46.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 47.

Pokrywa komory silnika - Rysa/odprysk 1



Photo 48.

Szyba czołowa - zdjęcie poglądowe 1

PHOTOGRAPHIC DOCUMENTATION




Photo 49.

Szyba czołowa - Pęknięcie/rozerwanie 1



Photo 50.

Zderzak - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 51.

Zderzak - Inne 2



Photo 52.

Błotnik przedni P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 53.

Felga aluminiowa tylna P - Rysa/odprysk 1



Photo 54.

Ścianka tylna L / Ścianka boczna L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 55.

Błotnik tylny L / Ściana boczna L - Rysa/odprysk 2



Photo 56.

Błotnik tylny L / Ściana boczna L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 57.

Felga aluminiowa tylna L - Rysa/odprysk 1



Photo 58.

Drzwi przed L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 59.

Drzwi przed L - Rysa/odprysk 2



Photo 60.

Próg L - zdjęcie poglądowe 1

PHOTOGRAPHIC DOCUMENTATION




Photo 61.
Próg L - Inne 1



Photo 62.
Felga Aluminiowa przednia L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 63.

Fotel prz. lew. - Inne 1



Photo 64.

Fotel prz. praw. - Rysa/odprysk 1