

DEKRA's commission No. : PKOL(W)/LODZ/84092/25/10/31
commission/ damage No. : 23/010216
Date of commission: 31-10-2025

DEKRA Poland - Headquarters
02-673 Warszawa, ul. Konstruktorska 12A

Client :

PKO Leasing SA
Świętokrzyska 36
00-116 Warszawa

Expert:

Kacper Sosnowski (NEW)
DEKRA Polska - współpraca O/Warszawa
Andrzej Sosnowski
DEKRA Polska - Centrala

NOTE:

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

Vehicle data

Group of objects (Eurotax)	jeeps
EC code (Eurotax)	0151586
Manufacturer	BMW
Model	X6 [G06] 19-23
Type / version	X6 M Competition
Body type	hatchback
Number of doors / seats	5/5
Curb weight [kg]	2295
Gross vehicle weight [kg]	2975
Wheelbase 1/2	2975
Engine type	spark ignition
Pollution reduction system	GPF
Engine capacity [ccm]	4395
Engine Power [hp/kW]	625/460
Gearbox	automatic
Registration /record No.	KK80767
VIN / serial number	WBSCY010309E09508
Date of first registration	12-03-2021
Date of next. tech. test	12-03-2026
Year of manufacture	2020 (year has been verified with the manufacturer's base)
Readout [km]	90 929 (read)
Body color / type of coating	black/double-layered, metallized

Tyres

axle	Wheel	Manufacturer, type	Size	Measured profile
Front	right	PIRELLI, P ZERO	295/35 21 107Y	4,0 mm
	left	PIRELLI, P ZERO	295/35 21 107Y	4,0 mm
back	right	PIRELLI, P ZERO	315/30 22 107Y	4,5 mm
	left	PIRELLI, P ZERO	315/30 22 107Y	4,5 mm

Standard equipment by Eurotax

- | | |
|--|---|
| 1. 4 or more zone automatic climate control, Air condition rear | 46. Follow me home |
| 2. Active Blind spot system, Blind spot warning | 47. Gesture control for multimedia, Gesture control for vehicle functions |
| 3. Active speed sign recognition | 48. Head-Up Display |
| 4. Airbag: other | 49. Headlamp wash nozzle heated |
| 5. Alarm | 50. Heated seat driver, Heated seat passenger |
| 6. Android Auto, Apple CarPlay | 51. Hill descent control |
| 7. Antilock-Brake-System (ABS) | 52. Interior decoration: other |
| 8. Armrest (s) front, Armrest (s) rear | 53. Interior lights: other accessories |
| 9. Automated High-beam assist | 54. Interior: other |
| 10. Automatic Emergency Call | 55. Interior: other |
| 11. Automatic Emergency Call | 56. Interior: other |
| 12. Automatic dimlight activation, Rain sensor | 57. Keyless Engine start |
| 13. Bluetooth interface, Bord entertainment: other accessories, Mobile phone, Wireless device charging | 58. Keyless entry, Keyless go |
| 14. Bluetooth interface, Digital instruments, Internet access, Navigation system, On board monitor, Radio, Touchscreen monitor, USB in, Voice control for audiosystem, Voice control for navigation system | 59. LED rear lights |
| 15. Bluetooth interface, Extra power outlet, USB in | 60. Lane control assistant |
| 16. Bord entertainment: other accessories | 61. Leather finish dashbord |
| 17. Bord entertainment: other accessories | 62. Leather steering wheel, Sports steering wheel |
| 18. Bord entertainment: other accessories | 63. Light Allow wheels over 21" |
| 19. Bord entertainment: other accessories, Soundsystem | 64. Limited slip differential: other |
| 20. Child lock manually | 65. Lumbar adjust driver, Lumbar adjust passenger |
| 21. Child seat fixation | 66. Metalic paint |
| 22. Collision Warning System | 67. Mobile Tire System |
| 23. Collision Warning System, Pedestrian Emergency Brake Assist | 68. Multi functional steering wheel |
| 24. Cornering Headlights, LED front dim light | 69. Other |
| 25. Cruise control, Distance control | 70. Other |
| 26. DAB radio | 71. Other |
| 27. Door mirrors autodimming, Door mirrors electrically foldable, Door mirrors heated, Mirror: others, Other | 72. Other |
| 28. Driver airbag, Head airbags front, Head airbags rear, Passenger airbag, Side airbag driver and passenger, Side airbags rear | 73. Other |
| 29. Driver seat electrically adjustable, Memory seat, Passenger seat electrically adjustable | 74. Other |
| 30. Driver-information-system | 75. Other |
| 31. ESP (Electronical Stabilizing Program), Traction control | 76. Other |
| 32. Electric parking brake | 77. Other |
| 33. Electric tailgate | 78. Park Assistant, Park Distance Control front, Park Distance Control rear, Rear view camera |
| 34. Engine: other | 79. Power assisted brakes |
| 35. Exterior design: other | 80. Power windows front, Power windows rear |
| 36. Exterior design: other | 81. Rear Cross Traffic Alert |
| 37. Exterior design: other | 82. Rear seat-backs foldable in two separate parts |
| 38. Exterior design: other | 83. Remote controlled central locking |
| 39. Exterior design: other | 84. Servotronic |
| 40. Exterior design: other | 85. Sport seats front |
| 41. Exterior design: other | 86. Steering wheel electrically adjustable |

- 42. Exterior lighting: other
- 43. Exterior lighting: other
- 44. Fire protection system
- 45. Floor mat

- 87. Tyre pressure control (RDC)
- 88. Upholstery with leather inserts
- 89. Wheel bolt locks

Dealer's equipment (selected items)

- 1. 360 view camera, Park Assistant -
- 2. Acoustic windows -
- 3. Active Emergency Brake Assist, Adaptive Cruise Control, Collision Warning System, Intersection Assist, Lane control assistant -
 - Tempomat aktywny z funkcją Stop&Go
 - System ostrzegający przed ruchem poprzecznym z przodu
 - Asystent unikania kolizji
 - Aktywna ochrona przed kolizją boczną
 - Asystent kierowania i pasa ruchu
 - Asystent zatrzymania awaryjnego
 - Asystent zmiany pasa ruchu
- 4. Armrest (s) front, Bord climate: other, Steering wheel heated -
 - Podłokietniki przednie ogrzewane
 - Kierownica ogrzewana
- 5. Digital key -
- 6. Door: other -
- 7. Engine: other -
- 8. Exterior design: other, Mirror: others -
- 9. Free service 3 years, more than 60 000 km -
- 10. Front seat with massage -
- 11. Glass tilt/slide sunroof electric -
- 12. Interior decoration: other -
- 13. Interior decoration: other, Leather upholstery -
- 14. Interior: other -
- 15. Interior: other -
- 16. Other -
- 17. Other -
- 18. Other -
- 19. Other, Sunblind tailgate window electric -
- 20. Rear spoiler -
- 21. Tinted rear windows -
- 22. Towbar removable -
- 23. Ventilated front seat -
- 24. {Światła laserowe BMW} -

Base value of the vehicle

Base value of the vehicle (net) -

Corrections

First registration

Equipment

Tyres

Other

State of the vehicle -
Aktualna sytuacja rynkowa -
Braki uszkodzenia stan -


Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 11-2025 POL) with regard to technical and market parameters affecting the value of the vehicle.

Basic print without information about the vehicle's value - duey to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 11-11-2025

DEKRA's expert:
Kacper Sosnowski (NEW)
Andrzej Sosnowski

Document issued electronically valid without signature.

Measurement of thickness of the vehicle lacquer coating


No. of controlled item	Controlled item	Measured range of thickness of the lacquer coat [μm]
1	Front cover	to 150
2	Left front fender	to 150
3	Left front pillar	to 150
4	Left front wall	to 150
5	Roof	to 150
6	Left middle pillar	to 150
7	Left side sill	to 150
8	Left rear wall	to 150
9	Left side wall	to 150
10	Cover/tailgate	to 150
11	Side right wall	to 150
12	Rear right door	to 150
13	Middle right pillar	to 150
14	Front right door	to 150
15	Right side sill	to 150
16	Right front pillar	to 150
17	Right front fender	to 150

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

During the inspection the registration proof of the vehicle was presented and its photo was taken and enclosed to the expertise.

During the inspection the service book was presented and its number is given below:
elektroniczne

Information concerning the origin of the vehicle

Lack of reliable data.

Additional comments on the car:

Not applicable.

Test drive

Test drive of the vehicle was conducted. Test drive in the full extent is not possible. Comment below:
ograniczenia placowe

Checking of the correctness and / or construction of identification / serial numbers of the object:

Not tested

Verification of the accuracy of the object data, including year of production, and other.

Not conducted - adopted according to the documents presented and indicated sources.

Anti-theft protection

fabryczne

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.
- The evaluation has been carried out basing on delivered documentation and organoleptic examination of the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the assessed object.
- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

Comments to the commission - regarding valuation**Kluczyki**

TAK

1

Expert comments - regarding valuation

Niesprawne elektryczne domykanie drzwi przednich lewych. Brak czterech dywaników. Odpryski na szybie czołowej. Rysy na samochodzie.

Rzeczoznawca dokonał oględzin pojazdu w warunkach parkingowych, co mogło ograniczyć pełną ocenę jego stanu technicznego. Dodatkowo, jeżeli jazda próbna została przeprowadzona (informacje w treści raportu), to wykonano ją w warunkach parkingowych, z niewielką prędkością, co może nie odzwierciedlać pełnych warunków eksploatacyjnych. Istnieje możliwość, że w innych okolicznościach ujawnią się dodatkowe uszkodzenia lub usterki, których nie można było wykryć podczas obecnych oględzin. Zalecamy zatem skorzystanie z możliwości oględzin pojazdu we własnym zakresie lub w Autoryzowanej Stacji Obsługi danej marki, co pozwoli na pełniejszą weryfikację stanu technicznego pojazdu przed udziałem w aukcji."

Restrictive disclaimer - regarding valuation

Nie weryfikowano szczegółowo stanu układu napędowego, zawieszenia, kierowniczego, hamulcowego oraz wydechowego. Ocena została wykonana bez użycia podnośnika i specjalistycznego sprzętu diagnostycznego, nie dokonywano demontażu osłon i innych elementów. Ocena określa ogólny stan pojazdu na dzień oględzin w miejscu jego udostępnienia, nie może być zatem traktowana jako kompleksowa ocena stanu technicznego. Specyfikacja wg. programu operacyjnego w zakresie wyposażenia standardowego i dodatkowego nie gwarantuje zgodności ze stanem faktycznym w zakresie możliwym do ustalenia przez rzeczoznawcę podczas oględzin pojazdu.

Pomiar grubości powłoki lakierowej wykonano w miejscach możliwych do ich wykonania pomiary nie gwarantują oryginalności poszczególnych elementów poddanych ocenie.

- W Ocenie/Raporcie uwzględniono niesprawności, uszkodzenia, braki itp., które były możliwe do stwierdzenia organoleptycznego, w warunkach oględzin (z uwzględnieniem: stanu czystości pojazdu, warunków atmosferycznych, oświetlenia itd.) oraz bez weryfikacji serwisowej, bez dostępu do spodu pojazdu, bez specjalistycznego sprzętu diagnostycznego (w tym bez diagnostyki komputerowej), bez jazdy próbnej wykonanej w warunkach drogowych z obciążeniem.
- W ramach Oceny/Raportu nie weryfikowano odczytanego stanu drogomierza z zapisami w urządzeniach elektronicznych pojazdu.
- Rzeczoznawca nie bierze na siebie odpowiedzialności za wady ukryte (prawne i fizyczne) oraz ewentualne skutki wynikające z dalszego użytkowania przedmiotu oceny, a także za skutki wykorzystania samej oceny.
- Podane przedziały grubości powłoki lakierowej, dotyczą punktów pomiarowych. Nie mogą być traktowane jako gwarancja, że grubość powłoki lakierowej w innych punktach nie wykracza poza te przedziały.
- Zawarte w niniejszej Ocenie/Raporcie informacje (w tym dotyczące wyposażenia) służą jedynie ogólnym celom informacyjnym. Ocena/Raport nie może być zatem traktowana jako oferta w rozumieniu przepisów Kodeksu Cywilnego oraz opisu towaru ani zapewnienia w rozumieniu art. 4 Ustawy z dnia 27 lipca 2002 roku o szczególnych warunkach sprzedaży konsumenckiej.
- Niniejsza Ocena/Raport nie jest szczegółową oceną stanu technicznego.

Ocenę/Raport wykonano w kierunku ujawnienia uszkodzeń nieakceptowanych z punktu widzenia właściwego przewodnika zwrotu pojazdu lub innych ustaleń ze Zleceniodawcą. Tym samym Ocena/Raport może nie ujmować typowych zużyć i uszkodzeń eksploatacyjnych.

PHOTOGRAPHIC DOCUMENTATION



Photo 1.

Przekątna przednia lewa



Photo 2.

Przód

PHOTOGRAPHIC DOCUMENTATION



Photo 3.

Przekątna przednia prawa



Photo 4.

Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 5.

Bok prawy z tyłu



Photo 6.

Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 7.

Tył



Photo 8.

Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 9.

Bok lewy z tyłu



Photo 10.

Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 11.

Próg lewy (widok od przodu)



Photo 12.

Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



Photo 13.
Spód pojazdu przód



Photo 14.
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION



Photo 15.

Tarcza hamulcowa przednia prawa



Photo 16.

Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 17.

Tarcza hamulcowa tylna lewa



Photo 18.

Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 19.
Bagażnik



Photo 20.
Koło zapasowe

PHOTOGRAPHIC DOCUMENTATION



Photo 21.
Komora silnika



Photo 22.
Numer identyfikacyjny

PHOTOGRAPHIC DOCUMENTATION



Photo 23.

Tabliczka znamionowa



Photo 24.

Zestaw wskaźników - przebieg

PHOTOGRAPHIC DOCUMENTATION



Photo 25.

Widok przez otwarte drzwi przednie lewe



Photo 26.

Kierownica z lewej strony

PHOTOGRAPHIC DOCUMENTATION



Photo 27.

Widok przez otwarte drzwi tylne lewe




Photo 28.

Widok z tylnej kanapy na deskę rozd.

PHOTOGRAPHIC DOCUMENTATION



Photo 29.

Konsola środkowa



Photo 30.

Tunel środkowy

A detailed view of the front interior of a BMW M5. The steering wheel is black leather with silver accents and the BMW logo in the center. The instrument cluster is a digital display showing various driving metrics. The infotainment screen displays a navigation map. The interior features a combination of black and light-colored leather upholstery.

[illegible]

DEKRA Polska Sp. z o.o.
02-673 Warszawa, ul. Konstruktorska 12A
www.dekra.pl

PHOTOGRAPHIC DOCUMENTATION



Photo 33.

Dow. Rej. Str.2 i klucze




Photo 34.

Książka serwisowa – dane

PHOTOGRAPHIC DOCUMENTATION



Photo 35.

Książka serwisowa – ostatni przegląd



Photo 36.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 37.
Zdjęcie do protokołu



Photo 38.
Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 39.

Zdjęcie do protokołu




Photo 40.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 41.

Zdjęcie do protokołu



Photo 42.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 43.

Zdjęcie do protokołu



Photo 44.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 45.

Zdjęcie do protokołu



Photo 46.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 47.

Zdjęcie do protokołu



Photo 48.

Pokrywa komory silnika - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 49.

Pokrywa komory silnika - Rysa/odprysk 2



Photo 50.

Pokrywa komory silnika() - Rysa/odprysk 3

PHOTOGRAPHIC DOCUMENTATION



Photo 51.

Szyba czołowa - zdjęcie poglądowe 1




Photo 52.

Szyba czołowa - Pęknięcie/rozerwanie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 53.

Błotnik przedni P - Wgniecenie/odkształcenie 1



Photo 54.

Felga aluminiowa przednia P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 55.

Listwa błotnika przedniego P - Wgniecenie/odkształcenie 1



Photo 56.

Drzwi przednie P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 57.

Drzwi tylne P - Rysa/odprysk 1



Photo 58.

Drzwi tylne P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 59.

Próg P - Wgniecenie/odkształcenie 1



Photo 60.

Słupek przedni P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 61.

Słupek przedni P - Wgniecenie/odkształcenie 1



Photo 62.

Ścianka tylna P / Ścianka boczna P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 63.

Felga aluminiowa tylna P - Rysa/odprysk 1



Photo 64.

Listwa krawędzi błotnika tyl P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 65.

Listwa krawędzi błotnika tyl P - Wgniecenie/odkształcenie 1



Photo 66.

Pokrywy bagażnika - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 67.

Zderzak tylny - Rysa/odprysk 1



Photo 68.

Zderzak tylny - Rysa/odprysk 2

PHOTOGRAPHIC DOCUMENTATION



Photo 69.

Zderzak tylny() - Rysa/odprysk 3



Photo 70.

Błotnik tylny L / Ściana boczna L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 71.

Listwa krawędzi błotnika tyl L - Wgniecenie/odkształcenie 1



Photo 72.

Drzwi przed L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 73.

Drzwi tylne L - Rysa/odprysk 1



Photo 74.

Słupki przedni L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 75.

Słupek przedni L - Wgniecenie/odkształcenie 1



Photo 76.

Felga Aluminiowa przednia L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 77.

Listwa błotnika przedniego L - Rysa/odprysk 1



Photo 78.

Reflektor L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 79.

Deska rozdzielcza - Pęknięcie/rozerwanie 1



Photo 80.

Koło kierownicy - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 81.

Fotel prz. lew. - Inne 1



Photo 82.

Tapicerka drzwi tylnych L - Pęknięcie/rozerwanie 1

PHOTOGRAPHIC DOCUMENTATION




Photo 83.

Wykładzina(y) słupka środkowego L - Inne 1