

DEKRA's commission No. : PKOL(W)/LODZ/30364/25/04/28
commission/ damage No. : 23/033529
Date of commission: 28-04-2025

DEKRA Poland - Headquarters
02-673 Warszawa, ul. Konstruktorska 12A

Client :

PKO Leasing SA
Świętokrzyska 36
00-116 Warszawa

Expert:

Kacper Sosnowski (NEW)
DEKRA Polska - współpraca O/Warszawa
Andrzej Sosnowski
DEKRA Polska - Centrala

NOTE:

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

Vehicle data

Group of objects (Eurotax)	vans up to 3.5 t
EC code (Eurotax)	0156142
Manufacturer	CITROEN
Model	Berlingo Van 1.5 BlueHDI Euro 6 1499ccm - 102KM
Type	2/2,4t 19-24 Berlingo Van 1.5 BlueHDI XL
Body type	FUR
Number of doors / seats	5/5
Curb weight [kg]	1597
Gross vehicle weight [kg]	2400
Wheelbase 1/2	2975
Engine type	Automatic ignition
Pollution reduction system	SCE
Engine capacity [ccm]	1499
Engine Power [hp/kW]	102/75
Gearbox	manual 6- gear
Registration /record No.	GA231KP
VIN / serial number	VR7EFYHT2PJ749988
Date of first registration	31-08-2023
Date of next. tech. test	31-08-2026
Year of manufacture	2023 (year has been verified with the manufacturer's base)
Readout [km]	50 787 (read)
Body color / type of coating	white/UNI

Tyres

axle	Wheel	Manufacturer, type	Size	Measured profile
Front	right	MOTRIO, WINTER FAR AWAY	205/60 16 92H	5,5 mm
	left	MOTRIO, WINTER FAR AWAY	205/60 16 92H	6,0 mm
back	right	MOTRIO, WINTER FAR AWAY	205/60 16 92H	6,0 mm

left	MOTRIO, WINTER FAR AWAY	205/60 16 92H	6,5 mm
------	----------------------------	---------------	--------

Standard equipment by Eurotax

- | | |
|---|---|
| 1. Additional gauges, On board monitor | 16. Luggage:other |
| 2. Air conditioning | 17. Luggage:other |
| 3. Airbag: other | 18. Mobile Tire System |
| 4. Automatic dimlight activation | 19. Passenger airbag, Side airbag driver and passenger |
| 5. Central locking | 20. Radio |
| 6. Cruise control | 21. Rear wing door with window |
| 7. Door mirror(s) electrically adjustable in general, Door mirrors heated | 22. Rear wing door with window |
| 8. Driver airbag | 23. Seats: other |
| 9. Driver conditioning monitoring | 24. Sliding door with window right, Sliding door with window left |
| 10. Driver seat height adjustable, Driver seat with adjustable inclination, Headrests front, Lumbar adjust driver, Seats: other | 25. Steel rims |
| 11. ESP (Electronical Stabilizing Program) | 26. Steering wheel manually adjustable |
| 12. Exterior design: other | 27. Storage facilities in general |
| 13. Extra power outlet | 28. Textile upholstery |
| 14. Kluczyk z pilotem zamka centralnego | 29. Tyre pressure control (RDC) |
| 15. Luggage:other | 30. Uni-Lackierung |

Dealer's equipment (selected items)

- | | |
|--|---|
| 1. CD-player, DAB radio, Radio | - |
| 2. Full size spare wheel | - |
| 3. Park Distance Control rear | - |
| 4. Sliding door with window right, Sliding door with window left | - |
| 5. Towbar preparation | - |

Additional equipment

- | | |
|-------------------------------|---|
| 1. Hak holowniczy stały | - |
|-------------------------------|---|

Base value of the vehicle

Base value of the vehicle (net)	-
---------------------------------------	---

CorrectionsFirst registrationEquipmentTyres

Other

Braki uszkodzenia, stan, -


Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 05-2025 POL) with regard to technical and market parameters affecting the value of the vehicle.

Basic print without information about the vehicle's value - duey to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 07-05-2025

DEKRA's expert:
Kacper Sosnowski (NEW)
Andrzej Sosnowski

Document issued electronically valid without signature.

Measurement of thickness of the vehicle lacquer coating


No. of controlled item	Controlled item	Measured range of thickness of the lacquer coat [μm]
1	Front cover	to 150
2	Leftfront fender	to 150
3	Left front pillar	to 150
4	Leftfront door	to 150
5	Roof	to 150
7	Left middle pillar	to 150
8	Left side sill	to 150
9	Left side door	to 150
10	Left side wall	to 150
12	Cover / tailgate	to 150
14	Right sidewall	to 150
16	Right side door	to 150
17	Right middle pillar	to 150
18	Right front door	to 150
19	Right side sill	to 150
20	Right front pillar	to 150
21	Right front fender	to 150

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

During the inspection the registration proof of the vehicle was presented and its photo was taken and enclosed to the expertise.

During the inspection the service book of the vehicle was not provided.

Information concerning the origin of the vehicle

Lack of reliable data.

Additional comments on the car:

Passenger car registered as a truck is fitted with a partition separating the passenger space from the luggage compartment.

Test drive

Test drive of the vehicle was conducted. Test drive in the full extent is not possible. Comment below: ograniczenia placowe

Checking of the correctness and / or construction of identification / serial numbers of the object:

Not tested

Verification of the accuracy of the object data, including year of production, and other.

Not conducted - adopted according to the documents presented and indicated sources.

Anti-theft protection

fabryczne

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.
- The evaluation has been carried out basing on delivered documentation and organoleptic examination of the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the assessed object.
- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

Comments to the commission - regarding valuation**Kluczyki**

TAK

2

Expert comments - regarding valuation

Rysy na samochodzie. Pojazd posiada hak. Brak kołpaków. Odpryski na szybie czołowej.

Rzeczoznawca dokonał oględzin pojazdu w warunkach parkingowych, co mogło ograniczyć pełną ocenę jego stanu technicznego. Dodatkowo, jeżeli jazda próbna została przeprowadzona (informacje w treści raportu), to wykonano ją w warunkach parkingowych, z niewielką prędkością, co może nie odzwierciedlać pełnych warunków eksploatacyjnych. Istnieje możliwość, że w innych okolicznościach ujawnią się dodatkowe uszkodzenia lub usterki, których nie można było wykryć podczas obecnych oględzin. Zalecamy zatem skorzystanie z możliwości oględzin pojazdu we własnym zakresie lub w Autoryzowanej Stacji Obsługi danej marki, co pozwoli na pełniejszą weryfikację stanu technicznego pojazdu przed udziałem w aukcji."

Restrictive disclaimer - regarding valuation

Nie weryfikowano szczegółowo stanu układu napędowego, zawieszenia, kierowniczego, hamulcowego oraz wydechowego. Ocena została wykonana bez użycia podnośnika i specjalistycznego sprzętu diagnostycznego, nie dokonywano demontażu osłon i innych elementów. Ocena określa ogólny stan pojazdu na dzień oględzin w miejscu jego udostępnienia, nie może być zatem traktowana jako kompleksowa ocena stanu technicznego. Specyfikacja wg. programu operacyjnego w zakresie wyposażenia standardowego i dodatkowego nie gwarantuje zgodności ze stanem faktycznym w zakresie możliwym do ustalenia przez rzeczoznawcę podczas oględzin pojazdu. Pomiar grubości powłoki lakierowej wykonano w miejscach możliwych do ich wykonania pomiary nie gwarantują oryginalności poszczególnych elementów poddanych ocenie.

- W Ocenie/Raporcie uwzględniono niesprawności, uszkodzenia, braki itp., które były możliwe do stwierdzenia organoleptycznego, w warunkach oględzin (z uwzględnieniem: stanu czystości pojazdu, warunków atmosferycznych, oświetlenia itd.) oraz bez weryfikacji serwisowej, bez dostępu do spodu pojazdu, bez specjalistycznego sprzętu diagnostycznego (w tym bez diagnostyki komputerowej), bez jazdy próbnej wykonanej w warunkach drogowych z obciążeniem.
- W ramach Oceny/Raportu nie weryfikowano odczytanego stanu drogomierza z zapisami w urządzeniach elektronicznych pojazdu.
- Rzeczoznawca nie bierze na siebie odpowiedzialności za wady ukryte (prawne i fizyczne) oraz ewentualne skutki wynikające z dalszego użytkowania przedmiotu oceny, a także za skutki wykorzystania samej oceny.
- Podane przedziały grubości powłoki lakierowej, dotyczą punktów pomiarowych. Nie mogą być traktowane jako gwarancja, że grubość powłoki lakierowej w innych punktach nie wykracza poza te przedziały.
- Zawarte w niniejszej Ocenie/Raporcie informacje (w tym dotyczące wyposażenia) służą jedynie ogólnym celom informacyjnym. Ocena/Raport nie może być zatem traktowana jako oferta w rozumieniu przepisów Kodeksu Cywilnego oraz opisu towaru ani zapewnienia w rozumieniu art. 4 Ustawy z dnia 27 lipca 2002 roku o szczególnych warunkach sprzedaży konsumenckiej.
- Niniejsza Ocena/Raport nie jest szczegółową oceną stanu technicznego.

Ocenę/Raport wykonano w kierunku ujawnienia uszkodzeń nieakceptowanych z punktu widzenia właściwego przewodnika zwrotu pojazdu lub innych ustaleń ze Zleceniodawcą. Tym samym Ocena/Raport może nie ujmować typowych zużyć i uszkodzeń eksploatacyjnych.

PHOTOGRAPHIC DOCUMENTATION



Photo 1.
Przekątna przednia lewa



Photo 2.
Przód

PHOTOGRAPHIC DOCUMENTATION



Photo 3.

Przekątna przednia prawa



Photo 4.

Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 5.
Bok prawy z tyłu



Photo 6.
Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 7.

Tył



Photo 8.

Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 9.

Bok lewy z tyłu



Photo 10.

Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 11.

Próg lewy (widok od przodu)



Photo 12.

Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



Photo 13.
Spód pojazdu przód



Photo 14.
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION



Photo 15.
Bagażnik



Photo 16.
Koło zapasowe

PHOTOGRAPHIC DOCUMENTATION



Photo 17.
Komora silnika



Photo 18.
Numer identyfikacyjny

PHOTOGRAPHIC DOCUMENTATION




Photo 19.

Tabliczka znamionowa



Photo 20.

Zestaw wskaźników - przebieg

PHOTOGRAPHIC DOCUMENTATION



Photo 21.

Widok przez otwarte drzwi przednie lewe



Photo 22.

Kierownica z lewej strony

PHOTOGRAPHIC DOCUMENTATION



Photo 23.

Widok przez otwarte drzwi tylne lewe



Photo 24.

Widok z tylnej kanapy na deskę rozdzielczą.

PHOTOGRAPHIC DOCUMENTATION




Photo 25.
Konsola środkowa




Photo 26.
Tunel środkowy

PHOTOGRAPHIC DOCUMENTATION**Photo 27.**

Kierownica (na wprost)

**Photo 28.**

Dowód rej. Str. 1

PHOTOGRAPHIC DOCUMENTATION



Photo 29.

Dow. Rej. Str.2 i klucze




Photo 30.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 31.

Zderzak - Rysa/odprysk 1



Photo 32.

Drzwi przednie P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 33.

Drzwi przednie P - Wgniecenie/odkształcenie 1



Photo 34.

Drzwi przednie P - Wgniecenie/odkształcenie 2

PHOTOGRAPHIC DOCUMENTATION



Photo 35.

Listwa drzwi przednich P - Rysa/odprysk 1



Photo 36.

Łotnik tylny P / Ściana boczna P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 37.

Pokrywy bagażnika - Rysa/odprysk 1



Photo 38.

Łotnik tylny L / Ściana boczna L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 39.

Drzwi przed L - Rysa/odprysk 1



Photo 40.

Drzwi przed L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 41.

Listwa drzwi przednich L - Rysa/odprysk 1



Photo 42.

Próg L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 43.

Deska rozdzielcza - Rysa/odprysk 1




Photo 44.

Podłokietnik środkowy przedni - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 45.

Fotel prz. lew. - Inne 1



Photo 46.

Fotel prz. praw. - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 47.
Fotel prz. praw. - Inne 2




Photo 48.
Kanapa tyl. - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 49.

Tapicerka drzwi przednich P - Rysa/odprysk 1



Photo 50.

Wykładzina podłogi bagażnika - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 51.

Ściana lewa - Wgniecenie/odkształcenie 1



Photo 52.

Ściana prawa - Wgniecenie/odkształcenie 1