

DEKRA's commission No. : PKOL(W)/LODZ/95753/25/12/05
commission/ damage No. : 01726/LF/24
Date of commission: 05-12-2025

DEKRA Poland - Headquarters
02-673 Warszawa, ul. Konstruktorska 12A

Client :

PKO Leasing SA
Świętokrzyska 36
00-116 Warszawa

Expert:

Kacper Sosnowski (NEW)
DEKRA Polska - współpraca O/Warszawa
Bartłomiej Chodakowski (NEW)
DEKRA Polska - współpraca O/Wrocław

NOTE:

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

Vehicle data

Group of objects (Eurotax)	jeeps
EC code (Eurotax)	0131129
Manufacturer	JAGUAR
Model	I-Pace 18-23
Type / version	I-Pace EV400 AWD S
Body type	KOM
Number of doors / seats	5/5
Curb weight [kg]	2244
Gross vehicle weight [kg]	2670
Wheelbase 1/2	2990
Engine type	elektryczny
Pollution reduction system	-
Engine capacity [ccm]	0
Engine Power [hp/kW]	400/294
Gearbox	automatic 1- gear
Registration /record No.	KWI4031G
VIN / serial number	SADHA2B14K1F66555
Date of first registration	24-11-2018
Readout [km]	79 442 (read)
Body color / type of coating	gray/METALIK

Tyres

axle	Wheel	Manufacturer, type	Size	Measured profile
Front	right	GRENLANDER, ICEHAWKE 1	245/50 20 105H	5,0 mm
	left	GRENLANDER, ICEHAWKE 1	245/50 20 105H	5,0 mm
back	right	GRENLANDER, ICEHAWKE 1	245/50 20 105H	6,5 mm
	left	GRENLANDER, ICEHAWKE 1	245/50 20 105H	6,0 mm

Standard equipment by Eurotax

- | | |
|--|--|
| 1. Acoustic windows | 37. Lane control assistant |
| 2. Active Emergency Brake Assist | 38. Leather steering wheel, Sports steering wheel |
| 3. Additional heating | 39. Light Alloy wheels 20" |
| 4. Alarm | 40. Limited slip differential: other |
| 5. Armrest (s) rear | 41. Mobile Tire System |
| 6. Blind spot warning | 42. Navigation system |
| 7. Bluetooth interface | 43. Off road suspension |
| 8. Bord entertainment: other accessories | 44. On board monitor |
| 9. City Emergency Brake Assist | 45. On board monitor |
| 10. Cruise control | 46. Other |
| 11. Door mirrors electrically foldable | 47. Other |
| 12. Driver airbag, Head airbags front, Passenger airbag, Side airbag driver and passenger | 48. Other |
| 13. Driver conditioning monitoring | 49. Other |
| 14. Driver seat height adjustable, Driver seat with adjustable inclination, Passenger seat height adjustable, Passenger seat with adjustable inclination | 50. Other |
| 15. Dualzone automatic climate control | 51. Other |
| 16. Electric parking brake | 52. Other |
| 17. Electronic controlled suspension | 53. Other |
| 18. Exterior design: other | 54. Park Assistant |
| 19. Exterior design: other | 55. Park Distance Control front, Park Distance Control rear |
| 20. Exterior design: other | 56. Power steering |
| 21. Exterior design: other | 57. Rain sensor |
| 22. Extra power outlet | 58. Rear Cross Traffic Alert |
| 23. Extra power outlet, USB in | 59. Rear seat-backs foldable in two separate parts |
| 24. Heat reflecting windows | 60. Rear view camera |
| 25. Heat reflecting windows | 61. Rear-view mirror autodimming |
| 26. Hill holder | 62. Selectable driveline characteristics |
| 27. Interior decoration: other | 63. Soundsystem |
| 28. Interior decoration: other | 64. Storage facilities in general |
| 29. Interior lights: other accessories | 65. Storage facilities in general |
| 30. Interior: other | 66. Storage facilities in general |
| 31. Interior: other | 67. Textile upholstery |
| 32. Interior: other | 68. Towbar |
| 33. Internet access | 69. Traffic sign recognition |
| 34. Keyless go | 70. Tyre pressure control (RDC) |
| 35. LED front dim light | 71. Uni-Lackierung |
| 36. LED rear lights | 72. Voice control for audiosystem, Voice control for navigation system |

Base value of the vehicle

Base value of the vehicle by Eurotax (net)

CorrectionsFirst registration

Mileage

Tyres

Other

Current market situation -


Above figure was estimated on the basis of price quotations of used cars on the Polish market taking into account the technical and market parameters affecting the value of the vehicle.

Basic print without information about the vehicle's value - duey to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 15-12-2025

DEKRA's expert:
Kacper Sosnowski (NEW)
Bartłomiej Chodakowski (NEW)

Document issued electronically valid without signature.

Measurement of thickness of the vehicle lacquer coating


No. of controlled item	Controlled item	Measured range of thickness of the lacquer coat [μm]
1	Front cover	to 150
3	Left front pillar	to 150
4	Left front wall	150 - 200
5	Roof	to 150
6	Left middle pillar	to 150
7	Left side sill	to 150
8	Left rear wall	150 - 2000
9	Left side wall	150 - 200
11	Side right wall	150 - 200
12	Rear right door	to 150
13	Middle right pillar	to 150
14	Front right door	to 150
15	Right side sill	to 150
16	Right front pillar	to 150

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

During the inspection the registration proof of the vehicle was presented and its photo was taken and enclosed to the expertise.

During the inspection the service book of the vehicle was not provided.

Information concerning the origin of the vehicle

Lack of reliable data.

Additional comments on the car:

Not applicable.

Test drive

Test drive of the vehicle was conducted. Test drive in the full extent is not possible. Comment below:
Warunki parkingowe

Checking of the correctness and / or construction of identification / serial numbers of the object:

Not tested

Verification of the accuracy of the object data, including year of production, and other.

Not conducted - adopted according to the documents presented and indicated sources.

Anti-theft protection

Immobilizer

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.
- The evaluation has been carried out basing on delivered documentation and organoleptic examination of the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the assessed object.
- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

Comments to the commission - regarding valuation**Kluczyki**

TAK

1

Expert comments - regarding valuation

Pierwsza rejestracja w kraju 30-01-2024. Pojazd elektryczny. Dostarczono pozwolenie czasowe. Rysy na samochodzie. Pokrywa bagażnika otwiera się i opada do połowy. Brak zaślepek w tylnej kanapie. Brak półki bagażnika. Odpryski na szybie czołowej.

Restrictive disclaimer - regarding valuation

- W Ocenie/Raporcie uwzględniono niesprawności, uszkodzenia, braki itp., które były możliwe do stwierdzenia organoleptycznego, w warunkach oględzin (z uwzględnieniem: stanu czystości pojazdu, warunków atmosferycznych, oświetlenia itd.) oraz bez weryfikacji serwisowej, bez dostępu do spodu pojazdu, bez specjalistycznego sprzętu diagnostycznego (w tym bez diagnostyki komputerowej), bez jazdy próbnej wykonanej w warunkach drogowych z obciążeniem.
- W ramach Oceny/Raportu nie weryfikowano odczytanego stanu drogomierza z zapisami w urządzeniach elektronicznych pojazdu.
- Rzeczoznawca nie bierze na siebie odpowiedzialności za wady ukryte (prawne i fizyczne) oraz ewentualne skutki wynikające z dalszego użytkowania przedmiotu oceny, a także za skutki wykorzystania samej oceny.
- Podane przedziały grubości powłoki lakierowej, dotyczą punktów pomiarowych. Nie mogą być traktowane jako gwarancja, że grubość powłoki lakierowej w innych punktach nie wykracza poza te przedziały.
- Zawarte w niniejszej Ocenie/Raporcie informacje (w tym dotyczące wyposażenia) służą jedynie ogólnym celom informacyjnym. Ocena/Raport nie może być zatem traktowana jako oferta w rozumieniu przepisów Kodeksu Cywilnego oraz opisu towaru ani zapewnienia w rozumieniu art. 4 Ustawy z dnia 27 lipca 2002 roku o szczególnych warunkach sprzedaży konsumenckiej.
- Niniejsza Ocena/Raport nie jest szczegółową oceną stanu technicznego.

Ocenę/Raport wykonano w kierunku ujawnienia uszkodzeń nieakceptowanych z punktu widzenia właściwego przewodnika zwrotu pojazdu lub innych ustaleń ze Zleceniodawcą. Tym samym Ocena/Raport może nie ujmować typowych zużyć i uszkodzeń eksploatacyjnych.

PHOTOGRAPHIC DOCUMENTATION



Photo 1.

Przekątna przednia lewa



Photo 2.

Przód

PHOTOGRAPHIC DOCUMENTATION



Photo 3.

Przekątna przednia prawa



Photo 4.

Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 5.

Bok prawy z tyłu



Photo 6.

Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 7.

Tył



Photo 8.

Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 9.

Bok lewy z tyłu



Photo 10.

Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 11.

Próg lewy (widok od przodu)



Photo 12.

Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



Photo 13.
Spód pojazdu przód



Photo 14.
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION




Photo 15.

Tarcza hamulcowa przednia prawa



Photo 16.

Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 17.

Tarcza hamulcowa tylna lewa



Photo 18.

Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 19.
Bagażnik



Photo 20.
Koło zapasowe

PHOTOGRAPHIC DOCUMENTATION



Photo 21.
Komora silnika



Photo 22.
Numer identyfikacyjny

PHOTOGRAPHIC DOCUMENTATION



Photo 23.

Tabliczka znamionowa



Photo 24.

Zestaw wskaźników - przebieg

PHOTOGRAPHIC DOCUMENTATION



Photo 25.

Widok przez otwarte drzwi przednie lewe



Photo 26.

Kierownica z lewej strony

PHOTOGRAPHIC DOCUMENTATION



Photo 27.

Widok przez otwarte drzwi tylne lewe



Photo 28.

Widok z tylnej kanapy na deskę rozd.

PHOTOGRAPHIC DOCUMENTATION



Photo 29.
Konsola środkowa



Photo 30.
Tunel środkowy


PHOTOGRAPHIC DOCUMENTATION



Photo 31.
Kierownica (na wprost)



Photo 32.
Przewód ładowania baterii trakcyjnej

PHOTOGRAPHIC DOCUMENTATION**Photo 33.**

Dow. rej. tym. Str. 1

**Photo 34.**

Dow. Rej. tym. Str.2 i klucze

PHOTOGRAPHIC DOCUMENTATION



Photo 35.

Instrukcje



Photo 36.

Zestaw naprawczy koła

PHOTOGRAPHIC DOCUMENTATION



Photo 37.

Zdjęcie do protokołu



Photo 38.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 39.
Zdjęcie do protokołu



Photo 40.
Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 41.
Zdjęcie do protokołu



Photo 42.
Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 43.

Zdjęcie do protokołu



Photo 44.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 45.

Zdjęcie do protokołu




Photo 46.

Pokrywa komory silnika - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 47.

Pokrywa komory silnika - Wgniecenie/odkształcenie 1



Photo 48.

Spoiler zderzaka przedniego - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 49.

Zderzak - Rysa/odprysk 1



Photo 50.

Zderzak - Rysa/odprysk 2

PHOTOGRAPHIC DOCUMENTATION



Photo 51.

Błotnik przedni P - Rysa/odprysk 1



Photo 52.

Błotnik przedni P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 53.

Drzwi przednie P - Rysa/odprysk 1



Photo 54.

Łotnik tylny P / Ściana boczna P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 55.

Pokrywy bagażnika - Rysa/odprysk 1



Photo 56.

Zderzak tylny cz L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 57.

Zderzak tylny cz P - Rysa/odprysk 1



Photo 58.

Błotnik tylny L / Ściana boczna L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION




Photo 59.

Drzwi przed L - Wgniecenie/odkształcenie 1



Photo 60.

Drzwi tylne L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 61.

Drzwi tylne L - Rysa/odprysk 2



Photo 62.

Drzwi tylne L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 63.

Lusterko zew L - Rysa/odprysk 1



Photo 64.

Słupek środkowy L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 65.

Błotnik przedni L - Wgniecenie/odkształcenie 1



Photo 66.

Fotel prz. lew. - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 67.

Kanapa tyl. - Wgniecenie/odkształcenie 1



Photo 68.

Półka/roleta tylna - Inne 1