

DEKRA's commission No. : PKOL(W)/LODZ/91928/25/11/26
commission/ damage No. : 24/025828
Date of commission: 26-11-2025

DEKRA Poland - Headquarters
02-673 Warszawa, ul. Konstruktorska 12A

Client :

PKO Leasing SA
Świętokrzyska 36
00-116 Warszawa

Expert:

Kacper Sosnowski (NEW)
DEKRA Polska - współpraca O/Warszawa
Tomasz Ziemniak (NEW)
DEKRA Polska - współpraca O/Konin

NOTE:

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

Vehicle data

Group of objects (Eurotax)	cars
EC code (Eurotax)	0135392
Manufacturer	BMW
Model	Seria 2 Cabrio [F23] 17-21
Type / version	220i GPF Sport Line aut
Body type	CAB
Number of doors / seats	2/4
Curb weight [kg]	1580
Gross vehicle weight [kg]	2010
Wheelbase 1/2	2690
Engine type	spark ignition
Pollution reduction system	GPF
Engine capacity [ccm]	1998
Engine Power [hp/kW]	184/135
Gearbox	automatic 8- gear
Registration /record No.	TK632EM
VIN / serial number	WBA2M310907J35284
Date of first registration	31-05-2021
Date of next. tech. test	31-05-2026
Year of manufacture	2021 (year has been verified with the manufacturer's base)
Readout [km]	32 750 (read)
Body color / type of coating	white/UNI

Tyres

axle	Wheel	Manufacturer, type	Size	Measured profile
Front	right	KUMHO, ECSTA PS71	225/45 17 91W	6,0 mm
	left	KUMHO, ECSTA PS71	225/45 17 91W	6,0 mm
back	right	KUMHO, ECSTA PS71	225/45 17 91W	6,0 mm
	left	KUMHO, ECSTA PS71	225/45 17 91W	6,0 mm

Standard equipment by Eurotax

- | | |
|---|---|
| 1. Airbag: other | 24. Light alloy wheels from 17" |
| 2. Antilock-Brake-System (ABS) | 25. Mobile Tire System |
| 3. Armrest (s) front | 26. Multi functional steering wheel |
| 4. Automatic climate control | 27. On board monitor, Other, Radio, Soundsystem |
| 5. Automatic dimlight activation, Rain sensor | 28. Other |
| 6. Bluetooth interface, Hands-free system, USB in | 29. Other |
| 7. Bord communication: other | 30. Other |
| 8. Bord communication: other | 31. Other |
| 9. Bord entertainment: other accessories | 32. Park Distance Control rear |
| 10. Child seat fixation | 33. Rear window heating |
| 11. Colored glass | 34. Seats: other |
| 12. Cruise control | 35. Selectable driveline characteristics |
| 13. DAB radio | 36. Servotronic |
| 14. Driver airbag, Passenger airbag, Side airbag driver and passenger | 37. Sport seats front |
| 15. ESP (Electronical Stabilizing Program), Traction control | 38. Start/Stop system |
| 16. Exterior lighting: other, Interior lights: other accessories | 39. Storage facilities in general |
| 17. Extra power outlet | 40. Telematic |
| 18. Floor mat | 41. Telematic |
| 19. Follow me home | 42. Textile top, Top: electrically operated |
| 20. Interior decoration: other | 43. Textile upholstery |
| 21. LED Fog Lamps | 44. Uni-Lackierung |
| 22. LED front dim light | 45. Wheel bolt locks |
| 23. Leather steering wheel, Sports steering wheel | 46. Windstop |

Dealer's equipment (selected items)

- | | |
|---|---|
| 1. Door mirrors autodimming, Door mirrors electrically foldable, Mirror: others, Rear-view mirror autodimming | - |
| 2. Driver seat electrically adjustable, Memory seat, Passenger seat electrically adjustable | - |
| 3. Heated seat driver, Heated seat passenger | - |
| 4. Keyless entry, Keyless go | - |
| 5. Leather upholstery | - |
| 6. Lumbar adjust driver, Lumbar adjust passenger | - |
| 7. Metal finish | - |
| 8. Park Assistant | - |
| 9. Park Distance Control front, Park Distance Control rear | - |
| 10. Rear view camera | - |
| 11. Runflat tyres | - |
| 12. Steering wheel heated | - |

Base value of the vehicle

Base value of the vehicle by Eurotax (net) -

Corrections

First registration

Mileage

Equipment

Tyres

Other

Korekta z tytułu uszkodzeń pojazdu -

Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 12-2025 POL) with regard to technical and market parameters affecting the value of the vehicle.


Basic print without information about the vehicle's value - duey to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 03-12-2025

DEKRA's expert:
Kacper Sosnowski (NEW)
Tomasz Ziemniak (NEW)

Document issued electronically valid without signature.

Measurement of thickness of the vehicle lacquer coating



No. of controlled item	Controlled item	Measured range of thickness of the lacquer coat [µm]
1	Front cover	to 150
2	Front left fender	to 150
3	Left front pillar	to 150
4	Front left door	to 150
5	Roof	to 150
6	Left middle pillar	to 150
7	Right side sill	to 150
9	Rear left fender	to 150
10	Cover/lid	to 150
11	Right rear fender	to 150
13	Right middle pillar	to 150
14	Right side sill	to 150
15	Front right door	to 150
16	Right front pillar	to 150
17	Front right fender	to 150

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

During the inspection the registration proof of the vehicle was presented and its photo was taken and enclosed to the expertise.

During the inspection the service book was presented and its number is given below:

Elektroniczna

Information concerning the origin of the vehicle

The vehicle purchased domestically from an authorized representative of the brand.

Anti-theft protection - immobilizer

- as a result of the inspection of the vehicle found no malfunctions of the immobilizer in the extent possible to determine during the inspection of the vehicle in the non- workshop conditions.

Anti-theft protection - other:

not found

Additional comments on the car:

Not applicable.

Test drive

The test drive has been conducted on a distance and in time enabling rough estimation of the technical condition of the vehicle.

Checking of the correctness and / or construction of identification / serial numbers of the object:

Not tested

Verification of the accuracy of the object data, including year of production, and other.

Not conducted - adopted according to the documents presented and indicated sources.

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.
- The evaluation has been carried out basing on delivered documentation and organoleptic examination of

the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the assessed object.

- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

Comments to the commission - regarding valuation

Kluczyki

TAK

1

Expert comments - regarding valuation

Nieprzyjemny zapach w samochodzie. Rysy na samochodzie.

Restrictive disclaimer - regarding valuation

- W Ocenie/Raporcie uwzględniono niesprawności, uszkodzenia, braki itp., które były możliwe do stwierdzenia organoleptycznego, w warunkach oględzin (z uwzględnieniem: stanu czystości pojazdu, warunków atmosferycznych, oświetlenia itd.) oraz bez weryfikacji serwisowej, bez dostępu do spodu pojazdu, bez specjalistycznego sprzętu diagnostycznego (w tym bez diagnostyki komputerowej), bez jazdy próbnej wykonanej w warunkach drogowych z obciążeniem.
- W ramach Oceny/Raportu nie weryfikowano odczytanego stanu drogomierza z zapisami w urządzeniach elektronicznych pojazdu.
- Rzeczoznawca nie bierze na siebie odpowiedzialności za wady ukryte (prawne i fizyczne) oraz ewentualne skutki wynikające z dalszego użytkowania przedmiotu oceny, a także za skutki wykorzystania samej oceny.
- Podane przedziały grubości powłoki lakierowej, dotyczą punktów pomiarowych. Nie mogą być traktowane jako gwarancja, że grubość powłoki lakierowej w innych punktach nie wykracza poza te przedziały.
- Zawarte w niniejszej Ocenie/Raporcie informacje (w tym dotyczące wyposażenia) służą jedynie ogólnym celom informacyjnym. Ocena/Raport nie może być zatem traktowana jako oferta w rozumieniu przepisów Kodeksu Cywilnego oraz opisu towaru ani zapewnienia w rozumieniu art. 4 Ustawy z dnia 27 lipca 2002 roku o szczególnych warunkach sprzedaży konsumenckiej.
- Niniejsza Ocena/Raport nie jest szczegółową oceną stanu technicznego.

Ocenę/Raport wykonano w kierunku ujawnienia uszkodzeń nieakceptowanych z punktu widzenia właściwego przewodnika zwrotu pojazdu lub innych ustaleń ze Zleceniodawcą. Tym samym Ocena/Raport może nie ujmować typowych zużyć i uszkodzeń eksploatacyjnych.

PHOTOGRAPHIC DOCUMENTATION



Photo 1.

Przekątna przednia lewa



Photo 2.

Przód

PHOTOGRAPHIC DOCUMENTATION



Photo 3.

Przekątna przednia prawa



Photo 4.

Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 5.

Bok prawy z tyłu



Photo 6.

Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 7.

Tył



Photo 8.

Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 9.

Bok lewy z tyłu



Photo 10.

Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 11.
Próg lewy (widok od przodu)



Photo 12.
Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



Photo 13.
Spód pojazdu przód




Photo 14.
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION



Photo 15.

Tarcza hamulcowa przednia prawa




Photo 16.

Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 17.

Tarcza hamulcowa tylna lewa



Photo 18.

Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 19.
Bagażnik



Photo 20.
Koło zapasowe

PHOTOGRAPHIC DOCUMENTATION



Photo 21.
Komora silnika



Photo 22.
Numer identyfikacyjny

PHOTOGRAPHIC DOCUMENTATION



Photo 23.

Tabliczka znamionowa



Photo 24.

Zestaw wskaźników - przebieg

PHOTOGRAPHIC DOCUMENTATION



Photo 25.

Widok przez otwarte drzwi przednie lewe



Photo 26.

Kierownica z lewej strony

PHOTOGRAPHIC DOCUMENTATION



Photo 27.

Widok przez otwarte drzwi tylne lewe



Photo 28.

Widok z tylnej kanapy na deskę rozd.

PHOTOGRAPHIC DOCUMENTATION



Photo 29.

Konsola środkowa



Photo 30.

Tunel środkowy

PHOTOGRAPHIC DOCUMENTATION



Photo 31.

Kierownica (na wprost)




Photo 32.

Dowód rej. Str. 1

PHOTOGRAPHIC DOCUMENTATION



Photo 33.

Dow. Rej. Str.2 i klucze



Photo 34.

Książka serwisowa – dane

PHOTOGRAPHIC DOCUMENTATION



Photo 35.

Książka serwisowa – ostatni przegląd



Photo 36.

Instrukcje

PHOTOGRAPHIC DOCUMENTATION



Photo 37.

Pokrywa komory silnika - zdjęcie poglądowe 1




Photo 38.

Pokrywa komory silnika - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 39.

Błotnik przedni P - Wgniecenie/odkształcenie 1



Photo 40.

Felga aluminiowa przednia P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 41.

Drzwi przednie P - Wgniecenie/odkształcenie 1



Photo 42.

Łotnik tylny P / Ściana boczna P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 43.

Felga aluminiowa tylna P - Rysa/odprysk 1



Photo 44.

Dach - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 45.

Felga aluminiowa tylna L - Rysa/odprysk 1



Photo 46.

Drzwi przed L - zdjęcie poglądowe 1

PHOTOGRAPHIC DOCUMENTATION



Photo 47.

Drzwi przed L - Rysa/odprysk 1



Photo 48.

Drzwi przed L - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 49.

Próg L - Rysa/odprysk 1



Photo 50.

Felga Aluminiowa przednia L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 51.

Fotel prz. lew. - Inne 1



Photo 52.

Uchwyt drzwi prze L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 53.

Wykładzina(y) słupka środkowego L - Rysa/odprysk 1