

DEKRA's commission No. : PKOL(W)/LODZ/39175/25/05/30
commission/ damage No. : 21/042740
Date of commission: 30-05-2025

DEKRA Poland - Headquarters
02-673 Warszawa, ul. Konstruktorska 12A

Client :

PKO Leasing SA
Świętokrzyska 36
00-116 Warszawa

Expert:

Kacper Sosnowski (NEW)
DEKRA Polska - współpraca O/Warszawa
Andrzej Sosnowski
DEKRA Polska - Centrala

NOTE:

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

Vehicle data

Group of objects (Eurotax)	jeeps
EC code (Eurotax)	0152643
Manufacturer	TOYOTA
Model	RAV4 21-
Type / version	RAV4 2.5 Hybrid Comfort 4x4
Body type	KOM
Number of doors / seats	5/5
Curb weight [kg]	1684
Gross vehicle weight [kg]	2225
Wheelbase 1/2	2690
Engine type	spark ignition
Pollution reduction system	GPF
Engine capacity [ccm]	2487
Engine Power [hp/kW]	177/131
Gearbox	automatic
Registration /record No.	DW7PJ20
VIN / serial number	JTMR63FV00J008006
Date of first registration	29-09-2021
Date of next. tech. test	29-09-2026
Year of manufacture	2021 (year has been verified with the manufacturer's base)
Readout [km]	170 279 (read)
Body color / type of coating	granatowy/double-layered, metallized

Tyres

axle	Wheel	Manufacturer, type	Size	Measured profile
Front	right	SAILUN, ICE BLAZER ALPINE EVO 1	225/55 18 102V	4,5 mm
	left	SAILUN, ICE BLAZER ALPINE EVO 1	225/55 18 102V	4,0 mm
back	right	SAILUN, ICE BLAZER ALPINE EVO 1	225/55 18 102V	3,5 mm
	left	SAILUN, ICE BLAZER ALPINE EVO 1	225/55 18 102V	3,0 mm

Standard equipment by Eurotax

- | | |
|---|--|
| 1. Adaptive Cruise Control | 49. LED Fog Lamps |
| 2. Additional gauges | 50. LED front dim light |
| 3. Android Auto, Apple CarPlay | 51. LED rear lights |
| 4. Antilock-Brake-System (ABS) | 52. Lane control assistant |
| 5. Armrest (s) front | 53. Leather gearshifter/switch, Leather steering wheel |
| 6. Armrest (s) rear | 54. Light alloy wheels from 17" |
| 7. Automated High-beam assist | 55. Luggage compartment cover |
| 8. Automatic Emergency Call | 56. Luggage:other |
| 9. Automatic dimlight activation | 57. Mobile Tire System |
| 10. Bluetooth interface | 58. Multi functional steering wheel |
| 11. Bord communication: other | 59. On board computer |
| 12. Bord entertainment: other accessories | 60. On board monitor |
| 13. Brake Assist, Pre-Crash System | 61. Other |
| 14. Bumpers: other | 62. Other |
| 15. CD-player, On board monitor, Radio | 63. Other |
| 16. Child seat fixation | 64. Other |
| 17. Comfort driver seat, Comfort passenger seat | 65. Other |
| 18. DAB radio | 66. Other |
| 19. Distribution of braking force electronically | 67. Other |
| 20. Door mirror(s) electrically adjustable in general | 68. Other |
| 21. Door mirrors electrically foldable | 69. Other |
| 22. Door mirrors heated | 70. Other |
| 23. Driver airbag, Head airbags front, Passenger airbag, Side airbag driver, Side airbag driver and passenger | 71. Other |
| 24. Driver knee airbag | 72. Park Distance Control rear |
| 25. Driver seat height adjustable | 73. Power assisted brakes |
| 26. Dualzone automatic climate control | 74. Power windows front, Power windows rear |
| 27. ESP (Electronical Stabilizing Program), Traction control | 75. Power windows front, Power windows rear |
| 28. Electric parking brake | 76. Rain sensor |
| 29. Exterior design: other | 77. Rear bench foldable in two separate parts |
| 30. Exterior design: other | 78. Rear spoiler |
| 31. Exterior design: other | 79. Rear view camera |
| 32. Exterior design: other | 80. Rear-view mirror autodimming |
| 33. Exterior design: other | 81. Remote controlled central locking |
| 34. Exterior design: other | 82. Rev counter |
| 35. Exterior lighting: other | 83. Roof railing |
| 36. Extra power outlet | 84. Roof: other |
| 37. Extra power outlet | 85. Selectable driveline characteristics |
| 38. Floor mat | 86. Selectable driveline characteristics |
| 39. Floor mat | 87. Steering wheel manually adjustabe |
| 40. Hill holder | 88. Textile upholstery |
| 41. Interior decoration: other | 89. Traction control |
| 42. Interior decoration: other | 90. Traffic sign recognition |
| 43. Interior lights: other accessories | 91. Tyre pressure control (RDC) |
| 44. Interior lights: other accessories | 92. USB in |
| 45. Interior lights: other accessories | 93. Uni-Lackierung |
| 46. Interior: other | 94. Vehicle imobilizer |
| 47. Keyless go | 95. {System stabilizacji przyczepy TSC} |
| 48. LED Daytime running lights | |

Dealer's equipment (selected items)

1. Diminished spare wheel, Electric tailgate, Keyless go, Light Alloy wheels 18'', Other,
Tinted rear windows -
System keyless entry

Szyby tylne przyciemniane
Ładowarka do telefonów - bezprzewodowa
Kłapa bagażnika otwierana bezdotykowo
Felgi aluminiowe 18 z ogumieniem 225/60
Koło zapasowe, dojazdowe
2. Metalic paint -

Base value of the vehicle

Base value of the vehicle by Eurotax (net) -

Corrections

First registration

Mileage

Equipment

Tyres

Other

Uszkodzenia, stan -


Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 06-2025 POL) with regard to technical and market parameters affecting the value of the vehicle.

Basic print without information about the vehicle's value - due to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 07-06-2025

DEKRA's expert:
Kacper Sosnowski (NEW)
Andrzej Sosnowski

Document issued electronically valid without signature.

Measurement of thickness of the vehicle lacquer coating


No. of controlled item	Controlled item	Measured range of thickness of the lacquer coat [μm]
1	Front cover	to 150
2	Left front fender	to 150
3	Left front pillar	to 150
4	Left front wall	to 150
5	Roof	to 150
6	Left middle pillar	to 150
7	Left side sill	to 150
8	Left rear wall	to 150
9	Left side wall	to 150
10	Cover/tailgate	to 150
11	Side right wall	to 150
12	Rear right door	to 150
13	Middle right pillar	to 150
14	Front right door	to 150
15	Right side sill	to 150
16	Right front pillar	to 150
17	Right front fender	to 150

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

During the inspection the registration proof of the vehicle was presented and its photo was taken and enclosed to the expertise.

During the inspection the service book was presented and its number is given below:

.

Information concerning the origin of the vehicle

Lack of reliable data.

Additional comments on the car:

Not applicable.

Test drive

Test drive of the vehicle was conducted. Test drive in the full extent is not possible. Comment below:
ograniczenia placowe

Checking of the correctness and / or construction of identification / serial numbers of the object:

Not tested

Verification of the accuracy of the object data, including year of production, and other.

Not conducted - adopted according to the documents presented and indicated sources.

Anti-theft protection

fabryczne

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.
- The evaluation has been carried out basing on delivered documentation and organoleptic examination of the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the assessed object.
- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

Comments to the commission - regarding valuation**Kluczyki**

TAK

2

Expert comments - regarding valuation

Rysy na samochodzie. Odpryski na szybie czołowej.

Rzeczoznawca dokonał oględzin pojazdu w warunkach parkingowych, co mogło ograniczyć pełną ocenę jego stanu technicznego. Dodatkowo, jeżeli jazda próbna została przeprowadzona (informacje w treści raportu), to wykonano ją w warunkach parkingowych, z niewielką prędkością, co może nie odzwierciedlać pełnych warunków eksploatacyjnych. Istnieje możliwość, że w innych okolicznościach ujawnią się dodatkowe uszkodzenia lub usterki, których nie można było wykryć podczas obecnych oględzin. Zalecamy zatem skorzystanie z możliwości oględzin pojazdu we własnym zakresie lub w Autoryzowanej Stacji Obsługi danej marki, co pozwoli na pełniejszą weryfikację stanu technicznego pojazdu przed udziałem w aukcji."

Restrictive disclaimer - regarding valuation

Nie weryfikowano szczegółowo stanu układu napędowego, zawieszenia, kierowniczego, hamulcowego oraz wydechowego. Ocena została wykonana bez użycia podnośnika i specjalistycznego sprzętu diagnostycznego, nie dokonywano demontażu osłon i innych elementów. Ocena określa ogólny stan pojazdu na dzień oględzin w miejscu jego udostępnienia, nie może być zatem traktowana jako kompleksowa ocena stanu technicznego. Specyfikacja wg. programu operacyjnego w zakresie wyposażenia standardowego i dodatkowego nie gwarantuje zgodności ze stanem faktycznym w zakresie możliwym do ustalenia przez rzeczoznawcę podczas oględzin pojazdu. Pomiar grubości powłoki lakierowej wykonano w miejscach możliwych do ich wykonania pomiary nie gwarantują oryginalności poszczególnych elementów poddanych ocenie.

- W Ocenie/Raporcie uwzględniono niesprawności, uszkodzenia, braki itp., które były możliwe do stwierdzenia organoleptycznego, w warunkach oględzin (z uwzględnieniem: stanu czystości pojazdu, warunków atmosferycznych, oświetlenia itd.) oraz bez weryfikacji serwisowej, bez dostępu do spodu pojazdu, bez specjalistycznego sprzętu diagnostycznego (w tym bez diagnostyki komputerowej), bez jazdy próbnej wykonanej w warunkach drogowych z obciążeniem.
- W ramach Oceny/Raportu nie weryfikowano odczytanego stanu drogomierza z zapisami w urządzeniach elektronicznych pojazdu.
- Rzeczoznawca nie bierze na siebie odpowiedzialności za wady ukryte (prawne i fizyczne) oraz ewentualne skutki wynikające z dalszego użytkowania przedmiotu oceny, a także za skutki wykorzystania samej oceny.
- Podane przedziały grubości powłoki lakierowej, dotyczą punktów pomiarowych. Nie mogą być traktowane jako gwarancja, że grubość powłoki lakierowej w innych punktach nie wykracza poza te przedziały.
- Zawarte w niniejszej Ocenie/Raporcie informacje (w tym dotyczące wyposażenia) służą jedynie ogólnym celom informacyjnym. Ocena/Raport nie może być zatem traktowana jako oferta w rozumieniu przepisów Kodeksu Cywilnego oraz opisu towaru ani zapewnienia w rozumieniu art. 4 Ustawy z dnia 27 lipca 2002 roku o szczególnych warunkach sprzedaży konsumenckiej.
- Niniejsza Ocena/Raport nie jest szczegółową oceną stanu technicznego.

Ocenę/Raport wykonano w kierunku ujawnienia uszkodzeń nieakceptowanych z punktu widzenia właściwego przewodnika zwrotu pojazdu lub innych ustaleń ze Zleceniodawcą. Tym samym Ocena/Raport może nie ujmować typowych zużyć i uszkodzeń eksploatacyjnych.

PHOTOGRAPHIC DOCUMENTATION



Photo 1.
Przekątna przednia lewa




Photo 2.
Przód

PHOTOGRAPHIC DOCUMENTATION



Photo 3.

Przekątna przednia prawa



Photo 4.

Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 5.

Bok prawy z tyłu



Photo 6.

Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 7.

Tył



Photo 8.

Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 9.

Bok lewy z tyłu



Photo 10.

Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 11.

Próg lewy (widok od przodu)



Photo 12.

Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



Photo 13.
Spód pojazdu przód



Photo 14.
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION



Photo 15.

Tarcza hamulcowa przednia prawa



Photo 16.

Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 17.

Tarcza hamulcowa tylna lewa



Photo 18.

Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 19.
Bagażnik



Photo 20.
Koło zapasowe

PHOTOGRAPHIC DOCUMENTATION



Photo 21.
Komora silnika



Photo 22.
Numer identyfikacyjny

PHOTOGRAPHIC DOCUMENTATION



Photo 23.

Tabliczka znamionowa



Photo 24.

Zestaw wskaźników - przebieg

PHOTOGRAPHIC DOCUMENTATION



Photo 25.

Widok przez otwarte drzwi przednie lewe



Photo 26.

Kierownica z lewej strony

PHOTOGRAPHIC DOCUMENTATION



Photo 27.

Widok przez otwarte drzwi tylne lewe



Photo 28.

Widok z tylnej kanapy na deskę rozd.

PHOTOGRAPHIC DOCUMENTATION



Photo 29.
Konsola środkowa



Photo 30.
Tunel środkowy

PHOTOGRAPHIC DOCUMENTATION



Photo 31.

Kierownica (na wprost)



Photo 32.

Dowód rej. Str. 1

PHOTOGRAPHIC DOCUMENTATION



Photo 33.

Dow. Rej. Str.2 i klucze




Photo 34.

Książka serwisowa – dane

PHOTOGRAPHIC DOCUMENTATION




Photo 35.

Książka serwisowa – ostatni przegląd




Photo 36.

Instrukcje

PHOTOGRAPHIC DOCUMENTATION



Photo 37.

Zdjęcie do protokołu



Photo 38.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 39.

Pokrywa komory silnika - Rysa/odprysk 1



Photo 40.

Spoiler zderzaka przedniego - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 41.

Zderzak przedni cz dolna - Rysa/odprysk 1



Photo 42.

Zderzak przedni cz dolna - Rysa/odprysk 2

PHOTOGRAPHIC DOCUMENTATION



Photo 43.

Błotnik przedni P - Rysa/odprysk 1



Photo 44.

Felga aluminiowa przednia P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 45.

Reflektor P - Rysa/odprysk 1



Photo 46.

Drzwi przednie P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 47.

Drzwi przednie P - Wgniecenie/odkształcenie 1



Photo 48.

Drzwi tylne P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION




Photo 49.

Drzwi tylne P - Wgniecenie/odkształcenie 1



Photo 50.

Lusterko zew P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 51.

Próg P - Wgniecenie/odkształcenie 1



Photo 52.

Próg P - Wgniecenie/odkształcenie 2

PHOTOGRAPHIC DOCUMENTATION



Photo 53.

Błotnik tylny P / Ściana boczna P - Wgniecenie/odkształcenie 1



Photo 54.

Zderzak tylny - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 55.

Zderzak tylny - Rysa/odprysk 2



Photo 56.

Zderzak tylny cz dolna - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 57.

Błotnik tylny L / Ściana boczna L - Wgniecenie/odkształcenie 1



Photo 58.

Błotnik tylny L / Ściana boczna L - Wgniecenie/odkształcenie 2

PHOTOGRAPHIC DOCUMENTATION



Photo 59.

Drzwi przed L - Rysa/odprysk 1



Photo 60.

Drzwi przed L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 61.

Drzwi tylne L - Rysa/odprysk 1



Photo 62.

Drzwi tylne L - Rysa/odprysk 2

PHOTOGRAPHIC DOCUMENTATION



Photo 63.

Próg L - Rysa/odprysk 1




Photo 64.

Słupek środkowy L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 65.

Felga Aluminiowa przednia L - Rysa/odprysk 1



Photo 66.

Listwa błotnika przedniego L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 67.

Koło kierownicy - Rysa/odprysk 1



Photo 68.

Fotel prz. lew. - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 69.

Fotel prz. praw. - Inne 1



Photo 70.

Kanapa tyl. - Inne 1