

DEKRA's commission No. : PKOL(W)/LODZ/55117/24/07/18
commission/ damage No. : 23/022955
Date of commission: 18-07-2024

DEKRA Poland - Headquarters
02-673 Warszawa, ul. Konstruktorska 12A

Client :
PKO Leasing Finance
PKO Leasing SA
Al. Śmigłego-Rydza 20
93-281 Łódź

Expert:
Marcin Sosnowski.
DEKRA Polska - Centrala
inż. Józef Orłowski
TU - Włocławek

NOTE:

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

Vehicle data

Group of objects (Eurotax)	jeeps
EC code (Eurotax)	0157653
Manufacturer	LAND ROVER
Model	Defender 130 22-
Type / version	Defender 130 3.0 D250 mHEV S
Body type	KOM
Number of doors / seats	5/5
Curb weight [kg]	2486
Gross vehicle weight [kg]	3380
Wheelbase 1/2	3022
Engine type	Automatic ignition
Pollution reduction system	KSC
Engine capacity [ccm]	2997
Engine Power [hp/kW]	249/183
Gearbox	automatic 8- gear
Registration /record No.	GD4J890
VIN / serial number	SALEA7BW5P2234851
Date of first registration	21-07-2023
Date of next. tech. test	21-07-2026
Year of manufacture	2023 (year has been verified with the manufacturer's base)
Readout [km]	34 069 (read)
Body color / type of coating	green/METALIK

Tyres

axle	Wheel	Manufacturer, type	Size	Measured profile
Front	right	PIRELLI, SCORPION ZERO	255/60 20 113V	5,5 mm
	left	PIRELLI, SCORPION ZERO	255/60 20 113V	5,5 mm
back	right	PIRELLI, SCORPION ZERO	255/60 20 113V	5,0 mm
	left	PIRELLI, SCORPION ZERO	255/60 20 113V	5,0 mm

Standard equipment by Eurotax

- | | |
|---|--|
| 1. 360 view camera | 29. Interior: other |
| 2. Active Emergency Brake Assist | 30. Interior: other |
| 3. Air suspension | 31. Keyless go |
| 4. Air suspension, Electronic controlled suspension | 32. Kierownica nie-skórzana premium |
| 5. Alarm | 33. LED front dim light |
| 6. All season tyres | 34. LED rear lights |
| 7. Android Auto | 35. Lane control assistant |
| 8. Apple CarPlay | 36. Luggage compartment cover |
| 9. Armrest (s) front | 37. On board monitor |
| 10. Armrest (s) front, Driver seat electrically adjustable, Driver seat height adjustable, Driver seat with adjustable inclination, Lumbar adjust driver, Lumbar adjust passenger, Passenger seat electrically adjustable, Passenger seat height adjustable, Passenger seat with adjustable inclination | 38. Other |
| 11. Armrest (s) rear, Rear seat-backs foldable in two separate parts | 39. Other |
| 12. Automated High-beam assist | 40. Panel zewnętrzny tylnych bocznych wizjerów |
| 13. Automatic headlight elevation control | 41. Radio cyfrowe (DAB, DAB+, DMB) - dostępność sygnału i stacji zgodnie z ofertą nadawców |
| 14. Bord climate: other | 42. Rear-view mirror autodimming |
| 15. Bord climate: other | 43. Roof railing |
| 16. Brak bezprzewodowego systemu do ładowania telefonu | 44. Siedzenia z tkaniny Robustec w kolorze Ebony z wnętrzem Ebony |
| 17. Brak pakietu dla palących | 45. Składany trzeci rząd siedzeń dzielony w proporcji 40:20:40 |
| 18. Cruise control | 46. Standardowy materiał wykończenia wnętrza |
| 19. Door mirror(s) electrically adjustable in general, Door mirrors autodimming, Door mirrors electrically foldable, Door mirrors heated, Floor lighting, Side indicators | 47. Steering wheel manually adjustable |
| 20. Drążek zmiany biegów wykonany z materiału Resist | 48. Sunblind rear side door manual |
| 21. Electronic controlled suspension | 49. System multimedialny Pivi Pro |
| 22. Exterior design: other | 50. Traffic sign recognition |
| 23. Felgi aluminiowe 19" 6-ramienne (wzór 6010) | 51. Trzystrefowa klimatyzacja z tylnym asystentem chłodzenia (pomocniczy agregat chłodniczy) |
| 24. Floor mat | 52. Tyre pressure control (RDC) |
| 25. Full size spare wheel | 53. Wspomaganie parkowania 360° |
| 26. Glass tilt/slide sunroof electric | 54. Wyświetlacz 11,4" |
| 27. Interior decoration: other | 55. Zestaw audio Sound System - 180W, 6 głośników |
| 28. Interior lights: other accessories | |

Dealer's equipment (selected items)

- | | |
|--|---|
| 1. Exterior design: other, Roof: other | - |
| 2. Felgi aluminiowe 20" 6-ramienne (wzór 6011) - Gloss Black | - |
| 3. Fog lamps | - |
| 4. Lakier Pangea Green | - |
| 5. Pakiet Cold Climate | - |
| Spryskiwacze lamp przednich | |
| Kierownica ogrzewana | |
| Dysze spryskiwaczy przedniej szyby z podgrzewaniem | |
| Szyba przednia ogrzewana | |
| 6. Pakiet Driver Assist | - |
| Asystent martwego punktu | |

- System ostrzegający przed potencjalną kolizją z tyłu
- Tempomat aktywny z asystentem jazdy w korku Stop & Go
- System wykrywania ruchu przecinającego drogę cofania
- Tempomat aktywny
- 7. Pakiet Premium Upgrade Interior -
- Kierownica skórzana
- Kolumna kierownicy z elektryczną regulacją położenia
- Dźwignia zmiany biegów wykończona skórą
- Uchwyty ISOFIX na przednim siedzeniu pasażera do mocowania dwóch fotelików dziecięcych
- Pakiet skórzany rozszerzony (środkowa część deski rozdzielczej, górne części bocznych drzwi ze skóry)
- Fotele przednie podgrzewane i wentylowane, regulowane w 18 kierunkach z pamięcią ustawień
- 8. Tinted rear windows, Windows: other -
- 9. Towbar removable -

Base value of the vehicle

Base value of the vehicle by Eurotax (net) -

Corrections

First registration

Mileage

Equipment

Tyres

Other

Earlier repairs -


Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 07-2024 POL) with regard to technical and market parameters affecting the value of the vehicle.

Basic print without information about the vehicle's value - due to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 24-07-2024

DEKRA's expert:
Marcin Sosnowski.
inż. Józef Orłowski

Document issued electronically valid without signature.

Measurement of thickness of the vehicle lacquer coating


No. of controlled item	Controlled item	Measured range of thickness of the lacquer coat [µm]
1	Front cover	150 - 300
2	Left front fender	150 - 300
3	Left front pillar	150 - 200
4	Left front wall	150 - 300
5	Roof	to 150
6	Left middle pillar	150 - 200
7	Left side sill	150 - 200
8	Left rear wall	150 - 300
9	Left side wall	150 - 300
10	Cover/tailgate	150 - 200
11	Side right wall	150 - 300
12	Rear right door	150 - 300
13	Middle right pillar	150 - 200
14	Front right door	150 - 300
15	Right side sill	150 - 200
16	Right front pillar	150 - 200
17	Right front fender	150 - 500

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

During the inspection the registration proof of the vehicle was presented and its photo was taken and enclosed to the expertise.

During the inspection the service book was presented and its number is given below:
elektroniczna

Information concerning the origin of the vehicle

The vehicle purchased domestically from an authorized representative of the brand.

Additional comments on the car:

Not applicable.

Test drive

Test drive of the vehicle was conducted. Test drive in the full extent is not possible. Comment below:
ograniczenia parkingowe

Checking of the correctness and / or construction of identification / serial numbers of the object:

Not tested

Verification of the accuracy of the object data, including year of production, and other.

Not conducted - adopted according to the documents presented and indicated sources.

Anti-theft protection

alarm immobilizer

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.
- The evaluation has been carried out basing on delivered documentation and organoleptic examination of the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the assessed object.
- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

Comments to the commission - regarding valuation

Kluczyki

TAK

2

PHOTOGRAPHIC DOCUMENTATION



Photo 1.

Przekątna przednia lewa



Photo 2.

Przód

PHOTOGRAPHIC DOCUMENTATION



Photo 3.

Przekątna przednia prawa



Photo 4.

Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 5.
Bok prawy z tyłu



Photo 6.
Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 7.

Tył



Photo 8.

Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 9.

Bok lewy z tyłu



Photo 10.

Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 11.

Próg lewy (widok od przodu)



Photo 12.

Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



Photo 13.
Spód pojazdu przód



Photo 14.
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION



Photo 15.

Tarcza hamulcowa przednia prawa



Photo 16.

Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 17.
Tarcza hamulcowa tylna lewa



Photo 18.
Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 19.
Bagażnik



Photo 20.
Koło zapasowe

PHOTOGRAPHIC DOCUMENTATION



Photo 21.
Komora silnika



Photo 22.
Numer identyfikacyjny

PHOTOGRAPHIC DOCUMENTATION



Photo 23.

Tabliczka znamionowa



Photo 24.

Zestaw wskaźników - przebieg

PHOTOGRAPHIC DOCUMENTATION



Photo 25.

Widok przez otwarte drzwi przednie lewe



Photo 26.

Kierownica z lewej strony

PHOTOGRAPHIC DOCUMENTATION



Photo 27.

Widok przez otwarte drzwi tylne lewe



Photo 28.

Widok z tylnej kanapy na deskę rozdzielczą

PHOTOGRAPHIC DOCUMENTATION



Photo 29.
Konsola środkowa



Photo 30.
Tunel środkowy

PHOTOGRAPHIC DOCUMENTATION

Photo 31.
Kierownica (na wprost)



Photo 32.
Dowód rej. Str. 1

PHOTOGRAPHIC DOCUMENTATION



Photo 33.

Dow. Rej. Str.2 i klucze



Photo 34.

Instrukcje

PHOTOGRAPHIC DOCUMENTATION



Photo 35.

Zdjęcie do protokołu




Photo 36.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 37.

Zdjęcie do protokołu



Photo 38.

Błotnik przedni L - Rysa/odprysk 1