

DEKRA's commission No. : PKOL(W)/LODZ/27086/25/04/14
commission/ damage No. : FUTURA
Date of commission: 14-04-2025

DEKRA Poland - Headquarters
02-673 Warszawa, ul. Konstruktorska 12A

Client :

PKO Leasing SA
Świętokrzyska 36
00-116 Warszawa

Expert:

Kacper Sosnowski (NEW)
DEKRA Polska - współpraca O/Warszawa
mgr inż. Andrzej Szymkowiak
DEKRA Polska - O. Wrocław

NOTE:

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

Vehicle data

Group of objects (Eurotax)	cars
EC code (Eurotax)	0154326
Manufacturer	HYUNDAI
Model	i30 20-24
Type / version	i30 1.5 DPI Smart
Body type	hatchback
Number of doors / seats	5/5
Curb weight [kg]	1241
Gross vehicle weight [kg]	1750
Wheelbase 1/2	2650
Engine type	spark ignition
Pollution reduction system	three-way catalytic converter
Emission standard	EURO 6
Engine capacity [ccm]	1498
Engine Power [hp/kW]	110/81
Gearbox	manual 6- gear
Registration /record No.	WD9075S
VIN / serial number	TMAH351CANJ188216
Date of first registration	02-08-2022
Date of next. tech. test	02-08-2025
Year of manufacture	2022 (year has been verified with the manufacturer's base)
Readout [km]	41 285 (read)
Body color / type of coating	silver/METALIK

Tyres

axle	Wheel	Manufacturer, type	Size	Measured profile
Front	right	Dębica, NAVIGATOR 3	205/55 R16 94V	3,0 mm
	left	Dębica, NAVIGATOR 3	205/55 R16 94V	3,0 mm
back	right	Dębica, NAVIGATOR 3	205/55 R16 94V	4,0 mm
	left	Dębica, NAVIGATOR 3	205/55 R16 94V	4,0 mm

Standard equipment by Eurotax

- | | |
|--|--|
| 1. Additional gauges | 39. Interior: other |
| 2. Alarm | 40. Interior: other |
| 3. Android Auto, Apple CarPlay, DAB radio, On board monitor, Radio, Touchscreen monitor | 41. Interior: other |
| 4. Antilock-Brake-System (ABS) | 42. LED Daytime running lights |
| 5. Armrest (s) front, Storage facilities in general | 43. Lane control assistant |
| 6. Armrest (s) rear | 44. Leather gearshifter/switch, Leather steering wheel |
| 7. Automatic dimlight activation | 45. Light Alloy wheels 16" |
| 8. Bluetooth interface, Voice control for audiosystem | 46. Lumbar adjust driver |
| 9. Bord climate: other | 47. On board computer |
| 10. Central locking | 48. Other |
| 11. Child lock manually | 49. Other |
| 12. Child seat fixation | 50. Park Distance Control rear |
| 13. Collision Warning System, Pre-Crash System | 51. Passenger seat height adjustable |
| 14. Cornering Headlights, Exterior lighting: other | 52. Power steering |
| 15. Cruise control | 53. Power windows front, Power windows rear |
| 16. Diminished spare wheel | 54. Rear bench foldable in two separate parts |
| 17. Door mirror(s) electrically adjustable in general, Door mirrors heated | 55. Rear headrests |
| 18. Door mirrors electrically foldable | 56. Rear spoiler, Third braking light |
| 19. Driver airbag, Passenger airbag | 57. Rear view camera |
| 20. Driver conditioning monitoring | 58. Rear window heating |
| 21. Driver seat height adjustable | 59. Soundsystem |
| 22. Dualzone automatic climate control | 60. Soundsystem |
| 23. ESP (Electronical Stabilizing Program) | 61. Soundsystem |
| 24. Exterior design: other | 62. Speed limiter |
| 25. Exterior design: other | 63. Steering wheel heated |
| 26. Exterior design: other | 64. Steering wheel manually adjustable |
| 27. Exterior design: other | 65. Steering wheel with radio operation |
| 28. Exterior design: other | 66. Storage facilities in general |
| 29. Exterior lighting: other, Side indicators | 67. Textile upholstery |
| 30. Extra power outlet | 68. Tie-down ring |
| 31. Extra power outlet | 69. Tinted rear windows |
| 32. Fog lamps | 70. Towbar preparation |
| 33. Head airbags front, Head airbags rear, Side airbag driver and passenger, Side airbags rear | 71. Transport/loading: other |
| 34. Heated seat driver, Heated seat passenger | 72. Tyre pressure control (RDC) |
| 35. Hill holder | 73. USB in |
| 36. Interior lights: other accessories | 74. Uni-Lackierung |
| 37. Interior lights: other accessories | 75. Vehicle immobilizer |
| 38. Interior lights: other accessories, Mirror: others, Other | |

Dealer's equipment (selected items)

1. Metallic paint -

Base value of the vehicle

Base value of the vehicle by Eurotax (net) -

CorrectionsFirst registrationEquipmentTyresOther

State of the vehicle -
The specific type of the operation -
Aktualna sytuacja rynkowa -


Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 04-2025 POL) with regard to technical and market parameters affecting the value of the vehicle.

Basic print without information about the vehicle's value - duey to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 17-04-2025

DEKRA's expert:
Kacper Sosnowski (NEW)
mgr inż. Andrzej Szymkowiak

Document issued electronically valid without signature.

Measurement of thickness of the vehicle lacquer coating


No. of controlled item	Controlled item	Measured range of thickness of the lacquer coat [μm]
1	Front cover	to 150
2	Front left fender	to 150
3	Left front pillar	to 150
4	Front left door	to 150
5	Roof	to 150
6	Left middle pillar	to 150
7	Right side sill	to 150
8	Left rear door	to 150
9	Rear left fender	to 150
10	Cover/lid	to 150
11	Right rear fender	to 150
12	Right rear door	to 150
13	Right middle pillar	to 150
14	Right side sill	to 150
15	Front right door	to 150
16	Right front pillar	to 150
17	Front right fender	to 150

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

During the inspection the registration proof of the vehicle was presented and its photo was taken and enclosed to the expertise.

During the inspection the service book was presented and its number is given below:

vin

Information concerning the origin of the vehicle

The vehicle purchased domestically from an authorized representative of the brand.

Anti-theft protection - immobilizer

- as a result of the inspection of the vehicle found no malfunctions of the immobilizer in the extent possible to determine during the inspection of the vehicle in the non- workshop conditions.

Anti-theft protection - other:

not found

Additional comments on the car:

Not applicable.

Test drive

Test drive of the vehicle was conducted. Test drive in the full extent is not possible. Comment below:

pojazd udostępniono w warunkach parkingowych

Checking of the correctness and / or construction of identification / serial numbers of the object:

Not tested

Verification of the accuracy of the object data, including year of production, and other.

Not conducted - adopted according to the documents presented and indicated sources.

- The read odometer status has not been verified with records in electronic equipment of the vehicle.

- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.

- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.

- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.

- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.

- The evaluation has been carried out basing on delivered documentation and organoleptic examination of

page 5/43

the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the assessed object.

- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

Comments to the commission - regarding valuation

Kluczyki

TAK

1

Expert comments - regarding valuation

Rysy na samochodzie. Pojazd po gradobiciu. Bardzo liczne wgniecenia. Odpryski na szybie czołowej.

Rzecznik dokonał oględzin pojazdu w warunkach parkingowych, co mogło ograniczyć pełną ocenę jego stanu technicznego. Dodatkowo, jeżeli jazda próbna została przeprowadzona (informacje w treści raportu), to wykonano ją w warunkach parkingowych, z niewielką prędkością, co może nie odzwierciedlać pełnych warunków eksploatacyjnych. Istnieje możliwość, że w innych okolicznościach ujawnią się dodatkowe uszkodzenia lub usterki, których nie można było wykryć podczas obecnych oględzin. Zalecamy zatem skorzystanie z możliwości oględzin pojazdu we własnym zakresie lub w Autoryzowanej Stacji Obsługi danej marki, co pozwoli na pełniejszą weryfikację stanu technicznego pojazdu przed udziałem w aukcji.

Restrictive disclaimer - regarding valuation

- W Ocenie/Raporcie uwzględniono niesprawności, uszkodzenia, braki itp., które były możliwe do stwierdzenia organoleptycznego, w warunkach oględzin (z uwzględnieniem: stanu czystości pojazdu, warunków atmosferycznych, oświetlenia itd.) oraz bez weryfikacji serwisowej, bez dostępu do spodu pojazdu, bez specjalistycznego sprzętu diagnostycznego (w tym bez diagnostyki komputerowej), bez jazdy próbnej wykonanej w warunkach drogowych z obciążeniem.
- W ramach Oceny/Raportu nie weryfikowano odczytanego stanu drogomierza z zapisami w urządzeniach elektronicznych pojazdu.
- Rzecznik nie bierze na siebie odpowiedzialności za wady ukryte (prawne i fizyczne) oraz ewentualne skutki wynikające z dalszego użytkowania przedmiotu oceny, a także za skutki wykorzystania samej oceny.
- Podane przedziały grubości powłoki lakierowej, dotyczą punktów pomiarowych. Nie mogą być traktowane jako gwarancja, że grubość powłoki lakierowej w innych punktach nie wykracza poza te przedziały.
- Zawarte w niniejszej Ocenie/Raporcie informacje (w tym dotyczące wyposażenia) służą jedynie ogólnym celom informacyjnym. Ocena/Raport nie może być zatem traktowana jako oferta w rozumieniu przepisów Kodeksu Cywilnego oraz opisu towaru ani zapewnienia w rozumieniu art. 4 Ustawy z dnia 27 lipca 2002 roku o szczególnych warunkach sprzedaży konsumenckiej.
- Niniejsza Ocena/Raport nie jest szczegółową oceną stanu technicznego.

Ocenę/Raport wykonano w kierunku ujawnienia uszkodzeń nieakceptowanych z punktu widzenia właściwego przewodnika zwrotu pojazdu lub innych ustaleń ze Zleceniodawcą. Tym samym Ocena/Raport może nie ujmować typowych zużyć i uszkodzeń eksploatacyjnych.

PHOTOGRAPHIC DOCUMENTATION



Photo 1.

Przekątna przednia lewa



Photo 2.

Przód

PHOTOGRAPHIC DOCUMENTATION



Photo 3.

Przekątna przednia prawa



Photo 4.

Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 5.
Bok prawy z tyłu



Photo 6.
Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 7.

Tył



Photo 8.

Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 9.

Bok lewy z tyłu



Photo 10.

Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 11.

Próg lewy (widok od przodu)



Photo 12.

Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



Photo 13.
Spód pojazdu przód



Photo 14.
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION



Photo 15.

Tarcza hamulcowa przednia prawa



Photo 16.

Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 17.

Tarcza hamulcowa tylna lewa



Photo 18.

Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 19.
Bagażnik



Photo 20.
Koło zapasowe

PHOTOGRAPHIC DOCUMENTATION



Photo 21.
Komora silnika



Photo 22.
Numer identyfikacyjny

PHOTOGRAPHIC DOCUMENTATION**Photo 23.**

Tabliczka znamionowa

**Photo 24.**

Zestaw wskaźników - przebieg

PHOTOGRAPHIC DOCUMENTATION



Photo 25.

Widok przez otwarte drzwi przednie lewe



Photo 26.

Kierownica z lewej strony

PHOTOGRAPHIC DOCUMENTATION



Photo 27.

Widok przez otwarte drzwi tylne lewe



Photo 28.

Widok z tylnej kanapy na deskę rozdz.

PHOTOGRAPHIC DOCUMENTATION



Photo 29.

Konsola środkowa



Photo 30.

Tunel środkowy

PHOTOGRAPHIC DOCUMENTATION




Photo 31.
Kierownica (na wprost)




Photo 32.
Dowód rej. Str. 1

PHOTOGRAPHIC DOCUMENTATION**Photo 33.**


Dow. Rej. Str.2 i klucze

**Photo 34.**

Książka serwisowa – dane

PHOTOGRAPHIC DOCUMENTATION**Photo 35.**

Książka serwisowa – ostatni przegląd

**Photo 36.**

Instrukcje

PHOTOGRAPHIC DOCUMENTATION



Photo 37.

Atrapa przednia - Wgniecenie/odkształcenie 1



Photo 38.

Atrapa przednia - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 39.

Pokrywa komory silnika - Rysa/odprysk 1



Photo 40.

Pokrywa komory silnika - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 41.

Pokrywa komory silnika - Wgniecenie/odkształcenie 2



Photo 42.

Zderzak - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 43.

Zderzak - Rysa/odprysk 2



Photo 44.

Drzwi przednie P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 45.

Drzwi przednie P - Wgniecenie/odkształcenie 1



Photo 46.

Drzwi tylne P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION




Photo 47.

Próg P - Rysa/odprysk 1



Photo 48.

Słupek przedni P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 49.

Błotnik tylny P / Ściana boczna P - Rysa/odprysk 1



Photo 50.

Błotnik tylny P / Ściana boczna P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 51.

Pokrywy bagażnika - Wgniecenie/odkształcenie 1



Photo 52.

Pokrywy bagażnika - Wgniecenie/odkształcenie 2

PHOTOGRAPHIC DOCUMENTATION



Photo 53.

Zderzak tylny - Rysa/odprysk 1



Photo 54.

Dach - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 55.

Dach - Wgniecenie/odkształcenie 2



Photo 56.

Dach() - Wgniecenie/odkształcenie 3

PHOTOGRAPHIC DOCUMENTATION



Photo 57.

Błotnik tylny L / Ściana boczna L - Wgniecenie/odkształcenie 1



Photo 58.

Błotnik tylny L / Ściana boczna L - Wgniecenie/odkształcenie 2

PHOTOGRAPHIC DOCUMENTATION



Photo 59.

Drzwi przed L - Wgniecenie/odkształcenie 1



Photo 60.

Drzwi tylne L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 61.

Listwa drzwi przednich L - Wgniecenie/odkształcenie 1



Photo 62.

Listwa drzwi przednich L - Wgniecenie/odkształcenie 2

PHOTOGRAPHIC DOCUMENTATION



Photo 63.

Listwa drzwi tylnych L - Wgniecenie/odkształcenie 1



Photo 64.

Lusterko zew L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 65.

Śłupek przedni L - Wgniecenie/odkształcenie 1



Photo 66.

Śłupek przedni L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 67.

Pokrywa schowka deski rozdzielczej - Rysa/odprysk 1



Photo 68.

Fotel prz. lew. - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 69.

Zaglówek fotela prz. L - Inne 1



Photo 70.

Tapicerka drzwi przednich P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 71.

Podsufitka - Inne 1



Photo 72.

Podsufitka - Inne 2

PHOTOGRAPHIC DOCUMENTATION



Photo 73.

Wykładzina(y) słupka przedniego L - Inne 1