

DEKRA's commission No. : PKOL(W)/LODZ/69483/26/07/27
commission/ damage No. : 23/030243
Date of commission: 27-07-2026

DEKRA Poland - Headquarters
02-673 Warszawa, ul. Konstruktorska 12A

Client :

PKO Leasing SA
Świętokrzyska 36
00-116 Warszawa

Expert:

Kacper Sosnowski (WSP)
DEKRA Polska - współpraca O/Warszawa
Andrzej Sosnowski
DEKRA Polska - Centrala

NOTE:

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

Vehicle data

Group of objects (Eurotax)	cars
EC code (Eurotax)	0137932
Manufacturer	BMW
Model	Seria 3 [G20] 18-22
Type / version	330d xDrive M Sport sport-aut
Body type	sedan
Number of doors / seats	4/5
Curb weight [kg]	1660
Gross vehicle weight [kg]	2255
Wheelbase 1/2	2851
Engine type	Automatic ignition
Pollution reduction system	KSC
Engine capacity [ccm]	2993
Engine Power [hp/kW]	265/195
Gearbox	automatic
Registration /record No.	DW6WH80
VIN / serial number	WBA5W11070FK33862
Date of first registration	13-10-2020
Date of next. tech. test	13-10-2026
Year of manufacture	2020 (year has been verified with the manufacturer's base)
Readout [km]	266 603 (read)
Body color / type of coating	gray/double-layered, metallized

Tyres

axle	Wheel	Manufacturer, type	Size	Measured profile
Front	right	VREDESTEIN, WINTRAC PRO +	225/40 19 93Y	4,5 mm
	left	VREDESTEIN, WINTRAC PRO +	225/40 19 93Y	5,0 mm
back	right	VREDESTEIN, WINTRAC PRO +	255/35 19 96Y	2,0 mm
	left	VREDESTEIN, WINTRAC PRO +	255/35 19 96Y	1,5 mm

Standard equipment by Eurotax

- | | |
|---|---|
| 1. Additional gauges | 36. LED Fog Lamps |
| 2. Additional gauges | 37. LED front dim light, LED rear lights |
| 3. Additional gauges, Other | 38. Light Alloy wheels 18" |
| 4. Aerodynamics package, Exterior design: other | 39. Limited slip differential in general |
| 5. Airbag: other | 40. Mobile Tire System |
| 6. Alarm | 41. Navigation system, Other, Park Assistant |
| 7. Alcantara upholstery, Textile upholstery | 42. Other |
| 8. Antilock-Brake-System (ABS) | 43. Other |
| 9. Armrest (s) front | 44. Other |
| 10. Armrest (s) rear | 45. Other |
| 11. Bluetooth interface, Hands-free system, USB in | 46. Other |
| 12. Bord communication: other | 47. Other |
| 13. Chassis: other | 48. Other |
| 14. Child seat fixation | 49. Other |
| 15. Colored glass | 50. Other |
| 16. Cruise control | 51. Park Distance Control front, Park Distance Control rear |
| 17. Driver airbag, Passenger airbag, Side airbag driver and passenger | 52. Particle filter |
| 18. ESP (Electronical Stabilizing Program), Traction control | 53. Power steering |
| 19. Exterior design: other | 54. Radio |
| 20. Exterior design: other | 55. Rain sensor |
| 21. Exterior design: other | 56. Rear headrests |
| 22. Exterior design: other | 57. Rear seat-backs foldable in two separate parts |
| 23. Exterior design: other | 58. Rear-view mirror autodimming |
| 24. Exterior design: other | 59. Remote controlled central locking |
| 25. Exterior design: other | 60. Selectable driveline characteristics |
| 26. Exterior lighting: other | 61. Sport seats front |
| 27. Extra power outlet | 62. Sport suspension |
| 28. Floor mat | 63. Sports steering wheel |
| 29. Follow me home | 64. Storage facilities in general |
| 30. Follow me home | 65. Telematic |
| 31. Hill holder, Other | 66. Telematic |
| 32. Interior lights: other accessories | 67. Trizone automatic climate control |
| 33. Interior lights: other accessories | 68. Tyre pressure control (RDC) |
| 34. Interior: other | 69. Uni-Lackierung |
| 35. Interior: other | 70. Wheel bolt locks |

Dealer's equipment (selected items)

- | | |
|---|---|
| 1. Accoustic windows | - |
| 2. Active Emergency Brake Assist, Adaptive Cruise Control, Lane control assistant, Rear view camera | - |
| 3. Adaptive light | - |
| 4. Additional gauges, Bluetooth interface, Head-Up Display, Navigation system, Other | - |
| 5. Automated High-beam assist | - |
| 6. DAB radio | - |
| 7. Door mirrors autodimming, Door mirrors electrically foldable, Mirror: others, Rear-view mirror autodimming | - |
| 8. Driver seat electrically adjustable, Memory seat, Passenger seat electrically adjustable | - |
| 9. Electric tailgate | - |
| 10. Gesture control for multimedia, Gesture control for vehicle functions | - |
| 11. Heated seat driver, Heated seat passenger | - |
| 12. Keyless entry, Keyless go | - |
| 13. Leather finish dashbord | - |
| 14. Leather upholstery | - |

15. Light Alloy wheels 19", Runflat tyres	-
16. Lumbar adjust driver, Lumbar adjust passenger	-
17. Mobile phone, Wireless device charging	-
18. Other	-
19. Other, Tinted rear windows	-
20. Park Assistant	-
21. Soundsystem	-
22. Steering wheel heated	-
23. Storage facilities in general	-

Base value of the vehicle

Base value of the vehicle by Eurotax (net) -

Corrections

First registration

Mileage

Equipment

Tyres

Other

Uszkodzenia, stan, weryfikacja serwisowa -

Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 08-2026 POL) with regard to technical and market parameters affecting the value of the vehicle.

Basic print without information about the vehicle's value - due to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 04-08-2026

DEKRA's expert:
Kacper Sosnowski (WSP)
Andrzej Sosnowski

Document issued electronically valid without signature.

Measurement of thickness of the vehicle lacquer coating


No. of controlled item	Controlled item	Measured range of thickness of the lacquer coat [μm]
1	Front cover	to 150
2	Front left fender	to 150
3	Left front pillar	to 150
4	Front left door	to 150
5	Roof	to 150
6	Left middle pillar	to 150
7	Right side sill	to 150
8	Left rear door	to 150
9	Rear left fender	to 150
10	Cover/lid	to 150
11	Right rear fender	to 150
12	Right rear door	to 150
13	Right middle pillar	to 150
14	Right side sill	to 150
15	Front right door	to 150
16	Right front pillar	to 150
17	Front right fender	to 150

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

During the inspection the registration proof of the vehicle was presented and its photo was taken and enclosed to the expertise.

During the inspection the service book was presented and its number is given below:
elektroniczna

Information concerning the origin of the vehicle

Lack of reliable data.

Anti-theft protection - immobilizer

- as a result of the inspection of the vehicle found no malfunctions of the immobilizer in the extent possible to determine during the inspection of the vehicle in the non- workshop conditions.

Anti-theft protection - other:

not found

Additional comments on the car:

Not applicable.

Test drive

Test drive of the vehicle was conducted. Test drive in the full extent is not possible. Comment below:
ograniczenia placowe

Checking of the correctness and / or construction of identification / serial numbers of the object:

Not tested

Verification of the accuracy of the object data, including year of production, and other.

Not conducted - adopted according to the documents presented and indicated sources.

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.
- The evaluation has been carried out basing on delivered documentation and organoleptic examination of

page 5/45

the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the assessed object.

- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

Comments to the commission - regarding valuation

Kluczyki

TAK

2

Expert comments - regarding valuation

Aktywna kontrolka silnika. Rysy na samochodzie. Odpryski na szybie czołowej. Niesprawne przyciski funkcyjne w jednym z kluczyków, grot prawidłowy. Informacja z placu o błędzie EGR.

Rzeczoznawca dokonał oględzin pojazdu w warunkach parkingowych, co mogło ograniczyć pełną ocenę jego stanu technicznego. Dodatkowo, jeżeli jazda próbna została przeprowadzona (informacje w treści raportu), to wykonano ją w warunkach parkingowych, z niewielką prędkością, co może nie odzwierciedlać pełnych warunków eksploatacyjnych. Istnieje możliwość, że w innych okolicznościach ujawnią się dodatkowe uszkodzenia lub usterki, których nie można było wykryć podczas obecnych oględzin. Zalecamy zatem skorzystanie z możliwości oględzin pojazdu we własnym zakresie lub w Autoryzowanej Stacji Obsługi danej marki, co pozwoli na pełniejszą weryfikację stanu technicznego pojazdu przed udziałem w aukcji."

Restrictive disclaimer - regarding valuation

Nie weryfikowano szczegółowo stanu układu napędowego, zawieszenia, kierowniczego, hamulcowego oraz wydechowego. Ocena została wykonana bez użycia podnośnika i specjalistycznego sprzętu diagnostycznego, nie dokonywano demontażu osłon i innych elementów. Ocena określa ogólny stan pojazdu na dzień oględzin w miejscu jego udostępnienia, nie może być zatem traktowana jako kompleksowa ocena stanu technicznego. Specyfikacja wg. programu operacyjnego w zakresie wyposażenia standardowego i dodatkowego nie gwarantuje zgodności ze stanem faktycznym w zakresie możliwym do ustalenia przez rzeczoznawcę podczas oględzin pojazdu.

Pomiar grubości powłoki lakierowej wykonano w miejscach możliwych do ich wykonania pomiary nie gwarantują oryginalności poszczególnych elementów poddanych ocenie.

- W Ocenie/Raporcie uwzględniono niesprawności, uszkodzenia, braki itp., które były możliwe do stwierdzenia organoleptycznego, w warunkach oględzin (z uwzględnieniem: stanu czystości pojazdu, warunków atmosferycznych, oświetlenia itd.) oraz bez weryfikacji serwisowej, bez dostępu do spodu pojazdu, bez specjalistycznego sprzętu diagnostycznego (w tym bez diagnostyki komputerowej), bez jazdy próbnej wykonanej w warunkach drogowych z obciążeniem.
- W ramach Oceny/Raporu nie weryfikowano odczytanego stanu drogomierza z zapisami w urządzeniach elektronicznych pojazdu.
- Rzeczoznawca nie bierze na siebie odpowiedzialności za wady ukryte (prawne i fizyczne) oraz ewentualne skutki wynikające z dalszego użytkowania przedmiotu oceny, a także za skutki wykorzystania samej oceny.
- Podane przedziały grubości powłoki lakierowej, dotyczą punktów pomiarowych. Nie mogą być traktowane jako gwarancja, że grubość powłoki lakierowej w innych punktach nie wykracza poza te przedziały.

- Zawarte w niniejszej Ocenie/Raporcie informacje (w tym dotyczące wyposażenia) służą jedynie ogólnym celom informacyjnym. Ocena/Raport nie może być zatem traktowana jako oferta w rozumieniu przepisów Kodeksu Cywilnego oraz opisu towaru ani zapewnienia w rozumieniu art. 4 Ustawy z dnia 27 lipca 2002 roku o szczególnych warunkach sprzedaży konsumenckiej.
- Niniejsza Ocena/Raport nie jest szczegółową oceną stanu technicznego.

Ocenę/Raport wykonano w kierunku ujawnienia uszkodzeń nieakceptowanych z punktu widzenia właściwego przewodnika zwrotu pojazdu lub innych ustaleń ze Zleceniodawcą. Tym samym Ocena/Raport może nie ujmować typowych zużyć i uszkodzeń eksploatacyjnych.

PHOTOGRAPHIC DOCUMENTATION



Photo 1.
Przekątna przednia lewa



Photo 2.
Przód

PHOTOGRAPHIC DOCUMENTATION



Photo 3.

Przekątna przednia prawa



Photo 4.

Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 5.
Bok prawy z tyłu



Photo 6.
Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 7.

Tył



Photo 8.

Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 9.

Bok lewy z tyłu



Photo 10.

Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 11.

Próg lewy (widok od przodu)



Photo 12.

Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



Photo 13.
Spód pojazdu przód



Photo 14.
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION



Photo 15.

Tarcza hamulcowa przednia prawa



Photo 16.

Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 17.

Tarcza hamulcowa tylna lewa



Photo 18.

Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 19.
Bagażnik



Photo 20.
Komora silnika

PHOTOGRAPHIC DOCUMENTATION



Photo 21.

Numer identyfikacyjny



Photo 22.

Tabliczka znamionowa

PHOTOGRAPHIC DOCUMENTATION



Photo 23.

Zestaw wskaźników - przebieg



Photo 24.

Zestaw wskaźników - serwis

PHOTOGRAPHIC DOCUMENTATION



Photo 25.

Widok przez otwarte drzwi przednie lewe



Photo 26.

Kierownica z lewej strony

PHOTOGRAPHIC DOCUMENTATION



Photo 27.

Widok przez otwarte drzwi tylne lewe



Photo 28.

Widok z tylnej kanapy na deskę rozdz.

PHOTOGRAPHIC DOCUMENTATION



Photo 29.
Konsola środkowa



Photo 30.
Tunel środkowy

PHOTOGRAPHIC DOCUMENTATION




Photo 31.

Kierownica (na wprost)



Photo 32.

Dowód rej. Str. 1

PHOTOGRAPHIC DOCUMENTATION**Photo 33.**

Książka serwisowa – dane

**Photo 34.**

Książka serwisowa – ostatni przegląd

PHOTOGRAPHIC DOCUMENTATION



Photo 35.

Dowód rej. str. 2



Photo 36.

Kluczyki

PHOTOGRAPHIC DOCUMENTATION



Photo 37.

Zdjęcie do protokołu



Photo 38.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 39.

Zdjęcie do protokołu



Photo 40.

Pokrywa komory silnika - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 41.

Pokrywa komory silnika - Wgniecenie/odkształcenie 1



Photo 42.

Wykładzina pokrywy komory silnika - Pęknięcie/rozerwanie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 43.

Zderzak - Rysa/odprysk 1



Photo 44.

Błotnik przedni P - zdjęcie poglądowe 1

PHOTOGRAPHIC DOCUMENTATION



Photo 45.

Błotnik przedni P - Rysa/odprysk 1



Photo 46.

Błotnik przedni P - Pęknięcie/rozerwanie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 47.

Felga aluminiowa przednia P - Rysa/odprysk 1



Photo 48.

Drzwi tylne P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 49.

Drzwi tylne P - Wgniecenie/odkształcenie 1



Photo 50.

Lusterko zew P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 51.

Próg P - Pęknięcie/rozerwanie 1



Photo 52.

Słupek przedni P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 53.

Błotnik tylny P / Ściana boczna P - Wgniecenie/odkształcenie 1



Photo 54.

Felga aluminiowa tylna P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 55.

Zderzak tylny - Rysa/odprysk 1



Photo 56.

Zderzak tylny - Rysa/odprysk 2

PHOTOGRAPHIC DOCUMENTATION



Photo 57.

Zderzak tylny - Wgniecenie/odkształcenie 1



Photo 58.

Zderzak tylny - Pęknięcie/rozerwanie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 59.

Dach - Wgniecenie/odkształcenie 1




Photo 60.

Dach - Wgniecenie/odkształcenie 2

PHOTOGRAPHIC DOCUMENTATION



Photo 61.

Błotnik tylny L / Ściana boczna L - Rysa/odprysk 1



Photo 62.

Błotnik tylny L / Ściana boczna L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 63.

Błotnik tylny L / Ściana boczna L - Wgniecenie/odkształcenie 2



Photo 64.

Felga aluminiowa tylna L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 65.

Drzwi przed L - Wgniecenie/odkształcenie 1




Photo 66.

Drzwi tylne L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION




Photo 67.

Lusterko zew L - Rysa/odprysk 1



Photo 68.

Słupek przedni L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 69.

Błotnik przedni L - Rysa/odprysk 1



Photo 70.

Felga Aluminiowa przednia L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 71.

Koło kierownicy - Rysa/odprysk 1



Photo 72.

Fotel prz. lew. - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION




Photo 73.

Fotel prz. lew. - Rysa/odprysk 2



Photo 74.

Fotel prz. praw. - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 75.

Tapicerka drzwi przednich L - Rysa/odprysk 1



Photo 76.

Tapicerka drzwi tylnych P - Rysa/odprysk 1