

DEKRA's commission No. : PKOL(W)/LODZ/58982/26/06/26
 commission/ damage No. : 00452/EO/23
 Date of commission: 26-06-2026

DEKRA Poland - Headquarters
 02-673 Warszawa, ul. Konstruktorska 12A

Client :

PKO Leasing SA
 Świętokrzyska 36
 00-116 Warszawa

Expert:

Kacper Sosnowski (WSP)
 DEKRA Polska - współpraca O/Warszawa
Andrzej Sosnowski
 DEKRA Polska - Centrala

NOTE:

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

Vehicle data

Group of objects (Eurotax)	cars
EC code (Eurotax)	0141484
Manufacturer	PORSCHE
Model	Taycan 19-24
Type / version	Taycan Turbo S
Body type	sedan
Number of doors / seats	4/4
Curb weight [kg]	2386
Gross vehicle weight [kg]	2870
Wheelbase 1/2	2900
Engine type	elektryczny
Pollution reduction system	-
Engine capacity [ccm]	0
Engine Power [hp/kW]	625/460 zgodnie z DR
Gearbox	automatic
Registration /record No.	KR9XY71
VIN / serial number	WP0ZZZY17PSA50166
Date of first registration	21-02-2023
Date of next. tech. test	21-02-2026
Year of manufacture	2022
Readout [km]	31 328 (read)
Body color / type of coating	gray/double-layered, metallized

Tyres

axle	Wheel	Manufacturer, type	Size	Measured profile
Front	right	GOODYEAR, EAGLE F1 ASYMETRIC3	265/35 21 101Y	5,5 mm
	left	GOODYEAR, EAGLE F1 ASYMETRIC3	265/35 21 101Y	5,5 mm
back	right	GOODYEAR, EAGLE F1 ASYMETRIC3	305/30 21 104Y	5,0 mm
	left	GOODYEAR, EAGLE F1 ASYMETRIC3	305/30 21 104Y	5,0 mm

Standard equipment by Eurotax

- | | |
|---|---|
| 1. Adaptive light, Automated High-beam assist, LED front dim light | 54. Interior decoration: other |
| 2. Additional gauges | 55. Interior lights: other accessories |
| 3. Aerodynamics package | 56. Interior lights: other accessories, Interior: other, Mirror: others |
| 4. Alarm | 57. Interior: other |
| 5. Android Auto, Apple CarPlay, Bord communication: other | 58. Interior: other |
| 6. Android Auto, Apple CarPlay, Gesture control for multimedia, Navigation system, On board monitor, Radio, Touchscreen monitor, Voice control for audiosystem, Voice control for navigation system | 59. Interior: other |
| 7. Antilock-Brake-System (ABS), Power assisted brakes, Traction control | 60. Keyless Engine start |
| 8. Armrest (s) front, Storage facilities in general | 61. LED Daytime running lights |
| 9. Armrest (s) rear, Rear seat-backs foldable in two separate parts, Seats: other | 62. Lane control assistant, Traffic sign recognition |
| 10. Automatic Emergency Call | 63. Light Allow wheels over 21'' |
| 11. Automatic climate control | 64. Luggage:other |
| 12. Automatic dimlight activation, Follow me home | 65. Luggage:other |
| 13. Automatic limited slip differential, Steering: other | 66. Metallic paint |
| 14. Battery with enhanced capacity / 2nd battery | 67. Mirror: others |
| 15. Bord climate: other | 68. Multi functional steering wheel, Sports steering wheel |
| 16. Bord communication: other | 69. On board monitor, Touchscreen monitor |
| 17. Bord communication: other | 70. Other |
| 18. Bord entertainment: other accessories, Chassis: other, Interior lights: other accessories, Other | 71. Other |
| 19. Bumpers: other | 72. Other |
| 20. Bumpers: other | 73. Other |
| 21. Cabin air filter | 74. Other |
| 22. Carbon finish | 75. Other |
| 23. Ceramic composite brakes | 76. Other |
| 24. Child seat fixation | 77. Other |
| 25. Collision Warning System, Pedestrian Emergency Brake Assist, Power assisted brakes, Pre-Crash System | 78. Other |
| 26. Colored glass, Windows: other | 79. Other |
| 27. Cruise control, Speed limiter | 80. Other |
| 28. DAB radio | 81. Other |
| 29. Door mirror(s) electrically adjustable in general, Door mirrors heated, Mirror: others | 82. Other |
| 30. Door mirrors autodimming, Rear-view mirror autodimming | 83. Other |
| 31. Driver airbag, Driver knee airbag, Head airbags front, Head airbags rear, Passenger airbag, Passenger knee airbag, Side airbag driver and passenger | 84. Park Assistant, Park Distance Control front, Park Distance Control rear |
| 32. Driver seat electrically adjustable, Memory seat, Passenger seat electrically adjustable, Sport seats front | 85. Rain sensor, Windscreenwiper: other |
| 33. Electric parking brake | 86. Rear axle strenghtened |
| 34. Electric tailgate | 87. Rear window heating |
| 35. Energy recovery system | 88. Remote controlled central locking |
| 36. Exterior design: other | 89. Roll over protection system |

- | | |
|--|---|
| 37. Exterior design: other | 90. Seatbelt pretensioner front, Seatbelt pretensioner rear |
| 38. Exterior design: other | 91. Seatbelts vertically adjustable front |
| 39. Exterior design: other | 92. Seats: other |
| 40. Exterior design: other | 93. Selectable driveline characteristics |
| 41. Exterior design: other | 94. Selectable driveline characteristics |
| 42. Exterior design: other | 95. Selectable driveline characteristics |
| 43. Exterior design: other | 96. Side Pre-Crash System |
| 44. Exterior design: other, Mirror: others | 97. Soundsystem |
| 45. Exterior design: other, Selectable driveline characteristics | 98. Storage facilities in general |
| 46. Exterior lighting: other | 99. Storage facilities in general, Wireless device charging |
| 47. Extra power outlet | 100. Textile upholstery |
| 48. Extra power outlet | 101. Third braking light |
| 49. Floor mat | 102. Traction control |
| 50. Heated seat driver, Heated seat passenger, Rear seat heating | 103. Tyre pressure control (RDC) |
| 51. Hydro pneumatic suspension | 104. USB in |
| 52. Interior decoration: other | 105. USB in |
| 53. Interior decoration: other | 106. Vehicle immobilizer |

Dealer's equipment (selected items)

- | | |
|---|---|
| 1. 4 or more zone automatic climate control | - |
| 2. Acoustic windows, Colored glass, Heat reflecting windows, Tinted rear windows | - |
| 3. Active lane change assistant | - |
| 4. Adaptive light, Automated High-beam assist, LED front dim light | - |
| 5. Adjustable suspension, Limited slip differential in general, Selectable central differential characteristics | - |
| 6. Exterior design: other | - |
| 7. Exterior design: other | - |
| 8. Exterior lighting: other | - |
| 9. Glass sunroof fixed | - |
| 10. Head-Up Display | - |
| 11. Interior decoration: other | - |
| 12. Interior decoration: other | - |
| 13. Interior decoration: other | - |
| 14. Interior decoration: other | - |
| 15. Interior decoration: other | - |
| 16. Interior decoration: other, Interior: other | - |
| 17. Interior: other | - |
| 18. Light Allow wheels over 21" | - |
| 19. On board monitor | - |
| 20. Other | - |
| 21. Other | - |
| 22. Soundsystem | - |
| 23. Steering wheel heated | - |
| 24. Video entertainment system | - |

Base value of the vehicle

Base value of the vehicle by Eurotax (net) -

CorrectionsFirst registrationEquipmentTyresOther

The validity of the technical examination -
Braki uszkodzenia -


Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 08-2026 POL) with regard to technical and market parameters affecting the value of the vehicle.

Basic print without information about the vehicle's value - duey to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 17-08-2026

DEKRA's expert:
Kacper Sosnowski (WSP)
Andrzej Sosnowski

Document issued electronically valid without signature.

Measurement of thickness of the vehicle lacquer coating


No. of controlled item	Controlled item	Measured range of thickness of the lacquer coat [μm]
1	Front cover	to 150
2	Front left fender	to 150
3	Left front pillar	to 150
4	Front left door	to 150
6	Left middle pillar	to 150
7	Right side sill	to 150
8	Left rear door	to 150
9	Rear left fender	to 150
10	Cover/lid	to 150
11	Right rear fender	to 150
12	Right rear door	to 150
13	Right middle pillar	to 150
14	Right side sill	to 150
15	Front right door	to 150
16	Right front pillar	to 150
17	Front right fender	to 150

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

Presented the following documents of the vehicle:

ksero pozwolenia czasowego

During the inspection the service book was presented and its number is given below:

.

Information concerning the origin of the vehicle

Lack of reliable data.

Anti-theft protection - immobilizer

- as a result of the inspection of the vehicle found no malfunctions of the immobilizer in the extent possible to determine during the inspection of the vehicle in the non- workshop conditions.

Anti-theft protection - other:

not found

Additional comments on the car:

Not applicable.

Test drive

Test drive of the vehicle was conducted. Test drive in the full extent is not possible. Comment below:
ograniczenia placowe

Checking of the correctness and / or construction of identification / serial numbers of the object:

Not tested

Verification of the accuracy of the object data, including year of production, and other.

Not conducted - adopted according to the documents presented and indicated sources.

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.
- The evaluation has been carried out basing on delivered documentation and organoleptic examination of

page 6/58

the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the assessed object.

- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

Comments to the commission - regarding valuation

Kluczyki

TAK

1

Expert comments - regarding valuation

Pojazd elektryczny. Dwa dywaniki w bagażniku. Rysy na samochodzie. Aktywna kontrolka ciśnienia w kołach. Informacja asystent ostrzegania i hamowania ograniczony. Informacja niezbędny wymiana płynu hamulcowego. Pojazd uszkodzony lewy przód. Dostarczono ksero pozwolenia czasowego. Brak aktualnych badań technicznych. Chwilowe zwiększenie mocy Launch Control do 761KM.

Rzeczoznawca dokonał oględzin pojazdu w warunkach parkingowych, co mogło ograniczyć pełną ocenę jego stanu technicznego. Dodatkowo, jeżeli jazda próbna została przeprowadzona (informacje w treści raportu), to wykonano ją w warunkach parkingowych, z niewielką prędkością, co może nie odzwierciedlać pełnych warunków eksploatacyjnych. Istnieje możliwość, że w innych okolicznościach ujawnią się dodatkowe uszkodzenia lub usterki, których nie można było wykryć podczas obecnych oględzin. Zalecamy zatem skorzystanie z możliwości oględzin pojazdu we własnym zakresie lub w Autoryzowanej Stacji Obsługi danej marki, co pozwoli na pełniejszą weryfikację stanu technicznego pojazdu przed udziałem w aukcji."

Restrictive disclaimer - regarding valuation

Nie weryfikowano szczegółowo stanu układu napędowego, zawieszenia, kierowniczego, hamulcowego oraz wydechowego. Ocena została wykonana bez użycia podnośnika i specjalistycznego sprzętu diagnostycznego, nie dokonywano demontażu osłon i innych elementów. Ocena określa ogólny stan pojazdu na dzień oględzin w miejscu jego udostępnienia, nie może być zatem traktowana jako kompleksowa ocena stanu technicznego. Specyfikacja wg. programu operacyjnego w zakresie wyposażenia standardowego i dodatkowego nie gwarantuje zgodności ze stanem faktycznym w zakresie możliwym do ustalenia przez rzeczoznawcę podczas oględzin pojazdu. Pomiar grubości powłoki lakierowej wykonano w miejscach możliwych do ich wykonania pomiary nie gwarantują oryginalności poszczególnych elementów poddanych ocenie.

- W Ocenie/Raporcie uwzględniono niesprawności, uszkodzenia, braki itp., które były możliwe do stwierdzenia organoleptycznego, w warunkach oględzin (z uwzględnieniem: stanu czystości pojazdu, warunków atmosferycznych, oświetlenia itd.) oraz bez weryfikacji serwisowej, bez dostępu do spodu pojazdu, bez specjalistycznego sprzętu diagnostycznego (w tym bez diagnostyki komputerowej), bez jazdy próbnej wykonanej w warunkach drogowych z obciążeniem.
- W ramach Oceny/Raportu nie weryfikowano odczytanego stanu drogomierza z zapisami w urządzeniach elektronicznych pojazdu.
- Rzeczoznawca nie bierze na siebie odpowiedzialności za wady ukryte (prawne i fizyczne) oraz ewentualne skutki wynikające z dalszego użytkowania przedmiotu oceny, a także za skutki wykorzystania samej oceny.

- Podane przedziały grubości powłoki lakierowej, dotyczą punktów pomiarowych. Nie mogą być traktowane jako gwarancja, że grubość powłoki lakierowej w innych punktach nie wykracza poza te przedziały.
- Zawarte w niniejszej Ocenie/Raporcie informacje (w tym dotyczące wyposażenia) służą jedynie ogólnym celom informacyjnym. Ocena/Raport nie może być zatem traktowana jako oferta w rozumieniu przepisów Kodeksu Cywilnego oraz opisu towaru ani zapewnienia w rozumieniu art. 4 Ustawy z dnia 27 lipca 2002 roku o szczególnych warunkach sprzedaży konsumenckiej.
- Niniejsza Ocena/Raport nie jest szczegółową oceną stanu technicznego.

Ocenę/Raport wykonano w kierunku ujawnienia uszkodzeń nieakceptowanych z punktu widzenia właściwego przewodnika zwrotu pojazdu lub innych ustaleń ze Zleceniodawcą. Tym samym Ocena/Raport może nie ujmować typowych zużyć i uszkodzeń eksploatacyjnych.

PHOTOGRAPHIC DOCUMENTATION



Photo 1.

Przekątna przednia lewa



Photo 2.

Przód

PHOTOGRAPHIC DOCUMENTATION



Photo 3.

Przekątna przednia prawa



Photo 4.

Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 5.

Bok prawy z tyłu



Photo 6.

Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 7.

Tył



Photo 8.

Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 9.

Bok lewy z tyłu



Photo 10.

Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 11.

Próg lewy (widok od przodu)



Photo 12.

Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



Photo 13.
Spód pojazdu przód



Photo 14.
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION




Photo 15.

Tarcza hamulcowa przednia prawa



Photo 16.

Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 17.

Tarcza hamulcowa tylna lewa



Photo 18.

Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 19.
Bagażnik



Photo 20.
Komora silnika

PHOTOGRAPHIC DOCUMENTATION



Photo 21.
Numer identyfikacyjny



Photo 22.
Tabliczka znamionowa

PHOTOGRAPHIC DOCUMENTATION



Photo 23.

Zestaw wskaźników - przebieg



Photo 24.

Zestaw wskaźników - serwis

PHOTOGRAPHIC DOCUMENTATION



Photo 25.

Widok przez otwarte drzwi przednie lewe



Photo 26.

Kierownica z lewej strony

PHOTOGRAPHIC DOCUMENTATION



Photo 27.

Widok przez otwarte drzwi tylne lewe



Photo 28.

Widok z tylnej kanapy na deskę rozdz.

PHOTOGRAPHIC DOCUMENTATION



Photo 29.
Konsola środkowa



Photo 30.
Tunel środkowy

PHOTOGRAPHIC DOCUMENTATION



Photo 31.
Kierownica (na wprost)



Photo 32.
Książka serwisowa – dane

PHOTOGRAPHIC DOCUMENTATION

Potwierdzenie przeprowadzenia przeglądu

Zaznaczyć krzyżykiem odpowiednie pola!

Wykonano przegląd przedsprzedażny (bezpłatny)

dnia: 25/11/22

Przebieg (km): 10

Nr zlecenia: 10637

PORSCHE CENTRUM Kraków 2600008

Pieczętka

Tak / Nie	Tak / Nie
☐ Przegląd	☐ Płyn hamulcowy wymieniony
☐ Środek do uszczelniania opon	☐

Potwierdzenie przeprowadzenia przeglądu

Wykonano przegląd eksploatacyjny

dnia:

Przebieg (km):

Nr zlecenia:

Pieczętka


Tak / Nie	Tak / Nie
☐ Przegląd	☐ Płyn hamulcowy wymieniony
☐ Środek do uszczelniania opon	☐

Photo 33.


Książka serwisowa – ostatni przegląd

**Photo 34.**

Przewód ładowania baterii trakcyjnej

PHOTOGRAPHIC DOCUMENTATION**Photo 35.**

Dowód rej. ksero Str. 1

**Photo 36.**

Dowód rej. ksero str. 2

PHOTOGRAPHIC DOCUMENTATION




Photo 37.

Instrukcje



Photo 38.

Zestaw naprawy koła

PHOTOGRAPHIC DOCUMENTATION



Photo 39.

Gniazdo ładowania / tankowania



Photo 40.

Kluczyki

PHOTOGRAPHIC DOCUMENTATION



Photo 41.
Zdjęcie do protokołu



Photo 42.
Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 43.

Zdjęcie do protokołu



Photo 44.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 45.

Zdjęcie do protokołu



Photo 46.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 47.

Zdjęcie do protokołu



Photo 48.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 49.

Zdjęcie do protokołu



Photo 50.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 51.

Zdjęcie do protokołu



Photo 52.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 53.

Zdjęcie do protokołu



Photo 54.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 55.

Zdjęcie do protokołu



Photo 56.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 57.

Zdjęcie do protokołu



Photo 58.

Listwa śr zderzaka przedniego - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 59.

Pokrywa komory silnika - Wgniecenie/odkształcenie 1



Photo 60.

Spoiler zderzaka przedniego - Pęknięcie/rozerwanie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 61.

Spoiler zderzaka przedniego - Inne 1




Photo 62.

Szyba czołowa - Pęknięcie/rozerwanie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 63.

Zderzak - zdjęcie poglądowe 1



Photo 64.

Zderzak - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 65.

Zderzak - Rysa/odprysk 2



Photo 66.

Zderzak() - Rysa/odprysk 3

PHOTOGRAPHIC DOCUMENTATION



Photo 67.

Zderzak - Pęknięcie/rozerwanie 1



Photo 68.

Zderzak - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 69.

Zderzak - Inne 2



Photo 70.

Felga aluminiowa przednia P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 71.

Drzwi przednie P - Rysa/odprysk 1



Photo 72.

Drzwi tylne P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 73.

Drzwi tylne P - Wgniecenie/odkształcenie 1



Photo 74.

Felga aluminiowa tylna P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 75.

Spojler zderzaka tylnego - Rysa/odprysk 1



Photo 76.

Spojler zderzaka tylnego - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 77.

Spojler zderzaka tylnego - Pęknięcie/rozerwanie 1



Photo 78.

Zderzak tylny - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 79.

Zderzak tylny - Wgniecenie/odkształcenie 1



Photo 80.

Zderzak tylny cz dolna - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 81.

Zderzak tylny cz dolna - Wgniecenie/odkształcenie 1



Photo 82.

Zderzak tylny cz dolna - Wgniecenie/odkształcenie 2

PHOTOGRAPHIC DOCUMENTATION



Photo 83.

Felga aluminiowa tylna L - Rysa/odprysk 1



Photo 84.

Drzwi przed L - zdjęcie poglądowe 1

PHOTOGRAPHIC DOCUMENTATION



Photo 85.

Drzwi przed L - Rysa/odprysk 1



Photo 86.

Drzwi przed L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 87.

Drzwi tylne L - Rysa/odprysk 1




Photo 88.

Drzwi tylne L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 89.

Próg L - Rysa/odprysk 1



Photo 90.

Próg L - Pęknięcie/rozerwanie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 91.

Błotnik przedni L - Wgniecenie/odkształcenie 1



Photo 92.

Błotnik przedni L - Wgniecenie/odkształcenie 2

PHOTOGRAPHIC DOCUMENTATION



Photo 93.

Felga Aluminiowa przednia L - Rysa/odprysk 1



Photo 94.

Deska rozdzielcza - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 95.

Koło kierownicy - Rysa/odprysk 1



Photo 96.

Tapicerka drzwi przednich L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 97.

Podsufitka - Inne 1



Photo 98.

Wykładzina(y) słupka środkowego L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 99.

Wykładzina(y) słupka środkowego P - Rysa/odprysk 1