

DEKRA's commission No. : PKOL(W)/LODZ/72770/24/09/20
 commission/ damage No. : 00481/LF/23
 Date of commission: 20-09-2024

DEKRA Poland - Headquarters
 02-673 Warszawa, ul. Konstruktorska 12A

Client :

PKO Leasing SA
 Świętokrzyska 36
 00-116 Warszawa

Expert:

Kacper Sosnowski (NEW)
 DEKRA Polska - współpraca O/Warszawa
Andrzej Sosnowski
 DEKRA Polska - Centrala

NOTE:

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

Vehicle data

| | |
|------------------------------|--|
| Group of objects (Eurotax) | cars |
| EC code (Eurotax) | 0145926 |
| Manufacturer | TOYOTA |
| Model | Corolla Sedan 18-22 |
| Type / version | Corolla 1.5 Comfort |
| Body type | sedan |
| Number of doors / seats | 4/5 |
| Curb weight [kg] | 1295 |
| Gross vehicle weight [kg] | 1795 |
| Wheelbase 1/2 | 2700 |
| Engine type | spark ignition |
| Pollution reduction system | GPF |
| Engine capacity [ccm] | 1490 |
| Engine Power [hp/kW] | 125/92 |
| Gearbox | manual 6- gear |
| Registration /record No. | WU7381P |
| VIN / serial number | NMTBA3BE30R047969 |
| Date of first registration | 25-04-2023 |
| Date of next. tech. test | 24-04-2026 |
| Year of manufacture | 2022 (year has been verified with the manufacturer's base) |
| Readout [km] | 33 963 (read) |
| Body color / type of coating | oliwkowy/double-layered, metallized |

Tyres

| axle | Wheel | Manufacturer, type | Size | Measured profile |
|-------|-------|-----------------------|---------------|------------------|
| Front | right | NEXEN, N BLUE 4SEASON | 205/55 16 91H | 4,0 mm |
| | left | NEXEN, N BLUE 4SEASON | 205/55 16 91H | 4,0 mm |
| back | right | NEXEN, N BLUE 4SEASON | 205/55 16 91H | 6,5 mm |
| | left | NEXEN, N BLUE 4SEASON | 205/55 16 91H | 6,5 mm |

Standard equipment by Eurotax

- | | |
|---|---|
| 1. Adaptive Cruise Control | 39. Interior lights: other accessories |
| 2. Additional gauges | 40. Interior: other |
| 3. Android Auto, Apple CarPlay | 41. Interior: other |
| 4. Antilock-Brake-System (ABS) | 42. Interior: other |
| 5. Armrest (s) front | 43. Keyless go |
| 6. Armrest (s) rear | 44. LED Daytime running lights |
| 7. Automated High-beam assist | 45. Lane control assistant |
| 8. Automatic Emergency Call | 46. Leather gearshifter/switch |
| 9. Automatic antenna/ window-antenna | 47. Leather steering wheel |
| 10. Automatic climate control | 48. Light Alloy wheels 16'' |
| 11. Automatic dimlight activation | 49. Mobile Tire System |
| 12. Bluetooth interface | 50. Multi functional steering wheel |
| 13. Bord climate: other | 51. On board computer |
| 14. Bord communication: other | 52. On board monitor |
| 15. Bord entertainment: other accessories | 53. Other |
| 16. Child lock manually | 54. Other |
| 17. Child seat fixation | 55. Other |
| 18. Cornering Headlights | 56. Other |
| 19. Distribution of braking force electronically | 57. Other |
| 20. Door mirror(s) electrically adjustable in general | 58. Other |
| 21. Door mirrors heated | 59. Power assisted brakes |
| 22. Driver airbag, Passenger airbag | 60. Power windows front, Power windows rear |
| 23. Driver knee airbag | 61. Pre-Crash System |
| 24. Driver seat height adjustable | 62. Radio |
| 25. ESP (Electronical Stabilizing Program) | 63. Radio |
| 26. ESP (Electronical Stabilizing Program), Traction control | 64. Rear bench foldable in two separate parts |
| 27. Exterior design: other | 65. Rear view camera |
| 28. Exterior design: other | 66. Remote controlled central locking |
| 29. Exterior lighting: other | 67. Rev counter |
| 30. Exterior lighting: other | 68. Seats: other |
| 31. Extra power outlet | 69. Side airbag driver and passenger |
| 32. Floor mat | 70. Steering wheel electrically adjustable |
| 33. Fog lamps | 71. Textile upholstery |
| 34. Head airbags front | 72. Traffic sign recognition |
| 35. Hill holder | 73. Tyre pressure control (RDC) |
| 36. Interior decoration: other | 74. USB in |
| 37. Interior decoration: other | 75. Uni-Lackierung |
| 38. Interior lights: other accessories | 76. Vehicle immobilizer |

Dealer's equipment (selected items)

1. Metallic paint -

Base value of the vehicle

Base value of the vehicle by Eurotax (net) -

Corrections

First registration

Mileage

Equipment

Tyres

Other

Uszkodzenia, stan

Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 09-2024 POL) with regard to technical and market parameters affecting the value of the vehicle.

Basic print without information about the vehicle's value - duey to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 30-09-2024

DEKRA's expert:
Kacper Sosnowski (NEW)
Andrzej Sosnowski

Document issued electronically valid without signature.

Measurement of thickness of the vehicle lacquer coating



| No. of controlled item | Controlled item | Measured range of thickness of the lacquer coat [μm] |
|------------------------|---------------------|---|
| 1 | Front cover | to 150 |
| 2 | Front left fender | to 150 |
| 3 | Left front pillar | to 150 |
| 4 | Front left door | to 150 |
| 5 | Roof | to 150 |
| 6 | Left middle pillar | to 150 |
| 7 | Right side sill | to 150 |
| 8 | Left rear door | to 150 |
| 9 | Rear left fender | to 150 |
| 10 | Cover/lid | to 150 |
| 11 | Right rear fender | to 150 |
| 12 | Right rear door | to 150 |
| 13 | Right middle pillar | to 150 |
| 14 | Right side sill | to 150 |
| 15 | Front right door | to 150 |
| 16 | Right front pillar | to 150 |
| 17 | Front right fender | to 150 |

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

During the inspection the registration proof of the vehicle was presented and its photo was taken and enclosed to the expertise.

During the inspection the service book was presented and its number is given below:

.

Information concerning the origin of the vehicle

Lack of reliable data.

Anti-theft protection - immobilizer

- as a result of the inspection of the vehicle found no malfunctions of the immobilizer in the extent possible to determine during the inspection of the vehicle in the non- workshop conditions.

Anti-theft protection - other:

not found

Additional comments on the car:

Not applicable.

Test drive

Test drive of the vehicle was conducted. Test drive in the full extent is not possible. Comment below:
ograniczenia placowe

Checking of the correctness and / or construction of identification / serial numbers of the object:

Not tested

Verification of the accuracy of the object data, including year of production, and other.

Not conducted - adopted according to the documents presented and indicated sources.

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.
- The evaluation has been carried out basing on delivered documentation and organoleptic examination of

the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the assessed object.

- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

Comments to the commission - regarding valuation

Kluczyki

TAK

2

Expert comments - regarding valuation

Rysy na samochodzie.

Restrictive disclaimer - regarding valuation

Nie weryfikowano szczegółowo stanu układu napędowego, zawieszenia, kierowniczego, hamulcowego oraz wydechowego. Ocena została wykonana bez użycia podnośnika i specjalistycznego sprzętu diagnostycznego, nie dokonywano demontażu osłon i innych elementów. Ocena określa ogólny stan pojazdu na dzień oględzin w miejscu jego udostępnienia, nie może być zatem traktowana jako kompleksowa ocena stanu technicznego. Specyfikacja wg. programu operacyjnego w zakresie wyposażenia standardowego i dodatkowego nie gwarantuje zgodności ze stanem faktycznym w zakresie możliwym do ustalenia przez rzeczoznawcę podczas oględzin pojazdu.

Pomiar grubości powłoki lakierowej wykonano w miejscach możliwych do ich wykonania pomiary nie gwarantują oryginalności poszczególnych elementów poddanych ocenie.

- W Ocenie/Raporcie uwzględniono niesprawności, uszkodzenia, braki itp., które były możliwe do stwierdzenia organoleptycznego, w warunkach oględzin (z uwzględnieniem: stanu czystości pojazdu, warunków atmosferycznych, oświetlenia itd.) oraz bez weryfikacji serwisowej, bez dostępu do spodu pojazdu, bez specjalistycznego sprzętu diagnostycznego (w tym bez diagnostyki komputerowej), bez jazdy próbnej wykonanej w warunkach drogowych z obciążeniem.
- W ramach Oceny/Raportu nie weryfikowano odczytanego stanu drogomierza z zapisami w urządzeniach elektronicznych pojazdu.
- Rzeczoznawca nie bierze na siebie odpowiedzialności za wady ukryte (prawne i fizyczne) oraz ewentualne skutki wynikające z dalszego użytkowania przedmiotu oceny, a także za skutki wykorzystania samej oceny.
- Podane przedziały grubości powłoki lakierowej, dotyczą punktów pomiarowych. Nie mogą być traktowane jako gwarancja, że grubość powłoki lakierowej w innych punktach nie wykracza poza te przedziały.
- Zawarte w niniejszej Ocenie/Raporcie informacje (w tym dotyczące wyposażenia) służą jedynie ogólnym celom informacyjnym. Ocena/Raport nie może być zatem traktowana jako oferta w rozumieniu przepisów Kodeksu Cywilnego oraz opisu towaru ani zapewnienia w rozumieniu art. 4 Ustawy z dnia 27 lipca 2002 roku o szczególnych warunkach sprzedaży konsumenckiej.
- Niniejsza Ocena/Raport nie jest szczegółową oceną stanu technicznego.

Ocenę/Raport wykonano w kierunku ujawnienia uszkodzeń nieakceptowanych z punktu widzenia właściwego przewodnika zwrotu pojazdu lub innych ustaleń ze Zleceniodawcą. Tym samym Ocena/Raport może nie ujmować typowych zużyć i uszkodzeń eksploatacyjnych.

PHOTOGRAPHIC DOCUMENTATION



Photo 1.
Przekątna przednia lewa



Photo 2.
Przód

PHOTOGRAPHIC DOCUMENTATION



Photo 3.

Przekątna przednia prawa



Photo 4.

Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 5.
Bok prawy z tyłu



Photo 6.
Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 7.
Tyl



Photo 8.
Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 9.
Bok lewy z tyłu



Photo 10.
Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 11.
Próg lewy (widok od przodu)



Photo 12.
Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



Photo 13.
Spód pojazdu przód



Photo 14.
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION




Photo 15.
Tarcza hamulcowa przednia prawa




Photo 16.
Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 17.

Tarcza hamulcowa tylna lewa




Photo 18.

Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 19.
Bagażnik



Photo 20.
Koło zapasowe

PHOTOGRAPHIC DOCUMENTATION



Photo 21.
Komora silnika



Photo 22.
Numer identyfikacyjny

PHOTOGRAPHIC DOCUMENTATION



Photo 23.
Tabliczka znamionowa



Photo 24.
Zestaw wskaźników - przebieg

PHOTOGRAPHIC DOCUMENTATION



Photo 25.

Widok przez otwarte drzwi przednie lewe



Photo 26.

Kierownica z lewej strony

PHOTOGRAPHIC DOCUMENTATION



Photo 27.

Widok przez otwarte drzwi tylne lewe




Photo 28.

Widok z tylnej kanapy na deskę rozdz.

PHOTOGRAPHIC DOCUMENTATION



Photo 29.
Konsola środkowa




Photo 30.
Tunel środkowy

PHOTOGRAPHIC DOCUMENTATION



Photo 31.
Kierownica (na wprost)



Photo 32.
Dowód rej. Str. 1

PHOTOGRAPHIC DOCUMENTATION



Photo 33.
Dow. Rej. Str.2 i klucze




Photo 34.
Książka serwisowa – dane

PHOTOGRAPHIC DOCUMENTATION




Photo 35.
Książka serwisowa – ostatni przegląd




Photo 36.
Instrukcje

PHOTOGRAPHIC DOCUMENTATION



Photo 37.
Zestaw naprawczy koła



Photo 38.
Pokrywa komory silnika - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 39.
Szyba czołowa - Pęknięcie/rozerwanie 1



Photo 40.
Szyba czołowa - Pęknięcie/rozerwanie 2

PHOTOGRAPHIC DOCUMENTATION



Photo 41.
Zderzak - Rysa/odprysk 1



Photo 42.
Zderzak - Rysa/odprysk 2

PHOTOGRAPHIC DOCUMENTATION



Photo 43.
Zderzak tylny - Rysa/odprysk 1



Photo 44.
Zderzak tylny - Rysa/odprysk 2

PHOTOGRAPHIC DOCUMENTATION



Photo 45.
Zderzak tylny - Wgniecenie/odkształcenie 1



Photo 46.
Dach - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 47.
Stupek przedni L - Inne 1



Photo 48.
Fotel prz. praw. - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 49.

Uchwyt drzwi prze P - Rysa/odprysk 1