

DEKRA's commission No. : PKOL(W)/LODZ/19354/25/03/17
commission/ damage No. : Futura
Date of commission: 17-03-2025

DEKRA Poland - Headquarters
02-673 Warszawa, ul. Konstruktorska 12A

Client :

PKO Leasing SA
Świętokrzyska 36
00-116 Warszawa

Expert:

Kacper Sosnowski (NEW)
DEKRA Polska - współpraca O/Warszawa
Paweł Szwabowicz
DEKRA Polska - O. Lubin

NOTE:

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

Vehicle data

Group of objects (Eurotax)	cars
EC code (Eurotax)	0145020
Manufacturer	AUDI
Model	A8 [4N] 17-21
Type / version	A8 L 60 TFSI mHEV Quattro Tiptr.
Body type	sedan
Number of doors / seats	4/5
Curb weight [kg]	2199
Gross vehicle weight [kg]	2820
Wheelbase 1/2	3128
Engine type	spark ignition
Supercompression	turbocompressor with intercooler
Pollution reduction system	three-way catalytic converter
Emission standard	EURO 6
Engine capacity [ccm]	3996
Engine Power [hp/kW]	460/338
Gearbox	automatic 8- gear
Registration /record No.	WD2933P
VIN / serial number	WAUZZZF80MN014310
Date of first registration	23-02-2021
Date of next. tech. test	23-02-2026
Year of manufacture	2021 (year has been verified with the manufacturer's base)
Readout [km]	110 113 (read)
Body color / type of coating	black/2-warstwowy metalik

Tyres

axle	Wheel	Manufacturer, type	Size	Measured profile
Front	right	MICHELIN, PILOT ALPIN 5	235/50 19 103H	4,0 mm
	left	MICHELIN, PILOT ALPIN 5	235/50 19 103H	4,0 mm
back	right	MICHELIN, PILOT ALPIN 5	235/50 19 103H	5,5 mm
	left	MICHELIN, PILOT ALPIN 5	235/50 19 103H	5,5 mm

Standard equipment by Eurotax

- | | |
|---|--|
| 1. 3 places rear bench | 27. LED Daytime running lights |
| 2. Additional gauges, On board computer | 28. LED front dim light |
| 3. Alarm | 29. LED rear lights |
| 4. Antilock-Brake-System (ABS) | 30. Leather gearshifter/switch |
| 5. Armrest (s) front, Storage facilities in general | 31. Leather steering wheel, Multi functional steering wheel |
| 6. Automatic air recirculation control | 32. Leather upholstery |
| 7. Bluetooth interface | 33. Lumbar adjust driver electric, Lumbar adjust passenger electric |
| 8. Bord communication: other | 34. Navigation system |
| 9. Child seat fixation | 35. Other |
| 10. Colored glass | 36. Other |
| 11. Colour stripe in windscreen, Windows: other | 37. Other |
| 12. Comfort driver seat, Comfort passenger seat, Driver seat electrically adjustable, Electrically adjustable rear seats, Memory seat, Passenger seat electrically adjustable | 38. Other |
| 13. Cruise control | 39. Other |
| 14. Diminished spare wheel | 40. Pakiet przeglądów serwisowych Audi 3 lata/90 000 km (Audi Perfect Lease) |
| 15. Door mirror with memory, Door mirror(s) electrically adjustable in general, Door mirrors electrically foldable, Door mirrors heated | 41. Park Distance Control front, Park Distance Control rear |
| 16. Driver airbag, Head airbags front, Passenger airbag, Side airbag driver, Side airbag driver and passenger, Side airbags rear | 42. Passive Tyre pressure control |
| 17. Dualzone automatic climate control | 43. Pre-Crash System |
| 18. Electric tailgate | 44. Rear headrests |
| 19. Exterior design: other | 45. Remote controlled central locking |
| 20. Floor mat | 46. Servotronic |
| 21. Headlamp wash | 47. Soundsystem |
| 22. Heated seat driver, Heated seat passenger, Rear seat heating | 48. Storage facilities in general |
| 23. Hydro pneumatic suspension | 49. Sunblind rear side door electric, Sunblind tailgate window electric |
| 24. Interior decoration: other | 50. Vehicle immobilizer |
| 25. Interior decoration: other | 51. Wheel bolt locks |
| 26. Interior lights: other accessories | |

Dealer's equipment (selected items)

- | | |
|---|---|
| 1. 4 or more zone automatic climate control | - |
| 2. Bord communication: other | - |
| 3. Door mirrors autodimming | - |
| 4. Exterior design: other | - |
| Listwa w przednim zderzaku w chromowana | |
| Klamki zewnętrzne chromowane | |
| Zderzak tylny z akcentami chromowanymi | |
| 5. Glass sunroof fixed | - |
| 6. Hands-free system | - |
| 7. Hatch/skibag in rear bench | - |
| 8. Interior decoration: other, Interior: other | - |
| Konsola środkowa w skórze Feinnappa ze szwem ozdobnym | |
| Podszybie w drzwiach w skórze Feinnappa ze szwem ozdobnym | |
| Obszycie poduszki powietrznej kierowcy w skórze Feinnappa ze szwem ozdobnym | |
| Podłokietniki w drzwiach w skórze Feinnappa | |
| Górna część deski rozdzielczej pokryta skórą Feinnappa ze szwem ozdobnym | |
| 9. Interior lights: other accessories | - |

10. Intersection Assist, Lane control assistant, Other, Pre-Crash System, Rear Cross Traffic Alert	-
Audi side assist z Audi pre sense rear, ostrzeż. przy wysiadaniu i asyst. ruchu poprzecznego z tyłu	
Asystent zapobiegania kolizjom na skrzyżowaniu	
11. Leather steering wheel, Multi functional steering wheel, Steering wheel with gear-switches	-
12. Light Alloy wheels 19"	-
13. Metallic paint	-
14. Other	-
15. Other	-
16. Other	-
17. Rear headrests	-
18. Rear view camera	-
19. Soundsystem	-
20. Soundsystem	-
21. Traffic sign recognition	-
22. Tyre pressure control (RDC)	-
23. Ventilated front seat	-
24. Windows: other	-
25. Zaciski hamulców w kolorze czarnym	-

Base value of the vehicle

Base value of the vehicle by Eurotax (net)

Corrections

First registration

Mileage

Equipment

Other

State of the vehicle	-
Braki i uszkodzenia	-
Aktywne kontrolki/sprawdzenie w serwisie	-
Aktualna sytuacja rynkowa/urealnienie wartości	-


Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 03-2025 POL) with regard to technical and market parameters affecting the value of the vehicle.

Basic print without information about the vehicle's value - due to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 26-03-2025

DEKRA's expert:
Kacper Sosnowski (NEW)
Paweł Szwabowicz

Document issued electronically valid without signature.

Measurement of thickness of the vehicle lacquer coating


No. of controlled item	Controlled item	Measured range of thickness of the lacquer coat [μm]
1	Front cover	to 150
2	Front left fender	to 150
3	Left front pillar	to 150
4	Front left door	to 150
6	Left middle pillar	to 150
7	Right side sill	to 150
8	Left rear door	to 150
9	Rear left fender	to 150
10	Cover/lid	to 150
11	Right rear fender	to 150
12	Right rear door	to 150
13	Right middle pillar	to 150
14	Right side sill	to 150
15	Front right door	to 150
16	Right front pillar	to 150
17	Front right fender	to 150

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

During the inspection the registration proof of the vehicle was presented and its photo was taken and enclosed to the expertise.

During the inspection the service book of the vehicle was not provided.

Information concerning the origin of the vehicle

The vehicle purchased domestically from an authorized representative of the brand.

Anti-theft protection - immobilizer

- as a result of the inspection of the vehicle found no malfunctions of the immobilizer in the extent possible to determine during the inspection of the vehicle in the non- workshop conditions.

Anti-theft protection - other:

alarm

Additional comments on the car:

Not applicable.

Test drive

Test drive of the vehicle was conducted. Test drive in the full extent is not possible. Comment below:
Warunki parkingowe

Checking of the correctness and / or construction of identification / serial numbers of the object:

Not tested

Verification of the accuracy of the object data, including year of production, and other.

Not conducted - adopted according to the documents presented and indicated sources.

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.
- The evaluation has been carried out basing on delivered documentation and organoleptic examination of the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the

page 6/35

assessed object.

- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

Comments to the commission - regarding valuation

Kluczyki

TAK

2

Expert comments - regarding valuation

Rysy na samochodzie. Nieprawny akumulator. Aktywna kontrolka silnika. Odpryski na szybie czołowej.

Restrictive disclaimer - regarding valuation

- W Ocenie/Raporcie uwzględniono niesprawności, uszkodzenia, braki itp., które były możliwe do stwierdzenia organoleptycznego, w warunkach oględzin (z uwzględnieniem: stanu czystości pojazdu, warunków atmosferycznych, oświetlenia itd.) oraz bez weryfikacji serwisowej, bez dostępu do spodu pojazdu, bez specjalistycznego sprzętu diagnostycznego (w tym bez diagnostyki komputerowej), bez jazdy próbnej wykonanej w warunkach drogowych z obciążeniem.
- W ramach Oceny/Raportu nie weryfikowano odczytanego stanu drogomierza z zapisami w urządzeniach elektronicznych pojazdu.
- Rzeczoznawca nie bierze na siebie odpowiedzialności za wady ukryte (prawne i fizyczne) oraz ewentualne skutki wynikające z dalszego użytkowania przedmiotu oceny, a także za skutki wykorzystania samej oceny.
- Podane przedziały grubości powłoki lakierowej, dotyczą punktów pomiarowych. Nie mogą być traktowane jako gwarancja, że grubość powłoki lakierowej w innych punktach nie wykracza poza te przedziały.
- Zawarte w niniejszej Ocenie/Raporcie informacje (w tym dotyczące wyposażenia) służą jedynie ogólnym celom informacyjnym. Ocena/Raport nie może być zatem traktowana jako oferta w rozumieniu przepisów Kodeksu Cywilnego oraz opisu towaru ani zapewnienia w rozumieniu art. 4 Ustawy z dnia 27 lipca 2002 roku o szczególnych warunkach sprzedaży konsumenckiej.
- Niniejsza Ocena/Raport nie jest szczegółową oceną stanu technicznego.

Ocenę/Raport wykonano w kierunku ujawnienia uszkodzeń nieakceptowanych z punktu widzenia właściwego przewodnika zwrotu pojazdu lub innych ustaleń ze Zleceniodawcą. Tym samym Ocena/Raport może nie ujmować typowych zużyć i uszkodzeń eksploatacyjnych.

PHOTOGRAPHIC DOCUMENTATION



Photo 1.
Przekątna przednia lewa



Photo 2.
Przód

PHOTOGRAPHIC DOCUMENTATION



Photo 3.

Przekątna przednia prawa



Photo 4.

Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 5.
Bok prawy z tyłu



Photo 6.
Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 7.

Tył



Photo 8.

Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION




Photo 9.

Bok lewy z tyłu




Photo 10.

Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 11.

Próg lewy (widok od przodu)



Photo 12.

Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



Photo 13.
Spód pojazdu przód



Photo 14.
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION



Photo 15.

Tarcza hamulcowa przednia prawa




Photo 16.

Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 17.

Tarcza hamulcowa tylna lewa



Photo 18.

Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 19.
Bagażnik



Photo 20.
Koło zapasowe

PHOTOGRAPHIC DOCUMENTATION



Photo 21.
Komora silnika



Photo 22.
Numer identyfikacyjny

PHOTOGRAPHIC DOCUMENTATION




Photo 23.
Tabliczka znamionowa



Photo 24.
Zestaw wskaźników - przebieg

PHOTOGRAPHIC DOCUMENTATION



Photo 25.

Widok przez otwarte drzwi przednie lewe



Photo 26.

Kierownica z lewej strony

PHOTOGRAPHIC DOCUMENTATION



Photo 27.

Widok przez otwarte drzwi tylne lewe



Photo 28.

Widok z tylnej kanapy na deskę rozd.

PHOTOGRAPHIC DOCUMENTATION



Photo 29.

Konsola środkowa



Photo 30.

Tunel środkowy

PHOTOGRAPHIC DOCUMENTATION**Photo 31.**


Kierownica (na wprost)

**Photo 32.**

Dowód rej. Str. 1

PHOTOGRAPHIC DOCUMENTATION**Photo 33.**

Dow. Rej. Str.2 i klucze

**Photo 34.**

Książka serwisowa – dane

PHOTOGRAPHIC DOCUMENTATION



Photo 35.

Książka serwisowa – ostatni przegląd




Photo 36.

Instrukcje

PHOTOGRAPHIC DOCUMENTATION



Photo 37.
Zdjęcie do protokołu




Photo 38.
Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 39.

Zdjęcie do protokołu



Photo 40.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 41.

Zdjęcie do protokołu



Photo 42.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION




Photo 43.

Pokrywa komory silnika - Rysa/odprysk 1



Photo 44.

Zderzak - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 45.

Drzwi tylne P - Rysa/odprysk 1



Photo 46.

Lusterko zew P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION




Photo 47.

Pokrywy bagażnika - Rysa/odprysk 1



Photo 48.

Zderzak tylny - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION




Photo 49.

Zderzak tylny - Rysa/odprysk 2



Photo 50.

Zderzak tylny() - Rysa/odprysk 3

PHOTOGRAPHIC DOCUMENTATION




Photo 51.

Drzwi przed L - Rysa/odprysk 1



Photo 52.

Drzwi przed L - Rysa/odprysk 2

PHOTOGRAPHIC DOCUMENTATION



Photo 53.

Drzwi tylne L - Rysa/odprysk 1



Photo 54.

Lusterko zew L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 55.

Konsola tunelu śr. - Rysa/odprysk 1



Photo 56.

Kanapa tyl. - Inne 1