

DEKRA's commission No. : PKOL(W)/LODZ/03290/26/01/15
commission/ damage No. : 21/026055
Date of commission: 15-01-2026

DEKRA Poland - Headquarters
02-673 Warszawa, ul. Konstruktorska 12A

Client :

PKO Leasing SA
Świętokrzyska 36
00-116 Warszawa

Expert:

Kacper Sosnowski (NEW)
DEKRA Polska - współpraca O/Warszawa
Andrzej Sosnowski
DEKRA Polska - Centrala

NOTE:

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

Vehicle data

Group of objects (Eurotax)	jeeps
EC code (Eurotax)	0139133
Manufacturer	BMW
Model	X5 [G05] 18-23
Type / version	X5 xDrive45e sport-aut
Body type	KOM
Number of doors / seats	5/5
Curb weight [kg]	2435
Gross vehicle weight [kg]	3150
Wheelbase 1/2	2975
Engine type	spark ignition
Pollution reduction system	GPF
Engine capacity [ccm]	2998
Engine Power [hp/kW]	286/210
Gearbox	automatic
Registration /record No.	FZ3633P
VIN / serial number	WBATA610009F62049
Date of first registration	18-02-2021
Date of next. tech. test	18-02-2026
Year of manufacture	2021
Readout [km]	206 459 (read)
Body color / type of coating	grafitowy/double-layered, metallized

Tyres

axle	Wheel	Manufacturer, type	Size	Measured profile
Front	right	HANKOOK, VENTUS S1 EVO3 SUV	275/45 20 110Y	3,5 mm
	left	HANKOOK, VENTUS S1 EVO3 SUV	275/45 20 110Y	3,5 mm
back	right	HANKOOK, VENTUS S1 EVO3 SUV	305/40 20 112Y	3,0 mm
	left	HANKOOK, VENTUS S1 EVO3 SUV	305/40 20 112Y	3,5 mm

Standard equipment by Eurotax

- | | |
|---|---|
| 1. Active speed sign recognition, Collision Warning System, Distance control, Lane control assistant | 35. Interior lights: other accessories |
| 2. Alarm | 36. LED Fog Lamps |
| 3. Android Auto, Apple CarPlay | 37. LED front dim light, LED rear lights |
| 4. Antilock-Brake-System (ABS) | 38. Leather steering wheel |
| 5. Armrest (s) front, Armrest (s) rear | 39. Light Alloy wheels 19" |
| 6. Artificial leather upholstery | 40. Luggage:other |
| 7. Automatic Emergency Call | 41. Mirror: others |
| 8. Automatic Emergency Call | 42. Mobile Tire System |
| 9. Automatic climate control | 43. Multi functional steering wheel |
| 10. Automatic dimlight activation, Rain sensor | 44. Other |
| 11. Bluetooth interface, Bord entertainment: other accessories, Navigation system, On board monitor, Touchscreen monitor | 45. Other |
| 12. Bord climate: other | 46. Other |
| 13. Bord entertainment: other accessories | 47. Other |
| 14. Bord entertainment: other accessories | 48. Other |
| 15. Child seat fixation | 49. Other |
| 16. Cruise control, Distance control | 50. Other |
| 17. DAB radio | 51. Other |
| 18. Driver airbag, Driver knee airbag, Head airbags front, Head airbags rear, Passenger airbag, Side airbag driver and passenger, Side airbags rear | 52. Park Assistant |
| 19. Driver seat electrically adjustable, Memory seat, Passenger seat electrically adjustable | 53. Park Distance Control front, Park Distance Control rear |
| 20. Driver-information-system | 54. Rear seat-backs foldable in two separate parts |
| 21. ESP (Electronical Stabilizing Program), Traction control | 55. Rear view camera |
| 22. Electric parking brake | 56. Remote controlled central locking |
| 23. Electric tailgate | 57. Roof railing |
| 24. Enhanced suspension | 58. Selectable driveline characteristics |
| 25. Exterior design: other | 59. Servotronic |
| 26. Exterior design: other | 60. Soundsystem |
| 27. Exterior design: other | 61. Sport seats front |
| 28. Extra power outlet, USB in | 62. Sports steering wheel |
| 29. Floor mat | 63. Start/Stop system |
| 30. Follow me home | 64. Steering wheel electrically adjustable |
| 31. Follow me home | 65. Uni-Lackierung |
| 32. Headlamp wash nozzle heated | 66. Vehicle charging cable |
| 33. Hill descent control | 67. Wheel bolt locks |
| 34. Interior decoration: other | |

Dealer's equipment (selected items)

- | | |
|--|---|
| 1. Accoustic windows | - |
| 2. Adaptive Cruise Control, Distance control | - |
| 3. Aerodynamics package, Exterior design: other | - |
| 4. Armrest (s) front, Heated seat driver, Heated seat passenger, Steering wheel heated | - |
| Fotele przednie ogrzewane | |
| Podłokietniki przednie ogrzewane | |
| Kierownica ogrzewana | |
| 5. Automated High-beam assist | - |
| 6. Blind spot warning, Collision Warning System, Other | - |
| Asystent martwego pola | |
| Ostrzeganie przed kolizją z tyłu | |
| System ostrzegający przed ruchem poprzecznym z tyłu | |

7. Bluetooth interface, Mobile phone, Wireless device charging	-
8. Bord entertainment: other accessories, Soundsystem	-
9. Comfort driver seat, Comfort passenger seat, Driver seat electrically adjustable, Memory seat, Passenger seat electrically adjustable	-
10. Cornering Headlights, LED front dim light	-
11. Exterior design: other	-
12. Exterior design: other	-
13. Interior: other	-
14. Leather upholstery	-
15. Light Alloy wheels 20'', Runflat tyres	-
16. Metallic paint	-
17. Other	-
18. Roof railing	-
19. Sports steering wheel	-
20. Steering: other	-
21. Tinted rear windows	-

Base value of the vehicle

Base value of the vehicle by Eurotax (net) -

Corrections

First registration

Mileage

Equipment

Tyres

Other

Earlier repairs -
Braki, uszkodzenia, stan. -


Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 02-2026 POL) with regard to technical and market parameters affecting the value of the vehicle.

Basic print without information about the vehicle's value - duey to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 02-02-2026

DEKRA's expert:
Kacper Sosnowski (NEW)
Andrzej Sosnowski

Document issued electronically valid without signature.

Measurement of thickness of the vehicle lacquer coating


No. of controlled item	Controlled item	Measured range of thickness of the lacquer coat [μm]
1	Front cover	to 150
2	Left front fender	to 150
3	Left front pillar	to 150
4	Left front wall	to 150
5	Roof	to 150
6	Left middle pillar	to 150
7	Left side sill	to 150
8	Left rear wall	to 150
9	Left side wall	to 150
10	Cover/tailgate	150 - 1000
11	Side right wall	to 150
12	Rear right door	to 150
13	Middle right pillar	to 150
14	Front right door	to 150
15	Right side sill	to 150
16	Right front pillar	to 150
17	Right front fender	to 150

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

Presented the following documents of the vehicle:

ksero pozwolenia czasowego

During the inspection the service book was presented and its number is given below:
elektroniczna

Information concerning the origin of the vehicle

Lack of reliable data.

Additional comments on the car:

Not applicable.

Test drive

Test drive of the vehicle was conducted. Test drive in the full extent is not possible. Comment below:
ograniczenia placowe

Checking of the correctness and / or construction of identification / serial numbers of the object:

Not tested

Verification of the accuracy of the object data, including year of production, and other.

Not conducted - adopted according to the documents presented and indicated sources.

Anti-theft protection

fabryczne

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.
- The evaluation has been carried out basing on delivered documentation and organoleptic examination of the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the assessed object.
- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

Comments to the commission - regarding valuation**Kluczyki**

TAK

1

Expert comments - regarding valuation

Dostarczono ksero pozwolenia czasowego. Rysy na samochodzie. Odpryski na szybie czołowej. Widoczne wady lakiernicze.

Rzeczoznawca dokonał oględzin pojazdu w warunkach parkingowych, co mogło ograniczyć pełną ocenę jego stanu technicznego. Dodatkowo, jeżeli jazda próbna została przeprowadzona (informacje w treści raportu), to wykonano ją w warunkach parkingowych, z niewielką prędkością, co może nie odzwierciedlać pełnych warunków eksploatacyjnych. Istnieje możliwość, że w innych okolicznościach ujawnią się dodatkowe uszkodzenia lub usterki, których nie można było wykryć podczas obecnych oględzin. Zalecamy zatem skorzystanie z możliwości oględzin pojazdu we własnym zakresie lub w Autoryzowanej Stacji Obsługi danej marki, co pozwoli na pełniejszą weryfikację stanu technicznego pojazdu przed udziałem w aukcji."

Restrictive disclaimer - regarding valuation

Nie weryfikowano szczegółowo stanu układu napędowego, zawieszenia, kierowniczego, hamulcowego oraz wydechowego. Ocena została wykonana bez użycia podnośnika i specjalistycznego sprzętu diagnostycznego, nie dokonywano demontażu osłon i innych elementów. Ocena określa ogólny stan pojazdu na dzień oględzin w miejscu jego udostępnienia, nie może być zatem traktowana jako kompleksowa ocena stanu technicznego. Specyfikacja wg. programu operacyjnego w zakresie wyposażenia standardowego i dodatkowego nie gwarantuje zgodności ze stanem faktycznym w zakresie możliwym do ustalenia przez rzeczoznawcę podczas oględzin pojazdu.

Pomiar grubości powłoki lakierowej wykonano w miejscach możliwych do ich wykonania pomiary nie gwarantują oryginalności poszczególnych elementów poddanych ocenie.

- W Ocenie/Raporcie uwzględniono niesprawności, uszkodzenia, braki itp., które były możliwe do stwierdzenia organoleptycznego, w warunkach oględzin (z uwzględnieniem: stanu czystości pojazdu, warunków atmosferycznych, oświetlenia itd.) oraz bez weryfikacji serwisowej, bez dostępu do spodu pojazdu, bez specjalistycznego sprzętu diagnostycznego (w tym bez diagnostyki komputerowej), bez jazdy próbnej wykonanej w warunkach drogowych z obciążeniem.
- W ramach Oceny/Raportu nie weryfikowano odczytanego stanu drogomierza z zapisami w urządzeniach elektronicznych pojazdu.
- Rzeczoznawca nie bierze na siebie odpowiedzialności za wady ukryte (prawne i fizyczne) oraz ewentualne skutki wynikające z dalszego użytkowania przedmiotu oceny, a także za skutki wykorzystania samej oceny.
- Podane przedziały grubości powłoki lakierowej, dotyczą punktów pomiarowych. Nie mogą być traktowane jako gwarancja, że grubość powłoki lakierowej w innych punktach nie wykracza poza te przedziały.
- Zawarte w niniejszej Ocenie/Raporcie informacje (w tym dotyczące wyposażenia) służą jedynie ogólnym celom informacyjnym. Ocena/Raport nie może być zatem traktowana jako oferta w rozumieniu przepisów Kodeksu Cywilnego oraz opisu towaru ani zapewnienia w rozumieniu art. 4 Ustawy z dnia 27 lipca 2002 roku o szczególnych warunkach sprzedaży konsumenckiej.
- Niniejsza Ocena/Raport nie jest szczegółową oceną stanu technicznego.

Ocenę/Raport wykonano w kierunku ujawnienia uszkodzeń nieakceptowanych z punktu widzenia właściwego przewodnika zwrotu pojazdu lub innych ustaleń ze Zleceniodawcą. Tym samym Ocena/Raport może nie ujmować typowych zużyć i uszkodzeń eksploatacyjnych.

PHOTOGRAPHIC DOCUMENTATION



Photo 1.

Przekątna przednia lewa



Photo 2.

Przód

PHOTOGRAPHIC DOCUMENTATION



Photo 3.

Przekątna przednia prawa



Photo 4.

Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 5.
Bok prawy z tyłu



Photo 6.
Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 7.

Tył



Photo 8.

Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 9.

Bok lewy z tyłu



Photo 10.

Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 11.

Próg lewy (widok od przodu)




Photo 12.

Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



Photo 13.
Spód pojazdu przód



Photo 14.
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION



Photo 15.

Tarcza hamulcowa przednia prawa



Photo 16.

Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 17.

Tarcza hamulcowa tylna lewa



Photo 18.

Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 19.
Bagażnik



Photo 20.
Koło zapasowe

PHOTOGRAPHIC DOCUMENTATION



Photo 21.
Komora silnika



Photo 22.
Numer identyfikacyjny

PHOTOGRAPHIC DOCUMENTATION



Photo 23.

Tabliczka znamionowa



Photo 24.

Zestaw wskaźników - przebieg

PHOTOGRAPHIC DOCUMENTATION



Photo 25.

Widok przez otwarte drzwi przednie lewe



Photo 26.

Kierownica z lewej strony

PHOTOGRAPHIC DOCUMENTATION



Photo 27.

Widok przez otwarte drzwi tylne lewe



Photo 28.

Widok z tylnej kanapy na deskę rozdz.

PHOTOGRAPHIC DOCUMENTATION



Photo 29.
Konsola środkowa



Photo 30.
Tunel środkowy

PHOTOGRAPHIC DOCUMENTATION



Photo 31.
Kierownica (na wprost)




Photo 32.
Książka serwisowa – dane

PHOTOGRAPHIC DOCUMENTATION




Photo 33.

Książka serwisowa – ostatni przegląd




Photo 34.

Przewód ładowania baterii trakcyjnej

PHOTOGRAPHIC DOCUMENTATION**Photo 35.**

Dow. rej. ksero Str. 1

**Photo 36.**

Dow. Rej. ksero Str.2 i klucze

PHOTOGRAPHIC DOCUMENTATION



Photo 37.

Zdjęcie do protokołu



Photo 38.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 39.

Zdjęcie do protokołu



Photo 40.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 41.

Pokrywa komory silnika - Rysa/odprysk 1



Photo 42.

Zderzak - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 43.

Felga aluminiowa przednia P - Rysa/odprysk 1



Photo 44.

Drzwi przednie P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 45.

Drzwi tylne P - Rysa/odprysk 1



Photo 46.

Drzwi tylne P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 47.

Błotnik tylny P / Ściana boczna P - Rysa/odprysk 1



Photo 48.

Błotnik tylny P / Ściana boczna P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 49.

Pokrywy bagażnika - zdjęcie poglądowe 1



Photo 50.

Pokrywy bagażnika - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 51.

Pokrywy bagażnika - Inne 1




Photo 52.

Dach - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 53.

Błotnik tylny L / Ściana boczna L - Rysa/odprysk 1




Photo 54.

Błotnik tylny L / Ściana boczna L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 55.

Lampa tylna zew L - Rysa/odprysk 1



Photo 56.

Lampa tylna zew L - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 57.

Drzwi przed L - Rysa/odprysk 1



Photo 58.

Drzwi przed L - Rysa/odprysk 2

PHOTOGRAPHIC DOCUMENTATION



Photo 59.

Drzwi przed L - Wgniecenie/odkształcenie 1



Photo 60.

Próg L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 61.

Konsola tunelu śr. - Rysa/odprysk 1



Photo 62.

Podłokietnik środkowy przedni - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 63.

Tapicerka drzwi przednich L - zdjęcie poglądowe 1



Photo 64.

Tapicerka drzwi przednich L - Pęknięcie/rozerwanie 1