

DEKRA's commission No. : PKOL(W)/LODZ/56134/24/07/23
commission/ damage No. : 23/012365
Date of commission: 23-07-2024

DEKRA Poland - Headquarters
02-673 Warszawa, ul. Konstruktorska 12A

Client :
PKO Leasing Finance
PKO Leasing SA
Al. Śmigłego-Rydza 20
93-281 Łódź

Expert:
Marcin Sosnowski.
DEKRA Polska - Centrala

NOTE:

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

Vehicle data

Group of objects (Eurotax)	jeeps
EC code (Eurotax)	0139130
Manufacturer	BMW
Model	X5 [G05] 18-23
Type / version	X5 xDrive25d sport-aut
Body type	KOM
Number of doors / seats	5/5
Curb weight [kg]	2070
Gross vehicle weight [kg]	2820
Wheelbase 1/2	2975
Engine type	Automatic ignition
Pollution reduction system	KSC
Engine capacity [ccm]	1995
Engine Power [hp/kW]	231/170
Gearbox	automatic
Registration /record No.	CT0666X
VIN / serial number	WBACV410909F81675
Date of first registration	05-03-2021
Date of next. tech. test	05-03-2024
Year of manufacture	2021 (year has been verified with the manufacturer's base)
Readout [km]	95 943 (read)
Body color / type of coating	white/UNI

Tyres

axle	Wheel	Manufacturer, type	Size	Measured profile
Front	right	PIRELLI, SCORPION WINTER	275/45 20 110V	5,0 mm
	left	PIRELLI, SCORPION WINTER	275/45 20 110V	5,0 mm
back	right	PIRELLI, SCORPION WINTER	305/40 20 112V	4,0 mm
	left	PIRELLI, SCORPION WINTER	305/40 20 112V	4,0 mm

Standard equipment by Eurotax

- | | |
|---|---|
| 1. Active speed sign recognition, Collision Warning System, Distance control, Lane control assistant | 32. Interior decoration: other |
| 2. Alarm | 33. Interior lights: other accessories |
| 3. Android Auto, Apple CarPlay | 34. LED Fog Lamps |
| 4. Antilock-Brake-System (ABS) | 35. LED front dim light, LED rear lights |
| 5. Armrest (s) front, Armrest (s) rear | 36. Leather steering wheel |
| 6. Artificial leather upholstery | 37. Light Alloy wheels 18" |
| 7. Automatic Emergency Call | 38. Luggage:other |
| 8. Automatic Emergency Call | 39. Mirror: others |
| 9. Automatic climate control | 40. Mobile Tire System |
| 10. Automatic dimlight activation, Rain sensor | 41. Multi functional steering wheel |
| 11. Bluetooth interface, Bord entertainment: other accessories, Navigation system, On board monitor, Touchscreen monitor | 42. Other |
| 12. Bord entertainment: other accessories | 43. Other |
| 13. Bord entertainment: other accessories | 44. Other |
| 14. Child seat fixation | 45. Other |
| 15. Cruise control, Distance control | 46. Other |
| 16. DAB radio | 47. Other |
| 17. Driver airbag, Driver knee airbag, Head airbags front, Head airbags rear, Passenger airbag, Side airbag driver and passenger, Side airbags rear | 48. Park Assistant |
| 18. Driver seat electrically adjustable, Memory seat, Passenger seat electrically adjustable | 49. Park Distance Control front, Park Distance Control rear |
| 19. Driver-information-system | 50. Rear seat-backs foldable in two separate parts |
| 20. ESP (Electronical Stabilizing Program), Traction control | 51. Rear view camera |
| 21. Electric parking brake | 52. Remote controlled central locking |
| 22. Electric tailgate | 53. Roof railing |
| 23. Exterior design: other | 54. Selectable driveline characteristics |
| 24. Exterior design: other | 55. Servotronic |
| 25. Exterior design: other | 56. Soundsystem |
| 26. Extra power outlet, USB in | 57. Sport seats front |
| 27. Floor mat | 58. Sports steering wheel |
| 28. Follow me home | 59. Start/Stop system |
| 29. Follow me home | 60. Steering wheel electrically adjustable |
| 30. Headlamp wash nozzle heated | 61. Uni-Lackierung |
| 31. Hill descent control | 62. Wheel bolt locks |

Dealer's equipment (selected items)

- | | |
|--|---|
| 1. 4 or more zone automatic climate control, Air condition rear | - |
| 2. Aerodynamics package, Body levelling, Exterior design: other, Interior: other, Leather finish dashbord, Leather upholstery, Light Alloy wheels 20", Roof railing, Runflat tyres, Sport suspension, Sports steering wheel, Steering: other | - |
| Podsufitka Individual w kolorze antracytowym | |
| Obramowania Shadow Line Individual, wysoki połysk | |
| Kierownica sportowa M | |
| Pakiet aerodynamiczny M | |
| Adaptacyjne zawieszenie M | |
| Relingi dachowe BMW Individual Shadow Line | |
| Tapicerka skórzana Vernasca | |
| Układ hamulcowy sportowy M | |
| Felgi aluminiowe 20", Star-Spoke 740 M Bicolour, z ogumieniem mieszanym Runflat | |
| Deska rozdzielcza wykończona skórą syntetyczną Sensatec | |
| 3. Door: other | - |

- 4. Heated seat driver, Heated seat passenger -
- 5. Leather upholstery -
- 6. Light Alloy wheels 20'', Runflat tyres -
- 7. Soundsystem -
- 8. {Światła laserowe BMW} -

Base value of the vehicle

Base value of the vehicle by Eurotax (net) -

Corrections

First registration

Mileage

Equipment

Tyres

Other

- Regularity of service review -
- The validity of the technical examination -
- Braki uszkodzenia, -


Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 07-2024 POL) with regard to technical and market parameters affecting the value of the vehicle.

Basic print without information about the vehicle's value - duey to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 29-07-2024

DEKRA's expert:
Marcin Sosnowski.

Document issued electronically valid without signature.

Measurement of thickness of the vehicle lacquer coating


No. of controlled item	Controlled item	Measured range of thickness of the lacquer coat [μm]
1	Front cover	to 150
2	Left front fender	to 150
3	Left front pillar	to 150
4	Left front wall	to 150
5	Roof	to 150
6	Left middle pillar	to 150
7	Left side sill	to 150
8	Left rear wall	to 150
9	Left side wall	to 150
10	Cover/tailgate	to 150
11	Side right wall	to 150
12	Rear right door	to 150
13	Middle right pillar	to 150
14	Front right door	to 150
15	Right side sill	to 150
16	Right front pillar	to 150
17	Right front fender	to 150

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

Presented the following documents of the vehicle:

ksero pozwolenia czasowego

During the inspection the service book was presented and its number is given below:
elektroniczna

Information concerning the origin of the vehicle

Lack of reliable data.

Additional comments on the car:

Not applicable.

Test drive

Test drive of the vehicle was conducted. Test drive in the full extent is not possible. Comment below:
ograniczenia placowe

Checking of the correctness and / or construction of identification / serial numbers of the object:

Not tested

Verification of the accuracy of the object data, including year of production, and other.

Not conducted - adopted according to the documents presented and indicated sources.

Anti-theft protection

fabryczne

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.
- The evaluation has been carried out basing on delivered documentation and organoleptic examination of the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the assessed object.
- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

Comments to the commission - regarding valuation**Kluczyki**

TAK

1

Expert comments - regarding valuation

Opony Run Flat. Aktywne komunikaty: wymaganego serwisu olejowego, płynu hamulcowego, zbliżający się serwis okładzin hamulcowych. Dostarczono 1 klucz.

Restrictive disclaimer - regarding valuation

Nie weryfikowano szczegółowo stanu układu napędowego, zawieszenia, kierowniczego, hamulcowego oraz wydechowego. Ocena została wykonana bez użycia podnośnika i specjalistycznego sprzętu diagnostycznego, nie dokonywano demontażu osłon i innych elementów. Ocena określa ogólny stan pojazdu na dzień oględzin w miejscu jego udostępnienia, nie może być zatem traktowana jako kompleksowa ocena stanu technicznego. Specyfikacja wg. programu operacyjnego w zakresie wyposażenia standardowego i dodatkowego nie gwarantuje zgodności ze stanem faktycznym w zakresie możliwym do ustalenia przez rzeczoznawcę podczas oględzin pojazdu.

Pomiar grubości powłoki lakierowej wykonano w miejscach możliwych do ich wykonania pomiary nie gwarantują oryginalności poszczególnych elementów poddanych ocenie.

- W Ocenie/Raporcie uwzględniono niesprawności, uszkodzenia, braki itp., które były możliwe do stwierdzenia organoleptycznego, w warunkach oględzin (z uwzględnieniem: stanu czystości pojazdu, warunków atmosferycznych, oświetlenia itd.) oraz bez weryfikacji serwisowej, bez dostępu do spodu pojazdu, bez specjalistycznego sprzętu diagnostycznego (w tym bez diagnostyki komputerowej), bez jazdy próbnej wykonanej w warunkach drogowych z obciążeniem.
- W ramach Oceny/Raportu nie weryfikowano odczytanego stanu drogomierza z zapisami w urządzeniach elektronicznych pojazdu.
- Rzeczoznawca nie bierze na siebie odpowiedzialności za wady ukryte (prawne i fizyczne) oraz ewentualne skutki wynikające z dalszego użytkowania przedmiotu oceny, a także za skutki wykorzystania samej oceny.
- Podane przedziały grubości powłoki lakierowej, dotyczą punktów pomiarowych. Nie mogą być traktowane jako gwarancja, że grubość powłoki lakierowej w innych punktach nie wykracza poza te przedziały.
- Zawarte w niniejszej Ocenie/Raporcie informacje (w tym dotyczące wyposażenia) służą jedynie ogólnym celom informacyjnym. Ocena/Raport nie może być zatem traktowana jako oferta w rozumieniu przepisów Kodeksu Cywilnego oraz opisu towaru ani zapewnienia w rozumieniu art. 4 Ustawy z dnia 27 lipca 2002 roku o szczególnych warunkach sprzedaży konsumenckiej.
- Niniejsza Ocena/Raport nie jest szczegółową oceną stanu technicznego.

Ocenę/Raport wykonano w kierunku ujawnienia uszkodzeń nieakceptowanych z punktu widzenia właściwego przewodnika zwrotu pojazdu lub innych ustaleń ze Zleceniodawcą. Tym samym Ocena/Raport może nie ujmować typowych zużyć i uszkodzeń eksploatacyjnych.

PHOTOGRAPHIC DOCUMENTATION



Photo 1.
Przekątna przednia lewa



Photo 2.
Przód

PHOTOGRAPHIC DOCUMENTATION



Photo 3.

Przekątna przednia prawa



Photo 4.

Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 5.

Bok prawy z tyłu



Photo 6.

Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 7.

Tył



Photo 8.

Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 9.

Bok lewy z tyłu



Photo 10.

Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 11.

Próg lewy (widok od przodu)



Photo 12.

Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



Photo 13.
Spód pojazdu przód



Photo 14.
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION



Photo 15.

Tarcza hamulcowa przednia prawa



Photo 16.

Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 17.

Tarcza hamulcowa tylna lewa



Photo 18.

Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 19.
Bagażnik



Photo 20.
Komora silnika

PHOTOGRAPHIC DOCUMENTATION



Photo 21.
Numer identyfikacyjny



Photo 22.
Tabliczka znamionowa

PHOTOGRAPHIC DOCUMENTATION



Photo 23.

Zestaw wskaźników - przebieg



Photo 24.

Widok przez otwarte drzwi przednie lewe

PHOTOGRAPHIC DOCUMENTATION



Photo 25.

Kierownica z lewej strony



Photo 26.

Widok przez otwarte drzwi tylne lewe

PHOTOGRAPHIC DOCUMENTATION



Photo 27.

Widok z tylnej kanapy na deskę rozd.



Photo 28.

Konsola środkowa


PHOTOGRAPHIC DOCUMENTATION



Photo 29.
Tunel środkowy



Photo 30.
Kierownica (na wprost)

PHOTOGRAPHIC DOCUMENTATION**Photo 31.**

Książka serwisowa – dane

**Photo 32.**

Książka serwisowa – ostatni przegląd

PHOTOGRAPHIC DOCUMENTATION**Photo 33.**

Dow. rej. tym. Str. 1

**Photo 34.**

Dow. Rej. tym. Str.2 i klucze

PHOTOGRAPHIC DOCUMENTATION




Photo 35.

Zdjęcie do protokołu



Photo 36.

Pokrywa komory silnika - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 37.

Pokrywa komory silnika - Rysa/odprysk 2



Photo 38.

Drzwi przednie P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 39.

Drzwi przednie P - Rysa/odprysk 2



Photo 40.

Drzwi tylne P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 41.

Lusterko zew P - Rysa/odprysk 1



Photo 42.

Łotnik tylny L / Ściana boczna L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 43.

Stupek przedni L - Rysa/odprysk 1