

DEKRA's commission No. : PKOL(W)/LODZ/18930/25/03/14
commission/ damage No. : 23/038597
Date of commission: 14-03-2025

DEKRA Poland - Headquarters
02-673 Warszawa, ul. Konstruktorska 12A

Client :

PKO Leasing SA
Świętokrzyska 36
00-116 Warszawa

Expert:

Kacper Sosnowski (NEW)
DEKRA Polska - współpraca O/Warszawa
Paweł Szwabowicz
DEKRA Polska - O. Lubin

NOTE:

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

Vehicle data

Group of objects (Eurotax)	jeeps
EC code (Eurotax)	0137805
Manufacturer	MERCEDES-BENZ
Model	EQC [N 293] 19-
Type / version	EQC 400 4-Matic
Body type	KOM
Number of doors / seats	5/5
Curb weight [kg]	2475
Gross vehicle weight [kg]	2940
Wheelbase 1/2	2873
Engine type	elektryczny
Pollution reduction system	-
Engine capacity [ccm]	0
Engine Power [hp/kW]	408/300
Gearbox	automatic 1- gear
Registration /record No.	EL5GE76
VIN / serial number	W1K2938901F009323
Date of first registration	24-08-2020
Year of manufacture	2020 (year has been verified with the manufacturer's base)
Readout [km]	82 855 (read)
Body color / type of coating	grafitowy/2-warstwowy metalik

Tyres

axle	Wheel	Manufacturer, type	Size	Measured profile
Front	right	DUNLOP, SP WINTER SPORT 4D	235/55 19 101V	4,0 mm
	left	DUNLOP, SP WINTER SPORT 4D	235/55 19 101V	4,0 mm
back	right	BRIDGESTONE, BLIZZAK LM 005	255/50 19 103T	4,0 mm
	left	BRIDGESTONE, BLIZZAK LM 005	255/50 19 103T	4,0 mm

Standard equipment by Eurotax

- | | |
|--|--|
| 1. Accoustic windows, Heat reflecting windows | 24. Keyless go |
| 2. Adaptive light, Automated High-beam assist | 25. Keyless go |
| 3. Alarm | 26. LED front dim light |
| 4. Alarm | 27. Lane control assistant |
| 5. Automatic climate control | 28. Leather steering wheel, Multi functional steering wheel, Sports steering wheel |
| 6. Blind spot warning | 29. Luggage compartment cover |
| 7. Bord entertainment: other accessories | 30. Lumbar adjust driver |
| 8. Bord entertainment: other accessories, Other, Soundsystem | 31. Mobile Tire System |
| 9. Brake Assist | 32. Navigation system |
| 10. Cruise control | 33. On board monitor |
| 11. Diminished spare wheel | 34. Other |
| 12. Door mirrors autodimming, Rear-view mirror autodimming | 35. Other |
| 13. Door mirrors electrically foldable | 36. Other |
| 14. Driver knee airbag | 37. Other |
| 15. Electric tailgate | 38. Other |
| 16. Extra power outlet | 39. Park Assistant, Park Distance Control front, Park Distance Control rear |
| 17. Floor mat | 40. Rain sensor |
| 18. Heat reflecting windows, Tinted rear windows | 41. Rear view camera |
| 19. Interior decoration: other | 42. Selectable driveline characteristics |
| 20. Interior lights: other accessories | 43. Steering wheel with gear-switches |
| 21. Interior: other | 44. Storage facilities in general |
| 22. Interior: other | 45. Tyre pressure control (RDC) |
| 23. Keyless go | 46. USB in |

Dealer's equipment (selected items)

- | | |
|--|---|
| 1. Artificial leather upholstery | - |
| 2. Bluetooth interface, Bord entertainment: other accessories, Glass tilt/slide sunroof electric, Heated seat driver, Heated seat passenger, Soundsystem | - |
| Dach szklany elektrycznie regulowany | |
| System nagłośnienia Burmester surround | |
| System bezprzewodowego ładowania telefonu i połączenie Bluetooth | |
| Pakiet Energizing | |
| 3. Bord climate: other | - |
| 4. Bord communication: other | - |
| Carplay | |
| Android Auto | |
| Apple CarPlay | |
| 5. Bord entertainment: other accessories | - |
| 6. Driver seat electrically adjustable, Memory seat | - |
| 7. Light Alloy wheels 19'' | - |
| 8. Metallic paint | - |
| 9. Rear view camera | - |

Base value of the vehicle

Base value of the vehicle by Eurotax (net)

CorrectionsFirst registrationEquipmentOther

Earlier repairs -
Braki i uszkodzenia -


Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 03-2025 POL) with regard to technical and market parameters affecting the value of the vehicle.

Basic print without information about the vehicle's value - duey to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 20-03-2025

DEKRA's expert:
Kacper Sosnowski (NEW)
Paweł Szwabowicz

Document issued electronically valid without signature.

Measurement of thickness of the vehicle lacquer coating


No. of controlled item	Controlled item	Measured range of thickness of the lacquer coat [μm]
1	Front cover	to 150
2	Left front fender	150 - 300
3	Left front pillar	to 150
4	Left front wall	to 150
5	Roof	to 150
6	Left middle pillar	to 150
7	Left side sill	to 150
8	Left rear wall	to 150
9	Left side wall	to 150
10	Cover/tailgate	to 150
11	Side right wall	to 150
12	Rear right door	to 150
13	Middle right pillar	to 150
14	Front right door	150 - 300
15	Right side sill	to 150
16	Right front pillar	to 150
17	Right front fender	to 150

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

During the inspection the registration proof of the vehicle was presented and its photo was taken and enclosed to the expertise.

During the inspection the service book of the vehicle was not provided.

Information concerning the origin of the vehicle

The vehicle purchased domestically from an authorized representative of the brand.

Additional comments on the car:

Not applicable.

Test drive

Test drive of the vehicle was conducted. Test drive in the full extent is not possible. Comment below:
Warunki parkingowe

Checking of the correctness and / or construction of identification / serial numbers of the object:

Not tested

Verification of the accuracy of the object data, including year of production, and other.

Additional verification of the production year was conducted.

Dealer Mercedes-Benz Polska

Anti-theft protection

Immobiliser

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.
- The evaluation has been carried out basing on delivered documentation and organoleptic examination of the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the assessed object.
- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

Comments to the commission - regarding valuation**Kluczyki**

TAK

1

Expert comments - regarding valuation

Rysy na samochodzie. Dostarczono ksero pozwolenia czasowego. Odpryski na szybie czołowej. Widoczne wady lakiernicze.

Restrictive disclaimer - regarding valuation

- W Ocenie/Raporcie uwzględniono niesprawności, uszkodzenia, braki itp., które były możliwe do stwierdzenia organoleptycznego, w warunkach oględzin (z uwzględnieniem: stanu czystości pojazdu, warunków atmosferycznych, oświetlenia itd.) oraz bez weryfikacji serwisowej, bez dostępu do spodu pojazdu, bez specjalistycznego sprzętu diagnostycznego (w tym bez diagnostyki komputerowej), bez jazdy próbnej wykonanej w warunkach drogowych z obciążeniem.
- W ramach Oceny/Raportu nie weryfikowano odczytanego stanu drogomierza z zapisami w urządzeniach elektronicznych pojazdu.
- Rzeczoznawca nie bierze na siebie odpowiedzialności za wady ukryte (prawne i fizyczne) oraz ewentualne skutki wynikające z dalszego użytkowania przedmiotu oceny, a także za skutki wykorzystania samej oceny.
- Podane przedziały grubości powłoki lakierowej, dotyczą punktów pomiarowych. Nie mogą być traktowane jako gwarancja, że grubość powłoki lakierowej w innych punktach nie wykracza poza te przedziały.
- Zawarte w niniejszej Ocenie/Raporcie informacje (w tym dotyczące wyposażenia) służą jedynie ogólnym celom informacyjnym. Ocena/Raport nie może być zatem traktowana jako oferta w rozumieniu przepisów Kodeksu Cywilnego oraz opisu towaru ani zapewnienia w rozumieniu art. 4 Ustawy z dnia 27 lipca 2002 roku o szczególnych warunkach sprzedaży konsumenckiej.
- Niniejsza Ocena/Raport nie jest szczegółową oceną stanu technicznego.

Ocenę/Raport wykonano w kierunku ujawnienia uszkodzeń nieakceptowanych z punktu widzenia właściwego przewodnika zwrotu pojazdu lub innych ustaleń ze Zleceniodawcą. Tym samym Ocena/Raport może nie ujmować typowych zużyć i uszkodzeń eksploatacyjnych.

PHOTOGRAPHIC DOCUMENTATION



Photo 1.
Przekątna przednia lewa



Photo 2.
Przód

PHOTOGRAPHIC DOCUMENTATION



Photo 3.

Przekątna przednia prawa



Photo 4.

Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 5.
Bok prawy z tyłu



Photo 6.
Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 7.

Tył



Photo 8.

Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 9.

Bok lewy z tyłu



Photo 10.

Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 11.

Próg lewy (widok od przodu)



Photo 12.

Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



Photo 13.
Spód pojazdu przód



Photo 14.
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION



Photo 15.

Tarcza hamulcowa przednia prawa




Photo 16.

Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 17.

Tarcza hamulcowa tylna lewa



Photo 18.

Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 19.
Bagażnik



Photo 20.
Koło zapasowe

PHOTOGRAPHIC DOCUMENTATION



Photo 21.
Komora silnika



Photo 22.
Numer identyfikacyjny

PHOTOGRAPHIC DOCUMENTATION



Photo 23.
Tabliczka znamionowa



Photo 24.
Zestaw wskaźników - przebieg

PHOTOGRAPHIC DOCUMENTATION



Photo 25.

Widok przez otwarte drzwi przednie lewe



Photo 26.

Kierownica z lewej strony

PHOTOGRAPHIC DOCUMENTATION



Photo 27.

Widok przez otwarte drzwi tylne lewe



Photo 28.

Widok z tylnej kanapy na deskę rozd.

PHOTOGRAPHIC DOCUMENTATION



Photo 29.
Konsola środkowa



Photo 30.
Tunel środkowy

PHOTOGRAPHIC DOCUMENTATION



Photo 31.
Kierownica (na wprost)



Photo 32.
Książka serwisowa – dane

PHOTOGRAPHIC DOCUMENTATION




Photo 33.

Książka serwisowa – ostatni przegląd




Photo 34.

Przewód ładowania baterii trakcyjnej

PHOTOGRAPHIC DOCUMENTATION**Photo 35.**

Dow. rej. ksero Str. 1

**Photo 36.**

Dow. Rej. ksero Str.2 i klucze

PHOTOGRAPHIC DOCUMENTATION



Photo 37.

Instrukcje



Photo 38.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 39.

Zdjęcie do protokołu



Photo 40.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 41.

Zdjęcie do protokołu




Photo 42.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 43.

Pokrywa komory silnika - Rysa/odprysk 1



Photo 44.

Felga aluminiowa przednia P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 45.

Drzwi przednie P - Wgniecenie/odkształcenie 1



Photo 46.

Drzwi przednie P - Wgniecenie/odkształcenie 2

PHOTOGRAPHIC DOCUMENTATION



Photo 47.

Drzwi tylne P - Rysa/odprysk 1



Photo 48.

Drzwi tylne P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 49.

Klamka drzwi tyl P - Rysa/odprysk 1



Photo 50.

Słupek przedni P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 51.

Błotnik tylny P / Ściana boczna P - Rysa/odprysk 1




Photo 52.

Błotnik tylny P / Ściana boczna P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 53.

Błotnik tylny P / Ściana boczna P - Wgniecenie/odkształcenie 2



Photo 54.

Felga aluminiowa tylna L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 55.

Felga aluminiowa tylna L - Rysa/odprysk 2



Photo 56.

Drzwi przed L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 57.

Drzwi tylne L - zdjęcie poglądowe 1



Photo 58.

Drzwi tylne L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION




Photo 59.

Drzwi tylne L - Inne 1



Photo 60.

Próg L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 61.
Próg L - Rysa/odprysk 2



Photo 62.
Próg L() - Rysa/odprysk 3

PHOTOGRAPHIC DOCUMENTATION



Photo 63.

Błotnik przedni L - Wgniecenie/odkształcenie 1



Photo 64.

Felga Aluminiowa przednia L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 65.

Koło kierownicy - Inne 1



Photo 66.

Fotel prz. lew. - Pęknięcie/rozerwanie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 67.

Wykładzina podłogi bagażnika - Inne 1