

DEKRA's commission No. : PKOL(W)/LODZ/91452/26/09/30
commission/ damage No. : 23/013596
Date of commission: 30-09-2026

DEKRA Poland - Headquarters
02-673 Warszawa, ul. Konstruktorska 12A

Client :

PKO Leasing SA
Świętokrzyska 36
00-116 Warszawa

Expert:

Kacper Sosnowski (WSP)
DEKRA Polska - współpraca O/Warszawa
inż. Józef Orłowski
TU - Włocławek

NOTE:

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

Vehicle data

Group of objects (Eurotax)	jeeps
EC code (Eurotax)	0151327
Manufacturer	CADILLAC
Model	XT6
Type	Premium Luxury
Body type	KOM
Number of doors / seats	5/6
Curb weight [kg]	2026
Gross vehicle weight [kg]	2722
Wheelbase 1/2	2864
Engine type	spark ignition
Pollution reduction system	GPF
Engine capacity [ccm]	1998
Engine Power [hp/kW]	238/175
Gearbox	automatic
Registration /record No.	SK318XS
VIN / serial number	1GYKP9R40NZ135183
Date of first registration	17-05-2023
Year of manufacture	2022
Readout [km]	113 938 (read)
Body color / type of coating	black/METALIK

Tyres

axle	Wheel	Manufacturer, type	Size	Measured profile
Front	right	BRIDGESTONE, TURANZA 6 ENLITEN	235/55 20 102V	4,0 mm
	left	BRIDGESTONE, TURANZA 6 ENLITEN	235/55 20 102V	4,0 mm
back	right	BRIDGESTONE, TURANZA 6 ENLITEN	235/55 20 102V	4,5 mm
	left	BRIDGESTONE, TURANZA 6 ENLITEN	235/55 20 102V	4,5 mm

Standard equipment by Eurotax

- | | |
|--|---|
| 1. Antilock-Brake-System (ABS) | 15. Park Assistant, Park Distance Control front, Park Distance Control rear, Rear view camera |
| 2. Automatic dimlight activation, Rain sensor | 16. Poduszki powietrzne chroniące głowy osób siedzących z przodu i z tyłu |
| 3. Cruise control, Distance control | 17. Side airbag driver and passenger |
| 4. Door mirror(s) electrically adjustable in general, Door mirrors heated | 18. Uni-Lackierung |
| 5. Driver knee airbag | 19. Vehicle immobilizer |
| 6. Drzwi tylne z mechanicznym zabezpieczeniem przed otwarciem przez dzieci | 20. Felgi aluminiowe 20 cali |
| 7. Kierownica wielofunkcyjna | 21. Dach szklany panoramiczny |
| 8. Klamki w kolorze nadwozia | 22. Head up display |
| 9. LED rear lights | 23. Kamery widzenia bocznego |
| 10. Leather steering wheel, Sports steering wheel | 24. Ogrzewanie tylnych siedzeń |
| 11. On board computer | 25. Podgrzewana kierownica |
| 12. Osłony przeciwsłoneczne | 26. Tapicerka skórzana |
| 13. Other | |
| 14. Other | |

Dealer's equipment (selected items)

1. Metallic paint -

Base value of the vehicle

Base value of the vehicle (net) -

CorrectionsFirst registrationMileageEquipmentTyresOther

stwierdzone braki i uszkodzenia -
brak badania techn. -


Above figure was estimated on the basis of price quotations of used cars on the Polish market taking into account the technical and market parameters affecting the value of the vehicle.

Basic print without information about the vehicle's value - due to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 06-10-2026

DEKRA's expert:
Kacper Sosnowski (WSP)
inż. Józef Orłowski

Document issued electronically valid without signature.

Measurement of thickness of the vehicle lacquer coating


No. of controlled item	Controlled item	Measured range of thickness of the lacquer coat [μm]
1	Front cover	to 150
2	Left front fender	to 150
3	Left front pillar	to 150
4	Left front wall	to 150
5	Roof	to 150
6	Left middle pillar	to 150
7	Left side sill	to 150
8	Left rear wall	to 150
9	Left side wall	to 150
10	Cover/tailgate	to 150
11	Side right wall	to 150
12	Rear right door	to 150
13	Middle right pillar	to 150
14	Front right door	to 150
15	Right side sill	to 150
16	Right front pillar	to 150
17	Right front fender	to 150

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

During the inspection the registration proof of the vehicle was presented and its photo was taken and enclosed to the expertise.

During the inspection the service book was presented and its number is given below:

.

Information concerning the origin of the vehicle

Lack of reliable data.

Additional comments on the car:

Not applicable.

Test drive

Test drive of the vehicle was conducted. Test drive in the full extent is not possible. Comment below: ograniczenia parkingowe

Checking of the correctness and / or construction of identification / serial numbers of the object:

Not tested

Verification of the accuracy of the object data, including year of production, and other.

Additional verification of the production year was conducted.

Car fast

Anti-theft protection

immobilizer

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.
- The evaluation has been carried out basing on delivered documentation and organoleptic examination of the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the assessed object.
- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its

page 5/56

availability location.

Comments to the commission - regarding valuation

Kluczyki

TAK

2

Expert comments - regarding valuation

Rysy na samochodzie. Aktywne kontrolki. Aktywna kontrolka ciśnienia w kołach. Aktywna kontrolka silnika. Informacja system wspomagania hamowania wymaga serwisowania. Układ stabilitrak wymaga serwisowania. Ograniczone działanie układu wspomagania kierowania. Układ oświetlenia AFL wymaga serwisu. Nierówna praca silnika, do weryfikacji serwisowej. Dostarczono ksero pozwolenia czasowego.

PHOTOGRAPHIC DOCUMENTATION



Photo 1.
Przekątna przednia lewa



Photo 2.
Przód

PHOTOGRAPHIC DOCUMENTATION



Photo 3.

Przekątna przednia prawa



Photo 4.

Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 5.
Bok prawy z tyłu



Photo 6.
Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 7.

Tył



Photo 8.

Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 9.

Bok lewy z tyłu



Photo 10.

Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 11.

Próg lewy (widok od przodu)



Photo 12.

Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



Photo 13.
Spód pojazdu przód



Photo 14.
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION



Photo 15.

Tarcza hamulcowa przednia prawa



Photo 16.

Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 17.

Tarcza hamulcowa tylna lewa



Photo 18.

Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 19.
Bagażnik



Photo 20.
Koło zapasowe

PHOTOGRAPHIC DOCUMENTATION



Photo 21.
Komora silnika



Photo 22.
Numer identyfikacyjny

PHOTOGRAPHIC DOCUMENTATION



Photo 23.

Tabliczka znamionowa



Photo 24.

Zestaw wskaźników - przebieg

PHOTOGRAPHIC DOCUMENTATION



Photo 25.

Zestaw wskaźników - serwis



Photo 26.

Widok przez otwarte drzwi przednie lewe

PHOTOGRAPHIC DOCUMENTATION



Photo 27.

Kierownica z lewej strony



Photo 28.

Widok przez otwarte drzwi tylne lewe

PHOTOGRAPHIC DOCUMENTATION



Photo 29.

Widok z tylnej kanapy na deskę rozd.



Photo 30.

Konsola środkowa

PHOTOGRAPHIC DOCUMENTATION



Photo 31.
Tunel środkowy



Photo 32.
Kierownica (na wprost)

PHOTOGRAPHIC DOCUMENTATION

of the service and maintenance work
of completed services and repairs

Y GARAGE APPOINTMENT.
e garage a quick overview of previous
necessary communication with the
submission of fair dealing applications.
hicle in order to ensure easy and quick

OR INSPECTION WORK WILL VARY
may not be appropriate for your vehicle.
(partner about the service and / or
the interval recommendations in this
ential available warranty coverage
service booklet does not replace the
cturer's recommended timeframe/
thout guarantee, excluding all liability
requirements.

VEHICLE INFORMATION

Manufacturer / Make: CADILLAC
Type / Model: XT6
Model - Finish: Premium Luxury
Chassis no. / Identification no.: 1G4YK9R40N2135183
Motor no. / Type: 2.0
Paint (color, code no.): Stellar Black Metallic
Upholstery / Leather (code no.):
Day of initial registration: 17.05.2023
Gears (shift / automatic): automatic
Fuel type (manufacturer recommendation): benzene
Extras:
Date of issue: 19.05.2023

Stamp

Photo 33.

Książka serwisowa – dane

CUSTOMER SERVICE / SERVICE RECORDS

Non-routine service **Major service**

Date: Odometer reading:

Motor oil (brand / quality):

Yes	No	Change of:
☐	☐	Battery (radio remote control)
☐	☐	Brake pads ☐ front ☐ back
☐	☐	Brake fluid
☐	☐	Transmission fluid
☐	☐	Belts drive
☐	☐	Air conditioning
☐	☐	Corrosion protection check
☐	☐	Fuel filter
☐	☐	Coolant
☐	☐	Air filter element
☐	☐	Pollens or activated carbon filter
☐	☐	Tire-filling system / repair kit
☐	☐	Winter check-up to ____ °C
☐	☐	Tension belt and tensioner
☐	☐	Spark plugs

Stamp / Signature of garage:

Date: Odometer reading:

CUSTOMER SERVICE / SERVICE RECORDS

Non-routine service **Major service**

Date: Odometer reading:

Motor oil (brand / quality):

Yes	No	Change of:
☐	☐	Battery (radio remote control)
☐	☐	Brake pads ☐ front ☐ back
☐	☐	Brake fluid
☐	☐	Transmission fluid
☐	☐	Belts drive
☐	☐	Air conditioning
☐	☐	Corrosion protection check
☐	☐	Fuel filter
☐	☐	Coolant
☐	☐	Air filter element
☐	☐	Pollens or activated carbon filter
☐	☐	Tire-filling system / repair kit
☐	☐	Winter check-up to ____ °C
☐	☐	Tension belt and tensioner
☐	☐	Spark plugs

Stamp / Signature of garage:

Date: Odometer reading:

CUSTOMER SERVICE / SERVICE RECORDS

Non-routine service **Major service**

Date: Odometer reading:

Motor oil (brand / quality):

Yes	No	Change of:
☐	☐	Battery (radio remote control)
☐	☐	Brake pads ☐ front ☐ back
☐	☐	Brake fluid
☐	☐	Transmission fluid
☐	☐	Belts drive
☐	☐	Air conditioning
☐	☐	Corrosion protection check
☐	☐	Fuel filter
☐	☐	Coolant
☐	☐	Air filter element
☐	☐	Pollens or activated carbon filter
☐	☐	Tire-filling system / repair kit
☐	☐	Winter check-up to ____ °C
☐	☐	Tension belt and tensioner
☐	☐	Spark plugs

Stamp / Signature of garage:

Date: Odometer reading:

CUSTOMER SERVICE / SERVICE RECORDS

Non-routine service **Major service**

Date: Odometer reading:

Motor oil (brand / quality):


Yes	No	Change of:
☐	☐	Battery (radio remote control)
☐	☐	Brake pads ☐ front ☐ back
☐	☐	Brake fluid
☐	☐	Transmission fluid
☐	☐	Belts drive
☐	☐	Air conditioning
☐	☐	Corrosion protection check
☐	☐	Fuel filter
☐	☐	Coolant
☐	☐	Air filter element
☐	☐	Pollens or activated carbon filter
☐	☐	Tire-filling system / repair kit
☐	☐	Winter check-up to ____ °C
☐	☐	Tension belt and tensioner
☐	☐	Spark plugs

Stamp / Signature of garage:


Date: Odometer reading:

Photo 34.

Książka serwisowa – ostatni przegląd

PHOTOGRAPHIC DOCUMENTATION**Photo 35.**

Dow. rej. ksero Str. 1

**Photo 36.**

Dow. Rej. ksero Str. 2

PHOTOGRAPHIC DOCUMENTATION



Photo 37.
Kluczyki



Photo 38.
Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 39.
Zdjęcie do protokołu



Photo 40.
Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 41.

Zdjęcie do protokołu



Photo 42.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 43.

Zdjęcie do protokołu



Photo 44.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 45.
Zdjęcie do protokołu



Photo 46.
Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 47.

Zdjęcie do protokołu



Photo 48.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 49.

Pokrywa komory silnika - zdjęcie poglądowe 1



Photo 50.

Pokrywa komory silnika - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 51.

Pokrywa komory silnika - Wgniecenie/odkształcenie 1



Photo 52.

Spoiler zderzaka przedniego - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 53.

Szyba czołowa - zdjęcie poglądowe 1




Photo 54.

Szyba czołowa - Pęknięcie/rozerwanie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 55.

Zderzak - Rysa/odprysk 1



Photo 56.

Zderzak przedni cz dolna - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 57.

Zderzak przedni cz dolna - Rysa/odprysk 2



Photo 58.

Zderzak przedni cz dolna - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 59.

Błotnik przedni P - Wgniecenie/odkształcenie 1



Photo 60.

Felga aluminiowa przednia P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 61.
Reflektor P - Rysa/odprysk 1



Photo 62.
Drzwi przednie P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 63.

Drzwi przednie P - Wgniecenie/odkształcenie 1



Photo 64.

Drzwi tylne P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 65.

Drzwi tylne P - Wgniecenie/odkształcenie 1



Photo 66.

Lusterko zew P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 67.

Próg P - Wgniecenie/odkształcenie 1



Photo 68.

Ścianka tylna P / Ścianka boczna P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 69.

Felga aluminiowa tylna P - Rysa/odprysk 1



Photo 70.

Lampa tylna zew P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 71.

Pokrywy bagażnika - Rysa/odprysk 1



Photo 72.

Szyba tylna - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 73.

Zderzak tylny - Rysa/odprysk 1



Photo 74.

Zderzak tylny - Rysa/odprysk 2

PHOTOGRAPHIC DOCUMENTATION



Photo 75.

Zderzak tylny() - Rysa/odprysk 3



Photo 76.

Zderzak tylny - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 77.

Zderzak tylny - Wgniecenie/odkształcenie 2



Photo 78.

Dach - zdjęcie poglądowe 1

PHOTOGRAPHIC DOCUMENTATION




Photo 79.

Dach - Inne 1



Photo 80.

Łotnik tylny L / Ściana boczna L - zdjęcie pogładowe 1

PHOTOGRAPHIC DOCUMENTATION



Photo 81.

Błotnik tylny L / Ściana boczna L - Rysa/odprysk 1



Photo 82.

Błotnik tylny L / Ściana boczna L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 83.

Felga aluminiowa tylna L - Rysa/odprysk 1



Photo 84.

Drzwi przed L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 85.

Drzwi przed L - Wgniecenie/odkształcenie 1



Photo 86.

Drzwi tylne L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 87.

Drzwi tylne L - Wgniecenie/odkształcenie 1



Photo 88.

Lusterko zew L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 89.

Próg L - Rysa/odprysk 1



Photo 90.

Słupek przedni L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION




Photo 91.

Słupek środkowy L - Wgniecenie/odkształcenie 1




Photo 92.

Łotnik przedni L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 93.

Felga Aluminiowa przednia L - Rysa/odprysk 1



Photo 94.

Koło kierownicy - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 95.

Fotel prz. lew. - Inne 1



Photo 96.

Fotel prz. praw. - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 97.

Tapicerka drzwi przednich P - Rysa/odprysk 1



Photo 98.

Tapicerka drzwi przednich P - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 99.

Osłona p/słoneczna lewa - Inne 1