

DEKRA's commission No. : PKOL(W)/LODZ/80099/26/08/27
commission/ damage No. : 25/020388
Date of commission: 27-08-2026

DEKRA Poland - Headquarters
02-673 Warszawa, ul. Konstruktorska 12A

Client :

PKO Leasing SA
Świętokrzyska 36
00-116 Warszawa

Expert:

Kacper Sosnowski (WSP)
DEKRA Polska - współpraca O/Warszawa
Arthur Rusik
DEKRA Polska - O. Gdańsk

NOTE:

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

Vehicle data

Group of objects (Eurotax)	cars
EC code (Eurotax)	0128685
Manufacturer	AUDI
Model	A8 [4N] 17-21
Type / version	A8 55 TFSI mHEV Quattro Tiptr.
Body type	sedan
Number of doors / seats	4/5
Curb weight [kg]	2110
Gross vehicle weight [kg]	2690
Wheelbase 1/2	2998
Engine type	spark ignition
Pollution reduction system	three-way catalytic converter
Engine capacity [ccm]	2995
Engine Power [hp/kW]	340/250
Gearbox	automatic 8- gear
Registration /record No.	SB412GV
VIN / serial number	WAUZZZF80LN007470
Date of first registration	30-06-2020
Year of manufacture	2020
Readout [km]	137 902 (read)
Body color / type of coating	black/METALIK

Tyres

axle	Wheel	Manufacturer, type	Size	Measured profile
Front	right	HANKOOK, WINTER ICEPT EVO3	265/40 20 104W	3,0 mm
	left	HANKOOK, WINTER ICEPT EVO3	265/40 20 104W	3,0 mm
back	right	HANKOOK, WINTER ICEPT EVO3	265/40 20 104W	3,0 mm
	left	HANKOOK, TEMPORARY USE ONLY	165/60 20 109M	2,0 mm

Standard equipment by Eurotax

- | | |
|---|---|
| 1. 3 places rear bench | 31. Leather gearshifter/switch |
| 2. Additional gauges, On board computer | 32. Leather steering wheel, Multi functional steering wheel |
| 3. Alarm | 33. Leather upholstery |
| 4. Antilock-Brake-System (ABS) | 34. Light Alloy wheels 18" |
| 5. Armrest (s) front, Storage facilities in general | 35. Lumbar adjust driver electric, Lumbar adjust passenger electric |
| 6. Automated High-beam assist | 36. Mirror: others |
| 7. Automatic air recirculation control | 37. Mirror: others |
| 8. Bluetooth interface | 38. Navigation system |
| 9. Bord communication: other | 39. Other |
| 10. Child seat fixation | 40. Other |
| 11. Colored glass | 41. Other |
| 12. Colour stripe in windscreen, Windows: other | 42. Other |
| 13. Comfort driver seat, Comfort passenger seat, Driver seat electrically adjustable, Electrically adjustable rear seats, Memory seat, Passenger seat electrically adjustable | 43. Other |
| 14. Cruise control | 44. Other |
| 15. Diminished spare wheel | 45. Other |
| 16. Door mirror with memory, Door mirror(s) electrically adjustable in general, Door mirrors electrically foldable, Door mirrors heated | 46. Park Distance Control front, Park Distance Control rear |
| 17. Driver airbag, Head airbags front, Passenger airbag, Side airbag driver, Side airbag driver and passenger, Side airbags rear | 47. Passive Tyre pressure control |
| 18. Dualzone automatic climate control | 48. Pre-Crash System |
| 19. Electric tailgate | 49. Pre-Crash System |
| 20. Exterior design: other | 50. Radio |
| 21. Floor mat | 51. Rear headrests |
| 22. Free service 3 years, more than 60 000 km | 52. Remote controlled central locking |
| 23. Hydro pneumatic suspension | 53. Servotronic |
| 24. Interior decoration: other | 54. Soundsystem |
| 25. Interior decoration: other | 55. Standard equipment to be completed when available |
| 26. Interior lights: other accessories | 56. Storage facilities in general |
| 27. LED Daytime running lights | 57. Uni-Lackierung |
| 28. LED front dim light | 58. Vehicle immobilizer |
| 29. LED rear lights | 59. Wheel bolt locks |
| 30. Lane control assistant | 60. {1- Wyposażenie opcjonalne w trakcie edycji} |

Dealer's equipment (selected items)

- | | |
|--|---|
| 1. 360 view camera | - |
| 2. 360 view camera | - |
| 3. Bord communication: other | - |
| 4. Bord entertainment: other accessories, On board monitor | - |
| 5. Door mirrors autodimming | - |
| 6. Driver conditioning monitoring, Lane control assistant | - |
| Ostrzeżenie przed niezamierzoną zmianą pasa ruchu z emergency assist | - |
| 7. Electric tailgate | - |
| 8. Front seat with massage, Ventilated front seat | - |
| 9. Glass sunroof fixed | - |
| 10. Hatch/skibag in rear bench | - |
| 11. Head-Up Display | - |
| 12. Headlamp wash | - |
| 13. Headlamp wash, LED front dim light, Side indicators | - |
| 14. Heated seat driver, Heated seat passenger, Rear seat heating | - |

- 15. Interior decoration: other, Interior: other -
 Konsola środkowa w skórze Feinnappa ze szwem ozdobnym
 Podszybie w drzwiach w skórze Feinnappa ze szwem ozdobnym
 Obszycie poduszki powietrznej kierowcy w skórze Feinnappa ze szwem ozdobnym
 Podłokietniki w drzwiach w skórze Feinnappa
 Górna część deski rozdzielczej pokryta skórą Feinnappa ze szwem ozdobnym
- 16. Interior lights: other accessories -
- 17. Interior: other -
 Podsufitka z Alcantary (czarna)
 Osłony przeciwsłoneczne Alcantara (czarne)
 Górna część poszycia słupków Alcantara (czarna)
- 18. Keyless go -
- 19. LED rear lights -
- 20. Lane control assistant, Other, Pre-Crash System, Rear Cross Traffic Alert -
- 21. Leather steering wheel, Multi functional steering wheel, Steering wheel with
 gear-switches -
- 22. Light Alloy wheels 20" -
- 23. Metallic paint -
- 24. Other -
- 25. Other -
- 26. Other -
- 27. Other -
 Gniazdo 12V w bagażniku
 Uchwyt na parasol
 Listwa ochronna krawędzi bagażnika ze stali szlachetnej
- 28. Park Distance Control front, Park Distance Control rear -
- 29. Rear headrests -
- 30. Soundsystem -
- 31. Sunblind rear side door electric, Sunblind tailgate window electric -
- 32. Tinted rear windows -
- 33. Traffic sign recognition -
- 34. Windows: other -

Base value of the vehicle

Base value of the vehicle by Eurotax (net) -

Corrections

First registration

Mileage

Equipment

Tyres

Other

Stan dbałości, stwierdzone uszkodzenia -


Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 08-2026 POL) with regard to technical and market parameters affecting the value of the vehicle.

Basic print without information about the vehicle's value - duey to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 31-08-2026

DEKRA's expert:
Kacper Sosnowski (WSP)
Arthur Rusik

Document issued electronically valid without signature.

Measurement of thickness of the vehicle lacquer coating


No. of controlled item	Controlled item	Measured range of thickness of the lacquer coat [μm]
1	Front cover	to 150
2	Front left fender	to 150
3	Left front pillar	to 150
4	Front left door	to 150
5	Roof	to 150
6	Left middle pillar	to 150
7	Right side sill	to 150
8	Left rear door	to 150
9	Rear left fender	to 150
10	Cover/lid	to 150
11	Right rear fender	to 150
12	Right rear door	to 150
13	Right middle pillar	to 150
14	Right side sill	to 150
15	Front right door	to 150
16	Right front pillar	to 150
17	Front right fender	to 150

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

The vehicle documents have not been presented. Below comments on this matter.
Ksero pozwolenia czasowego

Information concerning the origin of the vehicle

The vehicle purchased domestically from an authorized representative of the brand.

Anti-theft protection - immobilizer

- as a result of the inspection of the vehicle found no malfunctions of the immobilizer in the extent possible to determine during the inspection of the vehicle in the non- workshop conditions.

Anti-theft protection - other:

-other:

.

Additional comments on the car:

Not applicable.

Test drive

Test drive of the vehicle was conducted. Test drive in the full extent is not possible. Comment below:
warunki parkingowe

Checking of the correctness and / or construction of identification / serial numbers of the object:

Not tested

Verification of the accuracy of the object data, including year of production, and other.

Not conducted - adopted according to the documents presented and indicated sources.

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.
- The evaluation has been carried out basing on delivered documentation and organoleptic examination of the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the

page 6/40

assessed object.

- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

Comments to the commission - regarding valuation

Kluczyki

TAK

2

Expert comments - regarding valuation

Rysy na samochodzie. Cztery dywaniki w bagażniku. Zamontowane koło dojazdowe lewy tył. Koło w bagażniku. Dostarczono ksero pozwolenia czasowego. Aktywna kontrolka ciśnienia w kołach. Odpryski na szybie czołowej.

PHOTOGRAPHIC DOCUMENTATION



Photo 1.
Przekątna przednia lewa



Photo 2.
Przód

PHOTOGRAPHIC DOCUMENTATION



Photo 3.

Przekątna przednia prawa



Photo 4.

Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 5.
Bok prawy z tyłu



Photo 6.
Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 7.

Tył



Photo 8.

Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 9.

Bok lewy z tyłu



Photo 10.

Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 11.
Próg lewy (widok od przodu)



Photo 12.
Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



Photo 13.
Spód pojazdu przód



Photo 14.
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION



Photo 15.

Tarcza hamulcowa przednia prawa




Photo 16.

Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 17.

Tarcza hamulcowa tylna lewa



Photo 18.

Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 19.
Bagażnik



Photo 20.
Komora silnika

PHOTOGRAPHIC DOCUMENTATION



Photo 21.

Numer identyfikacyjny



Photo 22.

Tabliczka znamionowa

PHOTOGRAPHIC DOCUMENTATION



Photo 23.

Zestaw wskaźników - przebieg



Photo 24.

Zestaw wskaźników - serwis

PHOTOGRAPHIC DOCUMENTATION



Photo 25.

Widok przez otwarte drzwi przednie lewe



Photo 26.

Kierownica z lewej strony

PHOTOGRAPHIC DOCUMENTATION



Photo 27.

Widok przez otwarte drzwi tylne lewe



Photo 28.

Widok z tylnej kanapy na deskę rozd.

PHOTOGRAPHIC DOCUMENTATION



Photo 29.
Konsola środkowa




Photo 30.
Tunel środkowy

PHOTOGRAPHIC DOCUMENTATION




Photo 31.
Kierownica (na wprost)




Photo 32.
Książka serwisowa – dane

PHOTOGRAPHIC DOCUMENTATION**Photo 33.**

Książka serwisowa – ostatni przegląd

**Photo 34.**

Dow. rej. ksero Str. 1

PHOTOGRAPHIC DOCUMENTATION**Photo 35.**

Dow. Rej. ksero Str. 2

**Photo 36.**

Kluczyki

PHOTOGRAPHIC DOCUMENTATION



Photo 37.
Zdjęcie do protokołu



Photo 38.
Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 39.

Zdjęcie do protokołu



Photo 40.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 41.
Zdjęcie do protokołu



Photo 42.
Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 43.

Zdjęcie do protokołu



Photo 44.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION




Photo 45.

Zdjęcie do protokołu



Photo 46.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 47.

Zdjęcie do protokołu



Photo 48.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION




Photo 49.

Zdjęcie do protokołu



Photo 50.

Pokrywa komory silnika - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 51.

Pokrywa komory silnika - Wgniecenie/odkształcenie 1



Photo 52.

Zderzak przedni cz dolna - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 53.

Felga aluminiowa przednia P - Rysa/odprysk 1



Photo 54.

Opona przednia P - Pęknięcie/rozerwanie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 55.

Drzwi przednie P - Rysa/odprysk 1



Photo 56.

Drzwi tylne P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 57.

Felga aluminiowa tylna P - Rysa/odprysk 1



Photo 58.

Opona tylna P - Pęknięcie/rozerwanie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 59.

Zderzak tylny - Rysa/odprysk 1



Photo 60.

Zderzak tylny - Rysa/odprysk 2

PHOTOGRAPHIC DOCUMENTATION



Photo 61.

Drzwi przed L - Rysa/odprysk 1



Photo 62.

Drzwi tylne L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 63.

Felga Aluminiowa przednia L - Rysa/odprysk 1



Photo 64.

Opona przednia L - Pęknięcie/rozerwanie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 65.

Fotel prz. lew. - Rysa/odprysk 1



Photo 66.

Uchwyt drzwi tyl L - Pęknięcie/rozerwanie 1