

DEKRA's commission No. : PKOL(W)/LODZ/85606/25/11/05
commission/ damage No. : 21/055223
Date of commission: 05-11-2025

DEKRA Poland - Headquarters
02-673 Warszawa, ul. Konstruktorska 12A

Client :

PKO Leasing SA
Świętokrzyska 36
00-116 Warszawa

Expert:

Kacper Sosnowski (NEW)
DEKRA Polska - współpraca O/Warszawa
Tomasz Ziemniak (NEW)
DEKRA Polska - współpraca O/Konin

NOTE:

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

Vehicle data

Group of objects (Eurotax)	cars
EC code (Eurotax)	0150118
Manufacturer	RENAULT
Model	Arkana 21-23
Type / version	Arkana 1.3 TCe mHEV Zen EDC
Body type	hatchback
Number of doors / seats	5/5
Curb weight [kg]	1347
Gross vehicle weight [kg]	1876
Wheelbase 1/2	2720
Engine type	spark ignition
Pollution reduction system	GPF
Engine capacity [ccm]	1332
Engine Power [hp/kW]	140/103
Gearbox	automatic 7- gear
Registration /record No.	WU1204N
VIN / serial number	VF1RJL00167269208
Date of first registration	19-11-2021
Date of next. tech. test	18-11-2026
Year of manufacture	2021 (year has been verified with the manufacturer's base)
Readout [km]	140 255 (read)
Body color / type of coating	white/UNI

Tyres

axle	Wheel	Manufacturer, type	Size	Measured profile
Front	right	KUMHO, ECSTA HS51	215/60 17 96H	4,0 mm
	left	KUMHO, ECSTA HS51	215/60 17 96H	4,0 mm
back	right	KUMHO, ECSTA HS51	215/60 17 96H	4,0 mm
	left	KUMHO, ECSTA HS51	215/60 17 96H	4,0 mm

Standard equipment by Eurotax

- | | |
|---|---|
| 1. Active Emergency Brake Assist, Pedestrian Emergency Brake Assist | 23. LED front dim light |
| 2. Android Auto, Apple CarPlay, Bluetooth interface, DAB radio, On board monitor, Radio | 24. Lane control assistant |
| 3. Antilock-Brake-System (ABS) | 25. Light alloy wheels from 17" |
| 4. Automatic climate control | 26. Mobile Tire System |
| 5. Automatic dimlight activation, Rain sensor | 27. On board computer |
| 6. Body-coloured bumpers | 28. On board monitor |
| 7. Brake Assist | 29. Other |
| 8. Central locking | 30. Other |
| 9. Child seat fixation | 31. Park Distance Control front, Park Distance Control rear |
| 10. Cruise control | 32. Power steering |
| 11. Distance control | 33. Power windows front |
| 12. Door mirror(s) electrically adjustable in general, Door mirrors electrically foldable | 34. Power windows rear |
| 13. Driver airbag, Passenger airbag | 35. Rear bench foldable in two separate parts |
| 14. Driver seat with adjustable inclination, Passenger seat with adjustable inclination | 36. Rear headrests |
| 15. ESP (Electronical Stabilizing Program) | 37. Rear view camera |
| 16. Exterior design: other | 38. Seatbelts vertically adjustable front, Seatbelts vertically adjustable rear |
| 17. Exterior design: other | 39. Side airbag driver and passenger |
| 18. Head airbags front, Head airbags rear | 40. Textile upholstery |
| 19. Headrests front | 41. Traffic sign recognition |
| 20. Hill holder | 42. Tyre pressure control (RDC) |
| 21. Interior: other | 43. Uni-Lackierung |
| 22. Keyless go | |

Dealer's equipment (selected items)

- | | |
|---------------------------------|---|
| 1. Diminished spare wheel | - |
| 2. Other | - |

Base value of the vehicle

Base value of the vehicle by Eurotax (net) -

Corrections

First registration

Mileage

Equipment

Tyres

Other

Korekta z tytułu uszkodzeń pojazdu -

Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 11-2025 POL) with regard to technical and market parameters affecting the value of the vehicle.

Basic print without information about the vehicle's value - duey to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 15-11-2025

DEKRA's expert:
Kacper Sosnowski (NEW)
Tomasz Ziemniak (NEW)

Document issued electronically valid without signature.

Measurement of thickness of the vehicle lacquer coating


No. of controlled item	Controlled item	Measured range of thickness of the lacquer coat [μm]
1	Front cover	to 150
2	Front left fender	to 150
3	Left front pillar	to 150
4	Front left door	to 150
5	Roof	to 150
6	Left middle pillar	to 150
7	Right side sill	to 150
8	Left rear door	to 150
9	Rear left fender	to 150
10	Cover/lid	to 150
11	Right rear fender	to 150
12	Right rear door	to 150
13	Right middle pillar	to 150
14	Right side sill	to 150
15	Front right door	to 150
16	Right front pillar	to 150
17	Front right fender	to 150

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

During the inspection the registration proof of the vehicle was presented and its photo was taken and enclosed to the expertise.

During the inspection the service book was presented and its number is given below:

Brak nr

Information concerning the origin of the vehicle

The vehicle purchased domestically from an authorized representative of the brand.

Anti-theft protection - immobilizer

- as a result of the inspection of the vehicle found no malfunctions of the immobilizer in the extent possible to determine during the inspection of the vehicle in the non- workshop conditions.

Anti-theft protection - other:

not found

Additional comments on the car:

Not applicable.

Test drive

The test drive has been conducted on a distance and in time enabling rough estimation of the technical condition of the vehicle.

Checking of the correctness and / or construction of identification / serial numbers of the object:

Not tested

Verification of the accuracy of the object data, including year of production, and other.

Not conducted (with the exception of the year of production) - adopted according to the documents presented and indicated sources.

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.

- The evaluation has been carried out basing on delivered documentation and organoleptic examination of the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the assessed object.

- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

Comments to the commission - regarding valuation

Kluczyki

TAK

2

Expert comments - regarding valuation

Rysy na samochodzie. Nieprawne przyciski funkcyjne w jednym z kluczyków. Informacja bateria karty do wymiany.

Restrictive disclaimer - regarding valuation

- W Ocenie/Raporcie uwzględniono niesprawności, uszkodzenia, braki itp., które były możliwe do stwierdzenia organoleptycznego, w warunkach oględzin (z uwzględnieniem: stanu czystości pojazdu, warunków atmosferycznych, oświetlenia itd.) oraz bez weryfikacji serwisowej, bez dostępu do spodu pojazdu, bez specjalistycznego sprzętu diagnostycznego (w tym bez diagnostyki komputerowej), bez jazdy próbnej wykonanej w warunkach drogowych z obciążeniem.
- W ramach Oceny/Raportu nie weryfikowano odczytanego stanu drogomierza z zapisami w urządzeniach elektronicznych pojazdu.
- Rzeczoznawca nie bierze na siebie odpowiedzialności za wady ukryte (prawne i fizyczne) oraz ewentualne skutki wynikające z dalszego użytkowania przedmiotu oceny, a także za skutki wykorzystania samej oceny.
- Podane przedziały grubości powłoki lakierowej, dotyczą punktów pomiarowych. Nie mogą być traktowane jako gwarancja, że grubość powłoki lakierowej w innych punktach nie wykracza poza te przedziały.
- Zawarte w niniejszej Ocenie/Raporcie informacje (w tym dotyczące wyposażenia) służą jedynie ogólnym celom informacyjnym. Ocena/Raport nie może być zatem traktowana jako oferta w rozumieniu przepisów Kodeksu Cywilnego oraz opisu towaru ani zapewnienia w rozumieniu art. 4 Ustawy z dnia 27 lipca 2002 roku o szczególnych warunkach sprzedaży konsumenckiej.
- Niniejsza Ocena/Raport nie jest szczegółową oceną stanu technicznego.

Ocenę/Raport wykonano w kierunku ujawnienia uszkodzeń nieakceptowanych z punktu widzenia właściwego przewodnika zwrotu pojazdu lub innych ustaleń ze Zleceniodawcą. Tym samym Ocena/Raport może nie ujmować typowych zużyć i uszkodzeń eksploatacyjnych.

PHOTOGRAPHIC DOCUMENTATION



Photo 1.
Przekątna przednia lewa



Photo 2.
Przód

PHOTOGRAPHIC DOCUMENTATION



Photo 3.

Przekątna przednia prawa



Photo 4.

Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 5.
Bok prawy z tyłu



Photo 6.
Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 7.

Tył



Photo 8.

Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 9.

Bok lewy z tyłu



Photo 10.

Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 11.
Próg lewy (widok od przodu)



Photo 12.
Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



Photo 13.
Spód pojazdu przód



Photo 14.
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION



Photo 15.

Tarcza hamulcowa przednia prawa



Photo 16.

Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 17.

Tarcza hamulcowa tylna lewa



Photo 18.

Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 19.
Bagażnik



Photo 20.
Koło zapasowe

PHOTOGRAPHIC DOCUMENTATION



Photo 21.
Komora silnika




Photo 22.
Numer identyfikacyjny

PHOTOGRAPHIC DOCUMENTATION



Photo 23.

Tabliczka znamionowa



Photo 24.

Zestaw wskaźników - przebieg

PHOTOGRAPHIC DOCUMENTATION



Photo 25.

Widok przez otwarte drzwi przednie lewe




Photo 26.

Kierownica z lewej strony

PHOTOGRAPHIC DOCUMENTATION



Photo 27.

Widok przez otwarte drzwi tylne lewe



Photo 28.

Widok z tylnej kanapy na deskę rozd.

PHOTOGRAPHIC DOCUMENTATION



Photo 29.
Konsola środkowa




Photo 30.
Tunel środkowy

PHOTOGRAPHIC DOCUMENTATION



Photo 31.
Kierownica (na wprost)



Photo 32.
Dowód rej. Str. 1

PHOTOGRAPHIC DOCUMENTATION



Photo 33.

Dow. Rej. Str.2 i klucze





Photo 34.

Książka serwisowa – dane

PHOTOGRAPHIC DOCUMENTATION**Photo 35.**

Książka serwisowa – ostatni przegląd

**Photo 36.**

Instrukcje

PHOTOGRAPHIC DOCUMENTATION



Photo 37.

Pokrywa komory silnika - zdjęcie pogładowe 1



Photo 38.

Pokrywa komory silnika - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 39.

Spoiler zderzaka przedniego - Rysa/odprysk 1



Photo 40.

Zderzak - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 41.

Zderzak - Rysa/odprysk 2



Photo 42.

Drzwi przednie P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 43.

Próg P - Wgniecenie/odkształcenie 1



Photo 44.

Błotnik tylny P / Ściana boczna P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 45.

Błotnik tylny P / Ściana boczna P - Wgniecenie/odkształcenie 1



Photo 46.

Felga aluminiowa tylna P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 47.

Pokrywy bagażnika - Wgniecenie/odkształcenie 1



Photo 48.

Ścianka tylna L / Ścianka boczna L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 49.

Błotnik tylny L / Ściana boczna L - Wgniecenie/odkształcenie 1



Photo 50.

Błotnik tylny L / Ściana boczna L - Wgniecenie/odkształcenie 2

PHOTOGRAPHIC DOCUMENTATION



Photo 51.

Felga aluminiowa tylna L - Rysa/odprysk 1



Photo 52.

Drzwi tylne L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 53.

Próg L - Wgniecenie/odkształcenie 1



Photo 54.

Słupek środkowy L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 55.

Felga Aluminiowa przednia L - Rysa/odprysk 1



Photo 56.

Konsola tunelu śr. - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 57.

Fotel prz. lew. - Inne 1




Photo 58.

Fotel prz. lew. - Inne 2

PHOTOGRAPHIC DOCUMENTATION



Photo 59.

Fotel prz. praw. - Inne 1



Photo 60.

Kanapa tyl. - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 61.
Kanapa tyl. - Inne 2



Photo 62.
Podsufitka - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 63.
Podsufitka - Inne 2



Photo 64.
Wykładzina podłogi bagażnika - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 65.

Wykładzina pokrywy tylnej - Pęknięcie/rozerwanie 1