

DEKRA's commission No. : PKOL(W)/LODZ/25408/26/03/23
commission/ damage No. : 22/032652
Date of commission: 23-03-2026

DEKRA Poland - Headquarters
02-673 Warszawa, ul. Konstruktorska 12A

Client :

PKO Leasing SA
Świętokrzyska 36
00-116 Warszawa

Expert:

Kacper Sosnowski (WSP)
DEKRA Polska - współpraca O/Warszawa
Andrzej Sosnowski
DEKRA Polska - Centrala

NOTE:

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

Vehicle data

Group of objects (Eurotax)	jeeps
EC code (Eurotax)	0155903
Manufacturer	BMW
Model	X1 [U11] 22-
Type / version	X1 sDrive18i M Sport sport-aut
Body type	KOM
Number of doors / seats	5/5
Curb weight [kg]	1500
Gross vehicle weight [kg]	2075
Wheelbase 1/2	2692
Engine type	spark ignition
Pollution reduction system	GPF
Engine capacity [ccm]	1499
Engine Power [hp/kW]	136/100
Gearbox	automatic
Registration /record No.	KK65228
VIN / serial number	WBA11EE0205V84828
Date of first registration	10-11-2022
Date of next. tech. test	30-10-2027
Year of manufacture	2022 (year has been verified with the manufacturer's base)
Readout [km]	25 004 (read)
Body color / type of coating	blue/double-layered, metallized

Tyres

axle	Wheel	Manufacturer, type	Size	Measured profile
Front	right	NEXEN, NFERA SPORT SU2	225/55 18 102Y	5,0 mm
	left	NEXEN, NFERA SPORT SU2	225/55 18 102Y	5,0 mm
back	right	NEXEN, NFERA SPORT SU2	225/55 18 102Y	5,0 mm
	left	NEXEN, NFERA SPORT SU2	225/55 18 102Y	5,0 mm

Standard equipment by Eurotax

- | | |
|---|---|
| 1. Active body control | 34. Floor mat |
| 2. Active speed sign recognition | 35. Follow me home |
| 3. Alcantara upholstery, Upholstery with leather inserts | 36. Headlamp wash nozzle heated |
| 4. Android Auto, Apple CarPlay | 37. Interior lights: other accessories |
| 5. Antilock-Brake-System (ABS) | 38. Interior: other |
| 6. Armrest (s) front | 39. Interior: other |
| 7. Automatic Emergency Call | 40. Lane control assistant |
| 8. Automatic Emergency Call | 41. Leather finish dashbord |
| 9. Automatic dimlight activation, Rain sensor | 42. Leather steering wheel, Sports steering wheel |
| 10. Bluetooth interface, Hands-free system, Internet access, Navigation system, On board monitor, Radio, Touchscreen monitor | 43. Light Alloy wheels 18'' |
| 11. Bord entertainment: other accessories | 44. Metal finish |
| 12. Bord entertainment: other accessories | 45. Mobile Tire System |
| 13. Brake Assist, Collision Warning System, Pedestrian Emergency Brake Assist | 46. Other |
| 14. Central airbag driver and passenger | 47. Other |
| 15. Child seat fixation | 48. Other |
| 16. Child seat fixation | 49. Park Assistant, Park Distance Control front, Park Distance Control rear, Rear view camera |
| 17. Collision Warning System | 50. Power windows front, Power windows rear |
| 18. Cruise control, Distance control | 51. Rear seat-backs foldable in two separate parts |
| 19. DAB radio | 52. Remote controlled central locking |
| 20. Distribution of braking force electronically | 53. Roof railing |
| 21. Door mirror(s) electrically adjustable in general, Door mirrors heated | 54. Seats: other |
| 22. Driver airbag, Head airbags front, Head airbags rear, Passenger airbag, Side airbag driver and passenger, Side airbags rear | 55. Selectable driveline characteristics |
| 23. Driver-information-system | 56. Servotronic |
| 24. Dualzone automatic climate control | 57. Soundsystem |
| 25. ESP (Electronical Stabilizing Program), Traction control | 58. Sport seats front |
| 26. Electric parking brake | 59. Start/Stop system |
| 27. Electric tailgate | 60. Steering wheel manually adjustabe |
| 28. Exterior design: other | 61. Tyre pressure control (RDC) |
| 29. Exterior design: other | 62. USB in |
| 30. Exterior design: other | 63. Uni-Lackierung |
| 31. Exterior lighting: other | 64. Wheel bolt locks |
| 32. Extra power outlet | 65. {System stabilizacji przyczepy} |
| 33. Fire protection system | |

Dealer's equipment (selected items)

- | | |
|--|---|
| 1. Artificial leather upholstery | - |
| 2. Automated High-beam assist, Cornering Headlights, Digital key, Door mirror with memory, Door mirrors autodimming, Exterior lighting: other, Keyless entry, Keyless go, LED front dim light, Mirror: others, Other, Rear-view mirror autodimming, Wireless device charging | - |
| Asystent świateł drogowych | |
| Reflektory adaptacyjne LED, z funkcją BMW Selective Beam | |
| Taca do ładowania bezprzewodowego urządzeń | |
| Dostęp komfortowy z kluczykiem cyfrowym | |
| Pakiet funkcji lusterek(el. składane,pamięć,funkcja parkingowa,elektrochromatyczne,projekcja logo) | |
| Przygotowanie do ogrzewania kierownicy | |
| Przygotowanie do ogrzewania foteli przednich | |
| Przygotowanie do systemów asystujących kierowcy Plus | |

3. Driver seat electrically adjustable, Memory seat	-
4. Exterior design: other	-
5. Heated seat driver, Heated seat passenger	-
6. Metallic paint	-
7. Rear-view mirror autodimming	-
8. Steering wheel heated	-
9. Tinted rear windows	-
10. Towbar removable	-

Base value of the vehicle

Base value of the vehicle by Eurotax (net) -

CorrectionsFirst registrationEquipmentTyresOtherCurrent market situation -
Uszkodzenia, stan

Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 03-2026 POL) with regard to technical and market parameters affecting the value of the vehicle.

Basic print without information about the vehicle's value - duey to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 25-03-2026

DEKRA's expert:
Kacper Sosnowski (WSP)
Andrzej Sosnowski**Document issued electronically valid without signature.**

Measurement of thickness of the vehicle lacquer coating



No. of controlled item	Controlled item	Measured range of thickness of the lacquer coat [μm]
1	Front cover	to 150
2	Left front fender	to 150
3	Left front pillar	to 150
4	Left front wall	to 150
5	Roof	to 150
6	Left middle pillar	to 150
7	Left side sill	to 150
8	Left rear wall	to 150
9	Left side wall	to 150
10	Cover/tailgate	to 150
11	Side right wall	to 150
12	Rear right door	to 150
13	Middle right pillar	to 150
14	Front right door	to 150
15	Right side sill	to 150
16	Right front pillar	to 150
17	Right front fender	to 150

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

During the inspection the registration proof of the vehicle was presented and its photo was taken and enclosed to the expertise.

During the inspection the service book was presented and its number is given below:
elektroniczna

Information concerning the origin of the vehicle

Lack of reliable data.

Additional comments on the car:

Not applicable.

Test drive

Test drive of the vehicle was conducted. Test drive in the full extent is not possible. Comment below:
ograniczenia placowe

Checking of the correctness and / or construction of identification / serial numbers of the object:

Not tested

Verification of the accuracy of the object data, including year of production, and other.

Not conducted - adopted according to the documents presented and indicated sources.

Anti-theft protection

fabryczne

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.
- The evaluation has been carried out basing on delivered documentation and organoleptic examination of the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the assessed object.
- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

Comments to the commission - regarding valuation**Kluczyki**

TAK

2

Expert comments - regarding valuation

Cztery dywaniki w bagażniku. Rysy na samochodzie.

Rzeczoznawca dokonał oględzin pojazdu w warunkach parkingowych, co mogło ograniczyć pełną ocenę jego stanu technicznego. Dodatkowo, jeżeli jazda próbna została przeprowadzona (informacje w treści raportu), to wykonano ją w warunkach parkingowych, z niewielką prędkością, co może nie odzwierciedlać pełnych warunków eksploatacyjnych. Istnieje możliwość, że w innych okolicznościach ujawnią się dodatkowe uszkodzenia lub usterki, których nie można było wykryć podczas obecnych oględzin. Zalecamy zatem skorzystanie z możliwości oględzin pojazdu we własnym zakresie lub w Autoryzowanej Stacji Obsługi danej marki, co pozwoli na pełniejszą weryfikację stanu technicznego pojazdu przed udziałem w aukcji.”

Restrictive disclaimer - regarding valuation

Nie weryfikowano szczegółowo stanu układu napędowego, zawieszenia, kierowniczego, hamulcowego oraz wydechowego. Ocena została wykonana bez użycia podnośnika i specjalistycznego sprzętu diagnostycznego, nie dokonywano demontażu osłon i innych elementów. Ocena określa ogólny stan pojazdu na dzień oględzin w miejscu jego udostępnienia, nie może być zatem traktowana jako kompleksowa ocena stanu technicznego. Specyfikacja wg. programu operacyjnego w zakresie wyposażenia standardowego i dodatkowego nie gwarantuje zgodności ze stanem faktycznym w zakresie możliwym do ustalenia przez rzeczoznawcę podczas oględzin pojazdu.

Pomiar grubości powłoki lakierowej wykonano w miejscach możliwych do ich wykonania pomiary nie gwarantują oryginalności poszczególnych elementów poddanych ocenie.

- W Ocenie/Raporcie uwzględniono niesprawności, uszkodzenia, braki itp., które były możliwe do stwierdzenia organoleptycznego, w warunkach oględzin (z uwzględnieniem: stanu czystości pojazdu, warunków atmosferycznych, oświetlenia itd.) oraz bez weryfikacji serwisowej, bez dostępu do spodu pojazdu, bez specjalistycznego sprzętu diagnostycznego (w tym bez diagnostyki komputerowej), bez jazdy próbnej wykonanej w warunkach drogowych z obciążeniem.
- W ramach Oceny/Raportu nie weryfikowano odczytanego stanu drogomierza z zapisami w urządzeniach elektronicznych pojazdu.
- Rzeczoznawca nie bierze na siebie odpowiedzialności za wady ukryte (prawne i fizyczne) oraz ewentualne skutki wynikające z dalszego użytkowania przedmiotu oceny, a także za skutki wykorzystania samej oceny.
- Podane przedziały grubości powłoki lakierowej, dotyczą punktów pomiarowych. Nie mogą być traktowane jako gwarancja, że grubość powłoki lakierowej w innych punktach nie wykracza poza te przedziały.
- Zawarte w niniejszej Ocenie/Raporcie informacje (w tym dotyczące wyposażenia) służą jedynie ogólnym celom informacyjnym. Ocena/Raport nie może być zatem traktowana jako oferta w rozumieniu przepisów Kodeksu Cywilnego oraz opisu towaru ani zapewnienia w rozumieniu art. 4 Ustawy z dnia 27 lipca 2002 roku o szczególnych warunkach sprzedaży konsumenckiej.
- Niniejsza Ocena/Raport nie jest szczegółową oceną stanu technicznego.

Ocenę/Raport wykonano w kierunku ujawnienia uszkodzeń nieakceptowanych z punktu widzenia właściwego przewodnika zwrotu pojazdu lub innych ustaleń ze Zleceniodawcą. Tym samym Ocena/Raport może nie ujmować typowych zużyć i uszkodzeń eksploatacyjnych.

PHOTOGRAPHIC DOCUMENTATION



Photo 1.
Przekątna przednia lewa



Photo 2.
Przód

PHOTOGRAPHIC DOCUMENTATION



Photo 3.

Przekątna przednia prawa



Photo 4.

Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 5.
Bok prawy z tyłu



Photo 6.
Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 7.
Tył



Photo 8.
Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 9.
Bok lewy z tyłu



Photo 10.
Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 11.
Próg lewy (widok od przodu)



Photo 12.
Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



Photo 13.
Spód pojazdu przód



Photo 14.
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION



Photo 15.

Tarcza hamulcowa przednia prawa



Photo 16.

Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 17.
Tarcza hamulcowa tylna lewa



Photo 18.
Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 19.
Bagażnik



Photo 20.
Koło zapasowe

PHOTOGRAPHIC DOCUMENTATION



Photo 21.
Komora silnika



Photo 22.
Numer identyfikacyjny

PHOTOGRAPHIC DOCUMENTATION



Photo 23.
Tabliczka znamionowa



Photo 24.
Zestaw wskaźników - przebieg

PHOTOGRAPHIC DOCUMENTATION



Photo 25.

Widok przez otwarte drzwi przednie lewe



Photo 26.

Kierownica z lewej strony

PHOTOGRAPHIC DOCUMENTATION



Photo 27.

Widok przez otwarte drzwi tylne lewe



Photo 28.

Widok z tylnej kanapy na deskę rozd.

PHOTOGRAPHIC DOCUMENTATION



Photo 29.
Konsola środkowa




Photo 30.
Tunel środkowy

PHOTOGRAPHIC DOCUMENTATION



Photo 33.
Dow. Rej. Str.2 i klucze




Photo 34.
Książka serwisowa – dane

PHOTOGRAPHIC DOCUMENTATION




Photo 35.
Książka serwisowa – ostatni przegląd



Photo 36.
Instrukcje

PHOTOGRAPHIC DOCUMENTATION



Photo 37.
Zestaw naprawczy koła



Photo 38.
Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 39.
Zdjęcie do protokołu



Photo 40.
Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION




Photo 41.

Pokrywa komory silnika - Rysa/odprysk 1



Photo 42.

Listwa błotnika przedniego P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION




Photo 43.

Drzwi przednie P - Wgniecenie/odkształcenie 1



Photo 44.

Drzwi tylne P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 45.
Błotnik tylny P / Ściana boczna P - Wgniecenie/odkształcenie 1




Photo 46.
Błotnik tylny P / Ściana boczna P - Wgniecenie/odkształcenie 2

PHOTOGRAPHIC DOCUMENTATION



Photo 47.

Listwa krawędzi błotnika tyl P - Rysa/odprysk 1



Photo 48.

Błotnik tylny L / Ściana boczna L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 49.

Drzwi przed L - Rysa/odprysk 1



Photo 50.

Drzwi przed L - Rysa/odprysk 2

PHOTOGRAPHIC DOCUMENTATION



Photo 51.
Drzwi przed L - Wgniecenie/odkształcenie 1



Photo 52.
Drzwi tylne L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 53.
Drzwi tylne L - Wgniecenie/odkształcenie 1



Photo 54.
Klamka drzwi prz L - Rysa/odprysk 1