

DEKRA's commission No. : PKOL(W)/LODZ/03715/26/01/16
commission/ damage No. : 03477/EO/22
Date of commission: 16-01-2026

DEKRA Poland - Headquarters
02-673 Warszawa, ul. Konstruktorska 12A

Client :

PKO Leasing SA
Świętokrzyska 36
00-116 Warszawa

Expert:

Kacper Sosnowski (NEW)
DEKRA Polska - współpraca O/Warszawa
Andrzej Sosnowski
DEKRA Polska - Centrala

NOTE:

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

Vehicle data

Group of objects (Eurotax)	jeeps
EC code (Eurotax)	0145041
Manufacturer	BMW
Model	X7 [G07] 18-22
Type / version	X7 xDrive40d mHEV sport-aut
Body type	KOM
Number of doors / seats	5/7
Curb weight [kg]	2470
Gross vehicle weight [kg]	3295
Wheelbase 1/2	3105
Engine type	Automatic ignition
Pollution reduction system	KSC
Engine capacity [ccm]	2993
Engine Power [hp/kW]	340/250
Gearbox	automatic
Registration /record No.	ZK5721J
VIN / serial number	WBATB410809M54096
Date of first registration	18-08-2022
Date of next. tech. test	18-08-2027
Year of manufacture	2022 (year has been verified with the manufacturer's base)
Readout [km]	141 600 (read)
Body color / type of coating	black/double-layered, metallized

Tyres

axle	Wheel	Manufacturer, type	Size	Measured profile
Front	right	BRIDGESTONE, BLIZZAK LM001	285/45 21 113V	6,5 mm
	left	BRIDGESTONE, BLIZZAK LM001	285/45 21 113V	6,5 mm
back	right	BRIDGESTONE, BLIZZAK LM001	285/45 21 113V	6,5 mm
	left	BRIDGESTONE, BLIZZAK LM001	285/45 21 113V	6,5 mm

Standard equipment by Eurotax

- | | |
|--|---|
| 1. 2 single seats rear, 3 single seats middle, Electrically adjustable rear seats | 43. Floor mat |
| 2. 4 or more zone automatic climate control, Air condition rear | 44. Follow me home |
| 3. Accoustic windows | 45. Gesture control for multimedia, Gesture control for vehicle functions |
| 4. Active Blind spot system, Blind spot warning | 46. Glass tilt/slide sunroof electric |
| 5. Active body control | 47. Head-Up Display |
| 6. Active speed sign recognition | 48. Headlamp wash nozzle heated |
| 7. Adaptive light, LED front dim light | 49. Heated seat driver, Heated seat passenger |
| 8. Alarm | 50. Hill descent control |
| 9. Android Auto, Apple CarPlay | 51. Interior lights: other accessories |
| 10. Antilock-Brake-System (ABS) | 52. Interior: other |
| 11. Armrest (s) front, Armrest (s) rear | 53. Interior: other |
| 12. Automated High-beam assist | 54. Keyless entry, Keyless go |
| 13. Automatic Emergency Call | 55. LED Fog Lamps |
| 14. Automatic Emergency Call | 56. LED rear lights |
| 15. Automatic dimlight activation, Rain sensor | 57. Lane control assistant |
| 16. Bluetooth interface, Bord entertainment: other accessories, Mobile phone | 58. Leather finish dashbord |
| 17. Bluetooth interface, Digital instruments, Internet access, Navigation system, On board monitor, Radio, Touchscreen monitor, USB in, Voice control for audiosystem, Voice control for navigation system | 59. Leather steering wheel, Sports steering wheel |
| 18. Bluetooth interface, Mobile phone preparation, USB in | 60. Leather upholstery |
| 19. Bord entertainment: other accessories | 61. Light Alloy wheels 20'', Runflat tyres |
| 20. Bord entertainment: other accessories | 62. Luggage:other |
| 21. Bord entertainment: other accessories | 63. Mirror: others |
| 22. Cargo net | 64. Multi functional steering wheel, Steering wheel with radio operation |
| 23. Central locking | 65. Other |
| 24. Child seat fixation | 66. Other |
| 25. Collision Warning System | 67. Other |
| 26. Collision Warning System, Pedestrian Emergency Brake Assist | 68. Other |
| 27. Comfort driver seat, Comfort passenger seat | 69. Other |
| 28. Cruise control, Distance control | 70. Other |
| 29. DAB radio | 71. Other |
| 30. Digital key | 72. Other |
| 31. Door mirrors electrically foldable, Door mirrors heated | 73. Other |
| 32. Door: other | 74. Park Assistant, Park Distance Control front, Park Distance Control rear, Rear view camera |
| 33. Driver airbag, Head airbags front, Head airbags rear, Passenger airbag, Side airbag driver and passenger, Side airbags rear | 75. Rear Cross Traffic Alert |
| 34. Driver-information-system | 76. Rear seat-backs foldable in two separate parts |
| 35. ESP (Electronical Stabilizing Program), Traction control | 77. Selectable driveline characteristics |
| 36. Electric parking brake | 78. Servotronic |
| 37. Electric tailgate | 79. Soundsystem |
| 38. Exterior design: other | 80. Sport seats front |
| 39. Exterior design: other | 81. Steering wheel electrically adjustable |
| 40. Exterior design: other | 82. USB in |
| 41. Exterior lighting: other | 83. Uni-Lackierung |
| 42. Extra power outlet | 84. Wheel bolt locks |

Dealer's equipment (selected items)

1. 2 single seats middle, 2 single seats rear -
2. 360 view camera, Park Assistant -
3. 4 or more zone automatic climate control -
4. Active Emergency Brake Assist, Adaptive Cruise Control, Collision Warning System,
Distance control, Intersection Assist, Other, Side Pre-Crash System, Steering: other -
- Tempomat aktywny z funkcją Stop&Go
- System ostrzegający przed ruchem poprzecznym z przodu
- Asystent unikania kolizji
- Aktywna ochrona przed kolizją boczną
- Asystent kierowania i pasa ruchu
- Asystent zatrzymania awaryjnego
- Asystent zmiany pasa ruchu
- Asystent korytarza ratunkowego
5. Active body control, Air suspension -
6. Aerodynamics package, Exterior design: other -
7. Armrest (s) front, Bord climate: other, Steering wheel heated -
- Podłokietniki przednie ogrzewane
- Kierownica ogrzewana
8. Bluetooth interface, Mobile phone, Wireless device charging -
9. Bord entertainment: other accessories, Soundsystem -
10. Comfort driver seat, Comfort passenger seat, Driver seat electrically adjustable,
Memory seat, Passenger seat electrically adjustable -
11. Exterior design: other -
12. Exterior design: other -
13. Exterior design: other -
14. Front seat with massage -
15. Heated seat driver, Heated seat passenger, Rear seat heating -
16. Independent vehicle heater -
17. Interior decoration: other -
18. Interior: other -
19. Interior: other -
20. Leather finish dashbord -
21. Leather steering wheel, Sports steering wheel -
22. Leather upholstery -
23. Light Allow wheels over 21'', Runflat tyres -
24. Metallic paint -
25. Other -
26. Other -
27. Power steering -
28. Roof railing -
29. Steering: other -
30. Tinted rear windows -
31. Towbar removable -
32. Ventilated front seat -
33. Wood finish -
34. {Światła laserowe BMW} -

Base value of the vehicle

Base value of the vehicle by Eurotax (net) -

CorrectionsFirst registrationMileageEquipmentTyresOther

Current market situation -
Uszkodzenia stan, weryfikacja, serwisowa -


Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 01-2026 POL) with regard to technical and market parameters affecting the value of the vehicle.

Basic print without information about the vehicle's value - due to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 26-01-2026

DEKRA's expert:
Kacper Sosnowski (NEW)
Andrzej Sosnowski

Document issued electronically valid without signature.

Measurement of thickness of the vehicle lacquer coating


No. of controlled item	Controlled item	Measured range of thickness of the lacquer coat [µm]
1	Front cover	150 - 300
2	Left front fender	150 - 300
3	Left front pillar	150 - 300
4	Left front wall	150 - 300
5	Roof	150 - 300
6	Left middle pillar	to 150
7	Left side sill	to 150
8	Left rear wall	150 - 300
9	Left side wall	150 - 300
10	Cover/tailgate	150 - 300
11	Side right wall	150 - 300
12	Rear right door	150 - 300
13	Middle right pillar	to 150
14	Front right door	150 - 300
15	Right side sill	to 150
16	Right front pillar	150 - 300
17	Right front fender	150 - 300

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

During the inspection the registration proof of the vehicle was presented and its photo was taken and enclosed to the expertise.

During the inspection the service book was presented and its number is given below:
elektroniczne

Information concerning the origin of the vehicle

Lack of reliable data.

Additional comments on the car:

Not applicable.

Test drive

Test drive of the vehicle was conducted. Test drive in the full extent is not possible. Comment below:
ograniczenia placowe

Checking of the correctness and / or construction of identification / serial numbers of the object:

Not tested

Verification of the accuracy of the object data, including year of production, and other.

Not conducted - adopted according to the documents presented and indicated sources.

Anti-theft protection

fabryczne

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.
- The evaluation has been carried out basing on delivered documentation and organoleptic examination of the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the assessed object.
- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

Comments to the commission - regarding valuation**Kluczyki**

TAK

2

Expert comments - regarding valuation

Rysy na samochodzie. Plastikowy element w bagażniku. Informacja uzupełnij AdBlue. Informacja awaria automatycznej aktywacji PDC. Awaria kamery parkowania przód i tył. Pojazd oklejony folią. Pomiar lakieru wykonany na folii oprócz elementów próg lewy/prawy, słupek środkowy lewy/prawy. Lusterka i reflektory oklejone folią. Odpryski na szybie czołowej. Uszkodzony przód, zakres uszkodzeń do weryfikacji. Elektryczne i podgrzewane tylne fotele.

Rzeczoznawca dokonał oględzin pojazdu w warunkach parkingowych, co mogło ograniczyć pełną ocenę jego stanu technicznego. Dodatkowo, jeżeli jazda próbna została przeprowadzona (informacje w treści raportu), to wykonano ją w warunkach parkingowych, z niewielką prędkością, co może nie odzwierciedlać pełnych warunków eksploatacyjnych. Istnieje możliwość, że w innych okolicznościach ujawnią się dodatkowe uszkodzenia lub usterki, których nie można było wykryć podczas obecnych oględzin. Zalecamy zatem skorzystanie z możliwości oględzin pojazdu we własnym zakresie lub w Autoryzowanej Stacji Obsługi danej marki, co pozwoli na pełniejszą weryfikację stanu technicznego pojazdu przed udziałem w aukcji."

Restrictive disclaimer - regarding valuation

Nie weryfikowano szczegółowo stanu układu napędowego, zawieszenia, kierowniczego, hamulcowego oraz wydechowego. Ocena została wykonana bez użycia podnośnika i specjalistycznego sprzętu diagnostycznego, nie dokonywano demontażu osłon i innych elementów. Ocena określa ogólny stan pojazdu na dzień oględzin w miejscu jego udostępnienia, nie może być zatem traktowana jako kompleksowa ocena stanu technicznego. Specyfikacja wg. programu operacyjnego w zakresie wyposażenia standardowego i dodatkowego nie gwarantuje zgodności ze stanem faktycznym w zakresie możliwym do ustalenia przez rzeczoznawcę podczas oględzin pojazdu. Pomiar grubości powłoki lakierowej wykonano w miejscach możliwych do ich wykonania pomiary nie gwarantują oryginalności poszczególnych elementów poddanych ocenie.

- W Ocenie/Raporcie uwzględniono niesprawności, uszkodzenia, braki itp., które były możliwe do stwierdzenia organoleptycznego, w warunkach oględzin (z uwzględnieniem: stanu czystości pojazdu, warunków atmosferycznych, oświetlenia itd.) oraz bez weryfikacji serwisowej, bez dostępu do spodu pojazdu, bez specjalistycznego sprzętu diagnostycznego (w tym bez diagnostyki komputerowej), bez jazdy próbnej wykonanej w warunkach drogowych z obciążeniem.
- W ramach Oceny/Raportu nie weryfikowano odczytanego stanu drogomierza z zapisami w urządzeniach elektronicznych pojazdu.
- Rzeczoznawca nie bierze na siebie odpowiedzialności za wady ukryte (prawne i fizyczne) oraz ewentualne skutki wynikające z dalszego użytkowania przedmiotu oceny, a także za skutki wykorzystania samej oceny.
- Podane przedziały grubości powłoki lakierowej, dotyczą punktów pomiarowych. Nie mogą być traktowane jako gwarancja, że grubość powłoki lakierowej w innych punktach nie wykracza poza te przedziały.
- Zawarte w niniejszej Ocenie/Raporcie informacje (w tym dotyczące wyposażenia) służą jedynie ogólnym celom informacyjnym. Ocena/Raport nie może być zatem traktowana jako oferta w rozumieniu przepisów Kodeksu Cywilnego oraz opisu towaru ani zapewnienia w rozumieniu art. 4 Ustawy z dnia 27 lipca 2002 roku o szczególnych warunkach sprzedaży konsumenckiej.

- Niniejsza Ocena/Raport nie jest szczegółową oceną stanu technicznego.

Ocenę/Raport wykonano w kierunku ujawnienia uszkodzeń nieakceptowanych z punktu widzenia właściwego przewodnika zwrotu pojazdu lub innych ustaleń ze Zleceniodawcą. Tym samym Ocena/Raport może nie ujmować typowych zużyć i uszkodzeń eksploatacyjnych.

PHOTOGRAPHIC DOCUMENTATION



Photo 1.
Przekątna przednia lewa



Photo 2.
Przód

PHOTOGRAPHIC DOCUMENTATION



Photo 3.

Przekątna przednia prawa



Photo 4.

Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 5.
Bok prawy z tyłu



Photo 6.
Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 7.

Tył



Photo 8.

Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 9.

Bok lewy z tyłu



Photo 10.

Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 11.

Próg lewy (widok od przodu)




Photo 12.

Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



Photo 13.
Spód pojazdu przód



Photo 14.
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION



Photo 15.

Tarcza hamulcowa przednia prawa



Photo 16.

Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 17.

Tarcza hamulcowa tylna lewa




Photo 18.

Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 19.
Bagażnik



Photo 20.
Koło zapasowe

PHOTOGRAPHIC DOCUMENTATION



Photo 21.
Komora silnika



Photo 22.
Numer identyfikacyjny

PHOTOGRAPHIC DOCUMENTATION



Photo 23.

Tabliczka znamionowa



Photo 24.

Zestaw wskaźników - przebieg

PHOTOGRAPHIC DOCUMENTATION



Photo 25.

Widok przez otwarte drzwi przednie lewe



Photo 26.

Kierownica z lewej strony

PHOTOGRAPHIC DOCUMENTATION



Photo 27.

Widok przez otwarte drzwi tylne lewe




Photo 28.

Widok z tylnej kanapy na deskę rozd.

PHOTOGRAPHIC DOCUMENTATION



Photo 29.

Konsola środkowa




Photo 30.

Tunel środkowy

PHOTOGRAPHIC DOCUMENTATION



Photo 31.

Kierownica (na wprost)



Photo 32.

Dowód rej. Str. 1

PHOTOGRAPHIC DOCUMENTATION



Photo 33.

Dow. Rej. Str.2 i klucze




Photo 34.

Książka serwisowa – dane

PHOTOGRAPHIC DOCUMENTATION




Photo 35.

Książka serwisowa – ostatni przegląd



Photo 36.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 37.

Zdjęcie do protokołu




Photo 38.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 39.

Zdjęcie do protokołu



Photo 40.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 41.

Zdjęcie do protokołu



Photo 42.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION




Photo 43.

Zdjęcie do protokołu



Photo 44.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION




Photo 45.
Zdjęcie do protokołu



Photo 46.
Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 47.

Zdjęcie do protokołu



Photo 48.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 49.

Atrapa przednia - zdjęcie pogładowe 1



Photo 50.

Atrapa przednia - zdjęcie pogładowe 2

PHOTOGRAPHIC DOCUMENTATION



Photo 51.

Atrapa przednia - Pęknięcie/rozerwanie 1



Photo 52.

Atrapa przednia - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 53.

Krata zderzaka prz. - Pęknięcie/rozerwanie 1



Photo 54.

Krata zderzaka prz. - Pęknięcie/rozerwanie 2

PHOTOGRAPHIC DOCUMENTATION



Photo 55.

Listwa śr zderzaka przedniego - Rysa/odprysk 1



Photo 56.

Listwa śr zderzaka przedniego - Rysa/odprysk 2

PHOTOGRAPHIC DOCUMENTATION



Photo 57.

Pokrywa komory silnika - zdjęcie poglądowe 1



Photo 58.

Pokrywa komory silnika - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 59.

Szyba czołowa - zdjęcie poglądowe 1




Photo 60.

Szyba czołowa - Pęknięcie/rozerwanie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 61.

Zaślepka prz haka hol. - Inne 1



Photo 62.

Zderzak - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 63.

Zderzak - Rysa/odprysk 2



Photo 64.

Zderzak - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 65.

Zderzak - Pęknięcie/rozerwanie 1



Photo 66.

Zderzak - Pęknięcie/rozerwanie 2

PHOTOGRAPHIC DOCUMENTATION



Photo 67.

Błotnik przedni P - Rysa/odprysk 1



Photo 68.

Listwa błotnika przedniego P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 69.

Reflektor P - Pęknięcie/rozerwanie 1




Photo 70.

Drzwi przednie P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 71.

Drzwi tylne P - Wgniecenie/odkształcenie 1



Photo 72.

Listwa drzwi tylnych P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION




Photo 73.

Lusterko zew P - Inne 1



Photo 74.

Próg P - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 75.

Ścianka tylna P / Ścianka boczna P - Rysa/odprysk 1



Photo 76.

Ścianka tylna P / Ścianka boczna P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 77.

Lampa tylna zew P - Inne 1



Photo 78.

Listwa krawędzi błotnika tyl P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 79.

Pokrywy bagażnika - Wgniecenie/odkształcenie 1



Photo 80.

Spojler zderzaka tylnego - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 81.

Zderzak tylny - Wgniecenie/odkształcenie 1



Photo 82.

Ścianka tylna L / Ścianka boczna L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 83.

Drzwi tylne L - Wgniecenie/odkształcenie 1



Photo 84.

Nadkole przednie L - zdjęcie pogłądowe 1

PHOTOGRAPHIC DOCUMENTATION



Photo 85.

Nadkole przednie L - Pęknięcie/rozerwanie 1



Photo 86.

Podłokietnik środkowy przedni - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 87.

Tapicerka drzwi przednich L - Rysa/odprysk 1



Photo 88.

Tapicerka drzwi tylnych L - Pęknięcie/rozerwanie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 89.

Tapicerka drzwi tylnych P - Pęknięcie/rozerwanie 1