

DEKRA's commission No. : PKOL(W)/LODZ/80667/26/08/28
commission/ damage No. : 20/043739
Date of commission: 28-08-2026

DEKRA Poland - Headquarters
02-673 Warszawa, ul. Konstruktorska 12A

Client :

PKO Leasing SA
Świętokrzyska 36
00-116 Warszawa

Expert:

Kacper Sosnowski (WSP)
DEKRA Polska - współpraca O/Warszawa
mgr inż. Michał Świątek
DEKRA Polska - Centrala

NOTE:

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

Vehicle data

Group of objects (Eurotax)	jeeps
EC code (Eurotax)	0137462
Manufacturer	FORD
Model	Edge 19-20
Type / version	Edge 2.0 EcoBlue Twin-Turbo 4WD Vignale aut
Body type	KOM
Number of doors / seats	5/5
Curb weight [kg]	2043
Gross vehicle weight [kg]	2655
Wheelbase 1/2	2850
Engine type	Automatic ignition
Supercompression	turbocompressor with intercooler
Pollution reduction system	KSC
Emission standard	EURO 6
Engine capacity [ccm]	1997
Engine Power [hp/kW]	238/175
Gearbox	automatic 8- gear
Registration /record No.	FZ0288P
VIN / serial number	2FMTK4V36LBA53026
Date of first registration	12-10-2020
Date of next. tech. test	17-10-2026
Year of manufacture	2020 (year has been verified with the manufacturer's base)
Readout [km]	161 530 (read)
Body color / type of coating	white/double-layered, pearly

Tyres

axle	Wheel	Manufacturer, type	Size	Measured profile
Front	right	FIRESTONE, ROADHAWK	255/45 R20 105W	4,0 mm
	left	FIRESTONE, ROADHAWK	255/45 R20 105W	4,0 mm
back	right	FIRESTONE, ROADHAWK	255/45 R20 105W	3,0 mm
	left	FIRESTONE, ROADHAWK	255/45 R20 105W	3,0 mm

Standard equipment by Eurotax

- | | |
|---|---|
| 1. Accoustic windows | 37. Leather gearshifter/switch |
| 2. Additional gauges | 38. Leather steering wheel |
| 3. Additional heating | 39. Leather upholstery |
| 4. Airbag: other, Driver airbag, Head airbags front, Head airbags rear, Passenger airbag, Side airbag driver and passenger, Side airbags rear | 40. Light Alloy wheels 20" |
| 5. Antilock-Brake-System (ABS) | 41. Luggage compartment cover |
| 6. Automated High-beam assist, Lane control assistant | 42. On board monitor |
| 7. Automatic dimlight activation, Rain sensor, Rear-view mirror autodimming | 43. Other |
| 8. Cargo net | 44. Other |
| 9. Child lock electric | 45. Other |
| 10. Cornering Headlights, Fog lamps | 46. Other |
| 11. Cruise control | 47. Other |
| 12. DAB radio, Navigation system, On board monitor | 48. Park Distance Control front, Park Distance Control rear |
| 13. Diminished spare wheel | 49. Power assisted brakes |
| 14. Distribution of braking force electronically | 50. Power steering |
| 15. Door mirror with memory | 51. Power windows front, Power windows rear |
| 16. Door mirror(s) electrically adjustable in general, Door mirrors electrically foldable, Door mirrors heated, Side indicators | 52. Rain sensor, Windscreenwiper: other |
| 17. Driver seat electrically adjustable | 53. Rear bench foldable in two separate parts |
| 18. Driver seat electrically adjustable | 54. Rear spoiler |
| 19. Dualzone automatic climate control | 55. Rear view camera |
| 20. ESP (Electronical Stabilizing Program) | 56. Rear-view mirror autodimming |
| 21. Electric parking brake | 57. Remote controlled central locking |
| 22. Exterior design: other | 58. Roof railing |
| 23. Extra power outlet | 59. Sport seats front |
| 24. Floor mat | 60. Start/Stop system |
| 25. Headlamp wash nozzle heated, Windscreen heating | 61. Steering wheel heated |
| 26. Headrests front | 62. Steering wheel manually adjustable |
| 27. Heated seat driver, Heated seat passenger | 63. Steering wheel with gear-switches |
| 28. Hill holder | 64. Storage facilities in general |
| 29. Interior lights: other accessories | 65. Tie-down ring |
| 30. Interior: other | 66. Tinted rear windows |
| 31. Interior: other | 67. Traffic sign recognition |
| 32. Intersection Assist, Pre-Crash System | 68. Transmission: other |
| 33. Keyless go | 69. Tyre pressure control (RDC) |
| 34. LED front dim light | 70. Windscreen wash-nozzle heated |
| 35. LED rear lights | 71. Wireless device charging |
| 36. Leather finish dashbord | |

Dealer's equipment (selected items)

- | | |
|--|---|
| 1. 360 view camera, Adaptive Cruise Control, Alarm, Blind spot warning, Park Assistant | - |
| System wspomagający wykonanie manewrów parkowania Active Park Assist | |
| Alarm obwodowy i pojemnościowy | |
| Kamera parkowania z przodu | |
| System monitorowania martwego pola (BLIS) z Cross Traffic Alert, pakiet | |
| Tempomat inteligentny (ACC) Stop&Go | |
| 2. Glass tilt/slide sunroof electric, Interior lights: other accessories | - |
| 3. Headlamp wash | - |
| 4. Metallic paint | - |
| 5. Rear seat heating | - |

6. Ventilated front seat -

Base value of the vehicle

Base value of the vehicle by Eurotax (net) -

CorrectionsFirst registrationMileageEquipmentTyresOther

Earlier repairs -

Necessary repairs -

Braki i uszkodzenia -


Aktualna sytuacja rynkowa -

Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 09-2026 POL) with regard to technical and market parameters affecting the value of the vehicle.

Basic print without information about the vehicle's value - duey to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 01-09-2026

DEKRA's expert:
Kacper Sosnowski (WSP)
mgr inż. Michał Świątek**Document issued electronically valid without signature.**

Measurement of thickness of the vehicle lacquer coating


No. of controlled item	Controlled item	Measured range of thickness of the lacquer coat [μm]
1	Front cover	150 - 300
2	Left front fender	150 - 500
3	Left front pillar	150 - 300
4	Left front wall	150 - 500
6	Left middle pillar	150 - 200
7	Left side sill	150 - 300
8	Left rear wall	150 - 300
9	Left side wall	150 - 300
10	Cover/tailgate	150 - 300
11	Side right wall	150 - 300
12	Rear right door	150 - 300
13	Middle right pillar	150 - 300
14	Front right door	150 - 300
15	Right side sill	150 - 200
16	Right front pillar	150 - 300
17	Right front fender	150 - 300

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

During the inspection the registration proof of the vehicle was presented and its photo was taken and enclosed to the expertise.

During the inspection the service book of the vehicle was not provided.

Information concerning the origin of the vehicle

The vehicle purchased domestically from an authorized representative of the brand.

Additional comments on the car:

Not applicable.

Test drive

Test drive of the vehicle was conducted. Test drive in the full extent is not possible. Comment below:

.

Checking of the correctness and / or construction of identification / serial numbers of the object:

Not tested

Verification of the accuracy of the object data, including year of production, and other.

Not conducted - adopted according to the documents presented and indicated sources.

Anti-theft protection

immobiliser

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.
- The evaluation has been carried out basing on delivered documentation and organoleptic examination of the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the assessed object.
- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

Comments to the commission - regarding valuation**Kluczyki**

TAK

2

Expert comments - regarding valuation

Widoczne ślady użytkowania pojazdu: drobne rysy, odpryski, wgniecenia, zaplamienia. Widoczne ślady napraw lakierniczych elementów nadwozia.

Aktywna kontrolka niesprawności układu sterowania silnikiem. Głośna i nierówna praca silnika, do weryfikacji serwisowej.

Aktywna kontrolka wezwania do serwisu.

Restrictive disclaimer - regarding valuation

- W Ocenie/Raporcie uwzględniono niesprawności, uszkodzenia, braki itp., które były możliwe do stwierdzenia organoleptycznego, w warunkach oględzin (z uwzględnieniem: stanu czystości pojazdu, warunków atmosferycznych, oświetlenia itd.) oraz bez weryfikacji serwisowej, bez dostępu do spodu pojazdu, bez specjalistycznego sprzętu diagnostycznego (w tym bez diagnostyki komputerowej), bez jazdy próbnej wykonanej w warunkach drogowych z obciążeniem.
- W ramach Oceny/Raportu nie weryfikowano odczytanego stanu drogomierza z zapisami w urządzeniach elektronicznych pojazdu.
- Rzeczoznawca nie bierze na siebie odpowiedzialności za wady ukryte (prawne i fizyczne) oraz ewentualne skutki wynikające z dalszego użytkowania przedmiotu oceny, a także za skutki wykorzystania samej oceny.
- Podane przedziały grubości powłoki lakierowej, dotyczą punktów pomiarowych. Nie mogą być traktowane jako gwarancja, że grubość powłoki lakierowej w innych punktach nie wykracza poza te przedziały.
- Zawarte w niniejszej Ocenie/Raporcie informacje (w tym dotyczące wyposażenia) służą jedynie ogólnym celom informacyjnym. Ocena/Raport nie może być zatem traktowana jako oferta w rozumieniu przepisów Kodeksu Cywilnego oraz opisu towaru ani zapewnienia w rozumieniu art. 4 Ustawy z dnia 27 lipca 2002 roku o szczególnych warunkach sprzedaży konsumenckiej.
- Niniejsza Ocena/Raport nie jest szczegółową oceną stanu technicznego.

Ocenę/Raport wykonano w kierunku ujawnienia uszkodzeń nieakceptowanych z punktu widzenia właściwego przewodnika zwrotu pojazdu lub innych ustaleń ze Zleceniodawcą. Tym samym Ocena/Raport może nie ujmować typowych zużyć i uszkodzeń eksploatacyjnych.

PHOTOGRAPHIC DOCUMENTATION



Photo 1.
Przekątna przednia lewa



Photo 2.
Przód

PHOTOGRAPHIC DOCUMENTATION



Photo 3.

Przekątna przednia prawa



Photo 4.

Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 5.
Bok prawy z tyłu



Photo 6.
Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 7.

Tył



Photo 8.

Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 9.

Bok lewy z tyłu



Photo 10.

Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 11.
Próg lewy (widok od przodu)



Photo 12.
Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



Photo 13.
Spód pojazdu przód



Photo 14.
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION



Photo 15.

Tarcza hamulcowa przednia prawa



Photo 16.

Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 17.

Tarcza hamulcowa tylna lewa



Photo 18.

Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 19.
Bagażnik



Photo 20.
Koło zapasowe


PHOTOGRAPHIC DOCUMENTATION



Photo 21.
Komora silnika



Photo 22.
Numer identyfikacyjny

PHOTOGRAPHIC DOCUMENTATION**Photo 23.**

Tabliczka znamionowa

**Photo 24.**

Zestaw wskaźników - przebieg

PHOTOGRAPHIC DOCUMENTATION



Photo 25.

Zestaw wskaźników - serwis



Photo 26.

Widok przez otwarte drzwi przednie lewe

PHOTOGRAPHIC DOCUMENTATION



Photo 27.

Zdjęcie do protokołu



Photo 28.

Kierownica z lewej strony

PHOTOGRAPHIC DOCUMENTATION




Photo 29.

Zdjęcie do protokołu



Photo 30.

Widok przez otwarte drzwi tylne lewe

PHOTOGRAPHIC DOCUMENTATION



Photo 31.

Widok z tylnej kanapy na deskę rozdź.



Photo 32.

Konsola środkowa

PHOTOGRAPHIC DOCUMENTATION



Photo 33.
Zdjęcie do protokołu



Photo 34.
Tunel środkowy

PHOTOGRAPHIC DOCUMENTATION



Photo 35.
Zdjęcie do protokołu



Photo 36.
Kierownica (na wprost)

PHOTOGRAPHIC DOCUMENTATION



Photo 37.

Dowód rej. Str. 1



Photo 38.

Dow. Rej. Str. 2

PHOTOGRAPHIC DOCUMENTATION



Photo 39.

Kluczyki



Photo 40.

Ośłona silnika - ubytki materiału

PHOTOGRAPHIC DOCUMENTATION



Photo 41.

Pokrywa komory silnika - Rysa/odprysk 1



Photo 42.

Szyba czołowa - zdjęcie poglądowe 1

PHOTOGRAPHIC DOCUMENTATION




Photo 43.

Szyba czołowa - Pęknięcie/rozerwanie 1



Photo 44.

Wykładzina pokrywy komory silnika - Pęknięcie/rozerwanie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 45.

Zderzak - Rysa/odprysk 1



Photo 46.

Łotnik przedni P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 47.

Felga aluminiowa przednia P - Rysa/odprysk 1



Photo 48.

Drzwi przednie P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 49.

Błotnik tylny P / Ściana boczna P - zdjęcie pogładowe 1



Photo 50.

Błotnik tylny P / Ściana boczna P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 51.

Felga aluminiowa tylna P - Rysa/odprysk 1



Photo 52.

Pokrywy bagażnika - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 53.

Błotnik tylny L / Ściana boczna L - Wgniecenie/odkształcenie 1



Photo 54.

Felga aluminiowa tylna L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 55.

Lampa tylna zew L - Inne 1



Photo 56.

Drzwi tylna L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 57.

Drzwi tylne L - zdjęcie poglądowe 1



Photo 58.

Drzwi tylne L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 59.
Próg L - Rysa/odprysk 1



Photo 60.
Felga Aluminiowa przednia L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 61.

Koło kierownicy - Rysa/odprysk 1



Photo 62.

Fotel prz. lew. - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 63.

Fotel prz. praw. - Rysa/odprysk 1



Photo 64.

Tapicerka drzwi przednich P - Pęknięcie/rozerwanie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 65.

Osłona p/słoneczna lewa - Inne 1



Photo 66.

Osłona p/słoneczna prawa - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 67.
Podsufitka - Inne 1



Photo 68.
Podsufitka - Inne 2

PHOTOGRAPHIC DOCUMENTATION



Photo 69.

Wykładzina(y) słupka przedniego L - Inne 1



Photo 70.

Wykładzina(y) słupka środkowego L - Rysa/odprysk 1