

DEKRA's commission No. : PKOL(W)/LODZ/19273/25/03/17
commission/ damage No. : FUTURA
Date of commission: 17-03-2025

DEKRA Poland - Headquarters
02-673 Warszawa, ul. Konstruktorska 12A

Client :

PKO Leasing SA
Świętokrzyska 36
00-116 Warszawa

Expert:

Kacper Sosnowski (NEW)
DEKRA Polska - współpraca O/Warszawa
Andrzej Sosnowski
DEKRA Polska - Centrala

NOTE:

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

Vehicle data

Group of objects (Eurotax)	jeeps
EC code (Eurotax)	0116988
Manufacturer	MERCEDES-BENZ
Model	GLS 15-19
Type / version	GLS 350 d 4-Matic
Body type	KOM
Number of doors / seats	5/7
Curb weight [kg]	2540
Gross vehicle weight [kg]	3250
Wheelbase 1/2	3075
Engine type	Automatic ignition
Pollution reduction system	DPF
Engine capacity [ccm]	2987
Engine Power [hp/kW]	258/190
Gearbox	automatic
Registration /record No.	WD3069M
VIN / serial number	WDC1668241B220955
Date of first registration	09-01-2019
Date of next. tech. test	13-01-2026
Year of manufacture	2018 (year has been verified with the manufacturer's base)
Readout [km]	151 152 (read)
Body color / type of coating	black/UNI

Tyres

axle	Wheel	Manufacturer, type	Size	Measured profile
Front	right	GOODYEAR, ULTRAGRIP SUV	275/50 20 113V	7,0 mm
	left	GOODYEAR, ULTRAGRIP SUV	275/50 20 113V	7,0 mm
back	right	GOODYEAR, ULTRAGRIP SUV	275/50 20 113V	7,0 mm
	left	GOODYEAR, ULTRAGRIP SUV	275/50 20 113V	7,0 mm

Standard equipment by Eurotax

- | | |
|---|---|
| 1. 2 single seats rear | 31. Luggage compartment cover |
| 2. Alarm | 32. On board computer |
| 3. Alarm | 33. Other |
| 4. Antilock-Brake-System (ABS) | 34. Other |
| 5. Armrest (s) front, Storage facilities in general | 35. Other |
| 6. Armrest (s) rear | 36. Other |
| 7. Artificial leather upholstery | 37. Other |
| 8. Automatic climate control | 38. Other |
| 9. Bord entertainment: other accessories | 39. Other |
| 10. Bord entertainment: other accessories, Radio preparation | 40. Other |
| 11. CD-player, Radio | 41. Particle filter |
| 12. Child lock manually | 42. Power assisted brakes |
| 13. Child seat fixation | 43. Power steering |
| 14. Door mirror(s) electrically adjustable in general, Door mirrors heated, Side indicators | 44. Power windows front, Power windows rear |
| 15. Driver airbag, Head airbags front, Passenger airbag, Side airbag driver, Side airbag driver and passenger | 45. Pre-Crash System |
| 16. Driver knee airbag | 46. Rain sensor |
| 17. ESP (Electronical Stabilizing Program) | 47. Remote controlled central locking |
| 18. Electric tailgate | 48. Roof railing |
| 19. Exterior design: other | 49. Start/Stop system |
| 20. Glass tilt/slide sunroof electric | 50. Start/Stop system |
| 21. Heat reflecting windows | 51. Steering wheel manually adjustable |
| 22. Hill descent control | 52. Steering wheel with gear-switches |
| 23. Hill holder | 53. Storage facilities in general |
| 24. Hydro pneumatic suspension | 54. Third braking light |
| 25. Interior: other | 55. Traction control |
| 26. Interior: other | 56. Traction control |
| 27. LED Daytime running lights | 57. Uni-Lackierung |
| 28. LED rear lights | 58. Vehicle immobilizer |
| 29. Leather steering wheel, Multi functional steering wheel | 59. Wood finish |
| 30. Light Alloy wheels 18" | |

Dealer's equipment (selected items)

- | | |
|--|---|
| 1. Adaptive light, Automated High-beam assist | - |
| 2. Adaptive light, Automated High-beam assist, Cornering Headlights, LED front dim light | - |
| 3. Air condition rear | - |
| 4. Automatic climate control | - |
| 5. Blind spot warning, Brake Assist, Distance control, Lane control assistant, Pre-Crash System, Steering: other | - |
| Aktywny asystent martwego punktu | |
| Aktywny asystent utrzymania pasa ruchu | |
| BAS PLUS z asystentem skrzyżowań - asystent układu hamulcowego | |
| DISTRONIC PLUS (system kontroli odległości od poprzedzającego pojazdu) | |
| System PRE-SAFE PLUS | |
| Asystent układu kierowniczego | |
| Asystent skrzyżowań | |
| System PRE-SAFE PLUS | |
| Hamulce PRE-SAFE | |
| 6. Bord communication: other | - |
| Carplay | |
| Android Auto | |
| Apple CarPlay | |
| 7. Bord communication: other, Other | - |

- 8. Bord communication: other, Other -
- 9. Door mirrors autodimming, Door mirrors electrically foldable, Rear-view mirror
autodimming -
- Lusterko po stronie kierowcy oraz wsteczne automatycznie przyciemniające się
- Lusterka boczne składane elektrycznie
- Oświetlenie wnętrza Ambient z logo Mercedes
- 10. Head-Up Display -
- 11. Heated seat driver, Heated seat passenger -
- 12. Interior: other -
- 13. Light Alloy wheels 20" -
- 14. On board monitor -
- 15. Other -
- 16. Other -
- 17. Park Assistant, Park Distance Control front, Park Distance Control rear -
- 18. Rear bench/seats foldable -
- 19. Rear seat heating -
- 20. Rear view camera -
- 21. Selectable driveline characteristics -
- 22. Side airbags rear -
- 23. Telematic -
- 24. Tinted rear windows -
- 25. Tyre pressure control (RDC) -

Base value of the vehicle

Base value of the vehicle by Eurotax (net) -

Corrections

First registration

Mileage

Equipment

Tyres

Other

Uszkodzenia, stan -


Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 03-2025 POL) with regard to technical and market parameters affecting the value of the vehicle.

Basic print without information about the vehicle's value - due to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 24-03-2025

DEKRA's expert:
Kacper Sosnowski (NEW)
Andrzej Sosnowski

Document issued electronically valid without signature.

Measurement of thickness of the vehicle lacquer coating


No. of controlled item	Controlled item	Measured range of thickness of the lacquer coat [μm]
1	Front cover	to 150
2	Left front fender	to 150
3	Left front pillar	to 150
4	Left front wall	to 150
5	Roof	to 150
6	Left middle pillar	to 150
7	Left side sill	to 150
8	Left rear wall	to 150
9	Left side wall	to 150
10	Cover/tailgate	to 150
11	Side right wall	to 150
12	Rear right door	to 150
13	Middle right pillar	to 150
14	Front right door	to 150
15	Right side sill	to 150
16	Right front pillar	to 150
17	Right front fender	to 150

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

During the inspection the registration proof of the vehicle was presented and its photo was taken and enclosed to the expertise.

During the inspection the service book was presented and its number is given below:
elektroniczna

Information concerning the origin of the vehicle

Lack of reliable data.

Additional comments on the car:

Not applicable.

Test drive

Test drive of the vehicle was conducted. Test drive in the full extent is not possible. Comment below:
ograniczenia placowe

Checking of the correctness and / or construction of identification / serial numbers of the object:

Not tested

Verification of the accuracy of the object data, including year of production, and other.

Not conducted - adopted according to the documents presented and indicated sources.

Anti-theft protection

fabryczne

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.
- The evaluation has been carried out basing on delivered documentation and organoleptic examination of the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the assessed object.
- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

Comments to the commission - regarding valuation**Kluczyki**

TAK

2

Expert comments - regarding valuation

Rysy na samochodzie.

Rzecznik dokonał oględzin pojazdu w warunkach parkingowych, co mogło ograniczyć pełną ocenę jego stanu technicznego. Dodatkowo, jeżeli jazda próbna została przeprowadzona (informacje w treści raportu), to wykonano ją w warunkach parkingowych, z niewielką prędkością, co może nie odzwierciedlać pełnych warunków eksploatacyjnych. Istnieje możliwość, że w innych okolicznościach ujawnią się dodatkowe uszkodzenia lub usterki, których nie można było wykryć podczas obecnych oględzin. Zalecamy zatem skorzystanie z możliwości oględzin pojazdu we własnym zakresie lub w Autoryzowanej Stacji Obsługi danej marki, co pozwoli na pełniejszą weryfikację stanu technicznego pojazdu przed udziałem w aukcji."

Restrictive disclaimer - regarding valuation

Nie weryfikowano szczegółowo stanu układu napędowego, zawieszenia, kierowniczego, hamulcowego oraz wydechowego. Ocena została wykonana bez użycia podnośnika i specjalistycznego sprzętu diagnostycznego, nie dokonywano demontażu osłon i innych elementów. Ocena określa ogólny stan pojazdu na dzień oględzin w miejscu jego udostępnienia, nie może być zatem traktowana jako kompleksowa ocena stanu technicznego. Specyfikacja wg. programu operacyjnego w zakresie wyposażenia standardowego i dodatkowego nie gwarantuje zgodności ze stanem faktycznym w zakresie możliwym do ustalenia przez rzeczoznawcę podczas oględzin pojazdu. Pomiar grubości powłoki lakierowej wykonano w miejscach możliwych do ich wykonania pomiary nie gwarantują oryginalności poszczególnych elementów poddanych ocenie.

- W Ocenie/Raporcie uwzględniono niesprawności, uszkodzenia, braki itp., które były możliwe do stwierdzenia organoleptycznego, w warunkach oględzin (z uwzględnieniem: stanu czystości pojazdu, warunków atmosferycznych, oświetlenia itd.) oraz bez weryfikacji serwisowej, bez dostępu do spodu pojazdu, bez specjalistycznego sprzętu diagnostycznego (w tym bez diagnostyki komputerowej), bez jazdy próbnej wykonanej w warunkach drogowych z obciążeniem.
- W ramach Oceny/Raportu nie weryfikowano odczytanego stanu drogomierza z zapisami w urządzeniach elektronicznych pojazdu.
- Rzecznik nie bierze na siebie odpowiedzialności za wady ukryte (prawne i fizyczne) oraz ewentualne skutki wynikające z dalszego użytkowania przedmiotu oceny, a także za skutki wykorzystania samej oceny.
- Podane przedziały grubości powłoki lakierowej, dotyczą punktów pomiarowych. Nie mogą być traktowane jako gwarancja, że grubość powłoki lakierowej w innych punktach nie wykracza poza te przedziały.
- Zawarte w niniejszej Ocenie/Raporcie informacje (w tym dotyczące wyposażenia) służą jedynie ogólnym celom informacyjnym. Ocena/Raport nie może być zatem traktowana jako oferta w rozumieniu przepisów Kodeksu Cywilnego oraz opisu towaru ani zapewnienia w rozumieniu art. 4 Ustawy z dnia 27 lipca 2002 roku o szczególnych warunkach sprzedaży konsumenckiej.
- Niniejsza Ocena/Raport nie jest szczegółową oceną stanu technicznego.

Ocenę/Raport wykonano w kierunku ujawnienia uszkodzeń nieakceptowanych z punktu widzenia właściwego przewodnika zwrotu pojazdu lub innych ustaleń ze Zleceniodawcą. Tym samym Ocena/Raport może nie ujmować typowych zużyć i uszkodzeń eksploatacyjnych.

PHOTOGRAPHIC DOCUMENTATION



Photo 1.

Przekątna przednia lewa



Photo 2.

Przód

PHOTOGRAPHIC DOCUMENTATION



Photo 3.

Przekątna przednia prawa



Photo 4.

Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 5.

Bok prawy z tyłu



Photo 6.

Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 7.

Tył



Photo 8.

Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 9.

Bok lewy z tyłu



Photo 10.

Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 11.

Próg lewy (widok od przodu)



Photo 12.

Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



Photo 13.
Spód pojazdu przód



Photo 14.
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION



Photo 15.

Tarcza hamulcowa przednia prawa



Photo 16.

Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 17.

Tarcza hamulcowa tylna lewa



Photo 18.

Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 19.
Bagażnik



Photo 20.
Koło zapasowe

PHOTOGRAPHIC DOCUMENTATION



Photo 21.
Komora silnika



Photo 22.
Numer identyfikacyjny

PHOTOGRAPHIC DOCUMENTATION



Photo 23.

Tabliczka znamionowa



Photo 24.

Zestaw wskaźników - przebieg

PHOTOGRAPHIC DOCUMENTATION



Photo 25.

Widok przez otwarte drzwi przednie lewe



Photo 26.

Kierownica z lewej strony

PHOTOGRAPHIC DOCUMENTATION



Photo 27.

Widok przez otwarte drzwi tylne lewe



Photo 28.

Widok z tylnej kanapy na deskę rozd.

PHOTOGRAPHIC DOCUMENTATION



Photo 29.
Konsola środkowa



Photo 30.
Tunel środkowy

A detailed view of the front interior of a Mercedes-Benz S-Class (W223). The steering wheel is black with a perforated leather-like texture and features the Mercedes-Benz star emblem in the center. Behind the steering wheel is the instrument cluster, which includes two large analog dials for speed and engine RPM, and a central digital display showing navigation and vehicle information. To the right of the steering wheel is a large, high-resolution touchscreen display for the infotainment system, showing various menu icons. Below the screen is a control panel with physical buttons and a rotary knob. The center console and door panels are finished with light-colored wood trim. The overall design is modern and luxurious.

[illegible]

DEKRA Polska Sp. z o.o.
02-673 Warszawa, ul. Konstruktorska 12A
www.dekra.pl

PHOTOGRAPHIC DOCUMENTATION



Photo 33.

Dow. Rej. Str.2 i klucze



Photo 34.

Książka serwisowa – dane

PHOTOGRAPHIC DOCUMENTATION



Photo 35.

Książka serwisowa – ostatni przegląd



Photo 36.

Instrukcje

PHOTOGRAPHIC DOCUMENTATION



Photo 37.

Zestaw naprawczy koła



Photo 38.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 39.

Zdjęcie do protokołu



Photo 40.

Atrapa przednia - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 41.

Pokrywa komory silnika - Rysa/odprysk 1



Photo 42.

Pokrywa komory silnika - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 43.

Szyba czołowa - zdjęcie poglądowe 1




Photo 44.

Szyba czołowa - Pęknięcie/rozerwanie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 45.

Zderzak - Rysa/odprysk 1



Photo 46.

Felga aluminiowa przednia P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 47.

Drzwi przednie P - Rysa/odprysk 1



Photo 48.

Drzwi przednie P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 49.

Drzwi tylne P - zdjęcie poglądowe 1



Photo 50.

Drzwi tylne P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 51.

Drzwi tylne P - Inne 1




Photo 52.

Łotnik tylny P / Ściana boczna P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 53.

Lampa tylna zew P - Inne 1



Photo 54.

Listwa śr zderzaka tylnego - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 55.

Pokrywy bagażnika - Wgniecenie/odkształcenie 1



Photo 56.

Zderzak tylny - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 57.

Błotnik tylny L / Ściana boczna L - Rysa/odprysk 1




Photo 58.

Błotnik tylny L / Ściana boczna L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 59.

Lampa tylna zew L - Inne 1



Photo 60.

Drzwi przed L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 61.

Drzwi tylne L - Rysa/odprysk 1



Photo 62.

Drzwi tylne L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 63.

Próg L - Wgniecenie/odkształcenie 1



Photo 64.

Słupek środkowy L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 65.

Felga Aluminiowa przednia L - Rysa/odprysk 1



Photo 66.

Fotel prz. lew. - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 67.

Fotel prz. praw. - Pęknięcie/rozerwanie 1



Photo 68.

Osłona p/słoneczna lewa - Inne 1