

DEKRA's commission No. : PKOL(W)/LODZ/67179/25/09/09  
commission/ damage No. : 23/003740  
Date of commission: 09-09-2025

**DEKRA Poland - Headquarters**  
02-673 Warszawa, ul. Konstruktorska 12A

**Client :**

PKO Leasing SA  
Świętokrzyska 36  
00-116 Warszawa

**Expert:**

**Kacper Sosnowski (NEW)**  
DEKRA Polska - współpraca O/Warszawa  
**Andrzej Sosnowski**  
DEKRA Polska - Centrala

**NOTE:**

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

**Vehicle data**

|                              |                                                            |
|------------------------------|------------------------------------------------------------|
| Group of objects (Eurotax)   | jeeps                                                      |
| EC code (Eurotax)            | 0148413                                                    |
| Manufacturer                 | AUDI                                                       |
| Model                        | Q7 19-24                                                   |
| Type / version               | Q7 55 TFSI mHEV Quattro Tiptr.                             |
| Body type                    | KOM                                                        |
| Number of doors / seats      | 5/5                                                        |
| Curb weight [kg]             | 2151                                                       |
| Gross vehicle weight [kg]    | 2830                                                       |
| Wheelbase 1/2                | 2995                                                       |
| Engine type                  | spark ignition                                             |
| Pollution reduction system   | three-way catalytic converter                              |
| Engine capacity [ccm]        | 2995                                                       |
| Engine Power [hp/kW]         | 340/250                                                    |
| Gearbox                      | automatic 8- gear                                          |
| Registration /record No.     | SK693XJ                                                    |
| VIN / serial number          | WAUZZZ4M0PD007304                                          |
| Date of first registration   | 02-03-2023                                                 |
| Date of next. tech. test     | 02-03-2026                                                 |
| Year of manufacture          | 2022 (year has been verified with the manufacturer's base) |
| Readout [km]                 | 80 142 (read)                                              |
| Body color / type of coating | granatowy/double-layered, metallized                       |

**Tyres**

| axle  | Wheel | Manufacturer, type                  | Size           | Measured profile |
|-------|-------|-------------------------------------|----------------|------------------|
| Front | right | GOODYEAR, ULTRAGRIP PERFORMANCE SUV | 225/55 19 111H | 5,5 mm           |
|       | left  | GOODYEAR, ULTRAGRIP PERFORMANCE SUV | 225/55 19 111H | 5,5 mm           |
| back  | right | GOODYEAR, ULTRAGRIP PERFORMANCE SUV | 225/55 19 111H | 5,0 mm           |
|       | left  | GOODYEAR, ULTRAGRIP PERFORMANCE SUV | 225/55 19 111H | 5,0 mm           |

Standard equipment by Eurotax

- |                                                                                              |                                                    |
|----------------------------------------------------------------------------------------------|----------------------------------------------------|
| 1. Additional gauges, Park Distance Control front, Park Distance Control rear                | 35. LED Daytime running lights                     |
| 2. Alarm                                                                                     | 36. LED rear lights                                |
| 3. All wheel drive in general, Limited slip differential: other                              | 37. Leather upholstery                             |
| 4. Antilock-Brake-System (ABS)                                                               | 38. Light Alloy wheels 18"                         |
| 5. Armrest (s) front                                                                         | 39. Metal finish                                   |
| 6. Audi music interface                                                                      | 40. Mirror: others                                 |
| 7. Automatic climate control                                                                 | 41. Mobile Tire System                             |
| 8. Bez układu zmywania reflektorów                                                           | 42. On board computer, On board monitor            |
| 9. Bluetooth interface                                                                       | 43. Other                                          |
| 10. Child seat fixation                                                                      | 44. Other                                          |
| 11. Cruise control                                                                           | 45. Other                                          |
| 12. Door mirror with memory                                                                  | 46. Other                                          |
| 13. Door mirror(s) electrically adjustable in general                                        | 47. Oświetlenie wnętrza                            |
| 14. Door mirrors electrically foldable, Door mirrors heated                                  | 48. Passive Tyre pressure control                  |
| 15. Driver airbag, Passenger airbag                                                          | 49. Podparcia odcinka lędźwiowego kręgosłupa       |
| 16. Driver seat electrically adjustable, Memory seat, Passenger seat electrically adjustable | 50. Pre-Crash System                               |
| 17. Driver seat height adjustable, Passenger seat height adjustable                          | 51. Rear bench foldable in two separate parts      |
| 18. ESP (Electronical Stabilizing Program)                                                   | 52. Rear seat-backs foldable in two separate parts |
| 19. Electric parking brake                                                                   | 53. Rear-view mirror autodimming                   |
| 20. Electric tailgate                                                                        | 54. Reflektory podstawowe                          |
| 21. Elektroniczna blokada prędkości maksymalnej                                              | 55. Roof railing                                   |
| 22. Elektryczna nagrzewnica powietrza                                                        | 56. Selectable driveline characteristics           |
| 23. Exterior design: other                                                                   | 57. Servotronic                                    |
| 24. Exterior design: other                                                                   | 58. Soundsystem                                    |
| 25. Exterior design: other                                                                   | 59. Start/Stop system                              |
| 26. Floor mat                                                                                | 60. Steering wheel manually adjustable             |
| 27. Full Cabin Spoiler                                                                       | 61. Szyba przednia termoizolacyjna                 |
| 28. Górna część deski rozdzielczej ze szwem kontrastowym                                     | 62. Uni-Lackierung                                 |
| 29. Hamulce tarczowe z przodu (18")                                                          | 63. Wariant dla niepalących                        |
| 30. Hamulce tarczowe z tyłu (17")                                                            | 64. Wykończenie podłogi bagażnika wykładziną       |
| 31. Head airbags rear, Side airbag driver and passenger                                      | 65. Zagłówki z przodu                              |
| 32. Heat reflecting windows                                                                  | 66. Zawieszenie standardowe                        |
| 33. Hill holder                                                                              | 67. Zestaw wskaźników                              |
| 34. Kamera cofania                                                                           |                                                    |

Dealer's equipment (selected items)

- |                                   |   |
|-----------------------------------|---|
| 1. Armrest (s) front, Other ..... | - |
| 2. Body-coloured bumpers .....    | - |
| 3. Exterior design: other .....   | - |
| 4. Metallic paint .....           | - |
| 5. Roof railing .....             | - |
| 6. Towbar .....                   | - |

**Base value of the vehicle**

Base value of the vehicle by Eurotax (net) ..... -

## **Corrections**

First registration

Mileage

Equipment

Tyres

Other

Uszkodzenia, stan ..... -


Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 09-2025 POL) with regard to technical and market parameters affecting the value of the vehicle.

Basic print without information about the vehicle's value - duey to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 15-09-2025

DEKRA's expert:  
Kacper Sosnowski (NEW)  
Andrzej Sosnowski

**Document issued electronically valid without signature.**

Measurement of thickness of the vehicle lacquer coating


| No. of controlled item | Controlled item     | Measured range of thickness of the lacquer coat [ $\mu\text{m}$ ] |
|------------------------|---------------------|-------------------------------------------------------------------|
| 1                      | Front cover         | to 150                                                            |
| 2                      | Left front fender   | to 150                                                            |
| 3                      | Left front pillar   | to 150                                                            |
| 4                      | Left front wall     | to 150                                                            |
| 5                      | Roof                | to 150                                                            |
| 6                      | Left middle pillar  | to 150                                                            |
| 7                      | Left side sill      | to 150                                                            |
| 8                      | Left rear wall      | to 150                                                            |
| 9                      | Left side wall      | to 150                                                            |
| 10                     | Cover/tailgate      | to 150                                                            |
| 11                     | Side right wall     | to 150                                                            |
| 12                     | Rear right door     | to 150                                                            |
| 13                     | Middle right pillar | to 150                                                            |
| 14                     | Front right door    | to 150                                                            |
| 15                     | Right side sill     | to 150                                                            |
| 16                     | Right front pillar  | to 150                                                            |
| 17                     | Right front fender  | to 150                                                            |

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

During the inspection the registration proof of the vehicle was presented and its photo was taken and enclosed to the expertise.

During the inspection the service book was presented and its number is given below:  
elektroniczna

**Information concerning the origin of the vehicle**

Lack of reliable data.

**Additional comments on the car:**

Not applicable.

**Test drive**

Test drive of the vehicle was conducted. Test drive in the full extent is not possible. Comment below:  
ograniczenia placowe

**Checking of the correctness and / or construction of identification / serial numbers of the object:**

Not tested

**Verification of the accuracy of the object data, including year of production, and other.**

Not conducted - adopted according to the documents presented and indicated sources.

**Anti-theft protection**

fabryczne

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.
- The evaluation has been carried out basing on delivered documentation and organoleptic examination of the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the assessed object.
- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

Comments to the commission - regarding valuation**Kluczyki**

TAK

2

Expert comments - regarding valuation

Pojazd posiada hak. Rysy na samochodzie.

Rzeczoznawca dokonał oględzin pojazdu w warunkach parkingowych, co mogło ograniczyć pełną ocenę jego stanu technicznego. Dodatkowo, jeżeli jazda próbna została przeprowadzona (informacje w treści raportu), to wykonano ją w warunkach parkingowych, z niewielką prędkością, co może nie odzwierciedlać pełnych warunków eksploatacyjnych. Istnieje możliwość, że w innych okolicznościach ujawnią się dodatkowe uszkodzenia lub usterki, których nie można było wykryć podczas obecnych oględzin. Zalecamy zatem skorzystanie z możliwości oględzin pojazdu we własnym zakresie lub w Autoryzowanej Stacji Obsługi danej marki, co pozwoli na pełniejszą weryfikację stanu technicznego pojazdu przed udziałem w aukcji."

Restrictive disclaimer - regarding valuation

Nie weryfikowano szczegółowo stanu układu napędowego, zawieszenia, kierowniczego, hamulcowego oraz wydechowego. Ocena została wykonana bez użycia podnośnika i specjalistycznego sprzętu diagnostycznego, nie dokonywano demontażu osłon i innych elementów. Ocena określa ogólny stan pojazdu na dzień oględzin w miejscu jego udostępnienia, nie może być zatem traktowana jako kompleksowa ocena stanu technicznego. Specyfikacja wg. programu operacyjnego w zakresie wyposażenia standardowego i dodatkowego nie gwarantuje zgodności ze stanem faktycznym w zakresie możliwym do ustalenia przez rzeczoznawcę podczas oględzin pojazdu. Pomiar grubości powłoki lakierowej wykonano w miejscach możliwych do ich wykonania pomiary nie gwarantują oryginalności poszczególnych elementów poddanych ocenie.

- W Ocenie/Raporcie uwzględniono niesprawności, uszkodzenia, braki itp., które były możliwe do stwierdzenia organoleptycznego, w warunkach oględzin (z uwzględnieniem: stanu czystości pojazdu, warunków atmosferycznych, oświetlenia itd.) oraz bez weryfikacji serwisowej, bez dostępu do spodu pojazdu, bez specjalistycznego sprzętu diagnostycznego (w tym bez diagnostyki komputerowej), bez jazdy próbnej wykonanej w warunkach drogowych z obciążeniem.
- W ramach Oceny/Raportu nie weryfikowano odczytanego stanu drogomierza z zapisami w urządzeniach elektronicznych pojazdu.
- Rzeczoznawca nie bierze na siebie odpowiedzialności za wady ukryte (prawne i fizyczne) oraz ewentualne skutki wynikające z dalszego użytkowania przedmiotu oceny, a także za skutki wykorzystania samej oceny.
- Podane przedziały grubości powłoki lakierowej, dotyczą punktów pomiarowych. Nie mogą być traktowane jako gwarancja, że grubość powłoki lakierowej w innych punktach nie wykracza poza te przedziały.
- Zawarte w niniejszej Ocenie/Raporcie informacje (w tym dotyczące wyposażenia) służą jedynie ogólnym celom informacyjnym. Ocena/Raport nie może być zatem traktowana jako oferta w rozumieniu przepisów Kodeksu Cywilnego oraz opisu towaru ani zapewnienia w rozumieniu art. 4 Ustawy z dnia 27 lipca 2002 roku o szczególnych warunkach sprzedaży konsumenckiej.
- Niniejsza Ocena/Raport nie jest szczegółową oceną stanu technicznego.

Ocenę/Raport wykonano w kierunku ujawnienia uszkodzeń nieakceptowanych z punktu widzenia właściwego przewodnika zwrotu pojazdu lub innych ustaleń ze Zleceniodawcą. Tym samym Ocena/Raport może nie ujmować typowych zużyć i uszkodzeń eksploatacyjnych.

PHOTOGRAPHIC DOCUMENTATION



**Photo 1.**  
Przekątna przednia lewa



**Photo 2.**  
Przód

PHOTOGRAPHIC DOCUMENTATION



**Photo 3.**

Przekątna przednia prawa



**Photo 4.**

Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



**Photo 5.**  
Bok prawy z tyłu



**Photo 6.**  
Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



**Photo 7.**

Tył



**Photo 8.**

Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



**Photo 9.**

Bok lewy z tyłu



**Photo 10.**

Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



**Photo 11.**

Próg lewy (widok od przodu)



**Photo 12.**

Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



**Photo 13.**  
Spód pojazdu przód



**Photo 14.**  
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION



**Photo 15.**

Tarcza hamulcowa przednia prawa



**Photo 16.**

Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION



**Photo 17.**

Tarcza hamulcowa tylna lewa



**Photo 18.**

Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



**Photo 19.**  
Bagażnik



**Photo 20.**  
Koło zapasowe

PHOTOGRAPHIC DOCUMENTATION



**Photo 21.**  
Komora silnika



**Photo 22.**  
Numer identyfikacyjny

PHOTOGRAPHIC DOCUMENTATION



**Photo 23.**  
Tabliczka znamionowa



**Photo 24.**  
Zestaw wskaźników - przebieg

PHOTOGRAPHIC DOCUMENTATION



**Photo 25.**

Widok przez otwarte drzwi przednie lewe



**Photo 26.**

Kierownica z lewej strony

PHOTOGRAPHIC DOCUMENTATION



**Photo 27.**

Widok przez otwarte drzwi tylne lewe



**Photo 28.**

Widok z tylnej kanapy na deskę rozd.

PHOTOGRAPHIC DOCUMENTATION



**Photo 29.**  
Konsola środkowa



**Photo 30.**  
Tunel środkowy

## PHOTOGRAPHIC DOCUMENTATION



Photo 31.

Kierownica (na wprost)




Photo 32.

Dowód rej. Str. 1

PHOTOGRAPHIC DOCUMENTATION**Photo 33.**

Dow. Rej. Str.2 i klucze

**Photo 34.**

Książka serwisowa – dane

PHOTOGRAPHIC DOCUMENTATION



**Photo 35.**

Książka serwisowa – ostatni przegląd



**Photo 36.**

Instrukcje

PHOTOGRAPHIC DOCUMENTATION



**Photo 37.**  
Zestaw naprawczy koła



**Photo 38.**  
Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



**Photo 39.**

Listwa śr zderzaka przedniego - Pęknięcie/rozerwanie 1



**Photo 40.**

Pokrywa komory silnika - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 41.**

Spoiler zderzaka przedniego - Rysa/odprysk 1



**Photo 42.**

Zderzak - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 43.**

Błotnik przedni P - Wgniecenie/odkształcenie 1



**Photo 44.**

Drzwi tylne P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 45.**

Drzwi tylne P - Rysa/odprysk 2



**Photo 46.**

Listwa drzwi przednich P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 47.**

Listwa drzwi tylnych P - Rysa/odprysk 1



**Photo 48.**

Zderzak tylny - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 49.**

Błotnik tylny L / Ściana boczna L - Rysa/odprysk 1



**Photo 50.**

Drzwi przed L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 51.**

Drzwi tylne L - Rysa/odprysk 1



**Photo 52.**

Listwa drzwi przednich L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 53.**

Listwa drzwi tylnych L - Rysa/odprysk 1



**Photo 54.**

Uszczelka drzwi tylnych P - Pęknięcie/rozerwanie 1