

DEKRA's commission No. : PKOL(W)/LODZ/61020/25/08/19
commission/ damage No. : 24/056115
Date of commission: 19-08-2025

DEKRA Poland - Headquarters
02-673 Warszawa, ul. Konstruktorska 12A

Client :

PKO Leasing SA
Świętokrzyska 36
00-116 Warszawa

Expert:

Kacper Sosnowski (NEW)
DEKRA Polska - współpraca O/Warszawa
Andrzej Sosnowski
DEKRA Polska - Centrala

NOTE:

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

Vehicle data

Group of objects (Eurotax)	jeeps
EC code (Eurotax)	0145899
Manufacturer	CUPRA
Model	Formentor 20-24
Type / version	Formentor 2.0 TSI 4Drive VZ DSG
Body type	hatchback
Number of doors / seats	5/5
Curb weight [kg]	1591
Gross vehicle weight [kg]	2130
Wheelbase 1/2	2680
Engine type	spark ignition
Pollution reduction system	GPF
Engine capacity [ccm]	1984
Engine Power [hp/kW]	310/228
Gearbox	automatic
Registration /record No.	GD6S303
VIN / serial number	VSSZZZKM1RR038006
Date of first registration	21-12-2023
Date of next. tech. test	21-12-2026
Year of manufacture	2023
Readout [km]	35 475 (read)
Body color / type of coating	black/double-layered, metallized

Tyres

axle	Wheel	Manufacturer, type	Size	Measured profile
Front	right	PIRELLI, CINTURATO ALL SEASON SF3	245/40 19 98Y	4,5 mm
	left	PIRELLI, CINTURATO ALL SEASON SF3	245/40 19 98Y	4,5 mm
back	right	PIRELLI, CINTURATO ALL SEASON SF3	245/40 19 98Y	5,0 mm
	left	PIRELLI, CINTURATO ALL SEASON SF3	245/40 19 98Y	5,0 mm

Standard equipment by Eurotax

- | | |
|--|---|
| <ol style="list-style-type: none"> 1. Active Tyre pressure control 2. Adaptive Cruise Control 3. Adjustable suspension 4. Airbag: other 5. Android Auto, Apple CarPlay, Other 6. Antilock-Brake-System (ABS) 7. Armrest (s) front, Storage facilities in general 8. Armrest (s) rear 9. Artificial leather upholstery, Textile upholstery 10. Automated High-beam assist 11. Automatic dimlight activation 12. Automatic limited slip differential 13. Automatic limited slip differential 14. Blind spot warning 15. Bluetooth interface 16. Bord communication: other, Hands-free system, mp3 Player, Navigation system, On board monitor, Radio, USB in, Voice control for navigation system 17. Brake Assist 18. CUPRA CARE - 5 lat gwarancji CUPRA 19. Child seat fixation 20. Child seat fixation 21. Cornering Headlights, Fog lamps 22. DAB radio 23. Diminished spare wheel 24. Distance control 25. Door mirror(s) electrically adjustable in general, Door mirrors electrically foldable, Door mirrors heated 26. Driver airbag, Driver knee airbag, Head airbags front, Passenger airbag, Side airbag driver and passenger 27. Driver conditioning monitoring 28. Driver seat height adjustable, Lumbar adjust driver, Lumbar adjust passenger, Passenger seat height adjustable 29. Dywaniki welurowe z przodu i z tyłu 30. ESP (Electronical Stabilizing Program) 31. Electric parking brake 32. Exterior design: other 33. Exterior design: other 34. Exterior design: other 35. Exterior design: other 36. Exterior design: other 37. Exterior design: other 38. Exterior design: other 39. Exterior design: other 40. Exterior design: other, Roof railing 41. Extra power outlet 42. Extra power outlet 43. Follow me home 44. Funkcja automatyczna opóźnionego wyłączenia świateł Coming and Leaving Home | <ol style="list-style-type: none"> 50. Interior lights: other accessories 51. Interior lights: other accessories 52. Interior lights: other accessories 53. Interior lights: other accessories 54. Interior: other 55. Interior: other 56. Keyless Engine start, Multi functional steering wheel, Sports steering wheel, Steering wheel heated 57. Keyless go 58. LED Daytime running lights 59. LED front dim light 60. LED rear lights, Side indicators 61. Light Alloy wheels 19'' 62. Luggage: other 63. Mirror: others 64. Moulded sport seats 65. Nakładki na pedały, sportowe w kolorze srebrnego aluminium 66. On board monitor 67. Other 68. Other 69. Other 70. Other 71. Other 72. Other 73. Other 74. Other 75. Oświetlenie drzwi LED 76. Park Assistant, Park Distance Control front, Park Distance Control rear 77. Power windows front, Power windows rear 78. Półka na dokumenty pod fotelem kierowcy 79. Quick charging function, Storage facilities in general 80. Rain sensor 81. Rear seat-backs foldable in two separate parts 82. Rear spoiler 83. Rear view camera 84. Rear-view mirror autodimming 85. Seats: other 86. Selectable driveline characteristics 87. Servotronic 88. Speed limiter 89. Steering wheel with gear-switches 90. Storage facilities in general 91. Traction control 92. Traffic jam assist 93. Traffic sign recognition |
|--|---|

- | | |
|---|--|
| 45. Hamulce tarczowe z czarnymi zaciskami z napisem CUPRA | 94. Trizone automatic climate control |
| 46. Heated seat driver, Heated seat passenger | 95. Uni-Lackierung |
| 47. Interior decoration: other | 96. Zamek centralny ze zdalnym sterowaniem, dwa składane kluczyki, otwieranie drzwi bagażnika z pilota |
| 48. Interior lights: other accessories | 97. Zderzaki dedykowane CUPRA VZ |
| 49. Interior lights: other accessories | 98. {Asystent aktywnego utrzymywania pasa ruchu Lane Assist Plus} |

Dealer's equipment (selected items)

- | | |
|---|---|
| 1. 360 view camera | - |
| 2. Cornering Headlights, Follow me home, LED Daytime running lights, LED Fog Lamps, LED front dim light, LED rear lights, Side indicators | - |
| Funkcja opóźnionego wyłączenia świateł „Coming and Leaving Home” | |
| Światła do jazdy dziennej LED | |
| Oświetlenie powitalne LED w lusterkach bocznych | |
| Światła przeciwmgielne LED z funkcją doświetlania zakrętów | |
| Funkcja świateł autostradowych | |
| Lampy przednie Matrix LED z automatyczną regulacją natężenia | |
| Lampy tylne LED zintegrowane z dynamicznymi kierunkowskazami | |
| Funkcja automatyczna opóźnionego wyłączenia świateł Coming and Leaving Home | |
| 3. Door mirror with memory, Driver seat electrically adjustable, Moulded sport seats | - |
| Fotele przednie kubelkowe | |
| Tapicerka materiałowa z ekoskórą z przeszyciem w kolorze miedzi | |
| Fotel kierowcy z pełną regulacją elektryczną oraz pamięcią ustawień | |
| Lusterka z pamięcią ustawień | |
| 4. Light Alloy wheels 19” | - |
| 5. Metallic paint | - |

Base value of the vehicle

Base value of the vehicle by Eurotax (net) -

Corrections

First registration

Equipment

Tyres

Other

Current market situation	-
Uszkodzenia, stan	-


Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 08-2025 POL) with regard to technical and market parameters affecting the value of the vehicle.

Basic print without information about the vehicle's value - duey to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 25-08-2025

DEKRA's expert:
Kacper Sosnowski (NEW)
Andrzej Sosnowski

Document issued electronically valid without signature.

Measurement of thickness of the vehicle lacquer coating


No. of controlled item	Controlled item	Measured range of thickness of the lacquer coat [μm]
1	Front cover	to 150
2	Left front fender	to 150
3	Left front pillar	to 150
4	Left front wall	to 150
5	Roof	to 150
6	Left middle pillar	to 150
7	Left side sill	to 150
8	Left rear wall	to 150
9	Left side wall	to 150
10	Cover/tailgate	to 150
11	Side right wall	to 150
12	Rear right door	to 150
13	Middle right pillar	to 150
14	Front right door	to 150
15	Right side sill	to 150
16	Right front pillar	to 150
17	Right front fender	to 150

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

Presented the following documents of the vehicle:

- ksero pozwolenia czasowego,

During the inspection the service book was presented and its number is given below:
elektroniczna

Information concerning the origin of the vehicle

Lack of reliable data.

Additional comments on the car:

Not applicable.

Test drive

Test drive of the vehicle was conducted. Test drive in the full extent is not possible. Comment below:
ograniczenia placowe

Checking of the correctness and / or construction of identification / serial numbers of the object:

Not tested

Verification of the accuracy of the object data, including year of production, and other.

Not conducted - adopted according to the documents presented and indicated sources.

Anti-theft protection

fabryczne

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.
- The evaluation has been carried out basing on delivered documentation and organoleptic examination of the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the assessed object.
- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

Comments to the commission - regarding valuation**Kluczyki**

TAK

2

Expert comments - regarding valuation

Dostarczono ksero pozwolenia czasowego. Rysy na samochodzie. Odpryski na szybie czołowej.

Rzeczoznawca dokonał oględzin pojazdu w warunkach parkingowych, co mogło ograniczyć pełną ocenę jego stanu technicznego. Dodatkowo, jeżeli jazda próbna została przeprowadzona (informacje w treści raportu), to wykonano ją w warunkach parkingowych, z niewielką prędkością, co może nie odzwierciedlać pełnych warunków eksploatacyjnych. Istnieje możliwość, że w innych okolicznościach ujawnią się dodatkowe uszkodzenia lub usterki, których nie można było wykryć podczas obecnych oględzin. Zalecamy zatem skorzystanie z możliwości oględzin pojazdu we własnym zakresie lub w Autoryzowanej Stacji Obsługi danej marki, co pozwoli na pełniejszą weryfikację stanu technicznego pojazdu przed udziałem w aukcji."

Restrictive disclaimer - regarding valuation

Nie weryfikowano szczegółowo stanu układu napędowego, zawieszenia, kierowniczego, hamulcowego oraz wydechowego. Ocena została wykonana bez użycia podnośnika i specjalistycznego sprzętu diagnostycznego, nie dokonywano demontażu osłon i innych elementów. Ocena określa ogólny stan pojazdu na dzień oględzin w miejscu jego udostępnienia, nie może być zatem traktowana jako kompleksowa ocena stanu technicznego. Specyfikacja wg. programu operacyjnego w zakresie wyposażenia standardowego i dodatkowego nie gwarantuje zgodności ze stanem faktycznym w zakresie możliwym do ustalenia przez rzeczoznawcę podczas oględzin pojazdu. Pomiar grubości powłoki lakierowej wykonano w miejscach możliwych do ich wykonania pomiary nie gwarantują oryginalności poszczególnych elementów poddanych ocenie.

- W Ocenie/Raporcie uwzględniono niesprawności, uszkodzenia, braki itp., które były możliwe do stwierdzenia organoleptycznego, w warunkach oględzin (z uwzględnieniem: stanu czystości pojazdu, warunków atmosferycznych, oświetlenia itd.) oraz bez weryfikacji serwisowej, bez dostępu do spodu pojazdu, bez specjalistycznego sprzętu diagnostycznego (w tym bez diagnostyki komputerowej), bez jazdy próbnej wykonanej w warunkach drogowych z obciążeniem.
- W ramach Oceny/Raportu nie weryfikowano odczytanego stanu drogomierza z zapisami w urządzeniach elektronicznych pojazdu.
- Rzeczoznawca nie bierze na siebie odpowiedzialności za wady ukryte (prawne i fizyczne) oraz ewentualne skutki wynikające z dalszego użytkowania przedmiotu oceny, a także za skutki wykorzystania samej oceny.
- Podane przedziały grubości powłoki lakierowej, dotyczą punktów pomiarowych. Nie mogą być traktowane jako gwarancja, że grubość powłoki lakierowej w innych punktach nie wykracza poza te przedziały.
- Zawarte w niniejszej Ocenie/Raporcie informacje (w tym dotyczące wyposażenia) służą jedynie ogólnym celom informacyjnym. Ocena/Raport nie może być zatem traktowana jako oferta w rozumieniu przepisów Kodeksu Cywilnego oraz opisu towaru ani zapewnienia w rozumieniu art. 4 Ustawy z dnia 27 lipca 2002 roku o szczególnych warunkach sprzedaży konsumenckiej.
- Niniejsza Ocena/Raport nie jest szczegółową oceną stanu technicznego.

Ocenę/Raport wykonano w kierunku ujawnienia uszkodzeń nieakceptowanych z punktu widzenia właściwego przewodnika zwrotu pojazdu lub innych ustaleń ze Zleceniodawcą. Tym samym Ocena/Raport może nie ujmować typowych zużyć i uszkodzeń eksploatacyjnych.

PHOTOGRAPHIC DOCUMENTATION



Photo 1.

Przekątna przednia lewa



Photo 2.

Przód

PHOTOGRAPHIC DOCUMENTATION



Photo 3.

Przekątna przednia prawa



Photo 4.

Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 5.

Bok prawy z tyłu



Photo 6.

Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 7.

Tył



Photo 8.

Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 9.

Bok lewy z tyłu



Photo 10.

Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 11.

Próg lewy (widok od przodu)



Photo 12.

Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



Photo 13.
Spód pojazdu przód



Photo 14.
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION



Photo 15.

Tarcza hamulcowa przednia prawa



Photo 16.

Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 17.

Tarcza hamulcowa tylna lewa



Photo 18.

Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 19.
Bagażnik



Photo 20.
Koło zapasowe

PHOTOGRAPHIC DOCUMENTATION



Photo 21.
Komora silnika



Photo 22.
Numer identyfikacyjny

PHOTOGRAPHIC DOCUMENTATION



Photo 23.
Tabliczka znamionowa



Photo 24.
Zestaw wskaźników - przebieg

PHOTOGRAPHIC DOCUMENTATION



Photo 25.

Widok przez otwarte drzwi przednie lewe



Photo 26.

Kierownica z lewej strony

PHOTOGRAPHIC DOCUMENTATION



Photo 27.

Widok przez otwarte drzwi tylne lewe



Photo 28.

Widok z tylnej kanapy na deskę rozd.

PHOTOGRAPHIC DOCUMENTATION



Photo 29.

Konsola środkowa



Photo 30.

Tunel środkowy

PHOTOGRAPHIC DOCUMENTATION

Photo 31.
Kierownica (na wprost)




Photo 32.
Dow. rej. ksero Str. 1

PHOTOGRAPHIC DOCUMENTATION**Photo 33.**

Dow. Rej. ksero Str.2 i klucze

**Photo 34.**

Instrukcje

PHOTOGRAPHIC DOCUMENTATION



Photo 35.
Zdjęcie do protokołu



Photo 36.
Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION




Photo 37.

Pokrywa komory silnika - Rysa/odprysk 1



Photo 38.

Spoiler zderzaka przedniego - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 39.

Spoiler zderzaka przedniego - Rysa/odprysk 2




Photo 40.

Szyba czołowa - zdjęcie poglądowe 1

PHOTOGRAPHIC DOCUMENTATION




Photo 41.

Szyba czołowa - Pęknięcie/rozerwanie 1



Photo 42.

Zderzak - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 43.

Felga aluminiowa przednia P - Rysa/odprysk 1



Photo 44.

Listwa błotnika przedniego P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 45.

Drzwi przednie P - Rysa/odprysk 1



Photo 46.

Listwa drzwi przednich P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 47.

Próg P - Wgniecenie/odkształcenie 1



Photo 48.

Felga aluminiowa tylna P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 49.

Błotnik tylny L / Ściana boczna L - Rysa/odprysk 1



Photo 50.

Błotnik tylny L / Ściana boczna L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 51.

Felga aluminiowa tylna L - Rysa/odprysk 1



Photo 52.

Drzwi tylne L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 53.

Listwa drzwi przednich L - Rysa/odprysk 1



Photo 54.

Próg L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION




Photo 55.

Felga Aluminiowa przednia L - Rysa/odprysk 1



Photo 56.

Fotel prz. praw. - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 57.

Tapicerka drzwi przednich L - Rysa/odprysk 1



Photo 58.

Wykładzina(y) słupka tylnego L - Rysa/odprysk 1