

DEKRA's commission No. : PKOL(W)/LODZ/79923/24/10/15  
 commission/ damage No. : 22/010866  
 Date of commission: 15-10-2024

**DEKRA Poland - Headquarters**  
 02-673 Warszawa, ul. Konstruktorska 12A

**Client :**

PKO Leasing SA  
 Świętokrzyska 36  
 00-116 Warszawa

**Expert:**

**Kacper Sosnowski (NEW)**  
 DEKRA Polska - współpraca O/Warszawa  
**mgr inż. Andrzej Szymkowiak**  
 DEKRA Polska - O. Wrocław

**NOTE:**

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

**Vehicle data**

Group of objects (Eurotax)	cars
EC code (Eurotax)	0126753
Manufacturer	MERCEDES-BENZ
Model	S Klasa [W 222] 17-20
Type / version	AMG S 63 4-Matic+ L
Body type	sedan
Number of doors / seats	4/5
Curb weight [kg]	2185
Gross vehicle weight [kg]	2745
Wheelbase 1/2	3165
Engine type	spark ignition
Supercompression	turbocompressor with intercooler
Pollution reduction system	three-way catalytic converter
Emission standard	EURO 6
Engine capacity [ccm]	3982
Engine Power [hp/kW]	612/450
Gearbox	automatic 9- gear
Registration /record No.	E1TRAKO
VIN / serial number	WDD2221881A401225
Date of first registration	13-03-2018
Date of next. tech. test	28-06-2025
Year of manufacture	2018 (year has been verified with the manufacturer's base)
Readout [km]	102 778 (read)
Body color / type of coating	white/INNY

Tyres

axle	Wheel	Manufacturer, type	Size	Measured profile
Front	right	Continental, SportContact 6	265/30 R22 97Y	4,0 mm
	left	Continental, SportContact 6	265/30 R22 97Y	3,0 mm
back	right	Continental, SportContact 6	305/25 R22 99Y	4,0 mm
	left	Continental, SportContact 6	305/25 R22 99Y	4,0 mm

Standard equipment by Eurotax

- |   |   |
|---|---|
| 1. Alarm  | 25. Leather upholstery                  |
| 2. Antilock-Brake-System (ABS)  | 26. Light Alloy wheels 20"              |
| 3. Automated High-beam assist   | 27. Mobile Tire System                  |
| 4. Automatic dimlight activation  | 28. Other                               |
| 5. Automatic headlight elevation control, Cornering Headlights, LED front dim light   | 29. Other                               |
| 6. Bluetooth interface, CD-player, DVD-player, Internet access, Navigation system, On board monitor, Radio, USB in, Voice control for audiosystem, Voice control for navigation system, Voice control for telephone | 30. Other                               |
| 7. Colored glass  | 31. Other                               |
| 8. Door mirror with memory, Driver seat electrically adjustable   | 32. Other                               |
| 9. Door mirror(s) electrically adjustable in general  | 33. Other                               |
| 10. Door mirrors autodimming, Rear-view mirror autodimming  | 34. Other                               |
| 11. Door mirrors electrically foldable  | 35. Other                               |
| 12. Driver airbag, Head airbags front, Passenger airbag, Side airbag driver, Side airbag driver and passenger   | 36. Other                               |
| 13. Dualzone automatic climate control  | 37. Other                               |
| 14. ESP (Electronical Stabilizing Program)  | 38. Power assisted brakes               |
| 15. Exterior design: other  | 39. Pre-Crash System                    |
| 16. Exterior design: other, Interior: other   | 40. Pre-Crash System                    |
| 17. Exterior lighting: other  | 41. Rain sensor                         |
| 18. Floor mat   | 42. Soundsystem                         |
| 19. Front seat with massage, Pre-Crash System   | 43. Tyre pressure control (RDC)         |
| 20. Headrests front   | 44. Uni-Lackierung                      |
| 21. Heated seat driver, Heated seat passenger   | 45. Windscreenwiper: other              |
| 22. Interior decoration: other  | 46. Wood finish                         |
| 23. Interior lights: other accessories  | 47. vehicle tracking system preparation |
| 24. LED rear lights   |   |

Dealer's equipment (selected items)

- |   |   |
|---|---|
| 1. Air condition rear, Automatic climate control, Electrically adjustable rear seats, Other, Park Assistant, Park Distance Control rear, Pre-Crash System, Rear view camera   | - |
| Fotele tylne komfortowe - wentylowane i ogrzewane   |   |
| Klimatyzacja automatyczna - tył   |   |
| Zagłówki komfortowe Easy Adjust z przodu, po stronie pasażera składany i wyjmowany  |   |
| Fotele tylne regulowane elektrycznie z pamięcią ustawień  |   |
| Pakiet przeciwsłoneczny   |   |
| 2. Automatic Emergency Call   | - |
| 3. Bord communication: other, iPod Interface  | - |
| 4. Bord communication: other, iPod Interface  | - |
| 5. Bord entertainment: other accessories  | - |
| 6. CD-player  | - |
| 7. Carbon finish, Interior decoration: other  | - |
| 8. Ceramic composite brakes   | - |
| 9. DAB radio  | - |
| 10. Door mirror with memory, Door mirrors autodimming, Electric tailgate, Front seat with massage, Glass tilt/slide sunroof electric, Headrests front, Head-Up Display, Heated seat driver, Heated seat passenger, Interior: other, Keyless Engine start, Leather upholstery, Memory seat, Other, Park Assistant, Park Distance Control rear, Pre-Crash System, Rear-view mirror autodimming, Soundsystem, Steering: other, Ventilated front seat | - |
| Wielokonturowe, dynamiczne fotele przednie z f. masażu i PRE-SAFE   |   |
| Dach szklany panoramiczny - elektryczny   |   |

Tapicerka skórzana Nappa	
System nagłośnienia Burmester Surround	
Wspomaganie zamykania drzwi i bagażnika	
Pakiet Air-Balance	
HUD - wyświetlacz head-up	
Fotele przednie - wentylowane i ogrzewane	
Pakiet wspomagania asystenta jazdy Plus	
Pakiet pamięci foteli po stronie kierowcy i pasażera	
Pakiet zdalnego parkowania	
11. Electric tailgate, Keyless Engine start	-
System KEYLESS-GO - dostęp i uruchamianie pojazdu bez użycia kluczyka	
System otwierania/zamykania bagażnika za pomocą gestów	
HANDS-FREE ACCESS - bezdotykowe otwieranie bagażnika	
12. Exterior design: other	-
Lusterka boczne w obudowie z włókna węglowego	
Spojlery boczne oraz spojler tylny z nakładkami wykonanymi z włókna węglowego	
Poprzeczna podpora w spojlerze przednim z włókna węglowego	
13. Extra power outlet	-
14. Heated seat driver, Heated seat passenger, Other, Rear seat heating, Steering wheel heated	-
Kierownica wielofunkcyjna, ogrzewana	
Ogrzewany podłokietnik dla kierowcy i pasażera	
Podłokietnik przedni i tylni ogrzewany	
15. Interior: other	-
16. Keyless go	-
17. Memory seat, Rear headrests, Seats: other	-
Zagłówki komfortowe Easy Adjust z przodu, po stronie pasażera składany i wyjmowany	
Fotel pasażera z przodu z funk. Chauffeur (komfortowe ustaw. fotela dla pasażera siedzącego z tyłu)	
18. Other	-
19. Other	-
20. Other	-
21. Other	-
22. Other	-
23. Other	-
24. Other	-
25. Other	-
26. Other	-
27. Other	-
28. Other	-
Ograniczenie prędkości do 300 km/h	
29. Other	-
Listwy progowe Mercedes-Benz, podświetlane	
Pakiet elementów ozdobnych Exclusive	
30. Other	-
Poduszka powietrzna w pasach bezpieczeństwa z tyłu	
Podajnik pasa bezpieczeństwa	
31. Other, Rear headrests, Rear seat with massage	-
Wielokonturowe oparcia tylnych foteli z funkcją masażu	
32. Seats: other	-
33. Side airbags rear	-
34. Soundsystem	-
35. Sunblind rear side door manual	-
36. Sunblind tailgate window electric	-
37. Tailgate additional lock	-
38. Tinted rear windows	-
39. Under driving protection	-
40. Windscreen heating	-

Additional equipment

1. BRABUS POWER XTRA B40-700	-
------------------------------	---

2. Felgi 22 Brabus Monoblock ..... -

**Base value of the vehicle**

Base value of the vehicle by Eurotax (net) ..... -

**Corrections**First registrationEquipmentTyresOther

Regularity of service review ..... -

Earlier repairs ..... -

Stwierdzone braki, uszkodzenia (szacunkowo) ..... -

historia pojazdu ..... -


Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 10-2024 POL) with regard to technical and market parameters affecting the value of the vehicle.

Basic print without information about the vehicle's value - duey to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 24-10-2024

DEKRA's expert:  
Kacper Sosnowski (NEW)  
mgr inż. Andrzej Szymkowiak**Document issued electronically valid without signature.**

Measurement of thickness of the vehicle lacquer coating



No. of controlled item	Controlled item	Measured range of thickness of the lacquer coat [ $\mu\text{m}$ ]
1	Front cover	to 150
2	Front left fender	to 150
3	Left front pillar	to 150
4	Front left door	to 150
6	Left middle pillar	to 150
7	Right side sill	to 150
8	Left rear door	to 150
9	Rear left fender	to 150
10	Cover/lid	to 150
11	Right rear fender	150 - 1000
12	Right rear door	150 - 2000
13	Right middle pillar	to 150
14	Right side sill	to 150
15	Front right door	to 150
16	Right front pillar	to 150
17	Front right fender	to 150

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

During the inspection the registration proof of the vehicle was presented and its photo was taken and enclosed to the expertise.

During the inspection the service book of the vehicle was not provided.

**Information concerning the origin of the vehicle**

The vehicle purchased domestically from an authorized representative of the brand.

**Anti-theft protection - immobilizer**

- as a result of the inspection of the vehicle found no malfunctions of the immobilizer in the extent possible to determine during the inspection of the vehicle in the non- workshop conditions.

**Anti-theft protection - other:**

not found

**Additional comments on the car:**

Not applicable.

**Test drive**

Test drive of the vehicle was conducted. Test drive in the full extent is not possible. Comment below: pojazd udostępniono w warunkach parkingowych

**Checking of the correctness and / or construction of identification / serial numbers of the object:**

Not tested

**Verification of the accuracy of the object data, including year of production, and other.**

Not conducted - adopted according to the documents presented and indicated sources.

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.
- The evaluation has been carried out basing on delivered documentation and organoleptic examination of the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the

assessed object.

- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

---

Comments to the commission - regarding valuation

**Kluczyki**

TAK

2

---

Expert comments - regarding valuation

Wymagany przegląd BO. Pojazdu oklejony folią. Pomiar lakieru wykonany na folii. Aktywna kontrolka ciśnienia w oponach. Rysy na samochodzie.

Restrictive disclaimer - regarding valuation

- W Ocenie/Raporcie uwzględniono niesprawności, uszkodzenia, braki itp., które były możliwe do stwierdzenia organoleptycznego, w warunkach oględzin (z uwzględnieniem: stanu czystości pojazdu, warunków atmosferycznych, oświetlenia itd.) oraz bez weryfikacji serwisowej, bez dostępu do spodu pojazdu, bez specjalistycznego sprzętu diagnostycznego (w tym bez diagnostyki komputerowej), bez jazdy próbnej wykonanej w warunkach drogowych z obciążeniem.
- W ramach Oceny/Raportu nie weryfikowano odczytanego stanu drogomierza z zapisami w urządzeniach elektronicznych pojazdu.
- Rzeczoznawca nie bierze na siebie odpowiedzialności za wady ukryte (prawne i fizyczne) oraz ewentualne skutki wynikające z dalszego użytkowania przedmiotu oceny, a także za skutki wykorzystania samej oceny.
- Podane przedziały grubości powłoki lakierowej, dotyczą punktów pomiarowych. Nie mogą być traktowane jako gwarancja, że grubość powłoki lakierowej w innych punktach nie wykracza poza te przedziały.
- Zawarte w niniejszej Ocenie/Raporcie informacje (w tym dotyczące wyposażenia) służą jedynie ogólnym celom informacyjnym. Ocena/Raport nie może być zatem traktowana jako oferta w rozumieniu przepisów Kodeksu Cywilnego oraz opisu towaru ani zapewnienia w rozumieniu art. 4 Ustawy z dnia 27 lipca 2002 roku o szczególnych warunkach sprzedaży konsumenckiej.
- Niniejsza Ocena/Raport nie jest szczegółową oceną stanu technicznego.

Ocenę/Raport wykonano w kierunku ujawnienia uszkodzeń nieakceptowanych z punktu widzenia właściwego przewodnika zwrotu pojazdu lub innych ustaleń ze Zleceniodawcą. Tym samym Ocena/Raport może nie ujmować typowych zużyć i uszkodzeń eksploatacyjnych.

PHOTOGRAPHIC DOCUMENTATION



**Photo 1.**  
Przekątna przednia lewa



**Photo 2.**  
Przód



PHOTOGRAPHIC DOCUMENTATION



**Photo 3.**  
Przekątna przednia prawa



**Photo 4.**  
Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



**Photo 5.**  
Bok prawy z tyłu



**Photo 6.**  
Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



**Photo 7.**  
Tyl



**Photo 8.**  
Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



**Photo 9.**  
Bok lewy z tyłu



**Photo 10.**  
Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



**Photo 11.**  
Próg lewy (widok od przodu)



**Photo 12.**  
Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



**Photo 13.**  
Spód pojazdu przód



**Photo 14.**  
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION



**Photo 15.**

Tarcza hamulcowa przednia prawa



**Photo 16.**

Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION



**Photo 17.**  
Tarcza hamulcowa tylna lewa



**Photo 18.**  
Tarcza hamulcowa przednia lewa



PHOTOGRAPHIC DOCUMENTATION



**Photo 19.**  
Bagażnik



**Photo 20.**  
Koło zapasowe

PHOTOGRAPHIC DOCUMENTATION



**Photo 21.**  
Komora silnika



**Photo 22.**  
Numer identyfikacyjny

PHOTOGRAPHIC DOCUMENTATION



**Photo 23.**  
Tabliczka znamionowa



**Photo 24.**  
Zestaw wskaźników - przebieg

PHOTOGRAPHIC DOCUMENTATION



**Photo 25.**  
Zestaw wskaźników - serwis



**Photo 26.**  
Widok przez otwarte drzwi przednie lewe

PHOTOGRAPHIC DOCUMENTATION



**Photo 27.**  
Kierownica z lewej strony



**Photo 28.**  
Widok przez otwarte drzwi tylne lewe

PHOTOGRAPHIC DOCUMENTATION



**Photo 29.**

Widok z tylnej kanapy na deskę rozd.



**Photo 30.**

Konsola środkowa

PHOTOGRAPHIC DOCUMENTATION



**Photo 31.**  
Tunel środkowy



**Photo 32.**  
Kierownica (na wprost)

PHOTOGRAPHIC DOCUMENTATION



**Photo 33.**  
Dowód rej. Str. 1



**Photo 34.**  
Dow. Rej. Str.2 i Klucze



PHOTOGRAPHIC DOCUMENTATION



**Photo 35.**  
Książka serwisowa – dane



**Photo 36.**  
Książka serwisowa – ostatni przegląd



PHOTOGRAPHIC DOCUMENTATION



**Photo 39.**  
Zdjęcie do protokołu



**Photo 40.**  
Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



**Photo 41.**  
Zdjęcie do protokołu



**Photo 42.**  
Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



**Photo 43.**  
Zdjęcie do protokołu



**Photo 44.**  
Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



**Photo 45.**  
Zdjęcie do protokołu



**Photo 46.**  
Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



**Photo 47.**  
Zdjęcie do protokołu



**Photo 48.**  
Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



**Photo 49.**  
Zdjęcie do protokołu



**Photo 50.**  
Zdjęcie do protokołu



PHOTOGRAPHIC DOCUMENTATION



**Photo 51.**  
Zdjęcie do protokołu



**Photo 52.**  
Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



**Photo 53.**  
Zdjęcie do protokołu



**Photo 54.**  
Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



**Photo 55.**  
Zdjęcie do protokołu



**Photo 56.**  
Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



**Photo 57.**  
Zdjęcie do protokołu



**Photo 58.**  
Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



**Photo 59.**  
Zdjęcie do protokołu



**Photo 60.**  
Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



**Photo 61.**  
Zdjęcie do protokołu



**Photo 62.**  
Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



**Photo 63.**  
Zdjęcie do protokołu



**Photo 64.**  
Felga aluminiowa przednia P - zdjęcie poglądowe 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 65.**  
Felga aluminiowa przednia P - Rysa/odprysk 1



**Photo 66.**  
Drzwi przednie P - Rysa/odprysk 1



PHOTOGRAPHIC DOCUMENTATION



**Photo 67.**  
Drzwi tylne P - Wgniecenie/odkształcenie 1



**Photo 68.**  
Felga aluminiowa tylna P - zdjęcie poglądowe 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 69.**

Felga aluminiowa tylna P - Rysa/odprysk 1



**Photo 70.**

Felga Aluminiowa przednia L - zdjęcie pogładowe 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 71.**  
Felga Aluminiowa przednia L - Rysa/odprysk 1



**Photo 72.**  
Felga Aluminiowa przednia L - Rysa/odprysk 2