

DEKRA's commission No. : PKOL(W)/LODZ/84479/25/11/03
commission/ damage No. : 21/046227
Date of commission: 03-11-2025

DEKRA Poland - Headquarters
02-673 Warszawa, ul. Konstruktorska 12A

Client :

PKO Leasing SA
Świętokrzyska 36
00-116 Warszawa

Expert:

Kacper Sosnowski (NEW)
DEKRA Polska - współpraca O/Warszawa
Tomasz Ziemniak (NEW)
DEKRA Polska - współpraca O/Konin

NOTE:

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

Vehicle data

Group of objects (Eurotax)	cars
EC code (Eurotax)	0137766
Manufacturer	AUDI
Model	A6 [C8] 18-23
Type / version	A6 35 TDI mHEV S tronic
Body type	sedan
Number of doors / seats	4/5
Curb weight [kg]	1664
Gross vehicle weight [kg]	2255
Wheelbase 1/2	2924
Engine type	Automatic ignition
Pollution reduction system	KSC
Engine capacity [ccm]	1968
Engine Power [hp/kW]	163/120
Gearbox	automatic 7- gear
Registration /record No.	CT0461Y
VIN / serial number	WAUZZZF27MN058509
Date of first registration	16-02-2021
Date of next. tech. test	16-02-2024
Year of manufacture	2021 (year has been verified with the manufacturer's base)
Readout [km]	155 086 (read)
Body color / type of coating	white/METALIK

Tyres

axle	Wheel	Manufacturer, type	Size	Measured profile
Front	right	KUMHO, WINTER CRAFT WP72	245/45 19 102V	4,0 mm
	left	KUMHO, WINTER CRAFT WP72	245/45 19 102V	4,0 mm
back	right	KUMHO, WINTER CRAFT WP72	245/45 19 102V	5,0 mm
	left	KUMHO, WINTER CRAFT WP72	245/45 19 102V	5,0 mm

Standard equipment by Eurotax

- | | |
|--|---|
| 1. Alarm | 28. LED rear lights |
| 2. Armrest (s) front, Storage facilities in general | 29. Lane control assistant |
| 3. Automated High-beam assist | 30. Leather steering wheel, Multi functional steering wheel |
| 4. Bluetooth interface | 31. Light alloy wheels from 17" |
| 5. Bord communication: other | 32. Lumbar adjust driver electric, Lumbar adjust passenger electric |
| 6. Bord entertainment: other accessories | 33. Mirror: others |
| 7. Bumpers: other | 34. Mobile Tire System |
| 8. Child seat fixation | 35. On board computer |
| 9. Cruise control | 36. Other |
| 10. Door mirror with memory, Door mirrors electrically foldable, Door mirrors heated | 37. Other |
| 11. Door mirror(s) electrically adjustable in general | 38. Other |
| 12. Driver seat electrically adjustable, Memory seat, Passenger seat electrically adjustable | 39. Other |
| 13. Dualzone automatic climate control | 40. Other |
| 14. Electric tailgate | 41. Other |
| 15. Exterior design: other | 42. Power steering |
| 16. Exterior design: other | 43. Pre-Crash System |
| 17. Exterior design: other | 44. Pre-Crash System |
| 18. Floor mat | 45. Radio |
| 19. Free service 3 years, more than 60 000 km | 46. Rear-view mirror autodimming |
| 20. Head airbags front, Head airbags rear | 47. Remote controlled central locking |
| 21. Headrests front | 48. Selectable driveline characteristics |
| 22. Heat reflecting windows | 49. Servotronic |
| 23. Interior decoration: other | 50. Sport suspension |
| 24. Interior decoration: other | 51. Steering wheel manually adjustable |
| 25. Interior: other | 52. Textile upholstery |
| 26. LED Daytime running lights | 53. Tyre pressure control (RDC) |
| 27. LED front dim light | 54. Uni-Lackierung |

Dealer's equipment (selected items)

- | | |
|---|---|
| 1. Heated seat driver, Heated seat passenger, Park Distance Control front, Park Distance Control rear, Rear view camera | - |
| Fotele przednie ogrzewane | |
| Audi parking system przód/tył - czujniki parkowania | |
| Kamera ułatwiająca parkowanie | |
| 2. Metallic paint | - |

Base value of the vehicle

Base value of the vehicle by Eurotax (net) -

Corrections

First registration

Mileage

EquipmentTyresOther

Regularity of service review -
State of the vehicle -
Earlier repairs -
Korekta z tytułu uszkodzeń pojazdu -

Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 11-2025 POL) with regard to technical and market parameters affecting the value of the vehicle.

Basic print without information about the vehicle's value - duey to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 12-11-2025

DEKRA's expert:
Kacper Sosnowski (NEW)
Tomasz Ziemniak (NEW)

Document issued electronically valid without signature.

Measurement of thickness of the vehicle lacquer coating


No. of controlled item	Controlled item	Measured range of thickness of the lacquer coat [μm]
1	Front cover	to 150
2	Front left fender	to 150
3	Left front pillar	to 150
4	Front left door	to 150
5	Roof	to 150
6	Left middle pillar	to 150
7	Right side sill	to 150
8	Left rear door	to 150
9	Rear left fender	to 150
10	Cover/lid	to 150
11	Right rear fender	to 150
12	Right rear door	to 150
13	Right middle pillar	150 - 200
14	Right side sill	to 150
15	Front right door	to 150
16	Right front pillar	to 150
17	Front right fender	to 150

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

Presented the following documents of the vehicle:

Ksero pozwolenia czasowego

During the inspection the service book of the vehicle was not provided.

Information concerning the origin of the vehicle

The vehicle purchased domestically from an authorized representative of the brand.

Anti-theft protection - immobilizer

- as a result of the inspection of the vehicle found no malfunctions of the immobilizer in the extent possible to determine during the inspection of the vehicle in the non- workshop conditions.

Anti-theft protection - other:

not found

Additional comments on the car:

Not applicable.

Test drive

The test drive has been conducted on a distance and in time enabling rough estimation of the technical condition of the vehicle.

Checking of the correctness and / or construction of identification / serial numbers of the object:

Not tested

Verification of the accuracy of the object data, including year of production, and other.

Not conducted (with the exception of the year of production) - adopted according to the documents presented and indicated sources.

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.
- The evaluation has been carried out basing on delivered documentation and organoleptic examination of

page 5/44

the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the assessed object.

- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

Comments to the commission - regarding valuation

Kluczyki

TAK

1

Expert comments - regarding valuation

Dostarczono ksero pozwolenia czasowego. Brak kompresora zestawu naprawczego. Brak możliwości otworzenia bagażnika poprzez uchwyt, przy użyciu kluczyka otwiera się. Brak zaślepki w tylnej kanapie. Wymiana oleju wymagana od 9800km. Przegląd przekroczony od 27400km. Rysy na samochodzie. Odpryski na szybie czołowej. Substancja na samochodzie.

Restrictive disclaimer - regarding valuation

- W Ocenie/Raporcie uwzględniono niesprawności, uszkodzenia, braki itp., które były możliwe do stwierdzenia organoleptycznego, w warunkach oględzin (z uwzględnieniem: stanu czystości pojazdu, warunków atmosferycznych, oświetlenia itd.) oraz bez weryfikacji serwisowej, bez dostępu do spodu pojazdu, bez specjalistycznego sprzętu diagnostycznego (w tym bez diagnostyki komputerowej), bez jazdy próbnej wykonanej w warunkach drogowych z obciążeniem.
- W ramach Oceny/Raportu nie weryfikowano odczytanego stanu drogomierza z zapisami w urządzeniach elektronicznych pojazdu.
- Rzeczoznawca nie bierze na siebie odpowiedzialności za wady ukryte (prawne i fizyczne) oraz ewentualne skutki wynikające z dalszego użytkowania przedmiotu oceny, a także za skutki wykorzystania samej oceny.
- Podane przedziały grubości powłoki lakierowej, dotyczą punktów pomiarowych. Nie mogą być traktowane jako gwarancja, że grubość powłoki lakierowej w innych punktach nie wykracza poza te przedziały.
- Zawarte w niniejszej Ocenie/Raporcie informacje (w tym dotyczące wyposażenia) służą jedynie ogólnym celom informacyjnym. Ocena/Raport nie może być zatem traktowana jako oferta w rozumieniu przepisów Kodeksu Cywilnego oraz opisu towaru ani zapewnienia w rozumieniu art. 4 Ustawy z dnia 27 lipca 2002 roku o szczególnych warunkach sprzedaży konsumenckiej.
- Niniejsza Ocena/Raport nie jest szczegółową oceną stanu technicznego.

Ocenę/Raport wykonano w kierunku ujawnienia uszkodzeń nieakceptowanych z punktu widzenia właściwego przewodnika zwrotu pojazdu lub innych ustaleń ze Zleceniodawcą. Tym samym Ocena/Raport może nie ujmować typowych zużyć i uszkodzeń eksploatacyjnych.

PHOTOGRAPHIC DOCUMENTATION



Photo 1.
Przekątna przednia lewa



Photo 2.
Przód

PHOTOGRAPHIC DOCUMENTATION



Photo 3.

Przekątna przednia prawa



Photo 4.

Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 5.
Bok prawy z tyłu



Photo 6.
Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 7.

Tył



Photo 8.

Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 9.

Bok lewy z tyłu



Photo 10.

Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 11.

Próg lewy (widok od przodu)



Photo 12.

Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



Photo 13.
Spód pojazdu przód



Photo 14.
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION



Photo 15.

Tarcza hamulcowa przednia prawa



Photo 16.

Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 17.

Tarcza hamulcowa tylna lewa



Photo 18.

Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 19.
Bagażnik



Photo 20.
Koło zapasowe

PHOTOGRAPHIC DOCUMENTATION



Photo 21.
Komora silnika




Photo 22.
Numer identyfikacyjny

PHOTOGRAPHIC DOCUMENTATION



Photo 23.

Tabliczka znamionowa



Photo 24.

Zestaw wskaźników - przebieg

PHOTOGRAPHIC DOCUMENTATION



Photo 25.

Widok przez otwarte drzwi przednie lewe



Photo 26.

Kierownica z lewej strony

PHOTOGRAPHIC DOCUMENTATION



Photo 27.

Widok przez otwarte drzwi tylne lewe



Photo 28.

Widok z tylnej kanapy na deskę rozd.

PHOTOGRAPHIC DOCUMENTATION



Photo 29.

Konsola środkowa




Photo 30.

Tunel środkowy

PHOTOGRAPHIC DOCUMENTATION




Photo 31.
Kierownica (na wprost)



Photo 32.
Książka serwisowa – dane

PHOTOGRAPHIC DOCUMENTATION**Photo 33.**

Książka serwisowa – ostatni przegląd

**Photo 34.**

Dow. rej. ksero Str. 1

PHOTOGRAPHIC DOCUMENTATION




Photo 35.

Dow. Rej. ksero Str.2 i klucze



Photo 36.

Zestaw naprawczy koła

PHOTOGRAPHIC DOCUMENTATION



Photo 37.

Zdjęcie do protokołu




Photo 38.

Listwa śr zderzaka przedniego - Pęknięcie/rozerwanie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 39.

Listwa śr zderzaka przedniego - Pęknięcie/rozerwanie 2



Photo 40.

Zaślepka prz haka hol. - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 41.

Zderzak - Rysa/odprysk 1



Photo 42.

Zderzak - Rysa/odprysk 2

PHOTOGRAPHIC DOCUMENTATION



Photo 43.

Zderzak - Wgniecenie/odkształcenie 1



Photo 44.

Zderzak - Pęknięcie/rozerwanie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 45.

Felga aluminiowa przednia P - Rysa/odprysk 1



Photo 46.

Drzwi przednie P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 47.

Drzwi tylne P - Rysa/odprysk 1




Photo 48.

Drzwi tylne P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 49.

Drzwi tylne P - Wgniecenie/odkształcenie 2



Photo 50.

Lusterko zew P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 51.

Próg P - Wgniecenie/odkształcenie 1



Photo 52.

Słupek przedni P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 53.

Błotnik tylny P / Ściana boczna P - Wgniecenie/odkształcenie 1




Photo 54.

Felga aluminiowa tylna P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 55.

Opona tylna P - Pęknięcie/rozerwanie 1



Photo 56.

Zderzak tylny - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 57.

Zderzak tylny - Rysa/odprysk 2



Photo 58.

Zderzak tylny() - Rysa/odprysk 3

PHOTOGRAPHIC DOCUMENTATION



Photo 59.

Zderzak tylny cz dolna - Rysa/odprysk 1



Photo 60.

Dach - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 61.

Felga aluminiowa tylna L - Rysa/odprysk 1



Photo 62.

Drzwi przed L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 63.

Drzwi tylne L - Wgniecenie/odkształcenie 1



Photo 64.

Klamka drzwi prz L - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 65.

Próg L - Rysa/odprysk 1



Photo 66.

Słupek przedni L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 67.

Felga Aluminiowa przednia L - Rysa/odprysk 1



Photo 68.

Opona przednia L - Pęknięcie/rozerwanie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 69.

Konsola tunelu śr. - Rysa/odprysk 1



Photo 70.

Fotel prz. lew. - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 71.

Osłona p/słoneczna lewa - Inne 1



Photo 72.

Osłona p/słoneczna prawa - Inne 1

PHOTOGRAPHIC DOCUMENTATION




Photo 73.
Podsufitka - Inne 1



Photo 74.
Podsufitka - Inne 2

PHOTOGRAPHIC DOCUMENTATION



Photo 75.

Wykładzina(y) słupka przedniego L - Inne 1