

DEKRA's commission No. : PKOL(W)/LODZ/98690/26/10/21
commission/ damage No. : 21/040822
Date of commission: 21-10-2026

DEKRA Poland - Headquarters
02-673 Warszawa, ul. Konstruktorska 12A

Client :

PKO Leasing SA
Świętokrzyska 36
00-116 Warszawa

Expert:

Kacper Sosnowski (WSP)
DEKRA Polska - współpraca O/Warszawa
inż. Dariusz Pawliszyn
DEKRA Polska - O. Poznań

NOTE:

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

Vehicle data

Group of objects (Eurotax)	cars
EC code (Eurotax)	0152851
Manufacturer	KIA
Model	ProCeed 21-25
Type / version	ProCeed 1.6 T-GDI GT DCT
Body type	KOM
Number of doors / seats	5/5
Curb weight [kg]	1363
Gross vehicle weight [kg]	1900
Wheelbase 1/2	2650
Engine type	spark ignition
Pollution reduction system	GPF
Engine capacity [ccm]	1591
Engine Power [hp/kW]	204/150
Gearbox	automatic 7- gear
Registration /record No.	KR5WU33
VIN / serial number	U5YH6G17GNL049666
Date of first registration	08-10-2021
Date of next. tech. test	08-10-2026
Year of manufacture	2021 (year has been verified with the manufacturer's base)
Readout [km]	85 936 (read)
Body color / type of coating	black/double-layered, metallized

Tyres

axle	Wheel	Manufacturer, type	Size	Measured profile
Front	right	MICHELIN, PILOT SPORT 4	225/40 18 92Y	3,0 mm
	left	MICHELIN, PILOT SPORT 4	225/40 18 92Y	3,0 mm
back	right	MICHELIN, PILOT SPORT 4	225/40 18 92Y	3,5 mm
	left	MICHELIN, PILOT SPORT 4	225/40 18 92Y	3,0 mm

Standard equipment by Eurotax

- | | |
|--|---|
| 1. Alarm | 41. Leather gearshifter/switch, Leather steering wheel |
| 2. Android Auto, Apple CarPlay, Navigation system, Touchscreen monitor | 42. Light Alloy wheels 18" |
| 3. Antilock-Brake-System (ABS) | 43. Luggage compartment cover |
| 4. Armrest (s) rear | 44. Lumbar adjust driver electric, Lumbar adjust passenger electric |
| 5. Automated High-beam assist | 45. Metallic paint |
| 6. Automatic climate control | 46. Mirror: others, Side indicators |
| 7. Automatic dimlight activation | 47. Mobile Tire System |
| 8. Bluetooth interface, Bord communication: other, Bord entertainment: other accessories, DAB radio, Hands-free system, Radio, Steering wheel with radio operation, USB in | 48. On board computer |
| 9. Body-coloured bumpers, Exterior design: other | 49. Other |
| 10. Child seat fixation | 50. Other |
| 11. Cruise control | 51. Other |
| 12. Door mirror(s) electrically adjustable in general, Door mirrors heated | 52. Other |
| 13. Door mirrors electrically foldable | 53. Other |
| 14. Driver airbag, Head airbags front, Passenger airbag, Side airbag driver, Side airbag driver and passenger | 54. Other |
| 15. Driver conditioning monitoring | 55. Park Assistant, Park Distance Control rear |
| 16. Driver seat height adjustable | 56. Park Distance Control rear |
| 17. Driver-information-system | 57. Passenger seat height adjustable |
| 18. Driver-information-system, Other | 58. Power assisted brakes |
| 19. ESP (Electronical Stabilizing Program) | 59. Power windows front, Power windows rear |
| 20. Electric parking brake | 60. Rain sensor |
| 21. Exterior design: other | 61. Rear bench foldable in two separate parts |
| 22. Exterior design: other | 62. Rear view camera |
| 23. Exterior design: other | 63. Rear-view mirror autodimming |
| 24. Exterior design: other | 64. Seatbelt pretensioner front |
| 25. Exterior design: other | 65. Selectable driveline characteristics |
| 26. Extra power outlet | 66. Servotronic |
| 27. Fog lamps | 67. Sport seats front |
| 28. Full Cabin Spoiler | 68. Sports steering wheel |
| 29. Heated seat driver, Heated seat passenger | 69. Steering wheel heated |
| 30. Hill holder | 70. Steering wheel manually adjustable |
| 31. Interior: other | 71. Storage facilities in general |
| 32. Interior: other | 72. Storage facilities in general |
| 33. Interior: other | 73. Tinted rear windows |
| 34. Interior: other | 74. Traffic jam assist |
| 35. Interior: other | 75. Tyre pressure control (RDC) |
| 36. Keyless go | 76. USB in |
| 37. LED Daytime running lights | 77. Upholstery with leather inserts |
| 38. LED Daytime running lights, LED rear lights | 78. Vehicle immobilizer |
| 39. LED front dim light | 79. Windscreen heating |
| 40. Lane control assistant | |

Dealer's equipment (selected items)

1. Active speed sign recognition, Bluetooth interface, Bord entertainment: other accessories, Digital instruments, Other, Soundsystem -
 Indukcyjna ładowarka do telefonu
 Kia Supervision Cluster - cyfrowe zegary z kolorowym wyświetlaczem 12.3 cali
 Kia Intelligent Speed Warning - system rozpoznawania znaków ograniczeń prędkości
 System nagłośnienia JBL z 8 głośnikami, subwoofer-em i głośnikiem centralnym i wzmacniaczem 320W

- Bluetooth z możliwością podłączenia 2 urządzeń
2. Driver seat electrically adjustable, Electric tailgate, Memory seat -
Fotel kierowcy ustawiany elektrycznie w 8 kierunkach z pamięcią ustawień
Kia Smart Tailgate - funkcja automatycznego otwierania pokrywy bagażnika
3. Glass tilt/slide sunroof electric, Interior lights: other accessories -
4. Metallic paint -

Base value of the vehicle

Base value of the vehicle by Eurotax (net) -

Corrections

First registration

Mileage

Equipment

Tyres

Other

State of the vehicle -


Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 10-2026 POL) with regard to technical and market parameters affecting the value of the vehicle.

Basic print without information about the vehicle's value - due to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 26-10-2026

DEKRA's expert:
Kacper Sosnowski (WSP)
inż. Dariusz Pawliszyn

Document issued electronically valid without signature.

Measurement of thickness of the vehicle lacquer coating


No. of controlled item	Controlled item	Measured range of thickness of the lacquer coat [μm]
1	Front cover	to 150
2	Front left fender	to 150
3	Left front pillar	to 150
4	Front left door	to 150
6	Left middle pillar	to 150
7	Right side sill	to 150
8	Left rear door	to 150
9	Rear left fender	to 150
10	Cover/lid	to 150
11	Right rear fender	to 150
12	Right rear door	to 150
13	Right middle pillar	to 150
14	Right side sill	to 150
15	Front right door	to 150
16	Right front pillar	to 150
17	Front right fender	to 150

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

During the inspection the registration proof of the vehicle was presented and its photo was taken and enclosed to the expertise.

During the inspection the service book of the vehicle was not provided.

Information concerning the origin of the vehicle

The vehicle purchased domestically from an authorized representative of the brand.

Anti-theft protection - immobilizer

- as a result of the inspection of the vehicle found no malfunctions of the immobilizer in the extent possible to determine during the inspection of the vehicle in the non- workshop conditions.

Anti-theft protection - other:

not found

Additional comments on the car:

Not applicable.

Test drive

Test drive of the vehicle was conducted. Test drive in the full extent is not possible. Comment below: parking

Checking of the correctness and / or construction of identification / serial numbers of the object:

Not tested

Verification of the accuracy of the object data, including year of production, and other.

Not conducted - adopted according to the documents presented and indicated sources.

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.
- The evaluation has been carried out basing on delivered documentation and organoleptic examination of the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the

assessed object.

- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

Comments to the commission - regarding valuation

Kluczyki

TAK

2

Expert comments - regarding valuation

Rysy na samochodzie. Głośna praca układu wydechowego, do weryfikacji serwisowej. Nierówna praca silnika, do weryfikacji serwisowej. Odpryski na szybie czołowej.

Restrictive disclaimer - regarding valuation

- W Ocenie/Raporcie uwzględniono niesprawności, uszkodzenia, braki itp., które były możliwe do stwierdzenia organoleptycznego, w warunkach oględzin (z uwzględnieniem: stanu czystości pojazdu, warunków atmosferycznych, oświetlenia itd.) oraz bez weryfikacji serwisowej, bez dostępu do spodu pojazdu, bez specjalistycznego sprzętu diagnostycznego (w tym bez diagnostyki komputerowej), bez jazdy próbnej wykonanej w warunkach drogowych z obciążeniem.
- W ramach Oceny/Raportu nie weryfikowano odczytanego stanu drogomierza z zapisami w urządzeniach elektronicznych pojazdu.
- Rzeczoznawca nie bierze na siebie odpowiedzialności za wady ukryte (prawne i fizyczne) oraz ewentualne skutki wynikające z dalszego użytkowania przedmiotu oceny, a także za skutki wykorzystania samej oceny.
- Podane przedziały grubości powłoki lakierowej, dotyczą punktów pomiarowych. Nie mogą być traktowane jako gwarancja, że grubość powłoki lakierowej w innych punktach nie wykracza poza te przedziały.
- Zawarte w niniejszej Ocenie/Raporcie informacje (w tym dotyczące wyposażenia) służą jedynie ogólnym celom informacyjnym. Ocena/Raport nie może być zatem traktowana jako oferta w rozumieniu przepisów Kodeksu Cywilnego oraz opisu towaru ani zapewnienia w rozumieniu art. 4 Ustawy z dnia 27 lipca 2002 roku o szczególnych warunkach sprzedaży konsumenckiej.
- Niniejsza Ocena/Raport nie jest szczegółową oceną stanu technicznego.

Ocenę/Raport wykonano w kierunku ujawnienia uszkodzeń nieakceptowanych z punktu widzenia właściwego przewodnika zwrotu pojazdu lub innych ustaleń ze Zleceniodawcą. Tym samym Ocena/Raport może nie ujmować typowych zużyć i uszkodzeń eksploatacyjnych.

PHOTOGRAPHIC DOCUMENTATION



Photo 1.
Przekątna przednia lewa



Photo 2.
Przód

PHOTOGRAPHIC DOCUMENTATION



Photo 3.

Przekątna przednia prawa



Photo 4.

Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 5.

Bok prawy z tyłu



Photo 6.

Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 7.

Tył



Photo 8.

Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 9.

Bok lewy z tyłu



Photo 10.

Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 11.
Próg lewy (widok od przodu)



Photo 12.
Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



Photo 13.
Spód pojazdu przód



Photo 14.
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION



Photo 15.

Tarcza hamulcowa przednia prawa



Photo 16.

Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 17.

Tarcza hamulcowa tylna lewa



Photo 18.

Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 19.
Bagażnik



Photo 20.
Komora silnika

PHOTOGRAPHIC DOCUMENTATION



Photo 21.
Numer identyfikacyjny



Photo 22.
Tabliczka znamionowa

PHOTOGRAPHIC DOCUMENTATION



Photo 23.

Zestaw wskaźników - przebieg



Photo 24.

Zestaw wskaźników - serwis

PHOTOGRAPHIC DOCUMENTATION



Photo 25.

Widok przez otwarte drzwi przednie lewe



Photo 26.

Kierownica z lewej strony

PHOTOGRAPHIC DOCUMENTATION



Photo 27.

Widok przez otwarte drzwi tylne lewe



Photo 28.

Widok z tylnej kanapy na deskę rozd.

PHOTOGRAPHIC DOCUMENTATION



Photo 29.
Konsola środkowa



Photo 30.
Tunel środkowy


PHOTOGRAPHIC DOCUMENTATION




Photo 31.
Kierownica (na wprost)



Photo 32.
Dowód rej. Str. 1

PHOTOGRAPHIC DOCUMENTATION**Photo 33.**

Książka serwisowa – dane

**Photo 34.**

Książka serwisowa – ostatni przegląd

PHOTOGRAPHIC DOCUMENTATION



Photo 35.
Dow. Rej. Str. 2



Photo 36.
Instrukcje

PHOTOGRAPHIC DOCUMENTATION



Photo 37.
Zestaw naprawczy koła



Photo 38.
Kluczyki

PHOTOGRAPHIC DOCUMENTATION



Photo 39.
Zdjęcie do protokołu




Photo 40.
Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 41.

Pokrywa komory silnika - zdjęcie poglądowe 1




Photo 42.

Pokrywa komory silnika - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 43.

Spoiler zderzaka przedniego - Rysa/odprysk 1



Photo 44.

Łotnik przedni P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 45.

Felga aluminiowa przednia P - Rysa/odprysk 1



Photo 46.

Drzwi przednie P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 47.

Drzwi przednie P - Wgniecenie/odkształcenie 1



Photo 48.

Drzwi tylne P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 49.

Drzwi tylne P - Rysa/odprysk 2



Photo 50.

Drzwi tylne P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION




Photo 51.

Klamka drzwi prz P - Rysa/odprysk 1



Photo 52.

Słupek środkowy P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 53.

Stupek środkowy P - Wgniecenie/odkształcenie 1



Photo 54.

Błotnik tylny P / Ściana boczna P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 55.

Felga aluminiowa tylna P - Rysa/odprysk 1



Photo 56.

Pokrywy bagażnika - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 57.

Szyba tylna - Rysa/odprysk 1



Photo 58.

Zderzak tylny - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 59.

Błotnik tylny L / Ściana boczna L - zdjęcie poglądowe 1



Photo 60.

Błotnik tylny L / Ściana boczna L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 61.

Błotnik tylny L / Ściana boczna L - Wgniecenie/odkształcenie 1




Photo 62.

Błotnik tylny L / Ściana boczna L - Wgniecenie/odkształcenie 2

PHOTOGRAPHIC DOCUMENTATION



Photo 63.

Felga aluminiowa tylna L - Rysa/odprysk 1



Photo 64.

Drzwi przed L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 65.

Drzwi przed L - Wgniecenie/odkształcenie 1



Photo 66.

Drzwi tylne L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 67.

Drzwi tylne L - Rysa/odprysk 2



Photo 68.

Drzwi tylne L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 69.

Próg L - Wgniecenie/odkształcenie 1



Photo 70.

Felga Aluminiowa przednia L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 71.

Pokrywa schowka deski rozdzielczej - Rysa/odprysk 1



Photo 72.

Fotel prz. lewy - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 73.

Fotel prz. praw. - Inne 1



Photo 74.

Kanapa tyl. - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 75.
Kanapa tyl. - Inne 2



Photo 76.
Listwy progowe lew. - Rysa/odprysk 1