

DEKRA's commission No. : PKOL(W)/LODZ/00657/26/01/05
commission/ damage No. : 23/031151
Date of commission: 05-01-2026

DEKRA Poland - Headquarters
02-673 Warszawa, ul. Konstruktorska 12A

Client :

PKO Leasing SA
Świętokrzyska 36
00-116 Warszawa

Expert:

Kacper Sosnowski (NEW)
DEKRA Polska - współpraca O/Warszawa
Andrzej Sosnowski
DEKRA Polska - Centrala

NOTE:

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

Vehicle data

Group of objects (Eurotax)	cars
EC code (Eurotax)	0128687
Manufacturer	AUDI
Model	A8 [4N] 17-21
Type / version	A8 50 TDI mHEV Quattro Tiptr.
Body type	sedan
Number of doors / seats	4/5
Curb weight [kg]	2095
Gross vehicle weight [kg]	2710
Wheelbase 1/2	2998
Engine type	Automatic ignition
Pollution reduction system	KSC
Engine capacity [ccm]	2967
Engine Power [hp/kW]	286/210
Gearbox	automatic
Registration /record No.	GA173KN
VIN / serial number	WAUZZZF80MN023847
Date of first registration	09-09-2021
Date of next. tech. test	05-09-2026
Year of manufacture	2021
Readout [km]	165 768 (read)
Body color / type of coating	granatowy/double-layered, metallized

Tyres

axle	Wheel	Manufacturer, type	Size	Measured profile
Front	right	MICHELIN, PILOT ALPIN 5 SUV	235/55 18 104H	5,0 mm
	left	MICHELIN, PILOT ALPIN 5 SUV	235/55 18 104H	5,0 mm
back	right	MICHELIN, PILOT ALPIN 5 SUV	235/55 18 104H	4,5 mm
	left	MICHELIN, PILOT ALPIN 5 SUV	235/55 18 104H	4,5 mm

Standard equipment by Eurotax

- | | |
|---|--|
| 1. 3 places rear bench | 26. LED front dim light |
| 2. Additional gauges, On board computer | 27. LED rear lights |
| 3. Alarm | 28. Leather gearshifter/switch |
| 4. Antilock-Brake-System (ABS) | 29. Leather steering wheel, Multi functional steering wheel |
| 5. Armrest (s) front, Storage facilities in general | 30. Leather upholstery |
| 6. Automatic air recirculation control | 31. Light Alloy wheels 18" |
| 7. Bluetooth interface | 32. Lumbar adjust driver electric, Lumbar adjust passenger electric |
| 8. Bord communication: other | 33. Mobile Tire System |
| 9. Child seat fixation | 34. Navigation system |
| 10. Colored glass | 35. Other |
| 11. Colour stripe in windscreen, Windows: other | 36. Other |
| 12. Comfort driver seat, Comfort passenger seat, Driver seat electrically adjustable, Electrically adjustable rear seats, Memory seat, Passenger seat electrically adjustable | 37. Other |
| 13. Cruise control | 38. Pakiet przeglądów serwisowych Audi 3 lata/90 000 km (Audi Perfect Lease) |
| 14. Door mirror with memory, Door mirror(s) electrically adjustable in general, Door mirrors electrically foldable, Door mirrors heated | 39. Park Distance Control front, Park Distance Control rear |
| 15. Driver airbag, Head airbags front, Passenger airbag, Side airbag driver, Side airbag driver and passenger, Side airbags rear | 40. Passive Tyre pressure control |
| 16. Dualzone automatic climate control | 41. Pre-Crash System |
| 17. Electric tailgate | 42. Rear headrests |
| 18. Exterior design: other | 43. Remote controlled central locking |
| 19. Floor mat | 44. Servotronic |
| 20. Headlamp wash | 45. Soundsystem |
| 21. Hydro pneumatic suspension | 46. Storage facilities in general |
| 22. Interior decoration: other | 47. Uni-Lackierung |
| 23. Interior decoration: other | 48. Vehicle immobilizer |
| 24. Interior lights: other accessories | 49. Wheel bolt locks |
| 25. LED Daytime running lights | |

Dealer's equipment (selected items)

- | | |
|---|---|
| 1. 360 view camera | - |
| 2. 4 or more zone automatic climate control | - |
| 3. Armrest (s) rear, Electrically adjustable rear seats, Lumbar adjust rear electric, Memory seat, Other, Rear headrests, Sunblind rear side door electric, Sunblind tailgate window electric | - |
| Rolety przeciwsłoneczne elektryczne - szyba tylna oraz szyby boczne
Fotele tylne komfortowe, pojedyncze, regulowane elektrycznie
Pamięć ustawień dla foteli tylnych
Elektryczna regulacja pozycji fotela pasażera przez osobę siedzącą z tyłu
Zagłówki tylne komfortowe
Podłokietnik tylny komfortowy, z aplikacją dekoracyjną i panelem obsługi klimatyzacja 4-strefowa | |
| 4. Bord entertainment: other accessories, On board monitor | - |
| 5. DAB radio, TV | - |
| 6. Diminished spare wheel | - |
| 7. Door mirrors autodimming | - |
| 8. Electric tailgate | - |
| 9. Front seat with massage, Rear seat with massage, Ventilated front seat, Ventilated rear seat | - |
| Fotele przednie i tylne z funkcją wentylacji
Fotele przednie i tylne z funkcją masażu | |

10. Glass sunroof fixed	-
11. Hatch/skibag in rear bench	-
12. Head-Up Display	-
13. Headlamp wash, LED front dim light, Side indicators	-
14. Heated seat driver, Heated seat passenger, Rear seat heating	-
15. Independent vehicle heater	-
16. Interior decoration: other, Interior: other	-
Konsola środkowa w skórze Feinnappa ze szwem ozdobnym	
Podszybie w drzwiach w skórze Feinnappa ze szwem ozdobnym	
Obszycie poduszki powietrznej kierowcy w skórze Feinnappa ze szwem ozdobnym	
Podłokietniki w drzwiach w skórze Feinnappa	
Górna część deski rozdzielczej pokryta skórą Feinnappa ze szwem ozdobnym	
17. Interior lights: other accessories	-
18. LED rear lights	-
19. Lane control assistant	-
20. Leather steering wheel, Multi functional steering wheel, Steering wheel with gear-switches	-
21. Metallic paint	-
22. Other	-
23. Other	-
24. Park Assistant	-
25. Soundsystem	-
26. Tinted rear windows	-
27. Towbar preparation	-
28. Traffic sign recognition	-
29. Windows: other	-

Base value of the vehicle

Base value of the vehicle by Eurotax (net) -

Corrections

First registration

Mileage

Equipment

Tyres

Other

Earlier repairs	-
Aktualna sytuacja rynkowa	-
Braki uszkodzenia stan	-


Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 01-2026 POL) with regard to technical and market parameters affecting the value of the vehicle.

Basic print without information about the vehicle's value - duey to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 20-01-2026

DEKRA's expert:
Kacper Sosnowski (NEW)
Andrzej Sosnowski

Document issued electronically valid without signature.

Measurement of thickness of the vehicle lacquer coating


No. of controlled item	Controlled item	Measured range of thickness of the lacquer coat [μm]
1	Front cover	to 150
2	Front left fender	150 - 300
3	Left front pillar	to 150
4	Front left door	150 - 300
5	Roof	to 150
6	Left middle pillar	to 150
7	Right side sill	to 150
8	Left rear door	to 150
9	Rear left fender	to 150
10	Cover/lid	to 150
11	Right rear fender	to 150
12	Right rear door	to 150
13	Right middle pillar	to 150
14	Right side sill	to 150
15	Front right door	150 - 300
16	Right front pillar	150 - 300
17	Front right fender	150 - 300

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

Presented the following documents of the vehicle:

ksero pozwolenia czasowego

During the inspection the service book was presented and its number is given below:
elektroniczna

Information concerning the origin of the vehicle

Lack of reliable data.

Anti-theft protection - immobilizer

- as a result of the inspection of the vehicle found no malfunctions of the immobilizer in the extent possible to determine during the inspection of the vehicle in the non- workshop conditions.

Anti-theft protection - other:

not found

Additional comments on the car:

Not applicable.

Test drive

Test drive of the vehicle was conducted. Test drive in the full extent is not possible. Comment below:
ograniczenia placowe

Checking of the correctness and / or construction of identification / serial numbers of the object:

Not tested

Verification of the accuracy of the object data, including year of production, and other.

Not conducted - adopted according to the documents presented and indicated sources.

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.
- The evaluation has been carried out basing on delivered documentation and organoleptic examination of

the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the assessed object.

- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

Comments to the commission - regarding valuation

Kluczyki

TAK

1

Expert comments - regarding valuation

Dostarczono ksero pozwolenia czasowego. Pierwsza rejestracja w kraju 28-06-2023. Aktywna kontrolka ciśnienia w kołach. Rysy na samochodzie. Odpryski na szybie czołowej. Widoczne wady lakiernicze.

Rzeczoznawca dokonał oględzin pojazdu w warunkach parkingowych, co mogło ograniczyć pełną ocenę jego stanu technicznego. Dodatkowo, jeżeli jazda próbna została przeprowadzona (informacje w treści raportu), to wykonano ją w warunkach parkingowych, z niewielką prędkością, co może nie odzwierciedlać pełnych warunków eksploatacyjnych. Istnieje możliwość, że w innych okolicznościach ujawnią się dodatkowe uszkodzenia lub usterki, których nie można było wykryć podczas obecnych oględzin. Zalecamy zatem skorzystanie z możliwości oględzin pojazdu we własnym zakresie lub w Autoryzowanej Stacji Obsługi danej marki, co pozwoli na pełniejszą weryfikację stanu technicznego pojazdu przed udziałem w aukcji."

Restrictive disclaimer - regarding valuation

Nie weryfikowano szczegółowo stanu układu napędowego, zawieszenia, kierowniczego, hamulcowego oraz wydechowego. Ocena została wykonana bez użycia podnośnika i specjalistycznego sprzętu diagnostycznego, nie dokonywano demontażu osłon i innych elementów. Ocena określa ogólny stan pojazdu na dzień oględzin w miejscu jego udostępnienia, nie może być zatem traktowana jako kompleksowa ocena stanu technicznego. Specyfikacja wg. programu operacyjnego w zakresie wyposażenia standardowego i dodatkowego nie gwarantuje zgodności ze stanem faktycznym w zakresie możliwym do ustalenia przez rzeczoznawcę podczas oględzin pojazdu.

Pomiar grubości powłoki lakierowej wykonano w miejscach możliwych do ich wykonania pomiary nie gwarantują oryginalności poszczególnych elementów poddanych ocenie.

- W Ocenie/Raporcie uwzględniono niesprawności, uszkodzenia, braki itp., które były możliwe do stwierdzenia organoleptycznego, w warunkach oględzin (z uwzględnieniem: stanu czystości pojazdu, warunków atmosferycznych, oświetlenia itd.) oraz bez weryfikacji serwisowej, bez dostępu do spodu pojazdu, bez specjalistycznego sprzętu diagnostycznego (w tym bez diagnostyki komputerowej), bez jazdy próbnej wykonanej w warunkach drogowych z obciążeniem.
- W ramach Oceny/Raporu nie weryfikowano odczytanego stanu drogomierza z zapisami w urządzeniach elektronicznych pojazdu.
- Rzeczoznawca nie bierze na siebie odpowiedzialności za wady ukryte (prawne i fizyczne) oraz ewentualne skutki wynikające z dalszego użytkowania przedmiotu oceny, a także za skutki wykorzystania samej oceny.
- Podane przedziały grubości powłoki lakierowej, dotyczą punktów pomiarowych. Nie mogą być traktowane jako gwarancja, że grubość powłoki lakierowej w innych punktach nie wykracza poza te przedziały.

- Zawarte w niniejszej Ocenie/Raporcie informacje (w tym dotyczące wyposażenia) służą jedynie ogólnym celom informacyjnym. Ocena/Raport nie może być zatem traktowana jako oferta w rozumieniu przepisów Kodeksu Cywilnego oraz opisu towaru ani zapewnienia w rozumieniu art. 4 Ustawy z dnia 27 lipca 2002 roku o szczególnych warunkach sprzedaży konsumenckiej.
- Niniejsza Ocena/Raport nie jest szczegółową oceną stanu technicznego.

Ocenę/Raport wykonano w kierunku ujawnienia uszkodzeń nieakceptowanych z punktu widzenia właściwego przewodnika zwrotu pojazdu lub innych ustaleń ze Zleceniodawcą. Tym samym Ocena/Raport może nie ujmować typowych zużyć i uszkodzeń eksploatacyjnych.

PHOTOGRAPHIC DOCUMENTATION



Photo 1.
Przekątna przednia lewa



Photo 2.
Przód

PHOTOGRAPHIC DOCUMENTATION



Photo 3.

Przekątna przednia prawa



Photo 4.

Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 5.
Bok prawy z tyłu



Photo 6.
Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 7.

Tył



Photo 8.

Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 9.

Bok lewy z tyłu



Photo 10.

Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 11.

Próg lewy (widok od przodu)



Photo 12.

Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



Photo 13.
Spód pojazdu przód



Photo 14.
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION



Photo 15.

Tarcza hamulcowa przednia prawa



Photo 16.

Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION




Photo 17.

Tarcza hamulcowa tylna lewa



Photo 18.

Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 19.
Bagażnik



Photo 20.
Koło zapasowe

PHOTOGRAPHIC DOCUMENTATION



Photo 21.
Komora silnika



Photo 22.
Numer identyfikacyjny

PHOTOGRAPHIC DOCUMENTATION



Photo 23.
Tabliczka znamionowa



Photo 24.
Zestaw wskaźników - przebieg

PHOTOGRAPHIC DOCUMENTATION



Photo 25.

Widok przez otwarte drzwi przednie lewe



Photo 26.

Kierownica z lewej strony

PHOTOGRAPHIC DOCUMENTATION



Photo 27.

Widok przez otwarte drzwi tylne lewe



Photo 28.

Widok z tylnej kanapy na deskę rozdziel.

PHOTOGRAPHIC DOCUMENTATION



Photo 29.
Konsola środkowa




Photo 30.
Tunel środkowy

PHOTOGRAPHIC DOCUMENTATION

Photo 31.
Kierownica (na wprost)



Photo 32.
Dowód rej. Str. 1

PHOTOGRAPHIC DOCUMENTATION**Photo 33.**

Dow. Rej. Str.2 i klucze

**Photo 34.**

Książka serwisowa – dane

PHOTOGRAPHIC DOCUMENTATION



Photo 35.

Książka serwisowa – ostatni przegląd



Photo 36.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 37.

Zdjęcie do protokołu




Photo 38.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 39.

Zdjęcie do protokołu



Photo 40.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 41.

Zdjęcie do protokołu



Photo 42.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 43.

Zdjęcie do protokołu



Photo 44.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 45.

Zdjęcie do protokołu



Photo 46.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 47.

Zdjęcie do protokołu




Photo 48.

Pokrywa komory silnika - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 49.

Drzwi przednie P - Rysa/odprysk 1



Photo 50.

Drzwi tylne P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 51.

Błotnik tylny P / Ściana boczna P - Rysa/odprysk 1



Photo 52.

Pokrywy bagażnika - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 53.

Zderzak tylny - Rysa/odprysk 1



Photo 54.

Zderzak tylny - Rysa/odprysk 2

PHOTOGRAPHIC DOCUMENTATION



Photo 55.

Błotnik tylny L / Ściana boczna L - Rysa/odprysk 1



Photo 56.

Drzwi przed L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION




Photo 57.

Drzwi przed L - Wgniecenie/odkształcenie 1



Photo 58.

Drzwi przed L - Wgniecenie/odkształcenie 2

PHOTOGRAPHIC DOCUMENTATION



Photo 59.

Drzwi tylne L - Rysa/odprysk 1



Photo 60.

Słupek przedni L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 61.

Słupki przedni L - Rysa/odprysk 2



Photo 62.

Podłokietnik środkowy przedni - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 63.

Tapicerka drzwi tylnych P - Inne 1



Photo 64.

Osłona p/słoneczna lewa - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 65.

Podsufitka - Inne 1




Photo 66.

Wykładzina(y) słupka przedniego L - Inne 1