

DEKRA's commission No. : PKOL(W)/LODZ/85578/26/09/11
commission/ damage No. : 25/003741
Date of commission: 11-09-2026

DEKRA Poland - Headquarters
02-673 Warszawa, ul. Konstruktorska 12A

Client :

PKO Leasing SA
Świętokrzyska 36
00-116 Warszawa

Expert:

Kacper Sosnowski (WSP)
DEKRA Polska - współpraca O/Warszawa
inż. Józef Orłowski
TU - Włocławek

NOTE:

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

Vehicle data

Group of objects (Eurotax)	cars
EC code (Eurotax)	0149530
Manufacturer	FORD
Model	Mustang Fastback 18-24
Type / version	Mustang 5.0 V8 Mach 1 aut
Body type	CPE
Number of doors / seats	3/4
Curb weight [kg]	1774
Gross vehicle weight [kg]	2150
Wheelbase 1/2	2720
Engine type	spark ignition
Pollution reduction system	GPF
Engine capacity [ccm]	5038
Engine Power [hp/kW]	460/338
Gearbox	automatic 10- gear
Registration /record No.	W2DZIK2
VIN / serial number	1FA6P8R09N5551292
Date of first registration	03-10-2023
Date of next. tech. test	03-10-2026
Year of manufacture	2022 (year has been verified with the manufacturer's base)
Readout [km]	34 859 (read)
Body color / type of coating	orange/2-warstwowy uni

Tyres

axle	Wheel	Manufacturer, type	Size	Measured profile
Front	right	BRIDGESTONE, BLIZZAK LM005	255/40 19 100V	4,5 mm
	left	BRIDGESTONE, BLIZZAK LM005	255/40 19 100V	5,0 mm
back	right	BRIDGESTONE, BLIZZAK LM005	255/40 19 100V	3,5 mm
	left	BRIDGESTONE, BLIZZAK LM005	255/40 19 100V	3,0 mm

Standard equipment by Eurotax

- | | |
|---|--|
| 1. Active body control | 39. Interior: other, Storage facilities in general |
| 2. Alarm | 40. Internet access, Keyless entry, Other |
| 3. Android Auto, Apple CarPlay, Bluetooth interface, CD-player, DAB radio, Hands-free system, mp3 Player, Navigation system, On board monitor, Radio, Soundsystem, Touchscreen monitor, USB in, Voice control for audiosystem, Voice control for navigation system, Voice control for telephone | 41. Keyless go |
| 4. Antilock-Brake-System (ABS) | 42. Keyless go, Remote controlled central locking |
| 5. Automated High-beam assist, Automatic dimlight activation | 43. LED Daytime running lights |
| 6. Automatic dimlight activation | 44. LED front dim light |
| 7. Brake Assist, Collision Warning System, Pedestrian Emergency Brake Assist, Pre-Crash System | 45. LED rear lights |
| 8. Bumpers: other, Exterior design: other | 46. Lane control assistant |
| 9. Bumpers: other, Exterior design: other | 47. Leather steering wheel, Steering wheel heated |
| 10. Bumpers: other, Exterior design: other | 48. Light Alloy wheels 19" |
| 11. Child seat fixation | 49. Mobile Tire System |
| 12. Cruise control | 50. Multi functional steering wheel |
| 13. Digital instruments, On board monitor | 51. Other |
| 14. Distribution of braking force electronically | 52. Other |
| 15. Door mirror(s) electrically adjustable in general, Door mirrors electrically foldable, Door mirrors heated, Exterior lighting: other | 53. Other |
| 16. Driver airbag, Passenger airbag | 54. Other |
| 17. Driver knee airbag | 55. Other |
| 18. Driver seat electrically adjustable | 56. Other |
| 19. Driver-information-system, Other | 57. Passenger seat electrically adjustable |
| 20. Dualzone automatic climate control | 58. Power steering |
| 21. ESP (Electronical Stabilizing Program), Power assisted brakes, Traction control | 59. Power windows front |
| 22. Exterior design: other | 60. Rear bench foldable in two separate parts |
| 23. Exterior design: other | 61. Rear spoiler |
| 24. Exterior design: other | 62. Rear view camera |
| 25. Exterior design: other | 63. Rear-view mirror autodimming |
| 26. Exterior design: other | 64. Remote controlled central locking |
| 27. Exterior design: other | 65. Selectable driveline characteristics |
| 28. Exterior design: other | 66. Side airbag driver and passenger |
| 29. Floor mat | 67. Side indicators |
| 30. Fog lamps | 68. Sport seats front |
| 31. Head airbags front, Head airbags rear | 69. Steering wheel with gear-switches |
| 32. Heated seat driver, Heated seat passenger, Ventilated front seat | 70. Tyre pressure control (RDC) |
| 33. Hill holder | 71. Uni-Lackierung |
| 34. Interior lights: other accessories | 72. Upholstery with leather inserts |
| 35. Interior: other | 73. Vehicle immobilizer |
| 36. Interior: other | 74. Wheels: other |
| 37. Interior: other | 75. Windows: other |
| 38. Interior: other | 76. Windscreenwiper: other |

Dealer's equipment (selected items)

1. Exterior design: other, Leather upholstery -
 Tapicerka skórzana, perforowana Lux
 Pasy na masce i wzdłuż boków nadwozia, czarno-pomarańczowe
 Zaciski hamulcowe lakierowane na pomarańczowo

Base value of the vehicle

Base value of the vehicle by Eurotax (net) -


CorrectionsFirst registrationMileageEquipmentTyresOtherZwiększona grubość powłoki lakierniczej -
Stwierdzone braki i uszkodzenia -

Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 09-2026 POL) with regard to technical and market parameters affecting the value of the vehicle.

Basic print without information about the vehicle's value - duey to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 28-09-2026

DEKRA's expert:
Kacper Sosnowski (WSP)
inż. Józef Orłowski**Document issued electronically valid without signature.**

Measurement of thickness of the vehicle lacquer coating


No. of controlled item	Controlled item	Measured range of thickness of the lacquer coat [μm]
1	Front cover	150 - 200
2	Front left fender	150 - 200
3	Left front pillar	to 150
4	Front left door	150 - 200
5	Roof	150 - 200
6	Left middle pillar	to 150
7	Right side sill	to 150
9	Rear left fender	150 - 200
10	Cover/lid	150 - 200
11	Right rear fender	150 - 200
13	Right middle pillar	to 150
14	Right side sill	to 150
15	Front right door	150 - 200
16	Right front pillar	to 150
17	Front right fender	150 - 200

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

During the inspection the registration proof of the vehicle was presented and its photo was taken and enclosed to the expertise.

During the inspection the service book of the vehicle was not provided.

Information concerning the origin of the vehicle

The vehicle purchased domestically from an authorized representative of the brand.

Anti-theft protection - immobilizer

- as a result of the inspection of the vehicle found no malfunctions of the immobilizer in the extent possible to determine during the inspection of the vehicle in the non- workshop conditions.

Anti-theft protection - other:

not found

Additional comments on the car:

Not applicable.

Test drive

Test drive of the vehicle was conducted. Test drive in the full extent is not possible. Comment below: ograniczenia parkingowe

Checking of the correctness and / or construction of identification / serial numbers of the object:

Not tested

Verification of the accuracy of the object data, including year of production, and other.

Not conducted - adopted according to the documents presented and indicated sources.

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.
- The evaluation has been carried out basing on delivered documentation and organoleptic examination of the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the

page 5/30

assessed object.

- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

Comments to the commission - regarding valuation

Kluczyki

TAK

2

Expert comments - regarding valuation

Rysy na samochodzie. Aktywna kontrolka silnika. Niesprawne przyciski funkcyjne w jednym z kluczyków, grot prawidłowy. Brak płynu zestawu naprawczego. Informacja bateria kluczyka rozładowana. Odpryski na szybie czołowej.

PHOTOGRAPHIC DOCUMENTATION



Photo 1.

Przekątna przednia lewa



Photo 2.

Przód

PHOTOGRAPHIC DOCUMENTATION



Photo 3.

Przekątna przednia prawa



Photo 4.

Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 5.
Bok prawy z tyłu



Photo 6.
Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 7.
Tył



Photo 8.
Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 9.

Bok lewy z tyłu



Photo 10.

Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 11.
Próg lewy (widok od przodu)



Photo 12.
Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



Photo 13.
Spód pojazdu przód



Photo 14.
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION



Photo 15.

Tarcza hamulcowa przednia prawa



Photo 16.

Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 17.

Tarcza hamulcowa tylna lewa



Photo 18.

Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 19.
Bagażnik



Photo 20.
Komora silnika

PHOTOGRAPHIC DOCUMENTATION



Photo 21.
Numer identyfikacyjny



Photo 22.
Tabliczka znamionowa

PHOTOGRAPHIC DOCUMENTATION



Photo 23.

Zestaw wskaźników - przebieg



Photo 24.

Zestaw wskaźników - serwis

PHOTOGRAPHIC DOCUMENTATION



Photo 25.

Widok przez otwarte drzwi przednie lewe



Photo 26.

Kierownica z lewej strony

PHOTOGRAPHIC DOCUMENTATION



Photo 27.

Widok przez otwarte drzwi tylne lewe



Photo 28.

Widok z tylnej kanapy na deskę rozdzielczą

PHOTOGRAPHIC DOCUMENTATION



Photo 29.
Konsola środkowa




Photo 30.
Tuneł środkowy

PHOTOGRAPHIC DOCUMENTATION



Photo 31.

Kierownica (na wprost)



Photo 32.

Dowód rej. Str. 1

PHOTOGRAPHIC DOCUMENTATION



Photo 33.
Dow. Rej. Str. 2



Photo 34.
Zestaw naprawczy koła

PHOTOGRAPHIC DOCUMENTATION



Photo 35.
Kluczyki



Photo 36.
Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 37.
Zdjęcie do protokołu



Photo 38.
Pokrywa komory silnika - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 39.

Felga aluminiowa przednia P - Rysa/odprysk 1



Photo 40.

Drzwi przednie P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 41.
Zderzak tylny - Inne 1



Photo 42.
Zderzak tylny - Inne 2

PHOTOGRAPHIC DOCUMENTATION



Photo 43.

Błotnik tylny L / Ściana boczna L - Wgniecenie/odkształcenie 1




Photo 44.

Błotnik tylny L / Ściana boczna L - Wgniecenie/odkształcenie 2

PHOTOGRAPHIC DOCUMENTATION



Photo 45.

Drzwi przed L - Rysa/odprysk 1



Photo 46.

Słupek środkowy L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 47.

Wykładzina przestrzeni bagażowej - Rysa/odprysk 1