

DEKRA's commission No. : PKOL(W)/LODZ/89088/26/09/22
commission/ damage No. : 21/050722
Date of commission: 22-09-2026

DEKRA Poland - Headquarters
02-673 Warszawa, ul. Konstruktorska 12A

Client :

PKO Leasing SA
Świętokrzyska 36
00-116 Warszawa

Expert:

Kacper Sosnowski (WSP)
DEKRA Polska - współpraca O/Warszawa
Ivan Halaburda (WSP)
DEKRA Polska - współpraca O/Białystok

NOTE:

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

Vehicle data

Group of objects (Eurotax)	cars
EC code (Eurotax)	0144887
Manufacturer	OPEL
Model	Insignia B Grand Sport 20-22
Type / version	Insignia 2.0 CDTI GS Line S&S aut
Body type	hatchback
Number of doors / seats	5/5
Curb weight [kg]	1540
Gross vehicle weight [kg]	2200
Wheelbase 1/2	2829
Engine type	Automatic ignition
Pollution reduction system	KSC
Engine capacity [ccm]	1995
Engine Power [hp/kW]	174/128
Gearbox	automatic 8- gear
Registration /record No.	PO9UY82
VIN / serial number	W0VZT6GP9M1013582
Date of first registration	30-07-2021
Date of next. tech. test	28-07-2027
Year of manufacture	2021 (year has been verified with the manufacturer's base)
Readout [km]	212 984 (read)
Body color / type of coating	grafitowy/METALIK

Tyres

axle	Wheel	Manufacturer, type	Size	Measured profile
Front	right	UNIROYAL, RAINSPORT 5	245/45 18 100Y	5,5 mm
	left	UNIROYAL, RAINSPORT 5	245/45 18 100Y	5,5 mm
back	right	UNIROYAL, RAINSPORT 5	245/45 18 100Y	6,0 mm
	left	UNIROYAL, RAINSPORT 5	245/45 18 100Y	6,0 mm

Standard equipment by Eurotax

- | | |
|---|--|
| 1. Active Tyre pressure control | 33. Interior: other |
| 2. Additional heating | 34. LED Daytime running lights |
| 3. Airbag: other | 35. LED front dim light |
| 4. Android Auto, Apple CarPlay, Bluetooth interface, Hands-free system, On board monitor, Radio, Touchscreen monitor, Voice control for telephone | 36. LED rear lights |
| 5. Antilock-Brake-System (ABS) | 37. Leather steering wheel, Sports steering wheel |
| 6. Armrest (s) front, Extra power outlet, Storage facilities in general | 38. Light Alloy wheels 18" |
| 7. Automated High-beam assist | 39. Mirror: others |
| 8. Automated High-beam assist, Automatic dimlight activation | 40. Mobile Tire System |
| 9. Automatic climate control | 41. On board monitor |
| 10. Bord climate: other | 42. Other |
| 11. Bord climate: other | 43. Other |
| 12. Bord entertainment: other accessories | 44. Other |
| 13. Cabin air filter | 45. Park Distance Control front, Park Distance Control rear |
| 14. Collision Warning System | 46. Power assisted brakes |
| 15. Cruise control | 47. Power windows front, Power windows rear |
| 16. DAB radio | 48. Rain sensor |
| 17. Door mirror(s) electrically adjustable in general, Door mirrors heated | 49. Rear seat-backs foldable in two separate parts |
| 18. Driver airbag, Head airbags front, Head airbags rear, Passenger airbag, Side airbag driver and passenger | 50. Remote controlled central locking |
| 19. ESP (Electronical Stabilizing Program) | 51. Seats: other |
| 20. Exterior design: other | 52. Seats: other, Storage facilities in general |
| 21. Exterior design: other | 53. Sport seats front |
| 22. Exterior design: other | 54. Steering wheel heated |
| 23. Exterior design: other | 55. Steering wheel manually adjustable |
| 24. Exterior design: other | 56. Steering wheel with radio operation |
| 25. Fog lamps | 57. Steering: other |
| 26. Headrest rear, middle | 58. Textile upholstery |
| 27. Headrests front | 59. Tinted rear windows |
| 28. Hill holder | 60. Tyre pressure control (RDC) |
| 29. Interior decoration: other | 61. Uni-Lackierung |
| 30. Interior lights: other accessories | 62. Vehicle immobilizer |
| 31. Interior: other | 63. Windows: other |
| 32. Interior: other | 64. {Aktywny asystent utrzymania pasa ruchu, Lane Keep Assist} |

Dealer's equipment (selected items)

- | | |
|--|---|
| 1. Alarm | - |
| 2. Android Auto, Apple CarPlay, Bluetooth interface, Hands-free system, Navigation system, On board monitor, Radio, Touchscreen monitor, USB in, Voice control for audiosystem, Voice control for navigation system, Voice control for telephone | - |
| 3. Automated High-beam assist, LED front dim light, Traffic sign recognition | - |
| Kamera Opel Eye rozpoznająca znaki drogowe | |
| Reflektory pikselowe IntelliLux LED z automatycznym sterowaniem światłami drogowymi | |
| 4. Blind spot warning, Door mirrors electrically foldable, Exterior lighting: other, Rear Cross Traffic Alert, Rear view camera | - |
| Lusterka boczne składane elektrycznie z podświetleniem podłoża | |
| Kamera cofania cyfrowa | |
| Układ ostrzegania o pojeździe w martwym polu | |
| Układ ostrzegania o pojeździe zbliżającym się z tyłu | |

5. Metallic paint -
6. Wheels: other -

Base value of the vehicle

Base value of the vehicle by Eurotax (net) -

Corrections

First registration

Mileage

Equipment

Tyres

Other

Stan dbałości o pojazd -
Weryfikacja serwisowa -


Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 09-2026 POL) with regard to technical and market parameters affecting the value of the vehicle.

Basic print without information about the vehicle's value - due to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 23-09-2026

DEKRA's expert:
Kacper Sosnowski (WSP)
Ivan Halaburda (WSP)

Document issued electronically valid without signature.

Measurement of thickness of the vehicle lacquer coating


No. of controlled item	Controlled item	Measured range of thickness of the lacquer coat [μm]
1	Front cover	to 150
2	Front left fender	to 150
3	Left front pillar	to 150
4	Front left door	to 150
5	Roof	to 150
6	Left middle pillar	to 150
7	Right side sill	to 150
8	Left rear door	to 150
9	Rear left fender	to 150
10	Cover/lid	to 150
11	Right rear fender	to 150
12	Right rear door	to 150
13	Right middle pillar	to 150
14	Right side sill	to 150
15	Front right door	to 150
16	Right front pillar	to 150
17	Front right fender	to 150

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

During the inspection the registration proof of the vehicle was presented and its photo was taken and enclosed to the expertise.

During the inspection the service book was presented and its number is given below:

.

Information concerning the origin of the vehicle

The vehicle purchased domestically from an authorized representative of the brand.

Anti-theft protection - immobilizer

- as a result of the inspection of the vehicle found no malfunctions of the immobilizer in the extent possible to determine during the inspection of the vehicle in the non- workshop conditions.

Anti-theft protection - other:

not found

Additional comments on the car:

Not applicable.

Test drive

The test drive has been conducted on a distance and in time enabling rough estimation of the technical condition of the vehicle.

Checking of the correctness and / or construction of identification / serial numbers of the object:

Not tested

Verification of the accuracy of the object data, including year of production, and other.

Not conducted (with the exception of the year of production) - adopted according to the documents presented and indicated sources.

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.

- The evaluation has been carried out basing on delivered documentation and organoleptic examination of the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the assessed object.

- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

Comments to the commission - regarding valuation

Kluczyki

TAK

2

Expert comments - regarding valuation

Rysy na samochodzie. Poziom oleju silnikowego poniżej minimum. Nierówna praca silnika, do weryfikacji serwisowej. Odpryski na szybie czołowej.

PHOTOGRAPHIC DOCUMENTATION



Photo 1.
Przekątna przednia lewa



Photo 2.
Przód

PHOTOGRAPHIC DOCUMENTATION



Photo 3.

Przekątna przednia prawa



Photo 4.

Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 5.
Bok prawy z tyłu



Photo 6.
Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 7.

Tył



Photo 8.

Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 9.

Bok lewy z tyłu



Photo 10.

Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 11.

Próg lewy (widok od przodu)



Photo 12.

Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



Photo 13.
Spód pojazdu przód



Photo 14.
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION



Photo 15.

Tarcza hamulcowa przednia prawa



Photo 16.

Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 17.

Tarcza hamulcowa tylna lewa



Photo 18.

Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 19.
Bagażnik



Photo 20.
Komora silnika

PHOTOGRAPHIC DOCUMENTATION



Photo 21.

Numer identyfikacyjny



Photo 22.

Tabliczka znamionowa

PHOTOGRAPHIC DOCUMENTATION



Photo 23.

Zestaw wskaźników - przebieg



Photo 24.

Zestaw wskaźników - serwis

PHOTOGRAPHIC DOCUMENTATION



Photo 25.

Widok przez otwarte drzwi przednie lewe



Photo 26.

Kierownica z lewej strony

PHOTOGRAPHIC DOCUMENTATION



Photo 27.

Widok przez otwarte drzwi tylne lewe



Photo 28.

Widok z tylnej kanapy na deskę rozdz.

PHOTOGRAPHIC DOCUMENTATION



Photo 29.
Konsola środkowa



Photo 30.
Tunel środkowy

PHOTOGRAPHIC DOCUMENTATION



Photo 31.
Kierownica (na wprost)



Photo 32.
Dowód rej. Str. 1

PHOTOGRAPHIC DOCUMENTATION



Dane pojazdu / Przegląd przedprzedażny

Przegląd przedprzedażny i dostawa pojazdu
W celu zapewnienia, że samochód jest pozbawiony jakichkolwiek usterek, przed dostarczeniem pojazdu Klientowi przeprowadzany jest przegląd przedprzedażny.
Klient został poinformowany o częstotliwości czynności serwisowych, wymiany oleju oraz sprawdzania poziomu oleju oraz otrzymał listę kontrolną czynności obsługowych w ramach przeglądu przedprzedażnego.

Dane pojazdu

Model: Opel Insignia
Numer identyfikacyjny pojazdu: W0V2T6GP3412135-82
Typ silnika, numer silnika: MADx 0208
Skrzynia biegów: cebront
Kod koloru lakieru: GFG
Kod wykonczenia wnętrza: TAL
Numer kluczyka: 20084

Przegląd przedprzedażny

Autoryzacja: Spółka
Adres: 30-
Miejsce: 30-
Data: 30-

Photo 33.

Książka serwisowa – dane



Przegląd okresowy

Data: 25.09.23 km: 91752

Olej silnikowy: 0 W: 20
Lepkość: 0 W: 20
Środek przeciwzapalny: 0 W: 20
Temperatura: -32 °C

Przegląd okresowy

Data: 01.10.23 km: 113186

Olej silnikowy: 0 W: 20
Lepkość: 0 W: 20
Środek przeciwzapalny: 0 W: 20
Temperatura: -33 °C

Przegląd okresowy

Data: 18.02.25 km: 146000

Olej silnikowy: 0 W: 20
Lepkość: 0 W: 20
Środek przeciwzapalny: 0 W: 20
Temperatura: -33 °C

Potwierdzenie czynności serwisowych

Data: 18.02.26 km: 146000

Olej silnikowy: 0 W: 20
Lepkość: 0 W: 20
Środek przeciwzapalny: 0 W: 20
Temperatura: -33 °C

Następny przegląd według wskazań

Data: 25.09.24 km: 121700
(+ maks. 1 miesiąc) (+ maks. 1500 km)

Następny przegląd według wskazań

Data: 01.10.24 km: 143186
(+ maks. 1 miesiąc) (+ maks. 1500 km)

Następny przegląd według wskazań

Data: 18.02.25 km: 176000
(+ maks. 1 miesiąc) (+ maks. 1500 km)

Następny przegląd według wskazań

Data: 18.02.26 km: 176000
(+ maks. 1 miesiąc) (+ maks. 1500 km)

Photo 34.

Książka serwisowa – ostatni przegląd

PHOTOGRAPHIC DOCUMENTATION



Photo 35.
Dow. Rej. Str. 2



Photo 36.
Zestaw naprawczy koła

PHOTOGRAPHIC DOCUMENTATION



Photo 37.

Kluczyki



Photo 38.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION




Photo 39.

Pokrywa komory silnika - Rysa/odprysk 1



Photo 40.

Pokrywa komory silnika - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 41.

Zderzak - Rysa/odprysk 1



Photo 42.

Zderzak - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 43.

Błotnik przedni P - Wgniecenie/odkształcenie 1



Photo 44.

Felga aluminiowa przednia P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 45.

Drzwi przednie P - Rysa/odprysk 1




Photo 46.

Drzwi przednie P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 47.

Drzwi tylne P - Rysa/odprysk 1



Photo 48.

Drzwi tylne P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 49.

Błotnik tylny P / Ściana boczna P - Wgniecenie/odkształcenie 1



Photo 50.

Felga aluminiowa tylna P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 51.

Pokrywy bagażnika - Rysa/odprysk 1



Photo 52.

Szyba tylna - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 53.

Zderzak tylny - Rysa/odprysk 1



Photo 54.

Zderzak tylny - Rysa/odprysk 2

PHOTOGRAPHIC DOCUMENTATION



Photo 55.

Zderzak tylny - Wgniecenie/odkształcenie 1



Photo 56.

Dach - zdjęcie poglądowe 1

PHOTOGRAPHIC DOCUMENTATION



Photo 57.

Dach - Wgniecenie/odkształcenie 1




Photo 58.

Dach - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 59.

Błotnik tylny L / Ściana boczna L - Wgniecenie/odkształcenie 1




Photo 60.

Błotnik tylny L / Ściana boczna L - Wgniecenie/odkształcenie 2

PHOTOGRAPHIC DOCUMENTATION




Photo 61.

Felga aluminiowa tylna L - Rysa/odprysk 1



Photo 62.

Drzwi przed L - zdjęcie poglądowe 1

PHOTOGRAPHIC DOCUMENTATION



Photo 63.

Drzwi przed L - Rysa/odprysk 1



Photo 64.

Drzwi przed L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 65.

Drzwi tylne L - Rysa/odprysk 1



Photo 66.

Drzwi tylne L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION




Photo 67.

Felga Aluminiowa przednia L - Rysa/odprysk 1



Photo 68.

Koło kierownicy - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 69.

Fotel prz. lew. - Pęknięcie/rozerwanie 1



Photo 70.

Fotel prz. praw. - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 71.
Kanapa tyl. - Inne 1



Photo 72.
Wykładzina(y) słupka środkowego L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 73.

Wykładzina podłogi - zdjęcie poglądowe 1



Photo 74.

Wykładzina podłogi - Inne 1