

DEKRA's commission No. : PKOL(W)/LODZ/71043/26/07/30
commission/ damage No. : 22/036206
Date of commission: 30-07-2026

DEKRA Poland - Headquarters
02-673 Warszawa, ul. Konstruktorska 12A

Client :

PKO Leasing SA
Świętokrzyska 36
00-116 Warszawa

Expert:

Kacper Sosnowski (WSP)
DEKRA Polska - współpraca O/Warszawa
mgr inż. Michał Świątek
DEKRA Polska - Centrala

NOTE:

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

Vehicle data

Group of objects (Eurotax)	cars
EC code (Eurotax)	0142668
Manufacturer	MAZDA
Model	MX-30 EV 20-
Type / version	MX-30 35.5kWh Hikari
Body type	hatchback
Number of doors / seats	5/5
Curb weight [kg]	1645
Gross vehicle weight [kg]	2119
Wheelbase 1/2	2655
Engine type	elektryczny
Pollution reduction system	-
Emission standard	EEV
Engine capacity [ccm]	0
Engine Power [hp/kW]	145/107
Gearbox	automatic 1- gear
Registration /record No.	KR7XY36
VIN / serial number	JMZDR1WBJ00117591
Date of first registration	25-06-2021
Date of next. tech. test	25-06-2024
Year of manufacture	2021
Readout [km]	51 000 (read)
Body color / type of coating	red/multi-layered, pearly

Tyres

axle	Wheel	Manufacturer, type	Size	Measured profile
Front	right	Falken, EUROWINTER HS01 SUV XL	215/55 R18 99V	2,0 mm
	left	Falken, EUROWINTER HS01 SUV XL	215/55 R18 99V	4,0 mm
back	right	Falken, EUROWINTER HS01 SUV XL	215/55 R18 99V	5,0 mm

left Falken, EUROWINTER HS01 215/55 R18 99V
SUV XL

4,0 mm

Standard equipment by Eurotax

- | | |
|---|---|
| 1. Adaptive Cruise Control | 34. Interior: other |
| 2. Alarm | 35. Interior: other |
| 3. Android Auto, Apple CarPlay | 36. Keyless Engine start |
| 4. Armrest (s) front | 37. Keyless go |
| 5. Armrest (s) rear | 38. LED Daytime running lights |
| 6. Automatic climate control | 39. LED rear lights |
| 7. Automatic dimlight activation, Rain sensor | 40. Lane control assistant |
| 8. Bluetooth interface, Hands-free system | 41. Leather gearshifter/switch, Leather steering wheel |
| 9. Bord communication: other | 42. Light Alloy wheels 18" |
| 10. Bord entertainment: other accessories, On board monitor, Radio | 43. Mobile Tire System |
| 11. Brake Assist, Power assisted brakes | 44. Navigation system |
| 12. Central locking | 45. On board monitor |
| 13. Cornering Headlights, LED front dim light | 46. Other |
| 14. DAB radio, Radio | 47. Other |
| 15. Door mirror(s) electrically adjustable in general | 48. Other |
| 16. Door mirrors autodimming | 49. Other |
| 17. Door mirrors electrically foldable | 50. Park Distance Control front, Park Distance Control rear |
| 18. Door mirrors heated | 51. Power windows front |
| 19. Driver airbag, Passenger airbag, Side airbag driver, Side airbag driver and passenger | 52. Rear view camera |
| 20. Driver knee airbag | 53. Rear-view mirror autodimming |
| 21. Driver seat electrically adjustable, Memory seat | 54. Soundsystem |
| 22. Driver-information-system | 55. Steering wheel heated |
| 23. Driver-information-system | 56. Tinted rear windows |
| 24. ESP (Electronical Stabilizing Program) | 57. Traffic sign recognition |
| 25. Electric parking brake | 58. Transmission: other |
| 26. Extra power outlet | 59. Tyre pressure control (RDC) |
| 27. Head airbags front | 60. USB in |
| 28. Head-Up Display | 61. Upholstery with leather inserts |
| 29. Headlamp wash | 62. Vehicle charging cable |
| 30. Heated seat driver, Heated seat passenger | 63. Vehicle charging cable |
| 31. Hill holder | 64. Vehicle immobilizer |
| 32. Interior decoration: other | 65. Windscreenwiper: other |
| 33. Interior lights: other accessories | |

Dealer's equipment (selected items)

1. Metallic paint -

Base value of the vehicle

Base value of the vehicle by Eurotax (net) -

CorrectionsFirst registration

MileageEquipmentTyresOther

The validity of the technical examination -
Earlier repairs -
Braki i uszkodzenia -


Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 08-2026 POL) with regard to technical and market parameters affecting the value of the vehicle.

Basic print without information about the vehicle's value - duey to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 10-08-2026

DEKRA's expert:
Kacper Sosnowski (WSP)
mgr inż. Michał Świątek

Document issued electronically valid without signature.

Measurement of thickness of the vehicle lacquer coating


No. of controlled item	Controlled item	Measured range of thickness of the lacquer coat [μm]
1	Front cover	150 - 300
2	Front left fender	to 150
3	Left front pillar	to 150
4	Front left door	to 150
5	Roof	to 150
6	Left middle pillar	to 150
7	Right side sill	to 150
8	Left rear door	to 150
9	Rear left fender	150 - 300
10	Cover/lid	to 150
11	Right rear fender	to 150
12	Right rear door	to 150
13	Right middle pillar	to 150
14	Right side sill	to 150
15	Front right door	150 - 200
16	Right front pillar	to 150
17	Front right fender	150 - 200

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

During the inspection the service book of the vehicle was not provided.

Information concerning the origin of the vehicle

The vehicle purchased domestically from an authorized representative of the brand.

Anti-theft protection - immobilizer

- as a result of the inspection of the vehicle found no malfunctions of the immobilizer in the extent possible to determine during the inspection of the vehicle in the non- workshop conditions.

Anti-theft protection - other:

not found

Additional comments on the car:

Not applicable.

Test drive

Test drive of the vehicle was conducted. Test drive in the full extent is not possible. Comment below:

.

Checking of the correctness and / or construction of identification / serial numbers of the object:

Not tested

Verification of the accuracy of the object data, including year of production, and other.

Not conducted - adopted according to the documents presented and indicated sources.

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.
- The evaluation has been carried out basing on delivered documentation and organoleptic examination of the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the assessed object.

- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

Comments to the commission - regarding valuation

Kluczyki

TAK

1

Expert comments - regarding valuation

Aktywna kontrolka systemu monitorowania ciśnienia w ogumieniu.

Widoczne ślady użytkowania pojazdu: drobne rysy, odpryski, wgniecenia, zaplamienia. Widoczne ślady napraw lakierniczych elementów nadwozia.

Nieprzyjemny zapach wewnątrz pojazdu.

Restrictive disclaimer - regarding valuation

- W Ocenie/Raporcie uwzględniono niesprawności, uszkodzenia, braki itp., które były możliwe do stwierdzenia organoleptycznego, w warunkach oględzin (z uwzględnieniem: stanu czystości pojazdu, warunków atmosferycznych, oświetlenia itd.) oraz bez weryfikacji serwisowej, bez dostępu do spodu pojazdu, bez specjalistycznego sprzętu diagnostycznego (w tym bez diagnostyki komputerowej), bez jazdy próbnej wykonanej w warunkach drogowych z obciążeniem.
- W ramach Oceny/Raportu nie weryfikowano odczytanego stanu drogomierza z zapisami w urządzeniach elektronicznych pojazdu.
- Rzeczoznawca nie bierze na siebie odpowiedzialności za wady ukryte (prawne i fizyczne) oraz ewentualne skutki wynikające z dalszego użytkowania przedmiotu oceny, a także za skutki wykorzystania samej oceny.
- Podane przedziały grubości powłoki lakierowej, dotyczą punktów pomiarowych. Nie mogą być traktowane jako gwarancja, że grubość powłoki lakierowej w innych punktach nie wykracza poza te przedziały.
- Zawarte w niniejszej Ocenie/Raporcie informacje (w tym dotyczące wyposażenia) służą jedynie ogólnym celom informacyjnym. Ocena/Raport nie może być zatem traktowana jako oferta w rozumieniu przepisów Kodeksu Cywilnego oraz opisu towaru ani zapewnienia w rozumieniu art. 4 Ustawy z dnia 27 lipca 2002 roku o szczególnych warunkach sprzedaży konsumenckiej.
- Niniejsza Ocena/Raport nie jest szczegółową oceną stanu technicznego.

Ocenę/Raport wykonano w kierunku ujawnienia uszkodzeń nieakceptowanych z punktu widzenia właściwego przewodnika zwrotu pojazdu lub innych ustaleń ze Zleceniodawcą. Tym samym Ocena/Raport może nie ujmować typowych zużyć i uszkodzeń eksploatacyjnych.

PHOTOGRAPHIC DOCUMENTATION



Photo 1.
Przekątna przednia lewa



Photo 2.
Przód

PHOTOGRAPHIC DOCUMENTATION



Photo 3.

Przekątna przednia prawa



Photo 4.

Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 5.
Bok prawy z tyłu



Photo 6.
Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 7.

Tył



Photo 8.

Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 9.

Bok lewy z tyłu



Photo 10.

Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 11.
Próg lewy (widok od przodu)



Photo 12.
Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



Photo 13.
Spód pojazdu przód



Photo 14.
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION



Photo 15.

Tarcza hamulcowa przednia prawa



Photo 16.

Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 17.

Tarcza hamulcowa tylna lewa



Photo 18.

Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 19.
Bagażnik



Photo 20.
Zestaw naprawy koła

PHOTOGRAPHIC DOCUMENTATION



Photo 21.
Komora silnika



Photo 22.
Numer identyfikacyjny

PHOTOGRAPHIC DOCUMENTATION



Photo 23.
Tabliczka znamionowa



Photo 24.
Zestaw wskaźników - przebieg

PHOTOGRAPHIC DOCUMENTATION



Photo 25.

Zestaw wskaźników - serwis



Photo 26.

Widok przez otwarte drzwi przednie lewe

PHOTOGRAPHIC DOCUMENTATION



Photo 27.

Kierownica z lewej strony



Photo 28.

Widok przez otwarte drzwi tylne lewe

PHOTOGRAPHIC DOCUMENTATION



Photo 29.

Widok z tylnej kanapy na deskę rozd.



Photo 30.

Konsola środkowa

PHOTOGRAPHIC DOCUMENTATION



Photo 31.
Tunel środkowy



Photo 32.
Kierownica (na wprost)

PHOTOGRAPHIC DOCUMENTATION



Photo 33.

Przewód ładowania baterii trakcyjnej



Photo 34.

Gniazdo ładowania / tankowania

PHOTOGRAPHIC DOCUMENTATION



Photo 35.

Dow. rej. ksero Str. 1




Photo 36.

Dow. Rej. ksero Str. 2

PHOTOGRAPHIC DOCUMENTATION



Photo 37.

Kluczyki



Photo 38.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 39.
Wyposażenie



Photo 40.
Wyposażenie

PHOTOGRAPHIC DOCUMENTATION



Photo 41.
Wyposażenie



Photo 42.
Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 43.

Pokrywa komory silnika - Wgniecenie/odkształcenie 1



Photo 44.

Spoiler zderzaka przedniego - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 45.

Spoiler zderzaka przedniego - Wgniecenie/odkształcenie 1



Photo 46.

Spoiler zderzaka przedniego - Wgniecenie/odkształcenie 2

PHOTOGRAPHIC DOCUMENTATION



Photo 47.

Wykładzina pokrywy komory silnika - Pęknięcie/rozerwanie 1



Photo 48.

Wykładzina pokrywy komory silnika - Pęknięcie/rozerwanie 2

PHOTOGRAPHIC DOCUMENTATION



Photo 49.

Zderzak - Rysa/odprysk 1



Photo 50.

Zderzak - Rysa/odprysk 2

PHOTOGRAPHIC DOCUMENTATION



Photo 51.

Zderzak - Wgniecenie/odkształcenie 1



Photo 52.

Zderzak - Wgniecenie/odkształcenie 2

PHOTOGRAPHIC DOCUMENTATION



Photo 53.

Zderzak - Inne 1



Photo 54.

Zderzak przedni cz górna - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 55.

Blotnik przedni P - Rysa/odprysk 1



Photo 56.

Felga aluminiowa przednia P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 57.

Listwa krawędzi błotnika prz P - Rysa/odprysk 1



Photo 58.

Drzwi przednie P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 59.

Drzwi przednie P - Wgniecenie/odkształcenie 1



Photo 60.

Drzwi przednie P - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 61.

Drzwi przednie P - Inne 2




Photo 62.

Drzwi tylne P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 63.

Drzwi tylne P - Wgniecenie/odkształcenie 2



Photo 64.

Drzwi tylne P - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 65.
Drzwi tylne P - Inne 2



Photo 66.
Listwa drzwi przednich P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION




Photo 67.

Listwa drzwi tylnych P - Rysa/odprysk 1



Photo 68.

Lusterko zew P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 69.

Szyba boczna środkowa P - Rysa/odprysk 1



Photo 70.

Łotnik tylny P / Ściana boczna P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 71.

Błotnik tylny P / Ściana boczna P - Inne 1



Photo 72.

Felga aluminiowa tylna P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 73.

Listwa krawędzi błotnika tyl P - Rysa/odprysk 1



Photo 74.

Pokrywy bagażnika - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 75.

Pokrywy bagażnika - Rysa/odprysk 2



Photo 76.

Zderzak tylny - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 77.

Zderzak tylny - Rysa/odprysk 2



Photo 78.

Zderzak tylny() - Rysa/odprysk 3

PHOTOGRAPHIC DOCUMENTATION



Photo 79.

Dach - Wgniecenie/odkształcenie 1



Photo 80.

Dach - Wgniecenie/odkształcenie 2

PHOTOGRAPHIC DOCUMENTATION



Photo 81.

Błotnik tylny L / Ściana boczna L - Wgniecenie/odkształcenie 1



Photo 82.

Felga aluminiowa tylna L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 83.

Drzwi przed L - Rysa/odprysk 1



Photo 84.

Drzwi tylne L - zdjęcie poglądowe 1

PHOTOGRAPHIC DOCUMENTATION



Photo 85.

Drzwi tylne L - Wgniecenie/odkształcenie 1



Photo 86.

Drzwi tylne L - Wgniecenie/odkształcenie 2

PHOTOGRAPHIC DOCUMENTATION



Photo 87.

Listwa drzwi przednich L - Rysa/odprysk 1



Photo 88.

Lusterko zew L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 89.

Felga Aluminiowa przednia L - Rysa/odprysk 1



Photo 90.

Listwa krawędzi błotnika prz L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 91.

Uszczelka drzwi przednich L - Pęknięcie/rozerwanie 1



Photo 92.

Listwy progowe lew. - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 93.

Listwy progowe praw. - Wgniecenie/odkształcenie 1



Photo 94.

Półka/roleta tylna - Inne 1