

DEKRA's commission No. : PKOL(W)/LODZ/91148/26/09/29
commission/ damage No. : 21/047231
Date of commission: 29-09-2026

DEKRA Poland - Headquarters
02-673 Warszawa, ul. Konstruktorska 12A

Client :

PKO Leasing SA
Świętokrzyska 36
00-116 Warszawa

Expert:

Kacper Sosnowski (WSP)
DEKRA Polska - współpraca O/Warszawa
inż. Józef Orłowski
TU - Włocławek

NOTE:

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

Vehicle data

Group of objects (Eurotax)	jeeps
EC code (Eurotax)	0133967
Manufacturer	ALFA ROMEO
Model	Stelvio 17-22
Type / version	Stelvio 2.0 Turbo Business Q4 aut
Body type	hatchback
Number of doors / seats	5/5
Curb weight [kg]	1680
Gross vehicle weight [kg]	2350
Wheelbase 1/2	2818
Engine type	spark ignition
Pollution reduction system	three-way catalytic converter
Engine capacity [ccm]	1995
Engine Power [hp/kW]	200/148
Gearbox	automatic 8- gear
Registration /record No.	PO4VV73
VIN / serial number	ZARPAHLN7M7D15529
Date of first registration	28-10-2021
Date of next. tech. test	28-10-2026
Year of manufacture	2021
Readout [km]	59 821 (read)
Body color / type of coating	black/METALIK

Tyres

axle	Wheel	Manufacturer, type	Size	Measured profile
Front	right	PIRELLI, SCORPION WINTER	235/55 19 105V	2,0 mm
	left	PIRELLI, SCORPION WINTER	235/55 19 105V	2,5 mm
back	right	PIRELLI, SCORPION WINTER	235/55 19 105V	3,0 mm
	left	PIRELLI, SCORPION WINTER	235/55 19 105V	3,5 mm

Standard equipment by Eurotax

- | | |
|--|---|
| 1. Active Emergency Brake Assist | 30. Keyless entry |
| 2. Adaptive Cruise Control | 31. LED rear lights |
| 3. Alarm | 32. Lane control assistant |
| 4. Android Auto, Apple CarPlay | 33. Leather gearshifter/switch, Leather steering wheel, Sports steering wheel |
| 5. Automatic dimlight activation | 34. Light Alloy wheels 18" |
| 6. Bi-Xenon Head lamps | 35. Mobile Tire System |
| 7. Bord climate: other | 36. On board monitor |
| 8. Bord communication: other, DAB radio, On board monitor, Radio, Soundsystem, Touchscreen monitor | 37. Other |
| 9. Child seat fixation | 38. Other |
| 10. Collision Warning System | 39. Other |
| 11. DAB radio, Radio | 40. Paint: other, Uni-Lackierung |
| 12. Door mirror(s) electrically adjustable in general | 41. Park Distance Control rear |
| 13. Door mirrors electrically foldable, Door mirrors heated | 42. Power windows front, Power windows rear |
| 14. Driver airbag, Head airbags front, Head airbags rear, Passenger airbag, Side airbag driver and passenger | 43. Rain sensor |
| 15. Driver seat height adjustable, Driver seat with adjustable inclination, Passenger seat height adjustable, Passenger seat with adjustable inclination, Seats: other | 44. Rear-view mirror autodimming |
| 16. Dualzone automatic climate control | 45. Remote controlled central locking |
| 17. Electric tailgate | 46. Selectable driveline characteristics |
| 18. Electric tailgate | 47. Start/Stop system |
| 19. Exterior lighting: other | 48. Steering wheel manually adjustable |
| 20. Extra power outlet | 49. Steering wheel with radio operation |
| 21. Headlamp wash | 50. Storage facilities in general |
| 22. Heat reflecting windows | 51. Textile upholstery |
| 23. Hill descent control | 52. Traction control |
| 24. Interior decoration: other | 53. Traction control |
| 25. Interior decoration: other | 54. Tyre pressure control (RDC) |
| 26. Interior: other | 55. USB in |
| 27. Interior: other | 56. USB in |
| 28. Interior: other | 57. Wireless device charging |
| 29. Interior: other | |

Dealer's equipment (selected items)

- | | |
|---|---|
| 1. Automated High-beam assist, Blind spot warning, Door mirrors autodimming, Driver conditioning monitoring, Lane control assistant | - |
| Lusterka boczne elektrochromatyczne | |
| System automatycznego włączania światła drogowych | |
| Czujnik martwego pola aktywny | |
| System utrzymania pasa ruchu | |
| System ostrzegający o zmęczeniu kierowcy | |
| 2. Driver seat electrically adjustable, Memory seat, Passenger seat electrically adjustable | - |
| Fotel kierowcy z 6-cio stopniową elektryczną regulacją, pamięć ustawień | |
| Fotel pasażera z 6-cio stopniową elektryczną regulacją | |
| 3. Exterior design: other | - |
| 4. Extra power outlet | - |
| 5. Heated seat driver, Heated seat passenger, Steering wheel heated, Windscreen wash-nozzle heated | - |
| Fotele przednie podgrzewane | |
| Dysze przednich spryskiwaczy ogrzewane | |
| Kierownica podgrzewana | |

- 6. Interior lights: other accessories, Soundsystem -
Podświetlenie białe LED strefy stóp, wewnętrznych klamek drzwi oraz pod panelami drzwi
System Audio Sound Theatre - wzmacniacz 400W oraz 10 głośników (w tym subwoofer)
- 7. Light Alloy wheels 19" -
- 8. Metallic paint -
- 9. Park Distance Control front, Rear view camera -
Kamera cofania z dynamicznymi liniami
Czujniki parkowania przód
- 10. Roof railing -
- 11. Tinted rear windows -

Base value of the vehicle

Base value of the vehicle by Eurotax (net) -

Corrections

First registration

Mileage

Equipment

Tyres

Other

Earlier repairs -
stwierdzone braki i uszkodzenia -


Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 10-2026 POL) with regard to technical and market parameters affecting the value of the vehicle.

Basic print without information about the vehicle's value - due to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 02-10-2026

DEKRA's expert:
Kacper Sosnowski (WSP)
inż. Józef Orłowski

Document issued electronically valid without signature.

Measurement of thickness of the vehicle lacquer coating


No. of controlled item	Controlled item	Measured range of thickness of the lacquer coat [µm]
1	Front cover	150 - 200
2	Left front fender	to 150
3	Left front pillar	to 150
4	Left front wall	to 150
5	Roof	to 150
6	Left middle pillar	to 150
7	Left side sill	to 150
8	Left rear wall	to 150
9	Left side wall	to 150
10	Cover/tailgate	to 150
11	Side right wall	150 - 200
12	Rear right door	to 150
13	Middle right pillar	to 150
14	Front right door	to 150
15	Right side sill	to 150
16	Right front pillar	to 150
17	Right front fender	to 150

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

During the inspection the registration proof of the vehicle was presented and its photo was taken and enclosed to the expertise.

During the inspection the service book was presented and its number is given below:

.

Information concerning the origin of the vehicle

The vehicle purchased domestically from an authorized representative of the brand.

Additional comments on the car:

Not applicable.

Test drive

Test drive of the vehicle was conducted. Test drive in the full extent is not possible. Comment below: ograniczenia parkingowe

Checking of the correctness and / or construction of identification / serial numbers of the object:

Not tested

Verification of the accuracy of the object data, including year of production, and other.

Not conducted - adopted according to the documents presented and indicated sources.

Anti-theft protection

immobilizer

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.
- The evaluation has been carried out basing on delivered documentation and organoleptic examination of the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the assessed object.
- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

Comments to the commission - regarding valuation

Kluczyki

TAK

2

Expert comments - regarding valuation

Rysy na samochodzie. Niesprawne przyciski funkcyjne w jednym z kluczyków, grot prawidłowy. Odpryski na szybie czołowej.

PHOTOGRAPHIC DOCUMENTATION



Photo 1.
Przekątna przednia lewa



Photo 2.
Przód

PHOTOGRAPHIC DOCUMENTATION



Photo 3.

Przekątna przednia prawa



Photo 4.

Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 5.
Bok prawy z tyłu



Photo 6.
Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 7.

Tył



Photo 8.

Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 9.

Bok lewy z tyłu



Photo 10.

Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 11.

Próg lewy (widok od przodu)



Photo 12.

Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



Photo 13.
Spód pojazdu przód



Photo 14.
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION



Photo 15.

Tarcza hamulcowa przednia prawa



Photo 16.

Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 17.

Tarcza hamulcowa tylna lewa



Photo 18.

Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 19.
Bagażnik




Photo 20.
Komora silnika

PHOTOGRAPHIC DOCUMENTATION



Photo 21.
Numer identyfikacyjny



Photo 22.
Tabliczka znamionowa

PHOTOGRAPHIC DOCUMENTATION



Photo 23.

Zestaw wskaźników - przebieg



Photo 24.

Zestaw wskaźników - serwis

PHOTOGRAPHIC DOCUMENTATION



Photo 25.

Widok przez otwarte drzwi przednie lewe



Photo 26.

Kierownica z lewej strony

PHOTOGRAPHIC DOCUMENTATION



Photo 27.

Widok przez otwarte drzwi tylne lewe



Photo 28.

Widok z tylnej kanapy na deskę rozd.

PHOTOGRAPHIC DOCUMENTATION



Photo 29.
Konsola środkowa



Photo 30.
Tunel środkowy

PHOTOGRAPHIC DOCUMENTATION



Photo 31.
Kierownica (na wprost)



Photo 32.
Dowód rej. Str. 1

PHOTOGRAPHIC DOCUMENTATION



Certyfikat gwarancji

Kod Dealera 0075464	Nazwa Dealera VOYAGER GROUP SP. Z O.O.
Kod modelu/wersji/serii 630NA32	Nr nadwozia M7D15529
VIN ZARPAHLN7M7D15529	Nr rejestracyjny PO4VV73
Identyfikator dokumentu D1342BFEE9381624CF85D04B915A88D7	
Model Stelvio MY21 2.0 GME TURBO BENZYNA 200 KM AT Q4 BUSINESS	
Data rozpoczęcia gwarancji 05-11-2021	

Photo 33.

Książka serwisowa – dane

POTWIERDZENIE WYKONANIA OKRESOWYCH PRZEGŁADÓW TECHNICZNYCH

Wykaz czynności Okresowych Przeglądów Technicznych oraz terminy (przebieg km), w których należy je wykonać, podane są w Instrukcji Obsługi Pojazdu. Należy podać rodzaj wykonywanej interwencji (przebieg czy wymiana oleju silnikowego, jeśli przewidziane są odrębnie); uzupełnić wszystkie pola.

Tolerancja terminu wykonania przeglądu wynosi ± 1 miesiąc. Tolerancja przebiegu wynosi ± 1000 km.

MODEL

PRZEGŁĄD ☐

WYMIANA OLEJU ☐

PRZEGŁĄD PRZEWIDZANY DLA

STAN LICZNIKA W km

ZASTOSOWANO OLEJ SILNIKOWY (NAZWA I KLASA LEPKOŚCI)

NR NADWOZIA

DATA

PODPIS I PIECZĘĆ SERWISU

MODEL

PRZEGŁĄD ☐

WYMIANA OLEJU ☐

PRZEGŁĄD PRZEWIDZANY DLA

STAN LICZNIKA W km

ZASTOSOWANO OLEJ SILNIKOWY (NAZWA I KLASA LEPKOŚCI)

NR NADWOZIA

DATA

PODPIS I PIECZĘĆ SERWISU

Photo 34.

Książka serwisowa – ostatni przegląd

PHOTOGRAPHIC DOCUMENTATION**Photo 35.**

Dow. Rej. Str. 2

**Photo 36.**

Instrukcje

PHOTOGRAPHIC DOCUMENTATION



Photo 37.
Zestaw naprawczy koła



Photo 38.
Kluczyki

PHOTOGRAPHIC DOCUMENTATION



Photo 39.

Zdjęcie do protokołu



Photo 40.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 41.
Zdjęcie do protokołu



Photo 42.
Kratka/zaślepka halogenu P - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 43.

Szyba czołowa - zdjęcie poglądowe 1




Photo 44.

Szyba czołowa - Pęknięcie/rozerwanie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 45.

Wykładzina pokrywy komory silnika - Pęknięcie/rozerwanie 1



Photo 46.

Zderzak - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 47.

Zderzak - Wgniecenie/odkształcenie 1



Photo 48.

Zderzak - Pęknięcie/rozerwanie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 49.

Błotnik przedni P - Rysa/odprysk 1



Photo 50.

Błotnik przedni P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 51.

Błotnik tylny P / Ściana boczna P - Wgniecenie/odkształcenie 1



Photo 52.

Błotnik tylny P / Ściana boczna P - Wgniecenie/odkształcenie 2

PHOTOGRAPHIC DOCUMENTATION



Photo 53.

Błotnik tylny P / Ściana boczna P() - Wgniecenie/odkształcenie 3



Photo 54.

Zderzak tylny - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 55.

Zderzak tylny - Rysa/odprysk 2



Photo 56.

Zderzak tylny cz dolna - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION




Photo 57.

Dach - Wgniecenie/odkształcenie 1



Photo 58.

Ścianka tylna L / Ścianka boczna L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 59.

Błotnik tylny L / Ściana boczna L - Wgniecenie/odkształcenie 1



Photo 60.

Błotnik tylny L / Ściana boczna L - Wgniecenie/odkształcenie 2

PHOTOGRAPHIC DOCUMENTATION



Photo 61.

Drzwi przed L - Rysa/odprysk 1



Photo 62.

Drzwi przed L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 63.

Drzwi tylne L - Wgniecenie/odkształcenie 1




Photo 64.

Kanapa tyl. - Inne 1