

DEKRA's commission No. : PKOL(W)/LODZ/72289/25/09/24  
commission/ damage No. : 20/042657  
Date of commission: 24-09-2025

**DEKRA Poland - Headquarters**  
02-673 Warszawa, ul. Konstruktorska 12A

**Client :**

PKO Leasing SA  
Świętokrzyska 36  
00-116 Warszawa

**Expert:**

**Kacper Sosnowski (NEW)**  
DEKRA Polska - współpraca O/Warszawa  
**Andrzej Sosnowski**  
DEKRA Polska - Centrala

**NOTE:**

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

**Vehicle data**

|                              |                                                            |
|------------------------------|------------------------------------------------------------|
| Group of objects (Eurotax)   | jeeps                                                      |
| EC code (Eurotax)            | 0126868                                                    |
| Manufacturer                 | KIA                                                        |
| Model                        | Sorento 15-18                                              |
| Type / version               | Sorento 2.0 CRDI Business Line aut                         |
| Body type                    | KOM                                                        |
| Number of doors / seats      | 5/7                                                        |
| Curb weight [kg]             | 1873                                                       |
| Gross vehicle weight [kg]    | 2620                                                       |
| Wheelbase 1/2                | 2780                                                       |
| Engine type                  | Automatic ignition                                         |
| Pollution reduction system   | DPF                                                        |
| Engine capacity [ccm]        | 1995                                                       |
| Engine Power [hp/kW]         | 185/136                                                    |
| Gearbox                      | automatic 6- gear                                          |
| Registration /record No.     | TK2925Y                                                    |
| VIN / serial number          | KNAPH81ADH5317868                                          |
| Date of first registration   | 08-05-2017                                                 |
| Date of next. tech. test     | 19-08-2026                                                 |
| Year of manufacture          | 2017 (year has been verified with the manufacturer's base) |
| Readout [km]                 | 110 972 (read)                                             |
| Body color / type of coating | white/double-layered, metallized                           |

**Tyres**

| axle  | Wheel | Manufacturer, type | Size           | Measured profile |
|-------|-------|--------------------|----------------|------------------|
| Front | right | NOKIAN, WR SUV 3   | 235/55 19 105V | 4,0 mm           |
|       | left  | NOKIAN, WR SUV 3   | 235/55 19 105V | 4,0 mm           |
| back  | right | NOKIAN, WR SUV 3   | 235/55 19 105V | 4,5 mm           |
|       | left  | NOKIAN, WR SUV 3   | 235/55 19 105V | 4,5 mm           |

Standard equipment by Eurotax

- |                                                                                                                                                  |                                                                        |
|--------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------|
| 1. 2 single seats rear                                                                                                                           | 42. Leather gearshifter/switch, Leather steering wheel                 |
| 2. Accoustic windows                                                                                                                             | 43. Leather upholstery                                                 |
| 3. Adaptive light, Headlamp wash, Xenon-light                                                                                                    | 44. Light Alloy wheels 19"                                             |
| 4. Air condition rear, Automatic climate control                                                                                                 | 45. Luggage compartment cover                                          |
| 5. Alarm                                                                                                                                         | 46. Lumbar adjust driver electric                                      |
| 6. Antilock-Brake-System (ABS)                                                                                                                   | 47. Metal finish                                                       |
| 7. Armrest (s) front, Armrest (s) rear, Storage facilities in general                                                                            | 48. On board computer                                                  |
| 8. Automatic dimlight activation                                                                                                                 | 49. Other                                                              |
| 9. Blind spot warning                                                                                                                            | 50. Other                                                              |
| 10. Bluetooth interface, Bord communication: other, CD-player, Hands-free system, mp3 Player, Navigation system, Radio, Rear view camera, USB in | 51. Other                                                              |
| 11. Bluetooth interface, Bord communication: other, DAB radio, mp3 Player, Navigation system, Rear view camera, Soundsystem, USB in              | 52. Other                                                              |
| 12. Child seat fixation                                                                                                                          | 53. Other                                                              |
| 13. Cruise control                                                                                                                               | 54. Park Distance Control front, Park Distance Control rear            |
| 14. Door mirror(s) electrically adjustable in general                                                                                            | 55. Passenger seat electrically adjustable                             |
| 15. Door mirrors electrically foldable                                                                                                           | 56. Power assisted brakes                                              |
| 16. Door mirrors heated                                                                                                                          | 57. Power windows front, Power windows rear                            |
| 17. Driver airbag, Head airbags front, Passenger airbag, Side airbag driver, Side airbag driver and passenger                                    | 58. Rain sensor                                                        |
| 18. Driver seat electrically adjustable, Memory seat                                                                                             | 59. Rear Cross Traffic Alert                                           |
| 19. ESP (Electronical Stabilizing Program)                                                                                                       | 60. Rear seat heating                                                  |
| 20. Electric parking brake                                                                                                                       | 61. Rear seat-backs foldable in two separate parts                     |
| 21. Electric tailgate                                                                                                                            | 62. Rear-view mirror autodimming                                       |
| 22. Exterior design: other                                                                                                                       | 63. Remote controlled central locking                                  |
| 23. Exterior design: other                                                                                                                       | 64. Roof railing                                                       |
| 24. Exterior design: other                                                                                                                       | 65. Seatbelt pretensioner front, Seatbelts vertically adjustable front |
| 25. Exterior design: other, Side indicators                                                                                                      | 66. Start/Stop system                                                  |
| 26. Extra power outlet                                                                                                                           | 67. Steering wheel heated                                              |
| 27. Fog lamps                                                                                                                                    | 68. Steering wheel manually adjustabe                                  |
| 28. Full size spare wheel                                                                                                                        | 69. Steering wheel with radio operation                                |
| 29. Heated seat driver, Heated seat passenger                                                                                                    | 70. Storage facilities in general                                      |
| 30. Hill holder                                                                                                                                  | 71. Storage facilities in general                                      |
| 31. Interior decoration: other                                                                                                                   | 72. Sunblind rear side door manual                                     |
| 32. Interior lights: other accessories                                                                                                           | 73. Tinted rear windows                                                |
| 33. Interior: other                                                                                                                              | 74. Traffic sign recognition                                           |
| 34. Interior: other                                                                                                                              | 75. Tyre pressure control (RDC)                                        |
| 35. Interior: other                                                                                                                              | 76. USB in                                                             |
| 36. Interior: other                                                                                                                              | 77. Uni-Lackierung                                                     |
| 37. Keyless go, Other                                                                                                                            | 78. Vehicle imobilizer                                                 |
| 38. LED Daytime running lights                                                                                                                   | 79. Ventilated front seat                                              |
| 39. LED rear lights                                                                                                                              | 80. Windows: other                                                     |
| 40. Lane control assistant                                                                                                                       | 81. {TSA - system stabilizacji toru jazdy przyczepy}                   |
| 41. Lane control assistant                                                                                                                       |                                                                        |

Dealer's equipment (selected items)

1. Metalic paint .....

**Base value of the vehicle**

Base value of the vehicle by Eurotax (net) ..... -

**Corrections**EquipmentTyresOther

Current market situation ..... -

Uszkodzenia, braki, stan, weryfikacja serwisowa ..... -


Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 01-2026 POL) with regard to technical and market parameters affecting the value of the vehicle.

Basic print without information about the vehicle's value - duey to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 07-01-2026

DEKRA's expert:  
Kacper Sosnowski (NEW)  
Andrzej Sosnowski

**Document issued electronically valid without signature.**

Measurement of thickness of the vehicle lacquer coating


| No. of controlled item | Controlled item     | Measured range of thickness of the lacquer coat [ $\mu\text{m}$ ] |
|------------------------|---------------------|-------------------------------------------------------------------|
| 1                      | Front cover         | to 150                                                            |
| 2                      | Left front fender   | to 150                                                            |
| 3                      | Left front pillar   | to 150                                                            |
| 4                      | Left front wall     | to 150                                                            |
| 5                      | Roof                | to 150                                                            |
| 6                      | Left middle pillar  | to 150                                                            |
| 7                      | Left side sill      | to 150                                                            |
| 8                      | Left rear wall      | to 150                                                            |
| 9                      | Left side wall      | to 150                                                            |
| 10                     | Cover/tailgate      | to 150                                                            |
| 11                     | Side right wall     | to 150                                                            |
| 12                     | Rear right door     | to 150                                                            |
| 13                     | Middle right pillar | to 150                                                            |
| 14                     | Front right door    | to 150                                                            |
| 15                     | Right side sill     | to 150                                                            |
| 16                     | Right front pillar  | to 150                                                            |
| 17                     | Right front fender  | to 150                                                            |

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

During the inspection the registration proof of the vehicle was presented and its photo was taken and enclosed to the expertise.

During the inspection the service book was presented and its number is given below:

.

**Information concerning the origin of the vehicle**

Lack of reliable data.

**Additional comments on the car:**

Not applicable.

**Test drive**

Test drive of the vehicle was conducted. Test drive in the full extent is not possible. Comment below:  
ograniczenia placowe

**Checking of the correctness and / or construction of identification / serial numbers of the object:**

Not tested

**Verification of the accuracy of the object data, including year of production, and other.**

Not conducted - adopted according to the documents presented and indicated sources.

**Anti-theft protection**

fabryczne

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.
- The evaluation has been carried out basing on delivered documentation and organoleptic examination of the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the assessed object.
- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

Comments to the commission - regarding valuation**Kluczyki**

TAK

1

Expert comments - regarding valuation

Rysy na samochodzie. Aktywna kontrolka silnika. Odpryski na szybie czołowej.

Rzeczoznawca dokonał oględzin pojazdu w warunkach parkingowych, co mogło ograniczyć pełną ocenę jego stanu technicznego. Dodatkowo, jeżeli jazda próbna została przeprowadzona (informacje w treści raportu), to wykonano ją w warunkach parkingowych, z niewielką prędkością, co może nie odzwierciedlać pełnych warunków eksploatacyjnych. Istnieje możliwość, że w innych okolicznościach ujawnią się dodatkowe uszkodzenia lub usterki, których nie można było wykryć podczas obecnych oględzin. Zalecamy zatem skorzystanie z możliwości oględzin pojazdu we własnym zakresie lub w Autoryzowanej Stacji Obsługi danej marki, co pozwoli na pełniejszą weryfikację stanu technicznego pojazdu przed udziałem w aukcji."

Restrictive disclaimer - regarding valuation

Nie weryfikowano szczegółowo stanu układu napędowego, zawieszenia, kierowniczego, hamulcowego oraz wydechowego. Ocena została wykonana bez użycia podnośnika i specjalistycznego sprzętu diagnostycznego, nie dokonywano demontażu osłon i innych elementów. Ocena określa ogólny stan pojazdu na dzień oględzin w miejscu jego udostępnienia, nie może być zatem traktowana jako kompleksowa ocena stanu technicznego. Specyfikacja wg. programu operacyjnego w zakresie wyposażenia standardowego i dodatkowego nie gwarantuje zgodności ze stanem faktycznym w zakresie możliwym do ustalenia przez rzeczoznawcę podczas oględzin pojazdu. Pomiar grubości powłoki lakierowej wykonano w miejscach możliwych do ich wykonania pomiary nie gwarantują oryginalności poszczególnych elementów poddanych ocenie.

- W Ocenie/Raporcie uwzględniono niesprawności, uszkodzenia, braki itp., które były możliwe do stwierdzenia organoleptycznego, w warunkach oględzin (z uwzględnieniem: stanu czystości pojazdu, warunków atmosferycznych, oświetlenia itd.) oraz bez weryfikacji serwisowej, bez dostępu do spodu pojazdu, bez specjalistycznego sprzętu diagnostycznego (w tym bez diagnostyki komputerowej), bez jazdy próbnej wykonanej w warunkach drogowych z obciążeniem.
- W ramach Oceny/Raportu nie weryfikowano odczytanego stanu drogomierza z zapisami w urządzeniach elektronicznych pojazdu.
- Rzeczoznawca nie bierze na siebie odpowiedzialności za wady ukryte (prawne i fizyczne) oraz ewentualne skutki wynikające z dalszego użytkowania przedmiotu oceny, a także za skutki wykorzystania samej oceny.
- Podane przedziały grubości powłoki lakierowej, dotyczą punktów pomiarowych. Nie mogą być traktowane jako gwarancja, że grubość powłoki lakierowej w innych punktach nie wykracza poza te przedziały.
- Zawarte w niniejszej Ocenie/Raporcie informacje (w tym dotyczące wyposażenia) służą jedynie ogólnym celom informacyjnym. Ocena/Raport nie może być zatem traktowana jako oferta w rozumieniu przepisów Kodeksu Cywilnego oraz opisu towaru ani zapewnienia w rozumieniu art. 4 Ustawy z dnia 27 lipca 2002 roku o szczególnych warunkach sprzedaży konsumenckiej.
- Niniejsza Ocena/Raport nie jest szczegółową oceną stanu technicznego.

Ocenę/Raport wykonano w kierunku ujawnienia uszkodzeń nieakceptowanych z punktu widzenia właściwego przewodnika zwrotu pojazdu lub innych ustaleń ze Zleceniodawcą. Tym samym Ocena/Raport może nie ujmować typowych zużyć i uszkodzeń eksploatacyjnych.

PHOTOGRAPHIC DOCUMENTATION



**Photo 1.**  
Przekątna przednia lewa



**Photo 2.**  
Przód

PHOTOGRAPHIC DOCUMENTATION



**Photo 3.**

Przekątna przednia prawa



**Photo 4.**

Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



**Photo 5.**  
Bok prawy z tyłu



**Photo 6.**  
Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



**Photo 7.**

Tył



**Photo 8.**

Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



**Photo 9.**

Bok lewy z tyłu



**Photo 10.**

Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



**Photo 11.**

Próg lewy (widok od przodu)



**Photo 12.**

Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



**Photo 13.**  
Spód pojazdu przód



**Photo 14.**  
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION



**Photo 15.**

Tarcza hamulcowa przednia prawa



**Photo 16.**

Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION



**Photo 17.**

Tarcza hamulcowa tylna lewa



**Photo 18.**

Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



**Photo 19.**  
Bagażnik




**Photo 20.**  
Koło zapasowe

PHOTOGRAPHIC DOCUMENTATION



**Photo 21.**  
Komora silnika



**Photo 22.**  
Numer identyfikacyjny

PHOTOGRAPHIC DOCUMENTATION**Photo 23.**

Tabliczka znamionowa

**Photo 24.**

Zestaw wskaźników - przebieg

PHOTOGRAPHIC DOCUMENTATION



**Photo 25.**

Widok przez otwarte drzwi przednie lewe



**Photo 26.**

Kierownica z lewej strony

PHOTOGRAPHIC DOCUMENTATION



**Photo 27.**

Widok przez otwarte drzwi tylne lewe



**Photo 28.**

Widok z tylnej kanapy na deskę rozdz.

PHOTOGRAPHIC DOCUMENTATION



**Photo 29.**  
Konsola środkowa



**Photo 30.**  
Tunel środkowy

# PHOTOGRAPHIC DOCUMENTATION



**Photo 31.**

Kierownica (na wprost)




**Photo 32.**

Dowód rej. Str. 1

PHOTOGRAPHIC DOCUMENTATION**Photo 33.**

Dow. Rej. Str.2 i klucze

**Photo 34.**

Książka serwisowa – dane

PHOTOGRAPHIC DOCUMENTATION

REJESTR MECHANICZNYCH PRZEGLĄDÓW OKRESOWYCH

PRZEGLĄD I: 2018 km

Data przeglądu: 19-08-2018

Rzeczywisty przebieg pojazdu (km): 24583

Wynik badania testerem GDS: OK

Termin następnego przeglądu - data / przebieg: 19-08-2020 / 59583

Czytelne imię i nazwisko mechanika wykonującego OT: Grzegorz Zbilnicki

Czytelne imię i nazwisko osoby nadzorującej OT: Sławomir Lwowski

Wykonane czynności:

|                            | TAK                                 | NIE                                 |
|----------------------------|-------------------------------------|-------------------------------------|
| Wymiana oleju:             | <input checked="" type="checkbox"/> | <input type="checkbox"/>            |
| Wymiana płynu hamulcowego: | <input checked="" type="checkbox"/> | <input type="checkbox"/>            |
| Wymiana filtra paliwa:     | <input type="checkbox"/>            | <input checked="" type="checkbox"/> |
| Wymiana filtra powietrza:  | <input checked="" type="checkbox"/> | <input type="checkbox"/>            |

Czynności dodatkowe: Filtr kabinowy

**Photo 35.**

Książka serwisowa – ostatni przegląd

**Photo 36.**

Instrukcje

PHOTOGRAPHIC DOCUMENTATION



**Photo 37.**

Zdjęcie do protokołu



**Photo 38.**

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



**Photo 39.**

Zdjęcie do protokołu



**Photo 40.**

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



**Photo 41.**

Zdjęcie do protokołu



**Photo 42.**

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



**Photo 43.**

Zdjęcie do protokołu



**Photo 44.**

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



**Photo 45.**

Listwa śr zderzaka przedniego - Inne 1



**Photo 46.**


Pokrywa komory silnika - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 47.**

Pokrywa komory silnika - Pęknięcie/rozerwanie 1



**Photo 48.**

Pokrywa komory silnika - Inne 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 49.**

Spoiler zderzaka przedniego - Rysa/odprysk 1



**Photo 50.**

Zderzak przedni cz dolna - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 51.**

Zderzak przedni cz dolna - Pęknięcie/rozerwanie 1



**Photo 52.**

Drzwi przednie P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 53.**

Drzwi tylne P - Rysa/odprysk 1



**Photo 54.**

Drzwi tylne P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 55.**

Błotnik tylny P / Ściana boczna P - Wgniecenie/odkształcenie 1



**Photo 56.**

Felga aluminiowa tylna P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 57.**

Zderzak tylny - Wgniecenie/odkształcenie 1



**Photo 58.**

Ścianka tylna L / Ścianka boczna L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 59.**

Drzwi przed L - Wgniecenie/odkształcenie 1



**Photo 60.**

Drzwi tylne L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 61.**

Słupek przedni L - zdjęcie pogładowe 1



**Photo 62.**

Słupek przedni L - Inne 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 63.**

Fotel prz. lew. - Inne 1



**Photo 64.**

Fotel prz. praw. - Inne 1