

DEKRA's commission No. : PKOL(W)/LODZ/95349/25/12/04
commission/ damage No. : 22/024500
Date of commission: 04-12-2025

DEKRA Poland - Headquarters
02-673 Warszawa, ul. Konstruktorska 12A

Client :

PKO Leasing SA
Świętokrzyska 36
00-116 Warszawa

Expert:

Kacper Sosnowski (NEW)
DEKRA Polska - współpraca O/Warszawa
Andrzej Sosnowski
DEKRA Polska - Centrala

NOTE:

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

Vehicle data

Group of objects (Eurotax)	cars
EC code (Eurotax)	0141470
Manufacturer	SKODA
Model	Superb III 19-24
Type / version	Superb 1.4 TSI Plug-In Hybrid L&K DSG
Body type	hatchback
Number of doors / seats	5/5
Curb weight [kg]	1727
Gross vehicle weight [kg]	2251
Wheelbase 1/2	2841
Engine type	spark ignition
Pollution reduction system	GPF
Engine capacity [ccm]	1395
Engine Power [hp/kW]	156/115
Gearbox	automatic 6- gear
Registration /record No.	DW5TE40
VIN / serial number	TMBAW7NPXL7041054
Date of first registration	28-01-2020
Date of next. tech. test	24-01-2026
Year of manufacture	2019 (year has been verified with the manufacturer's base)
Readout [km]	188 090 (read)
Body color / type of coating	red/double-layered, metallized

Tyres

axle	Wheel	Manufacturer, type	Size	Measured profile
Front	right	BARUM, POLARIS 5	235/45 18 98V	3,5 mm
	left	BARUM, POLARIS 5	235/45 18 98V	3,5 mm
back	right	PIRELLI, SOTTOZERO 3	235/45 18 98V	3,0 mm
	left	FIRESTONE, ROADHAWK	245/40 18 97Y	4,0 mm

Standard equipment by Eurotax

- | | |
|--|---|
| 1. Acoustic windows | 52. Lane control assistant |
| 2. Active body control, Selectable driveline characteristics | 53. Leather steering wheel, Multi functional steering wheel |
| 3. Antilock-Brake-System (ABS) | 54. Light Alloy wheels 18" |
| 4. Armrest (s) front | 55. Lumbar adjust driver, Lumbar adjust passenger |
| 5. Artificial leather upholstery, Upholstery with leather inserts | 56. Mobile Tire System |
| 6. Automated High-beam assist | 57. On board computer |
| 7. Automatic climate control | 58. Other |
| 8. Automatic limited slip differential | 59. Other |
| 9. Blind spot warning | 60. Other |
| 10. Bluetooth interface | 61. Other |
| 11. Bluetooth interface | 62. Other |
| 12. Bord communication: other, DVD-player, Navigation system, On board monitor, USB in, Voice control for navigation system | 63. Other |
| 13. Bord entertainment: other accessories, Radio preparation | 64. Other |
| 14. Brake Assist, Distance control | 65. Other |
| 15. Cargo net | 66. Other |
| 16. Child seat fixation | 67. Other |
| 17. Cornering Headlights, Fog lamps | 68. Other |
| 18. Cruise control | 69. Other |
| 19. DAB radio | 70. Other |
| 20. Door mirror with memory | 71. Other |
| 21. Door mirror(s) electrically adjustable in general, Door mirrors autodimming, Door mirrors electrically foldable, Door mirrors heated, Rear-view mirror autodimming | 72. Other |
| 22. Driver airbag, Head airbags front, Passenger airbag, Side airbag driver, Side airbag driver and passenger | 73. Other |
| 23. Driver knee airbag | 74. Other |
| 24. Driver seat electrically adjustable, Memory seat | 75. Other |
| 25. Driver seat electrically adjustable, Memory seat, Passenger seat electrically adjustable | 76. Other |
| 26. Driver seat height adjustable, Passenger seat height adjustable | 77. Other |
| 27. Driver-information-system | 78. Park Distance Control front, Park Distance Control rear |
| 28. ESP (Electronical Stabilizing Program) | 79. Passenger airbag |
| 29. Exterior design: other | 80. Pedestrian Emergency Brake Assist |
| 30. Exterior design: other | 81. Power assisted brakes |
| 31. Exterior design: other | 82. Power assisted brakes |
| 32. Exterior design: other | 83. Power assisted brakes |
| 33. Exterior design: other | 84. Power windows front |
| 34. Extra power outlet | 85. Power windows rear |
| 35. Extra power outlet | 86. Rain sensor |
| 36. Hatch/skibag in rear bench | 87. Rear Cross Traffic Alert |
| 37. Headlamp wash | 88. Rear seat-backs foldable in two separate parts |
| 38. Headrests front, Rear headrests | 89. Rear view camera |
| 39. Heated seat driver, Heated seat passenger, Rear seat heating | 90. Rear-view mirror autodimming |
| 40. Hill holder | 91. Remote controlled central locking |
| 41. Interior decoration: other | 92. Soundsystem |
| 42. Interior lights: other accessories | 93. Storage facilities in general |
| 43. Interior lights: other accessories | 94. Storage facilities in general |

- | | |
|--|------------------------------------|
| 44. Interior lights: other accessories | 95. Storage facilities in general |
| 45. Interior lights: other accessories | 96. Telematic |
| 46. Interior: other | 97. Tinted rear windows |
| 47. Interior: other | 98. Traction control |
| 48. Interior: other | 99. Tyre pressure control (RDC) |
| 49. Keyless go | 100. Uni-Lackierung |
| 50. LED front dim light | 101. Vehicle immobilizer |
| 51. LED rear lights | 102. Windscreen wash-nozzle heated |

Dealer's equipment (selected items)

- | | |
|---|---|
| 1. Additional gauges | - |
| 2. Electric tailgate | - |
| 3. Leather steering wheel, Multi functional steering wheel, Steering wheel heated,
Steering wheel with gear-switches | - |
| 4. Metallic paint | - |
| 5. Rear wiper | - |
| 6. Windscreen heating | - |

Base value of the vehicle

Base value of the vehicle by Eurotax (net) -

Corrections

First registration

Mileage

Equipment

Tyres

Other

Earlier repairs	-
Uszkodzenia, stan	-


Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 12-2025 POL) with regard to technical and market parameters affecting the value of the vehicle.

Basic print without information about the vehicle's value - due to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 18-12-2025

DEKRA's expert:
Kacper Sosnowski (NEW)
Andrzej Sosnowski

Document issued electronically valid without signature.

Measurement of thickness of the vehicle lacquer coating


No. of controlled item	Controlled item	Measured range of thickness of the lacquer coat [μm]
1	Front cover	to 150
2	Front left fender	to 150
3	Left front pillar	to 150
4	Front left door	150 - 2000
5	Roof	to 150
6	Left middle pillar	to 150
7	Right side sill	to 150
8	Left rear door	to 150
9	Rear left fender	to 150
10	Cover/lid	to 150
11	Right rear fender	to 150
12	Right rear door	to 150
13	Right middle pillar	to 150
14	Right side sill	to 150
15	Front right door	to 150
16	Right front pillar	to 150
17	Front right fender	to 150

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

During the inspection the registration proof of the vehicle was presented and its photo was taken and enclosed to the expertise.

During the inspection the service book was presented and its number is given below:
elektroniczna

Information concerning the origin of the vehicle

Lack of reliable data.

Anti-theft protection - immobilizer

- as a result of the inspection of the vehicle found no malfunctions of the immobilizer in the extent possible to determine during the inspection of the vehicle in the non- workshop conditions.

Anti-theft protection - other:

not found

Additional comments on the car:

Not applicable.

Test drive

Test drive of the vehicle was conducted. Test drive in the full extent is not possible. Comment below:
ograniczenia placowe

Checking of the correctness and / or construction of identification / serial numbers of the object:

Not tested

Verification of the accuracy of the object data, including year of production, and other.

Not conducted - adopted according to the documents presented and indicated sources.

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.
- The evaluation has been carried out basing on delivered documentation and organoleptic examination of

page 6/50

the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the assessed object.

- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

Comments to the commission - regarding valuation

Kluczyki

TAK

1

Expert comments - regarding valuation

Aktywna kontrolka ciśnienia w kołach. Informacja wymienić baterie w kluczyku. Informacja front assist niedostępny. Brak zaślepek w tylnej kanapie. Rysy na samochodzie. Odpryski na szybie czołowej.

Rzeczoznawca dokonał oględzin pojazdu w warunkach parkingowych, co mogło ograniczyć pełną ocenę jego stanu technicznego. Dodatkowo, jeżeli jazda próbna została przeprowadzona (informacje w treści raportu), to wykonano ją w warunkach parkingowych, z niewielką prędkością, co może nie odzwierciedlać pełnych warunków eksploatacyjnych. Istnieje możliwość, że w innych okolicznościach ujawnią się dodatkowe uszkodzenia lub usterki, których nie można było wykryć podczas obecnych oględzin. Zalecamy zatem skorzystanie z możliwości oględzin pojazdu we własnym zakresie lub w Autoryzowanej Stacji Obsługi danej marki, co pozwoli na pełniejszą weryfikację stanu technicznego pojazdu przed udziałem w aukcji."

Restrictive disclaimer - regarding valuation

Nie weryfikowano szczegółowo stanu układu napędowego, zawieszenia, kierowniczego, hamulcowego oraz wydechowego. Ocena została wykonana bez użycia podnośnika i specjalistycznego sprzętu diagnostycznego, nie dokonywano demontażu osłon i innych elementów. Ocena określa ogólny stan pojazdu na dzień oględzin w miejscu jego udostępnienia, nie może być zatem traktowana jako kompleksowa ocena stanu technicznego. Specyfikacja wg. programu operacyjnego w zakresie wyposażenia standardowego i dodatkowego nie gwarantuje zgodności ze stanem faktycznym w zakresie możliwym do ustalenia przez rzeczoznawcę podczas oględzin pojazdu.

Pomiar grubości powłoki lakierowej wykonano w miejscach możliwych do ich wykonania pomiary nie gwarantują oryginalności poszczególnych elementów poddanych ocenie.

- W Ocenie/Raporcie uwzględniono niesprawności, uszkodzenia, braki itp., które były możliwe do stwierdzenia organoleptycznego, w warunkach oględzin (z uwzględnieniem: stanu czystości pojazdu, warunków atmosferycznych, oświetlenia itd.) oraz bez weryfikacji serwisowej, bez dostępu do spodu pojazdu, bez specjalistycznego sprzętu diagnostycznego (w tym bez diagnostyki komputerowej), bez jazdy próbnej wykonanej w warunkach drogowych z obciążeniem.
- W ramach Oceny/Raporu nie weryfikowano odczytanego stanu drogomierza z zapisami w urządzeniach elektronicznych pojazdu.
- Rzeczoznawca nie bierze na siebie odpowiedzialności za wady ukryte (prawne i fizyczne) oraz ewentualne skutki wynikające z dalszego użytkowania przedmiotu oceny, a także za skutki wykorzystania samej oceny.
- Podane przedziały grubości powłoki lakierowej, dotyczą punktów pomiarowych. Nie mogą być traktowane jako gwarancja, że grubość powłoki lakierowej w innych punktach nie wykracza poza te przedziały.

- Zawarte w niniejszej Ocenie/Raporcie informacje (w tym dotyczące wyposażenia) służą jedynie ogólnym celom informacyjnym. Ocena/Raport nie może być zatem traktowana jako oferta w rozumieniu przepisów Kodeksu Cywilnego oraz opisu towaru ani zapewnienia w rozumieniu art. 4 Ustawy z dnia 27 lipca 2002 roku o szczególnych warunkach sprzedaży konsumenckiej.
- Niniejsza Ocena/Raport nie jest szczegółową oceną stanu technicznego.

Ocenę/Raport wykonano w kierunku ujawnienia uszkodzeń nieakceptowanych z punktu widzenia właściwego przewodnika zwrotu pojazdu lub innych ustaleń ze Zleceniodawcą. Tym samym Ocena/Raport może nie ujmować typowych zużyć i uszkodzeń eksploatacyjnych.

PHOTOGRAPHIC DOCUMENTATION



Photo 1.

Przekątna przednia lewa



Photo 2.

Przód

PHOTOGRAPHIC DOCUMENTATION



Photo 3.

Przekątna przednia prawa



Photo 4.

Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 5.

Bok prawy z tyłu



Photo 6.

Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 7.

Tył



Photo 8.

Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 9.

Bok lewy z tyłu



Photo 10.

Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 11.

Próg lewy (widok od przodu)




Photo 12.

Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



Photo 13.
Spód pojazdu przód



Photo 14.
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION




Photo 15.

Tarcza hamulcowa przednia prawa



Photo 16.

Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION




Photo 17.

Tarcza hamulcowa tylna lewa




Photo 18.

Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 19.
Bagażnik



Photo 20.
Koło zapasowe

PHOTOGRAPHIC DOCUMENTATION



Photo 21.
Komora silnika



Photo 22.
Numer identyfikacyjny

PHOTOGRAPHIC DOCUMENTATION



Photo 23.
Tabliczka znamionowa



Photo 24.
Zestaw wskaźników - przebieg

PHOTOGRAPHIC DOCUMENTATION



Photo 25.

Widok przez otwarte drzwi przednie lewe



Photo 26.

Kierownica z lewej strony

PHOTOGRAPHIC DOCUMENTATION



Photo 27.

Widok przez otwarte drzwi tylne lewe



Photo 28.

Widok z tylnej kanapy na deskę rozd.

PHOTOGRAPHIC DOCUMENTATION



Photo 29.
Konsola środkowa




Photo 30.
Tunel środkowy

PHOTOGRAPHIC DOCUMENTATION



Photo 31.

Kierownica (na wprost)



Photo 32.

Dowód rej. Str. 1

PHOTOGRAPHIC DOCUMENTATION



Photo 33.

Dow. Rej. Str.2 i klucze



Photo 34.

Książka serwisowa – dane

PHOTOGRAPHIC DOCUMENTATION



Photo 35.

Książka serwisowa – ostatni przegląd



Photo 36.

Przewód ładowania baterii trakcyjnej

PHOTOGRAPHIC DOCUMENTATION



Photo 37.

Zestaw naprawczy koła



Photo 38.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 39.

Zdjęcie do protokołu



Photo 40.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 41.

Zdjęcie do protokołu



Photo 42.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 43.

Zdjęcie do protokołu



Photo 44.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 45.

Zdjęcie do protokołu



Photo 46.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 47.

Zdjęcie do protokołu



Photo 48.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 49.

Zdjęcie do protokołu



Photo 50.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 51.

Zdjęcie do protokołu



Photo 52.

Atrapa przednia - Pęknięcie/rozerwanie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 53.

Atrapa przednia - Pęknięcie/rozerwanie 2



Photo 54.

Atrapa przednia() - Pęknięcie/rozerwanie 3

PHOTOGRAPHIC DOCUMENTATION



Photo 55.

Listwa śr zderzaka przedniego - Inne 1



Photo 56.

Pokrywa komory silnika - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 57.

Pokrywa komory silnika - Pęknięcie/rozerwanie 1



Photo 58.

Zderzak - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 59.

Zderzak - Pęknięcie/rozerwanie 1



Photo 60.

Zderzak - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 61.

Felga aluminiowa przednia P - Rysa/odprysk 1



Photo 62.

Drzwi przednie P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 63.

Drzwi tylne P - Rysa/odprysk 1



Photo 64.

Drzwi tylne P - Rysa/odprysk 2

PHOTOGRAPHIC DOCUMENTATION




Photo 65.

Drzwi tylne P - Wgniecenie/odkształcenie 1



Photo 66.

Łotnik tylny P / Ściana boczna P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 67.

Felga aluminiowa tylna P - Rysa/odprysk 1




Photo 68.

Zderzak tylny - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 69.

Zderzak tylny - Pęknięcie/rozerwanie 1



Photo 70.

Dach - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 71.

Błotnik tylny L / Ściana boczna L - Rysa/odprysk 1



Photo 72.

Błotnik tylny L / Ściana boczna L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 73.

Błotnik tylny L / Ściana boczna L - Wgniecenie/odkształcenie 2



Photo 74.

Felga aluminiowa tylna L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 75.

Drzwi przed L - Rysa/odprysk 1



Photo 76.

Drzwi przed L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 77.

Drzwi tylne L - Rysa/odprysk 1



Photo 78.

Drzwi tylne L - Rysa/odprysk 2

PHOTOGRAPHIC DOCUMENTATION



Photo 79.

Drzwi tylne L - Wgniecenie/odkształcenie 1



Photo 80.

Lusterko zew L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 81.

Fotel prz. lew. - Inne 1



Photo 82.

Osłona p/słoneczna prawa - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 83.

Wykładzina(y) słupka przedniego P - Rysa/odprysk 1



Photo 84.

Wykładzina podłogi bagażnika - Inne 1