

DEKRA's commission No. : PKOL(W)/LODZ/27474/25/04/15  
commission/ damage No. : 23/005316  
Date of commission: 15-04-2025

**DEKRA Poland - Headquarters**  
02-673 Warszawa, ul. Konstruktorska 12A

**Client :**

PKO Leasing SA  
Świętokrzyska 36  
00-116 Warszawa

**Expert:**

**Kacper Sosnowski (NEW)**  
DEKRA Polska - współpraca O/Warszawa  
**Maciej Teodorczuk (NEW)**  
DEKRA Polska - współpraca O/Warszawa

**NOTE:**

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

**Vehicle data**

|                              |                                                            |
|------------------------------|------------------------------------------------------------|
| Group of objects (Eurotax)   | cars                                                       |
| EC code (Eurotax)            | 0158199                                                    |
| Manufacturer                 | MERCEDES-BENZ                                              |
| Model                        | A Klasa [W177] 22-                                         |
| Type / version               | A 45 S AMG 4-Matic 8G-DCT                                  |
| Body type                    | hatchback                                                  |
| Number of doors / seats      | 5/5                                                        |
| Curb weight [kg]             | 1640                                                       |
| Gross vehicle weight [kg]    | 2130                                                       |
| Wheelbase 1/2                | 2729                                                       |
| Engine type                  | spark ignition                                             |
| Supercompression             | turbocompressor with intercooler                           |
| Pollution reduction system   | GPF                                                        |
| Engine capacity [ccm]        | 1991                                                       |
| Engine Power [hp/kW]         | 421/310                                                    |
| Gearbox                      | automatic 8- gear                                          |
| Registration /record No.     | D0ALAMG                                                    |
| VIN / serial number          | W1K3F5EBXPN303289                                          |
| Date of first registration   | 09-03-2023                                                 |
| Date of next. tech. test     | 09-03-2026                                                 |
| Year of manufacture          | 2023 (year has been verified with the manufacturer's base) |
| Readout [km]                 | 35 499 (read)                                              |
| Body color / type of coating | gray/METALIK                                               |

Tyres

| axle  | Wheel | Manufacturer, type         | Size          | Measured profile |
|-------|-------|----------------------------|---------------|------------------|
| Front | right | HANKOOK, WINTER ICEPT EVO3 | 245/40 19 98V | 1,5 mm           |
|       | left  | HANKOOK, WINTER ICEPT EVO3 | 245/40 19 98V | 1,5 mm           |
| back  | right | HANKOOK, WINTER ICEPT EVO3 | 245/40 19 98V | 2,5 mm           |

left HANKOOK, WINTER ICEPT 245/40 19 98V  
EVO3

4,5 mm

Standard equipment by Eurotax

- |                                                                   |                                                          |
|-------------------------------------------------------------------|----------------------------------------------------------|
| 1. Alarm                                                          | 28. Other                                                |
| 2. Artificial leather upholstery, Textile upholstery              | 29. Other                                                |
| 3. Artificial leather upholstery, Textile upholstery              | 30. Other                                                |
| 4. Automatic Emergency Call                                       | 31. Other                                                |
| 5. Brake Assist                                                   | 32. Other                                                |
| 6. Cruise control                                                 | 33. Other                                                |
| 7. DAB radio                                                      | 34. Other                                                |
| 8. Door mirrors electrically foldable                             | 35. Other                                                |
| 9. Driver knee airbag                                             | 36. Other                                                |
| 10. Dualzone automatic climate control                            | 37. Other                                                |
| 11. Exterior design: other                                        | 38. Other                                                |
| 12. Exterior design: other                                        | 39. Other                                                |
| 13. Floor mat                                                     | 40. Pakiet asystenta parkowania z kamerą 360             |
| 14. Heated seat driver, Heated seat passenger                     | 41. Rain sensor                                          |
| 15. Interior lights: other accessories                            | 42. Rear seat-backs foldable                             |
| 16. Interior: other                                               | 43. Selectable driveline characteristics                 |
| 17. Interior: other                                               | 44. Sport seats front                                    |
| 18. Lane control assistant                                        | 45. Sport suspension                                     |
| 19. Leather steering wheel, Multi functional steering wheel       | 46. Steering: other                                      |
| 20. Leather steering wheel, Sports steering wheel                 | 47. Storage facilities in general                        |
| 21. Light Alloy wheels 19"                                        | 48. System aktywnego monitorowania ciśnienia w oponach   |
| 22. Lusterko wsteczne automatycznie przyciemniane                 | 49. System nawigacji MBUX premium                        |
| 23. Mobile Tire System                                            | 50. Tyre pressure control (RDC)                          |
| 24. Multi functional steering wheel                               | 51. USB in                                               |
| 25. On board monitor                                              | 52. Uni-Lackierung                                       |
| 26. Osłony przeciwsłoneczne - wysuwane z podświetlanym lusterkiem | 53. Zbiornik paliwa o zwiększonej pojemności - 51 litrów |
| 27. Other                                                         |                                                          |

Dealer's equipment (selected items)

- |                                                                                           |   |
|-------------------------------------------------------------------------------------------|---|
| 1. AMG Line Premium Plus .....                                                            | - |
| 2. Alarm Guard 360 Plus .....                                                             | - |
| 3. Automatic headlight elevation control, Cornering Headlights, LED front dim light ..... | - |
| 4. Bord communication: other, iPod Interface, Mobile phone preparation .....              | - |
| Apple CarPlay                                                                             |   |
| Android Auto                                                                              |   |
| 5. Distance control .....                                                                 | - |
| 6. Door mirror with memory, Driver seat electrically adjustable .....                     | - |
| 7. Extra power outlet, Interior decoration: other .....                                   | - |
| Gniazdo 12V w bagażniku                                                                   |   |
| Zabezpieczenie krawędzi ładunkowej w chromie                                              |   |
| 8. Glass tilt/slide sunroof electric .....                                                | - |
| 9. Light Alloy wheels 19" .....                                                           | - |
| 10. Memory seat, Passenger seat electrically adjustable .....                             | - |
| 11. Metal finish .....                                                                    | - |
| 12. On board monitor .....                                                                | - |
| 13. Other .....                                                                           | - |
| 14. Other .....                                                                           | - |
| 15. Other .....                                                                           | - |
| 16. Other .....                                                                           | - |
| 17. Other .....                                                                           | - |
| 18. Other .....                                                                           | - |
| 19. Pakiet aerodynamiczny AMG .....                                                       | - |
| Pakiet AMG Night                                                                          |   |

|                                    |   |
|------------------------------------|---|
| Pakiet AMG Night II                |   |
| 20. Pre-Crash System, Seats: other | - |
| 21. Soundsystem                    | - |
| 22. Storage facilities in general  | - |
| 23. Traffic sign recognition       | - |

**Base value of the vehicle**

|                                            |   |
|--------------------------------------------|---|
| Base value of the vehicle by Eurotax (net) | - |
|--------------------------------------------|---|

**Corrections**First registrationEquipmentTyresOther

|                                         |   |
|-----------------------------------------|---|
| Earlier repairs                         | - |
| Stwierdzone braki, usterki, uszkodzenia | - |


Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 04-2025 POL) with regard to technical and market parameters affecting the value of the vehicle.

Basic print without information about the vehicle's value - duey to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 22-04-2025

DEKRA's expert:  
Kacper Sosnowski (NEW)  
Maciej Teodorczuk (NEW)

**Document issued electronically valid without signature.**

Measurement of thickness of the vehicle lacquer coating


| No. of controlled item | Controlled item     | Measured range of thickness of the lacquer coat [ $\mu\text{m}$ ] |
|------------------------|---------------------|-------------------------------------------------------------------|
| 1                      | Front cover         | to 150                                                            |
| 2                      | Front left fender   | to 150                                                            |
| 3                      | Left front pillar   | to 150                                                            |
| 4                      | Front left door     | 150 - 200                                                         |
| 5                      | Roof                | to 150                                                            |
| 6                      | Left middle pillar  | to 150                                                            |
| 7                      | Right side sill     | to 150                                                            |
| 8                      | Left rear door      | 150 - 200                                                         |
| 9                      | Rear left fender    | 150 - 1000                                                        |
| 10                     | Cover/lid           | to 150                                                            |
| 11                     | Right rear fender   | 150 - 200                                                         |
| 12                     | Right rear door     | 150 - 200                                                         |
| 13                     | Right middle pillar | to 150                                                            |
| 14                     | Right side sill     | to 150                                                            |
| 15                     | Front right door    | 150 - 300                                                         |
| 16                     | Right front pillar  | 150 - 200                                                         |
| 17                     | Front right fender  | to 150                                                            |

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

Presented the following documents of the vehicle:

Skan pozwolenia czasowego.

Raport z bazy CEPiK.

During the inspection the service book was presented and its number is given below:

Książka serwisowa elektroniczna.

**Information concerning the origin of the vehicle**

The vehicle purchased domestically from an authorized representative of the brand.

**Anti-theft protection - immobilizer**

- as a result of the inspection of the vehicle found no malfunctions of the immobilizer in the extent possible to determine during the inspection of the vehicle in the non- workshop conditions.

**Anti-theft protection - other:**

not found

**Additional comments on the car:**

Not applicable.

**Test drive**

Test drive of the vehicle was conducted. Test drive in the full extent is not possible. Comment below:

Ograniczenia parkingowe.

**Checking of the correctness and / or construction of identification / serial numbers of the object:**

Not tested

**Verification of the accuracy of the object data, including year of production, and other.**

Not conducted - adopted according to the documents presented and indicated sources.

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.

- The evaluation has been carried out basing on delivered documentation and organoleptic examination of the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the assessed object.

- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

---

#### Comments to the commission - regarding valuation

##### **Kluczyki**

TAK

2

---

#### Expert comments - regarding valuation

Podczas oględzin udostępniono dwa kluczyk/i do pojazdu.

Specyfikacja wg programu operacyjnego w zakresie wyposażenia standardowego i dodatkowego nie gwarantuje zgodności ze stanem faktycznym, w zakresie możliwym do ustalenia przez rzeczoznawcę podczas oględzin pojazdu.

Pomiar grubości powłoki lakierowej wykonano w miejscach możliwych do ich wykonania, pomiary nie gwarantują oryginalności poszczególnych elementów poddanym ocenie.

Pojazd posiada charakterystyczne uszkodzenia natury eksploatacyjnej w postaci:

- punktowych odprysków;
- drobnych wierzchnich zarysowań powłoki lakierowej;
- śladów użytkowania tapicerki.

Opinię przeprowadzono organoleptycznie bez użycia podnośnika, specjalistycznego sprzętu diagnostycznego oraz użycia specjalistycznych metod badawczych (np. mechanoskopijnych). Podane powyżej uwagi i spostrzeżenia określają ogólny stan pojazdu w chwili oględzin, umożliwiając oszacowanie wartości rynkowej. Wobec powyższego powyższa opinia nie może być traktowana jako szczegółowa ocena stanu technicznego pojazdu.

Brak zaślepek na tylnej kanapie.

#### Restrictive disclaimer - regarding valuation

- W Ocenie/Raporcie uwzględniono niesprawności, uszkodzenia, braki itp., które były możliwe do stwierdzenia organoleptycznego, w warunkach oględzin (z uwzględnieniem: stanu czystości pojazdu, warunków atmosferycznych, oświetlenia itd.) oraz bez weryfikacji serwisowej, bez dostępu do spodu pojazdu, bez specjalistycznego sprzętu diagnostycznego (w tym bez diagnostyki komputerowej), bez jazdy próbnej wykonanej w warunkach drogowych z obciążeniem.
- W ramach Oceny/Raporu nie weryfikowano odczytanego stanu drogomierza z zapisami w urządzeniach elektronicznych pojazdu.
- Rzeczoznawca nie bierze na siebie odpowiedzialności za wady ukryte (prawne i fizyczne) oraz ewentualne skutki wynikające z dalszego użytkowania przedmiotu oceny, a także za skutki wykorzystania samej oceny.
- Podane przedziały grubości powłoki lakierowej, dotyczą punktów pomiarowych. Nie mogą być traktowane jako gwarancja, że grubość powłoki lakierowej w innych punktach nie wykracza poza te przedziały.

- Zawarte w niniejszej Ocenie/Raporcie informacje (w tym dotyczące wyposażenia) służą jedynie ogólnym celom informacyjnym. Ocena/Raport nie może być zatem traktowana jako oferta w rozumieniu przepisów Kodeksu Cywilnego oraz opisu towaru ani zapewnienia w rozumieniu art. 4 Ustawy z dnia 27 lipca 2002 roku o szczególnych warunkach sprzedaży konsumenckiej.
- Niniejsza Ocena/Raport nie jest szczegółową oceną stanu technicznego.

Ocenę/Raport wykonano w kierunku ujawnienia uszkodzeń nieakceptowanych z punktu widzenia właściwego przewodnika zwrotu pojazdu lub innych ustaleń ze Zleceniodawcą. Tym samym Ocena/Raport może nie ujmować typowych zużyć i uszkodzeń eksploatacyjnych.

PHOTOGRAPHIC DOCUMENTATION



**Photo 1.**

Przekątna przednia lewa



**Photo 2.**

Przód

PHOTOGRAPHIC DOCUMENTATION



**Photo 3.**

Przekątna przednia prawa



**Photo 4.**

Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



**Photo 5.**

Bok prawy z tyłu



**Photo 6.**

Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



**Photo 7.**

Tył



**Photo 8.**

Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



**Photo 9.**

Bok lewy z tyłu



**Photo 10.**

Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



**Photo 11.**

Próg lewy (widok od przodu)




**Photo 12.**

Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



**Photo 13.**  
Spód pojazdu przód



**Photo 14.**  
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION



**Photo 15.**

Tarcza hamulcowa przednia prawa



**Photo 16.**


Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION



**Photo 17.**

Tarcza hamulcowa tylna lewa



**Photo 18.**

Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



**Photo 19.**  
Bagażnik



**Photo 20.**  
Koło zapasowe

PHOTOGRAPHIC DOCUMENTATION



**Photo 21.**  
Komora silnika



**Photo 22.**  
Numer identyfikacyjny

PHOTOGRAPHIC DOCUMENTATION



**Photo 23.**  
Tabliczka znamionowa



**Photo 24.**  
Zestaw wskaźników - przebieg

PHOTOGRAPHIC DOCUMENTATION



**Photo 25.**

Widok przez otwarte drzwi przednie lewe



**Photo 26.**

Kierownica z lewej strony

PHOTOGRAPHIC DOCUMENTATION



**Photo 27.**

Widok przez otwarte drzwi tylne lewe



**Photo 28.**

Widok z tylnej kanapy na deskę rozdz.

PHOTOGRAPHIC DOCUMENTATION



**Photo 29.**

Konsola środkowa



**Photo 30.**

Tunel środkowy

PHOTOGRAPHIC DOCUMENTATION




**Photo 31.**  
Kierownica (na wprost)



**Photo 32.**  
Książka serwisowa – dane

PHOTOGRAPHIC DOCUMENTATION**Photo 33.**

Książka serwisowa – ostatni przegląd

**Photo 34.**

Dow. rej. ksero Str. 1

PHOTOGRAPHIC DOCUMENTATION**Photo 35.**

Dow. Rej. ksero Str.2 i klucze

**Photo 36.**

Zestaw naprawczy koła

PHOTOGRAPHIC DOCUMENTATION



**Photo 37.**

Zdjęcie do protokołu



**Photo 38.**

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



**Photo 39.**


Zdjęcie do protokołu



**Photo 40.**

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



**Photo 41.**

Zdjęcie do protokołu



**Photo 42.**


Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



**Photo 43.**

Zdjęcie do protokołu



**Photo 44.**

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



**Photo 45.**

Zdjęcie do protokołu



**Photo 46.**

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



**Photo 47.**

Zdjęcie do protokołu



**Photo 48.**

Zderzak - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 49.**

Felga aluminiowa przednia P - Rysa/odprysk 1



**Photo 50.**

Drzwi tylne P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 51.**

Próg P - Rysa/odprysk 1



**Photo 52.**

Ścianka tylna P / Ścianka boczna P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 53.**

Błotnik tylny P / Ściana boczna P - Wgniecenie/odkształcenie 1



**Photo 54.**

Pokrywy bagażnika - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 55.**

Pokrywy bagażnika - Wgniecenie/odkształcenie 1



**Photo 56.**

Zderzak tylny - Inne 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 57.**

Drzwi tylne L - Rysa/odprysk 1



**Photo 58.**

Próg L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 59.**

Kanapa tyl. - Inne 1



**Photo 60.**

Wykładzina podłogi bagażnika - Inne 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 61.**

Wykładzina pokrywy tylnej - Rysa/odprysk 1