

DEKRA's commission No. : PKOL(W)/LODZ/73884/25/09/30
commission/ damage No. : 24/038139
Date of commission: 30-09-2025

DEKRA Poland - Headquarters
02-673 Warszawa, ul. Konstruktorska 12A

Client :

PKO Leasing SA
Świętokrzyska 36
00-116 Warszawa

Expert:

Kacper Sosnowski (NEW)
DEKRA Polska - współpraca O/Warszawa
Andrzej Sosnowski
DEKRA Polska - Centrala

NOTE:

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

Vehicle data

Group of objects (Eurotax)	cars
EC code (Eurotax)	0133910
Manufacturer	TOYOTA
Model	Camry 18-20
Type / version	Camry 2.5 Hybrid Executive CVT
Body type	sedan
Number of doors / seats	4/5
Curb weight [kg]	1630
Gross vehicle weight [kg]	2100
Wheelbase 1/2	2825
Engine type	spark ignition
Pollution reduction system	three-way catalytic converter
Engine capacity [ccm]	2487
Engine Power [hp/kW]	177/131
Gearbox	automatic
Registration /record No.	CT390CR
VIN / serial number	JTNB23HK403065759
Date of first registration	31-03-2020
Date of next. tech. test	16-09-2024
Year of manufacture	2020
Readout [km]	210 116 (read)
Body color / type of coating	brązowy/double-layered, metallized

Tyres

axle	Wheel	Manufacturer, type	Size	Measured profile
Front	right	HANKOOK, WINTER ICEPT EVO 3	225/45 18 95V	4,0 mm
	left	HANKOOK, WINTER ICEPT EVO 3	225/45 18 95V	4,0 mm
back	right	CONTINENTAL, WINTER CONTACT TS850P	235/45 18 98V	3,0 mm
	left	CONTINENTAL, WINTER CONTACT TS850P	235/45 18 98V	3,0 mm

Standard equipment by Eurotax

- | | |
|--|---|
| 1. Adaptive Cruise Control | 41. Leather gearshifter/switch, Leather steering wheel |
| 2. Additional gauges | 42. Leather upholstery |
| 3. Alarm | 43. Light Alloy wheels 18" |
| 4. Antilock-Brake-System (ABS) | 44. Luggage:other |
| 5. Armrest (s) rear | 45. Mobile Tire System |
| 6. Automated High-beam assist | 46. Multi functional steering wheel |
| 7. Automatic climate control | 47. Navigation system |
| 8. Automatic dimlight activation | 48. On board computer |
| 9. Blind spot warning | 49. On board monitor |
| 10. Bluetooth interface, mp3 Player, Radio | 50. Other |
| 11. Bord communication: other | 51. Other |
| 12. Bumpers: other | 52. Other |
| 13. Cargo net | 53. Other |
| 14. Child seat fixation | 54. Park Distance Control front, Park Distance Control rear |
| 15. Distribution of braking force electronically | 55. Passenger seat electrically adjustable |
| 16. Door mirror(s) electrically adjustable in general, Door mirrors heated | 56. Power assisted brakes |
| 17. Door mirrors electrically foldable | 57. Power steering |
| 18. Driver airbag, Passenger airbag | 58. Power windows front |
| 19. Driver knee airbag | 59. Power windows rear |
| 20. Driver seat electrically adjustable | 60. Pre-Crash System |
| 21. ESP (Electronical Stabilizing Program) | 61. Radio |
| 22. Electric tailgate | 62. Rain sensor |
| 23. Exterior design: other | 63. Rear Cross Traffic Alert |
| 24. Exterior design: other | 64. Rear bench foldable in two separate parts |
| 25. Exterior design: other | 65. Rear view camera |
| 26. Extra power outlet | 66. Rear-view mirror autodimming |
| 27. Fog lamps | 67. Remote controlled central locking |
| 28. Head airbags front | 68. Selectable driveline characteristics |
| 29. Headlamp wash | 69. Side airbag driver and passenger |
| 30. Heated seat driver, Heated seat passenger | 70. Side indicators |
| 31. Hill holder | 71. Side indicators |
| 32. Interior decoration: other | 72. Steering wheel electrically adjustable |
| 33. Interior decoration: other | 73. Tinted rear windows |
| 34. Interior lights: other accessories | 74. Traction control |
| 35. Keyless go | 75. Traffic sign recognition |
| 36. Keyless go | 76. Tyre pressure control (RDC) |
| 37. LED Daytime running lights | 77. USB in |
| 38. LED front dim light | 78. Uni-Lackierung |
| 39. LED rear lights | 79. Vehicle immobilizer |
| 40. Lane control assistant | |

Dealer's equipment (selected items)

1. Metallic paint -

Base value of the vehicle

Base value of the vehicle by Eurotax (net) -

CorrectionsFirst registrationMileageEquipmentTyresOther

Earlier repairs -
Braki, uszkodzenia stan, weryfikacja serwisowa -


Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 10-2025 POL) with regard to technical and market parameters affecting the value of the vehicle.

Basic print without information about the vehicle's value - due to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 10-10-2025

DEKRA's expert:
Kacper Sosnowski (NEW)
Andrzej Sosnowski

Document issued electronically valid without signature.

Measurement of thickness of the vehicle lacquer coating


No. of controlled item	Controlled item	Measured range of thickness of the lacquer coat [μm]
1	Front cover	to 150
2	Front left fender	to 150
3	Left front pillar	to 150
4	Front left door	to 150
5	Roof	to 150
6	Left middle pillar	to 150
7	Right side sill	to 150
8	Left rear door	to 150
9	Rear left fender	150 - 300
10	Cover/lid	to 150
11	Right rear fender	150 - 2000
12	Right rear door	150 - 500
13	Right middle pillar	to 150
14	Right side sill	to 150
15	Front right door	to 150
16	Right front pillar	to 150
17	Front right fender	to 150

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

Presented the following documents of the vehicle:

ksero pozwolenia czasowego

During the inspection the service book was presented and its number is given below:

.

Information concerning the origin of the vehicle

Lack of reliable data.

Anti-theft protection - immobilizer

- as a result of the inspection of the vehicle found no malfunctions of the immobilizer in the extent possible to determine during the inspection of the vehicle in the non- workshop conditions.

Anti-theft protection - other:

not found

Additional comments on the car:

Not applicable.

Test drive

Test drive of the vehicle was conducted. Test drive in the full extent is not possible. Comment below:
ograniczenia placowe

Checking of the correctness and / or construction of identification / serial numbers of the object:

Not tested

Verification of the accuracy of the object data, including year of production, and other.

Not conducted - adopted according to the documents presented and indicated sources.

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.
- The evaluation has been carried out basing on delivered documentation and organoleptic examination of

page 5/46

the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the assessed object.

- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

Comments to the commission - regarding valuation

Kluczyki

TAK

1

Expert comments - regarding valuation

Dostarczono ksero pozwolenia czasowego. Rysy na samochodzie. Widoczne wady lakiernicze. Niesprawne czujniki parkowania tył.

Rzeczoznawca dokonał oględzin pojazdu w warunkach parkingowych, co mogło ograniczyć pełną ocenę jego stanu technicznego. Dodatkowo, jeżeli jazda próbna została przeprowadzona (informacje w treści raportu), to wykonano ją w warunkach parkingowych, z niewielką prędkością, co może nie odzwierciedlać pełnych warunków eksploatacyjnych. Istnieje możliwość, że w innych okolicznościach ujawnią się dodatkowe uszkodzenia lub usterki, których nie można było wykryć podczas obecnych oględzin. Zalecamy zatem skorzystanie z możliwości oględzin pojazdu we własnym zakresie lub w Autoryzowanej Stacji Obsługi danej marki, co pozwoli na pełniejszą weryfikację stanu technicznego pojazdu przed udziałem w aukcji."

Restrictive disclaimer - regarding valuation

Nie weryfikowano szczegółowo stanu układu napędowego, zawieszenia, kierowniczego, hamulcowego oraz wydechowego. Ocena została wykonana bez użycia podnośnika i specjalistycznego sprzętu diagnostycznego, nie dokonywano demontażu osłon i innych elementów. Ocena określa ogólny stan pojazdu na dzień oględzin w miejscu jego udostępnienia, nie może być zatem traktowana jako kompleksowa ocena stanu technicznego. Specyfikacja wg. programu operacyjnego w zakresie wyposażenia standardowego i dodatkowego nie gwarantuje zgodności ze stanem faktycznym w zakresie możliwym do ustalenia przez rzeczoznawcę podczas oględzin pojazdu.

Pomiar grubości powłoki lakierowej wykonano w miejscach możliwych do ich wykonania pomiary nie gwarantują oryginalności poszczególnych elementów poddanych ocenie.

- W Ocenie/Raporcie uwzględniono niesprawności, uszkodzenia, braki itp., które były możliwe do stwierdzenia organoleptycznego, w warunkach oględzin (z uwzględnieniem: stanu czystości pojazdu, warunków atmosferycznych, oświetlenia itd.) oraz bez weryfikacji serwisowej, bez dostępu do spodu pojazdu, bez specjalistycznego sprzętu diagnostycznego (w tym bez diagnostyki komputerowej), bez jazdy próbnej wykonanej w warunkach drogowych z obciążeniem.
- W ramach Oceny/Raportu nie weryfikowano odczytanego stanu drogomierza z zapisami w urządzeniach elektronicznych pojazdu.
- Rzeczoznawca nie bierze na siebie odpowiedzialności za wady ukryte (prawne i fizyczne) oraz ewentualne skutki wynikające z dalszego użytkowania przedmiotu oceny, a także za skutki wykorzystania samej oceny.
- Podane przedziały grubości powłoki lakierowej, dotyczą punktów pomiarowych. Nie mogą być traktowane jako gwarancja, że grubość powłoki lakierowej w innych punktach nie wykracza poza te przedziały.

- Zawarte w niniejszej Ocenie/Raporcie informacje (w tym dotyczące wyposażenia) służą jedynie ogólnym celom informacyjnym. Ocena/Raport nie może być zatem traktowana jako oferta w rozumieniu przepisów Kodeksu Cywilnego oraz opisu towaru ani zapewnienia w rozumieniu art. 4 Ustawy z dnia 27 lipca 2002 roku o szczególnych warunkach sprzedaży konsumenckiej.
- Niniejsza Ocena/Raport nie jest szczegółową oceną stanu technicznego.

Ocenę/Raport wykonano w kierunku ujawnienia uszkodzeń nieakceptowanych z punktu widzenia właściwego przewodnika zwrotu pojazdu lub innych ustaleń ze Zleceniodawcą. Tym samym Ocena/Raport może nie ujmować typowych zużyć i uszkodzeń eksploatacyjnych.

PHOTOGRAPHIC DOCUMENTATION



Photo 1.
Przekątna przednia lewa



Photo 2.
Przód

PHOTOGRAPHIC DOCUMENTATION



Photo 3.

Przekątna przednia prawa



Photo 4.

Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 5.

Bok prawy z tyłu



Photo 6.

Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 7.

Tył



Photo 8.

Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 9.

Bok lewy z tyłu



Photo 10.

Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 11.

Próg lewy (widok od przodu)




Photo 12.

Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



Photo 13.
Spód pojazdu przód



Photo 14.
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION



Photo 15.

Tarcza hamulcowa przednia prawa



Photo 16.

Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 17.

Tarcza hamulcowa tylna lewa



Photo 18.

Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 19.
Bagażnik



Photo 20.
Koło zapasowe

PHOTOGRAPHIC DOCUMENTATION



Photo 21.
Komora silnika



Photo 22.
Numer identyfikacyjny

PHOTOGRAPHIC DOCUMENTATION



Photo 23.
Tabliczka znamionowa



Photo 24.
Zestaw wskaźników - przebieg

PHOTOGRAPHIC DOCUMENTATION



Photo 25.

Widok przez otwarte drzwi przednie lewe



Photo 26.

Kierownica z lewej strony

PHOTOGRAPHIC DOCUMENTATION



Photo 27.

Widok przez otwarte drzwi tylne lewe



Photo 28.

Widok z tylnej kanapy na deskę rozdz.

PHOTOGRAPHIC DOCUMENTATION




Photo 29.
Konsola środkowa




Photo 30.
Tunel środkowy

PHOTOGRAPHIC DOCUMENTATION**Photo 31.**

Kierownica (na wprost)

**Photo 32.**


Książka serwisowa – dane

PHOTOGRAPHIC DOCUMENTATION**Photo 33.**


Książka serwisowa – ostatni przegląd

**Photo 34.**

Dow. rej. ksero Str. 1

PHOTOGRAPHIC DOCUMENTATION**Photo 35.**

Dow. Rej. ksero Str.2 i klucze

**Photo 36.**

Instrukcje

PHOTOGRAPHIC DOCUMENTATION



Photo 37.

Zdjęcie do protokołu



Photo 38.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 39.

Pokrywa komory silnika - zdjęcie poglądowe 1




Photo 40.

Pokrywa komory silnika - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 41.

Szyba czołowa - zdjęcie poglądowe 1




Photo 42.

Szyba czołowa - Pęknięcie/rozerwanie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 43.

Wykładzina pokrywy komory silnika - Pęknięcie/rozerwanie 1



Photo 44.

Zderzak - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 45.

Zderzak - Wgniecenie/odkształcenie 1



Photo 46.

Łotnik przedni P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 47.

Błotnik przedni P - Inne 1



Photo 48.

Felga aluminiowa przednia P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 49.

Drzwi przednie P - Rysa/odprysk 1



Photo 50.

Drzwi przednie P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 51.

Drzwi tylne P - Wgniecenie/odkształcenie 1



Photo 52.

Lusterko zew P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 53.

Błotnik tylny P / Ściana boczna P - Wgniecenie/odkształcenie 1



Photo 54.

Felga aluminiowa tylna P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 55.

Opona tylna P - Inne 1



Photo 56.

Czujniki parkowania tył - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 57.

Pokrywy bagażnika - Wgniecenie/odkształcenie 1



Photo 58.

Zderzak tylny - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 59.

Zderzak tylny - Pęknięcie/rozerwanie 1



Photo 60.

Dach - zdjęcie pogładowe 1

PHOTOGRAPHIC DOCUMENTATION



Photo 61.

Dach - Inne 1




Photo 62.

Błotnik tylny L / Ściana boczna L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 63.

Błotnik tylny L / Ściana boczna L - Wgniecenie/odkształcenie 2



Photo 64.

Felga aluminiowa tylna L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 65.

Drzwi przed L - Rysa/odprysk 1



Photo 66.

Drzwi przed L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION




Photo 67.

Drzwi tylne L - Wgniecenie/odkształcenie 1



Photo 68.

Lusterko zew L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 69.

Słupek przedni L - Rysa/odprysk 1



Photo 70.

Felga Aluminiowa przednia L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 71.

Nadkole przednie L - Inne 1



Photo 72.

Gałka dźwigni zmiany biegów - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 73.

Koło kierownicy - Rysa/odprysk 1



Photo 74.

Fotel prz. lew. - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 75.

Fotel prz. praw. - Inne 1



Photo 76.

Fotel prz. praw. - Inne 2

PHOTOGRAPHIC DOCUMENTATION



Photo 77.

Podsufitka - Inne 1