

DEKRA's commission No. : PKOL(W)/LODZ/61000/25/08/19
commission/ damage No. : 24/011087
Date of commission: 19-08-2025

DEKRA Poland - Headquarters
02-673 Warszawa, ul. Konstruktorska 12A

Client :

PKO Leasing SA
Świętokrzyska 36
00-116 Warszawa

Expert:

Kacper Sosnowski (NEW)
DEKRA Polska - współpraca O/Warszawa
Andrzej Sosnowski
DEKRA Polska - Centrala

NOTE:

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

Vehicle data

Group of objects (Eurotax)	jeeps
EC code (Eurotax)	0147744
Manufacturer	CUPRA
Model	Formentor 20-24
Type / version	Formentor 1.5 TSI DSG
Body type	hatchback
Number of doors / seats	5/5
Curb weight [kg]	1422
Gross vehicle weight [kg]	1980
Wheelbase 1/2	2679
Engine type	spark ignition
Pollution reduction system	GPF
Engine capacity [ccm]	1498
Engine Power [hp/kW]	150/110
Gearbox	automatic
Registration /record No.	EL9JX23
VIN / serial number	VSSZZZKM2RR045188
Date of first registration	26-03-2024
Date of next. tech. test	26-03-2027
Year of manufacture	2023 (year has been verified with the manufacturer's base)
Readout [km]	105 537 (read)
Body color / type of coating	black/double-layered, metallized

Tyres

axle	Wheel	Manufacturer, type	Size	Measured profile
Front	right	KORMORAN, SNOW	245/45 18 100V	4,0 mm
	left	KORMORAN, SNOW	245/45 18 100V	4,0 mm
back	right	KORMORAN, SNOW	245/45 18 100V	6,5 mm
	left	KORMORAN, SNOW	245/45 18 100V	6,5 mm

Standard equipment by Eurotax

1. Active Tyre pressure control
2. Adaptive Cruise Control
3. Airbag: other
4. Android Auto, Apple CarPlay, Other
5. Antilock-Brake-System (ABS)
6. Armrest (s) front, Storage facilities in general
7. Armrest (s) rear
8. Artificial leather upholstery, Textile upholstery
9. Automated High-beam assist
10. Automatic dimlight activation
11. Automatic limited slip differential
12. Automatic limited slip differential
13. Bluetooth interface
14. Bord communication: other, Hands-free system, mp3 Player, On board monitor, Radio, USB in, Voice control for audiosystem
15. Brake Assist
16. CUPRA CARE - 5 lat gwarancji CUPRA
17. Child seat fixation
18. Child seat fixation
19. Cornering Headlights, Fog lamps
20. DAB radio
21. Distance control
22. Door mirror(s) electrically adjustable in general, Door mirrors electrically foldable, Door mirrors heated
23. Driver airbag, Driver knee airbag, Head airbags front, Passenger airbag, Side airbag driver and passenger
24. Driver conditioning monitoring
25. Driver seat height adjustable, Lumbar adjust driver, Lumbar adjust passenger, Passenger seat height adjustable
26. Dywaniki welurowe z przodu i z tyłu
27. ESP (Electronical Stabilizing Program)
28. Electric parking brake
29. Exterior design: other
30. Exterior design: other
31. Exterior design: other
32. Exterior design: other
33. Exterior design: other
34. Exterior design: other
35. Exterior design: other
36. Exterior design: other
37. Exterior design: other, Roof railing
38. Extra power outlet
39. Extra power outlet
40. Felgi aluminiowe 18 CUPRA MACHINED SPORT BLACK MATT / SILVER z ogumieniem 245/45
41. Follow me home
42. Funkcja automatyczna opóźnionego wyłączenia świateł Coming and Leaving Home
43. Heated seat driver, Heated seat passenger
44. Interior decoration: other
45. Interior lights: other accessories
46. Interior lights: other accessories
47. Interior lights: other accessories
48. Interior lights: other accessories
49. Interior lights: other accessories
50. Interior: other
51. Interior: other
52. Keyless go
53. LED Daytime running lights
54. LED front dim light
55. LED rear lights, Side indicators
56. Lane control assistant
57. Luggage: other
58. Mirror: others
59. Multi functional steering wheel, Sports steering wheel, Steering wheel heated
60. On board monitor
61. Other
62. Other
63. Other
64. Other
65. Other
66. Other
67. Oświetlenie drzwi LED
68. Park Assistant, Park Distance Control front, Park Distance Control rear
69. Power windows front, Power windows rear
70. Półka na dokumenty pod fotelem kierowcy
71. Rain sensor
72. Rear seat-backs foldable in two separate parts
73. Rear spoiler
74. Rear view camera
75. Rear-view mirror autodimming
76. Seats: other
77. Selectable driveline characteristics
78. Servotronic
79. Speed limiter
80. Sport seats front
81. Steering wheel with gear-switches
82. Storage facilities in general
83. Traction control
84. Trizone automatic climate control
85. Uni-Lackierung
86. Zamek centralny ze zdalnym sterowaniem, dwa składane kluczyki, otwieranie drzwi bagażnika z pilota

Dealer's equipment (selected items)

1. Diminished spare wheel -
2. Door mirror with memory, Driver seat electrically adjustable, Moulded sport seats -
Fotele przednie kubelkowe
Tapicerka materiałowa z ekoskórą z przeszyciem w kolorze miedzi
Fotel kierowcy z pełną regulacją elektryczną oraz pamięcią ustawień
Lusterka z pamięcią ustawień
3. Metallic paint -

Base value of the vehicle

Base value of the vehicle by Eurotax (net) -

Corrections

First registration

Mileage

Equipment

Other

Current market situation -
Uszkodzenia, stan -


Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 08-2025 POL) with regard to technical and market parameters affecting the value of the vehicle.

Basic print without information about the vehicle's value - due to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 25-08-2025

DEKRA's expert:
Kacper Sosnowski (NEW)
Andrzej Sosnowski

Document issued electronically valid without signature.

Measurement of thickness of the vehicle lacquer coating


No. of controlled item	Controlled item	Measured range of thickness of the lacquer coat [μm]
1	Front cover	to 150
2	Left front fender	to 150
3	Left front pillar	to 150
4	Left front wall	to 150
5	Roof	to 150
6	Left middle pillar	to 150
7	Left side sill	to 150
8	Left rear wall	to 150
9	Left side wall	to 150
10	Cover/tailgate	to 150
11	Side right wall	to 150
12	Rear right door	to 150
13	Middle right pillar	to 150
14	Front right door	to 150
15	Right side sill	to 150
16	Right front pillar	to 150
17	Right front fender	to 150

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

During the inspection the service book was presented and its number is given below:
elektroniczna

Information concerning the origin of the vehicle

Lack of reliable data.

Additional comments on the car:

Not applicable.

Test drive

Test drive of the vehicle was conducted. Test drive in the full extent is not possible. Comment below:
ograniczenia placowe

Checking of the correctness and / or construction of identification / serial numbers of the object:

Not tested

Verification of the accuracy of the object data, including year of production, and other.

Not conducted - adopted according to the documents presented and indicated sources.

Anti-theft protection

fabryczne

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.
- The evaluation has been carried out basing on delivered documentation and organoleptic examination of the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the assessed object.
- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

Comments to the commission - regarding valuation**Kluczyki**

TAK

2

Expert comments - regarding valuation

Rysy na samochodzie. Brak półki bagażnika. Odpryski na szybie czołowej.

Rzeczoznawca dokonał oględzin pojazdu w warunkach parkingowych, co mogło ograniczyć pełną ocenę jego stanu technicznego. Dodatkowo, jeżeli jazda próbna została przeprowadzona (informacje w treści raportu), to wykonano ją w warunkach parkingowych, z niewielką prędkością, co może nie odzwierciedlać pełnych warunków eksploatacyjnych. Istnieje możliwość, że w innych okolicznościach ujawnią się dodatkowe uszkodzenia lub usterki, których nie można było wykryć podczas obecnych oględzin. Zalecamy zatem skorzystanie z możliwości oględzin pojazdu we własnym zakresie lub w Autoryzowanej Stacji Obsługi danej marki, co pozwoli na pełniejszą weryfikację stanu technicznego pojazdu przed udziałem w aukcji."

Restrictive disclaimer - regarding valuation

Nie weryfikowano szczegółowo stanu układu napędowego, zawieszenia, kierowniczego, hamulcowego oraz wydechowego. Ocena została wykonana bez użycia podnośnika i specjalistycznego sprzętu diagnostycznego, nie dokonywano demontażu osłon i innych elementów. Ocena określa ogólny stan pojazdu na dzień oględzin w miejscu jego udostępnienia, nie może być zatem traktowana jako kompleksowa ocena stanu technicznego. Specyfikacja wg. programu operacyjnego w zakresie wyposażenia standardowego i dodatkowego nie gwarantuje zgodności ze stanem faktycznym w zakresie możliwym do ustalenia przez rzeczoznawcę podczas oględzin pojazdu. Pomiar grubości powłoki lakierowej wykonano w miejscach możliwych do ich wykonania pomiary nie gwarantują oryginalności poszczególnych elementów poddanych ocenie.

- W Ocenie/Raporcie uwzględniono niesprawności, uszkodzenia, braki itp., które były możliwe do stwierdzenia organoleptycznego, w warunkach oględzin (z uwzględnieniem: stanu czystości pojazdu, warunków atmosferycznych, oświetlenia itd.) oraz bez weryfikacji serwisowej, bez dostępu do spodu pojazdu, bez specjalistycznego sprzętu diagnostycznego (w tym bez diagnostyki komputerowej), bez jazdy próbnej wykonanej w warunkach drogowych z obciążeniem.
- W ramach Oceny/Raportu nie weryfikowano odczytanego stanu drogomierza z zapisami w urządzeniach elektronicznych pojazdu.
- Rzeczoznawca nie bierze na siebie odpowiedzialności za wady ukryte (prawne i fizyczne) oraz ewentualne skutki wynikające z dalszego użytkowania przedmiotu oceny, a także za skutki wykorzystania samej oceny.
- Podane przedziały grubości powłoki lakierowej, dotyczą punktów pomiarowych. Nie mogą być traktowane jako gwarancja, że grubość powłoki lakierowej w innych punktach nie wykracza poza te przedziały.
- Zawarte w niniejszej Ocenie/Raporcie informacje (w tym dotyczące wyposażenia) służą jedynie ogólnym celom informacyjnym. Ocena/Raport nie może być zatem traktowana jako oferta w rozumieniu przepisów Kodeksu Cywilnego oraz opisu towaru ani zapewnienia w rozumieniu art. 4 Ustawy z dnia 27 lipca 2002 roku o szczególnych warunkach sprzedaży konsumenckiej.
- Niniejsza Ocena/Raport nie jest szczegółową oceną stanu technicznego.

Ocenę/Raport wykonano w kierunku ujawnienia uszkodzeń nieakceptowanych z punktu widzenia właściwego przewodnika zwrotu pojazdu lub innych ustaleń ze Zleceniodawcą. Tym samym Ocena/Raport może nie ujmować typowych zużyć i uszkodzeń eksploatacyjnych.

PHOTOGRAPHIC DOCUMENTATION



Photo 1.

Przekątna przednia lewa



Photo 2.

Przód

PHOTOGRAPHIC DOCUMENTATION



Photo 3.

Przekątna przednia prawa



Photo 4.

Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 5.
Bok prawy z tyłu



Photo 6.
Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 7.

Tył



Photo 8.

Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 9.

Bok lewy z tyłu



Photo 10.

Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 11.

Próg lewy (widok od przodu)




Photo 12.

Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



Photo 13.
Spód pojazdu przód



Photo 14.
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION



Photo 15.

Tarcza hamulcowa przednia prawa



Photo 16.

Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 17.

Tarcza hamulcowa tylna lewa



Photo 18.

Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 19.
Bagażnik



Photo 20.
Koło zapasowe

PHOTOGRAPHIC DOCUMENTATION



Photo 21.
Komora silnika




Photo 22.
Numer identyfikacyjny

PHOTOGRAPHIC DOCUMENTATION



Photo 23.

Tabliczka znamionowa



Photo 24.

Zestaw wskaźników - przebieg

PHOTOGRAPHIC DOCUMENTATION



Photo 25.

Widok przez otwarte drzwi przednie lewe



Photo 26.

Kierownica z lewej strony

PHOTOGRAPHIC DOCUMENTATION



Photo 27.

Widok przez otwarte drzwi tylne lewe



Photo 28.

Widok z tylnej kanapy na deskę rozdz.

PHOTOGRAPHIC DOCUMENTATION



Photo 29.
Konsola środkowa




Photo 30.
Tunel środkowy

PHOTOGRAPHIC DOCUMENTATION**Photo 31.**

Kierownica (na wprost)

**Photo 32.**

Dowód rej. Str. 1

PHOTOGRAPHIC DOCUMENTATION



Photo 33.

Dow. Rej. Str.2 i klucze



Photo 34.

Instrukcje

PHOTOGRAPHIC DOCUMENTATION



Photo 35.

Zdjęcie do protokołu




Photo 36.

Pokrywa komory silnika - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 37.

Zderzak - Rysa/odprysk 1



Photo 38.

Lusterko zew P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 39.

Błotnik tylny P / Ściana boczna P - Rysa/odprysk 1



Photo 40.

Błotnik tylny P / Ściana boczna P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 41.

Listwa krawędzi błotnika tyl P - Rysa/odprysk 1



Photo 42.

Zderzak tylny cz dolna - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 43.

Zderzak tylny cz P - Rysa/odprysk 1



Photo 44.

Błotnik tylny L / Ściana boczna L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 45.

Drzwi przed L - Rysa/odprysk 1



Photo 46.

Drzwi tylne L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 47.

Drzwi tylne L - Wgniecenie/odkształcenie 1



Photo 48.

Próg L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 49.

Słupek przedni L - Rysa/odprysk 1



Photo 50.

Fotel prz. lew. - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 51.
Kanapa tyl. - Inne 1



Photo 52.
Uchwyt drzwi tyl L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION




Photo 53.

Wykładzina(y) słupka tylnego L - Rysa/odprysk 1




Photo 54.

Wykładzina(y) słupka tylnego P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 55.

Półka/roleta tylna - Inne 1