

DEKRA's commission No. : PKOL(W)/LODZ/76737/26/08/17
commission/ damage No. : 23/012901
Date of commission: 17-08-2026

DEKRA Poland - Headquarters
02-673 Warszawa, ul. Konstruktorska 12A

Client :

PKO Leasing SA
Świętokrzyska 36
00-116 Warszawa

Expert:

Kacper Sosnowski (WSP)
DEKRA Polska - współpraca O/Warszawa
inż. Dariusz Pawliszyn
DEKRA Polska - O. Poznań

NOTE:

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

Vehicle data

Group of objects (Eurotax)	jeeps
EC code (Eurotax)	0155568
Manufacturer	BMW
Model	X7 [G07] 22-
Type / version	X7 M60i xDrive mHEV sport-aut
Body type	KOM
Number of doors / seats	5/7
Curb weight [kg]	2600
Gross vehicle weight [kg]	3355
Wheelbase 1/2	3105
Engine type	spark ignition
Pollution reduction system	GPF
Engine capacity [ccm]	4395
Engine Power [hp/kW]	530/390
Gearbox	automatic 8- gear
Registration /record No.	FZ1561T
VIN / serial number	WBA31EM0009R93445
Date of first registration	10-05-2023
Date of next. tech. test	09-05-2026
Year of manufacture	2023 (year has been verified with the manufacturer's base)
Readout [km]	49 617 (read)
Body color / type of coating	blue/double-layered, metallized

Tyres

axle	Wheel	Manufacturer, type	Size	Measured profile
Front	right	PIRELLI, SCORPION WINTER	275/40 22 107V	2,0 mm
	left	PIRELLI, SCORPION WINTER	275/40 22 107V	2,0 mm
back	right	PIRELLI, SCORPION WINTER	315/35 22 111V	3,0 mm
	left	PIRELLI, SCORPION WINTER	315/35 22 111V	3,0 mm

Standard equipment by Eurotax

- | | |
|---|---|
| 1. 2 single seats rear | 53. Free service 4 years or more, more than 60000 km |
| 2. 2 single seats rear, 3 single seats middle | 54. Gesture control for multimedia, Gesture control for vehicle functions |
| 3. 4 or more zone automatic climate control, Air condition rear | 55. Glass tilt/slide sunroof electric |
| 4. Accoustic windows | 56. Gwarancja na baterie wysokiego napięcia - 6 lat z limitem 100.000 km |
| 5. Active Blind spot system, Blind spot warning | 57. Gwarancja na pojazd bez limitu kilometrów - 2 lata |
| 6. Active body control, Air suspension | 58. Headlamp wash nozzle heated |
| 7. Aerodynamics package, Exterior design: other | 59. Heated seat driver, Heated seat passenger |
| 8. Alarm | 60. Hill descent control |
| 9. Android Auto, Apple CarPlay | 61. Interior lights: other accessories |
| 10. Antilock-Brake-System (ABS) | 62. Interior: other |
| 11. Armrest (s) front, Armrest (s) rear | 63. Interior: other |
| 12. Automated High-beam assist | 64. Keyless Engine start |
| 13. Automatic Emergency Call | 65. LED rear lights |
| 14. Automatic Emergency Call | 66. Leather steering wheel, Sports steering wheel |
| 15. Automatic dimlight activation, Rain sensor | 67. Leather upholstery |
| 16. Bord entertainment: other accessories | 68. Light Allow wheels over 21'', Runflat tyres |
| 17. Bord entertainment: other accessories | 69. Limited slip differential: other |
| 18. Bord entertainment: other accessories, Mobile phone | 70. Luggage:other |
| 19. Bord entertainment: other accessories, Soundsystem | 71. Luggage:other, Transport/loading: other |
| 20. Child lock manually | 72. Mirror: others |
| 21. Child seat fixation | 73. Multi functional steering wheel |
| 22. Collision Warning System | 74. Other |
| 23. Collision Warning System | 75. Other |
| 24. Comfort driver seat, Comfort passenger seat, Driver seat electrically adjustable, Lumbar adjust driver electric, Lumbar adjust passenger electric, Passenger seat electrically adjustable | 76. Other |
| 25. Cornering Headlights, LED front dim light | 77. Other |
| 26. Cruise control, Distance control | 78. Other |
| 27. DAB radio | 79. Other |
| 28. Digital instruments, Head-Up Display, Navigation system, On board monitor, Touchscreen monitor | 80. Other |
| 29. Digital key, Keyless entry, Keyless go | 81. Other |
| 30. Door mirror(s) electrically adjustable in general, Door mirrors autodimming, Door mirrors electrically foldable, Door mirrors heated, Mirror: others | 82. Park Assistant, Park Distance Control front, Park Distance Control rear, Rear view camera |
| 31. Door: other | 83. Power assisted brakes |
| 32. Driver airbag, Head airbags front, Head airbags rear, Passenger airbag, Side airbag driver and passenger, Side airbags rear | 84. Power steering |
| 33. Driver seat electrically adjustable, Memory seat, Passenger seat electrically adjustable | 85. Power windows front, Power windows rear |
| 34. Driver-information-system | 86. Rear Cross Traffic Alert |
| 35. ESP (Electronical Stabilizing Program), Traction control | 87. Rear seat-backs foldable in two separate parts |
| 36. Electric parking brake | 88. Remote controlled central locking |
| 37. Electric tailgate | 89. Roof railing |
| 38. Enhanced suspension | 90. Selectable driveline characteristics |

- | | |
|------------------------------|--|
| 39. Exterior design: other | 91. Servotronic |
| 40. Exterior design: other | 92. Side Pre-Crash System |
| 41. Exterior design: other | 93. Speed limiter |
| 42. Exterior design: other | 94. Start/Stop system |
| 43. Exterior design: other | 95. Steering wheel manually adjustable |
| 44. Exterior design: other | 96. Storage facilities in general |
| 45. Exterior design: other | 97. Tyre pressure control (RDC) |
| 46. Exterior design: other | 98. USB in |
| 47. Exterior lighting: other | 99. Uni-Lackierung |
| 48. Extra power outlet | 100. Wheel bolt locks |
| 49. Fire protection system | 101. Wireless device charging |
| 50. Floor mat | 102. Wood finish |
| 51. Follow me home | 103. {System stabilizacji przyczepy} |
| 52. Follow me home | |

Dealer's equipment (selected items)

- | | |
|--|---|
| 1. 360 view camera, Autonomous parking system, Park Assistant, Steering: other | - |
| 2. 4 or more zone automatic climate control | - |
| 3. Active Emergency Brake Assist, Adaptive Cruise Control, City Emergency Brake Assist, Collision Warning System, Distance control, Intersection Assist, Pre-Crash System, Side Pre-Crash System | - |
| Tempomat aktywny z funkcją Stop&Go | |
| System ostrzegający przed ruchem poprzecznym z przodu | |
| Asystent unikania kolizji | |
| Asystent kierowania i pasa ruchu | |
| Asystent zatrzymania awaryjnego | |
| Asystent zmiany pasa ruchu | |
| Asystent utrzymania pasa ruchu z aktywną ochroną przed kolizją boczną | |
| System ostrzegania przed kolizją podczas opuszczania pojazdu | |
| Asystent pasa awaryjnego | |
| 4. Bord entertainment: other accessories, Soundsystem | - |
| 5. Exterior design: other, Interior: other, Steering: other | - |
| Obramowania M Shadow Line z wysokim połyskiem o rozszerzonym zakresie | |
| Układ hamulcowy sportowy M, czarny na wysoki połysk | |
| Pasy bezpieczeństwa z paskami w barwach M | |
| 6. Exterior design: other, Mirror: others | - |
| 7. Front seat with massage, Glass tilt/slide sunroof electric rear, Interior decoration: other, Leather finish dashbord, Ventilated front seat | - |
| Dach szklany panoramiczny Sky Lounge z zintegrowanymi diodami LED | |
| Funkcja masażu w oparciach siedzeń przednich | |
| Aplikacje szklane CraftedClarity na elementach wnętrza | |
| Panel deski rozdzielczej BMW Individual pokryty skórą Walknappa | |
| Fotele przednie z aktywną wentylacją | |
| 8. Interior decoration: other | - |
| 9. Interior: other | - |
| 10. Light alloy wheels 22", Runflat tyres | - |
| 11. Metallic paint | - |
| 12. Sport seats front | - |
| 13. Steering: other | - |
| 14. Sunblind rear side door electric | - |

Base value of the vehicle

Base value of the vehicle by Eurotax (net) -

Corrections

Equipment

Tyres

Other

State of the vehicle -


Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 08-2026 POL) with regard to technical and market parameters affecting the value of the vehicle.

Basic print without information about the vehicle's value - duey to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 19-08-2026

DEKRA's expert:
Kacper Sosnowski (WSP)
inż. Dariusz Pawliszyn

Document issued electronically valid without signature.

Measurement of thickness of the vehicle lacquer coating


No. of controlled item	Controlled item	Measured range of thickness of the lacquer coat [μm]
1	Front cover	to 150
2	Left front fender	to 150
3	Left front pillar	to 150
4	Left front wall	to 150
5	Roof	to 150
6	Left middle pillar	to 150
7	Left side sill	to 150
8	Left rear wall	to 150
9	Left side wall	to 150
10	Cover/tailgate	to 150
11	Side right wall	to 150
12	Rear right door	to 150
13	Middle right pillar	to 150
14	Front right door	to 150
15	Right side sill	to 150
16	Right front pillar	to 150
17	Right front fender	to 150

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

During the inspection the registration proof of the vehicle was presented and its photo was taken and enclosed to the expertise.

During the inspection the service book of the vehicle was not provided.

Information concerning the origin of the vehicle

The vehicle purchased domestically from an authorized representative of the brand.

Additional comments on the car:

Not applicable.

Test drive

Test drive of the vehicle was conducted. Test drive in the full extent is not possible. Comment below: parking

Checking of the correctness and / or construction of identification / serial numbers of the object:

Not tested

Verification of the accuracy of the object data, including year of production, and other.

Not conducted - adopted according to the documents presented and indicated sources.

Anti-theft protection

.

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.
- The evaluation has been carried out basing on delivered documentation and organoleptic examination of the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the assessed object.
- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

Comments to the commission - regarding valuation**Kluczyki**

TAK

2

Expert comments - regarding valuation

Rysy na samochodzie. Brak aktualnych badań technicznych. Odpryski na szybie czołowej.

Restrictive disclaimer - regarding valuation

- W Ocenie/Raporcie uwzględniono niesprawności, uszkodzenia, braki itp., które były możliwe do stwierdzenia organoleptycznego, w warunkach oględzin (z uwzględnieniem: stanu czystości pojazdu, warunków atmosferycznych, oświetlenia itd.) oraz bez weryfikacji serwisowej, bez dostępu do spodu pojazdu, bez specjalistycznego sprzętu diagnostycznego (w tym bez diagnostyki komputerowej), bez jazdy próbnej wykonanej w warunkach drogowych z obciążeniem.
- W ramach Oceny/Raportu nie weryfikowano odczytanego stanu drogomierza z zapisami w urządzeniach elektronicznych pojazdu.
- Rzeczoznawca nie bierze na siebie odpowiedzialności za wady ukryte (prawne i fizyczne) oraz ewentualne skutki wynikające z dalszego użytkowania przedmiotu oceny, a także za skutki wykorzystania samej oceny.
- Podane przedziały grubości powłoki lakierowej, dotyczą punktów pomiarowych. Nie mogą być traktowane jako gwarancja, że grubość powłoki lakierowej w innych punktach nie wykracza poza te przedziały.
- Zawarte w niniejszej Ocenie/Raporcie informacje (w tym dotyczące wyposażenia) służą jedynie ogólnym celom informacyjnym. Ocena/Raport nie może być zatem traktowana jako oferta w rozumieniu przepisów Kodeksu Cywilnego oraz opisu towaru ani zapewnienia w rozumieniu art. 4 Ustawy z dnia 27 lipca 2002 roku o szczególnych warunkach sprzedaży konsumenckiej.
- Niniejsza Ocena/Raport nie jest szczegółową oceną stanu technicznego.

Ocenę/Raport wykonano w kierunku ujawnienia uszkodzeń nieakceptowanych z punktu widzenia właściwego przewodnika zwrotu pojazdu lub innych ustaleń ze Zleceniodawcą. Tym samym Ocena/Raport może nie ujmować typowych zużyć i uszkodzeń eksploatacyjnych.

PHOTOGRAPHIC DOCUMENTATION



Photo 1.
Przekątna przednia lewa



Photo 2.
Przód

PHOTOGRAPHIC DOCUMENTATION



Photo 3.

Przekątna przednia prawa



Photo 4.

Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 5.

Bok prawy z tyłu



Photo 6.

Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 7.

Tył



Photo 8.

Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 9.

Bok lewy z tyłu



Photo 10.

Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 11.
Próg lewy (widok od przodu)



Photo 12.
Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



Photo 13.
Spód pojazdu przód



Photo 14.
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION



Photo 15.

Tarcza hamulcowa przednia prawa



Photo 16.

Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 17.

Tarcza hamulcowa tylna lewa



Photo 18.

Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 19.
Bagażnik



Photo 20.
Komora silnika

PHOTOGRAPHIC DOCUMENTATION



Photo 21.

Numer identyfikacyjny




Photo 22.

Tabliczka znamionowa

PHOTOGRAPHIC DOCUMENTATION



Photo 23.

Zestaw wskaźników - przebieg



Photo 24.

Zestaw wskaźników - serwis

PHOTOGRAPHIC DOCUMENTATION




Photo 25.

Widok przez otwarte drzwi przednie lewe



Photo 26.

Kierownica z lewej strony

PHOTOGRAPHIC DOCUMENTATION



Photo 27.

Widok przez otwarte drzwi tylne lewe



Photo 28.

Widok z tylnej kanapy na deskę rozdz.

PHOTOGRAPHIC DOCUMENTATION



Photo 29.
Konsola środkowa



Photo 30.
Tuneł środkowy

PHOTOGRAPHIC DOCUMENTATION




Photo 31.
Kierownica (na wprost)



Photo 32.
Dowód rej. Str. 1

PHOTOGRAPHIC DOCUMENTATION**Photo 33.**

Książka serwisowa – dane

**Photo 34.**

Książka serwisowa – ostatni przegląd

PHOTOGRAPHIC DOCUMENTATION

Photo 35.
Dow. Rej. Str. 2



Photo 36.
Kluczyki

PHOTOGRAPHIC DOCUMENTATION



Photo 37.

Zdjęcie do protokołu



Photo 38.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 39.

Zdjęcie do protokołu



Photo 40.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 41.
Zdjęcie do protokołu



Photo 42.
Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 43.

Zdjęcie do protokołu



Photo 44.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 45.
Zdjęcie do protokołu



Photo 46.
Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 47.

Zdjęcie do protokołu




Photo 48.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION




Photo 49.

Pokrywa komory silnika - Rysa/odprysk 1



Photo 50.

Światnik przedni P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 51.

Felga aluminiowa przednia P - Rysa/odprysk 1



Photo 52.

Opona przednia P - Pęknięcie/rozerwanie 1

PHOTOGRAPHIC DOCUMENTATION




Photo 53.

Drzwi przednie P - Rysa/odprysk 1



Photo 54.

Drzwi tylne P - zdjęcie pogładowe 1

PHOTOGRAPHIC DOCUMENTATION



Photo 55.

Drzwi tylne P - Rysa/odprysk 1



Photo 56.

Drzwi tylne P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 57.

Błotnik tylny P / Ściana boczna P - Rysa/odprysk 1



Photo 58.

Błotnik tylny P / Ściana boczna P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION




Photo 59.

Pokrywy bagażnika - Rysa/odprysk 1



Photo 60.

Zderzak tylny - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION




Photo 61.

Zderzak tylny - Rysa/odprysk 2



Photo 62.

Zderzak tylny() - Rysa/odprysk 3

PHOTOGRAPHIC DOCUMENTATION



Photo 63.

Felga aluminiowa tylna L - Rysa/odprysk 1



Photo 64.

Opona tylna L - Pęknięcie/rozerwanie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 65.

Drzwi przed L - Rysa/odprysk 1



Photo 66.

Drzwi tylne L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 67.

Próg L - Wgniecenie/odkształcenie 1



Photo 68.

Felga Aluminiowa przednia L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 69.

Opona przednia L - Pęknięcie/rozerwanie 1



Photo 70.

Podłokietnik środkowy przedni - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION




Photo 71.

Fotel prz. lew. - Rysa/odprysk 1