

DEKRA's commission No. : PKOL(W)/LODZ/78584/26/08/21  
commission/ damage No. : 24/022138  
Date of commission: 21-08-2026

**DEKRA Poland - Headquarters**  
02-673 Warszawa, ul. Konstruktorska 12A

**Client :**

PKO Leasing SA  
Świętokrzyska 36  
00-116 Warszawa

**Expert:**

**Kacper Sosnowski (WSP)**  
DEKRA Polska - współpraca O/Warszawa  
**mgr inż. Michał Świątek**  
DEKRA Polska - Centrala

**NOTE:**

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

**Vehicle data**

|                              |                                                            |
|------------------------------|------------------------------------------------------------|
| Group of objects (Eurotax)   | cars                                                       |
| EC code (Eurotax)            | 0149304                                                    |
| Manufacturer                 | AUDI                                                       |
| Model                        | A3 Sportback 20-24                                         |
| Type / version               | A3 30 TDI S tronic                                         |
| Body type                    | hatchback                                                  |
| Number of doors / seats      | 5/5                                                        |
| Curb weight [kg]             | 1368                                                       |
| Gross vehicle weight [kg]    | 1920                                                       |
| Wheelbase 1/2                | 2636                                                       |
| Engine type                  | Automatic ignition                                         |
| Supercompression             | turbocompressor with intercooler                           |
| Pollution reduction system   | KSC                                                        |
| Emission standard            | EURO 6                                                     |
| Engine capacity [ccm]        | 1968                                                       |
| Engine Power [hp/kW]         | 116/85                                                     |
| Gearbox                      | automatic 7- gear                                          |
| Registration /record No.     | ST7547W                                                    |
| VIN / serial number          | WAUZZZGY7RA095691                                          |
| Date of first registration   | 29-05-2024                                                 |
| Date of next. tech. test     | 29-05-2027                                                 |
| Year of manufacture          | 2024 (year has been verified with the manufacturer's base) |
| Readout [km]                 | 70 549 (read)                                              |
| Body color / type of coating | silver/double-layered, metallized                          |

Tyres

| axle  | Wheel | Manufacturer, type | Size           | Measured profile |
|-------|-------|--------------------|----------------|------------------|
| Front | right | NEXEN, NBLUE S     | 205/55 R16 91V | 4,0 mm           |
|       | left  | NEXEN, NBLUE S     | 205/55 R16 91V | 3,5 mm           |
| back  | right | NEXEN, NBLUE S     | 205/55 R16 91V | 4,0 mm           |
|       | left  | NEXEN, NBLUE S     | 205/55 R16 91V | 3,5 mm           |

Standard equipment by Eurotax

- |                                                              |                                                                                                |
|--------------------------------------------------------------|------------------------------------------------------------------------------------------------|
| 1. Air conditioning                                          | 26. Interior: other                                                                            |
| 2. Antilock-Brake-System (ABS)                               | 27. Interior: other                                                                            |
| 3. Armrest (s) front                                         | 28. LED front dim light                                                                        |
| 4. Automatic dimlight activation, Rain sensor                | 29. LED rear lights                                                                            |
| 5. Bluetooth interface                                       | 30. Leather steering wheel, Multi functional steering wheel, Steering wheel with gear-switches |
| 6. Bord entertainment: other accessories, Radio preparation  | 31. Light Alloy wheels 16"                                                                     |
| 7. Child lock manually                                       | 32. Lusterka boczne regulowane elektrycznie i ogrzewane                                        |
| 8. Comfort driver seat, Comfort passenger seat               | 33. Mobile Tire System                                                                         |
| 9. Daytime running lights                                    | 34. Oparcie tylne składane                                                                     |
| 10. Driver airbag, Passenger airbag                          | 35. Other                                                                                      |
| 11. ESP (Electronical Stabilizing Program)                   | 36. Other                                                                                      |
| 12. Exterior design: other                                   | 37. Other                                                                                      |
| 13. Exterior design: other                                   | 38. Other                                                                                      |
| 14. Exterior design: other                                   | 39. Park Distance Control rear                                                                 |
| 15. Extra power outlet                                       | 40. Passive Tyre pressure control                                                              |
| 16. Floor mat                                                | 41. Radio MMI plus                                                                             |
| 17. Free service 4 years or more, more than 60000 km         | 42. Rear headrests                                                                             |
| 18. Full Cabin Spoiler                                       | 43. Rear-view mirror autodimming                                                               |
| 19. Hamulce tarczowe z przodu (15")                          | 44. Servotronic                                                                                |
| 20. Hamulec postojowy - elektromechaniczny                   | 45. Speed limiter                                                                              |
| 21. Head airbags front, Head airbags rear, Side airbags rear | 46. Start/Stop system                                                                          |
| 22. Headrests front                                          | 47. Sygnalizacja niezapiętych pasów bezpieczeństwa                                             |
| 23. Heat reflecting windows                                  | 48. Tapicerka tkaninowa Index                                                                  |
| 24. Independent vehicle heater                               | 49. Vehicle immobilizer                                                                        |
| 25. Interior decoration: other                               | 50. i-Size i top tether dla skrajnych tylnych siedzeń                                          |

Dealer's equipment (selected items)

- |                                                                                                                      |   |
|----------------------------------------------------------------------------------------------------------------------|---|
| 1. Accoustic windows .....                                                                                           | - |
| 2. Alarm, Automatic climate control, Cruise control, Keyless go, Lumbar adjust driver, Lumbar adjust passenger ..... | - |
| Fotele przednie ogrzewane                                                                                            |   |
| Fotele przednie z elektryczną regulacją podparcia kręgosłupa                                                         |   |
| Tempomat                                                                                                             |   |
| Klimatyzacja automatyczna, 2-strefowa                                                                                |   |
| Alarm antywłamaniowy, kluczyk komfortowy z funkcją Safelock                                                          |   |
| Tempomat                                                                                                             |   |
| Podparcie odcinka lędźwiowego dla foteli przednich 4-zakresowe                                                       |   |
| Fotele przednie ogrzewane                                                                                            |   |
| 3. Bord communication: other .....                                                                                   | - |
| 4. Lakier metalik .....                                                                                              | - |
| 5. Park Assistant, Park Distance Control front, Park Distance Control rear .....                                     | - |
| 6. Rear view camera .....                                                                                            | - |

**Base value of the vehicle**

Base value of the vehicle by Eurotax (net) ..... -

## **Corrections**

First registration

Mileage

Equipment

Tyres

Other

State of the vehicle .....

Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 08-2026 POL) with regard to technical and market parameters affecting the value of the vehicle.


Basic print without information about the vehicle's value - duey to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 25-08-2026

DEKRA's expert:  
Kacper Sosnowski (WSP)  
mgr inż. Michał Świątek

**Document issued electronically valid without signature.**

## Measurement of thickness of the vehicle lacquer coating



| No. of controlled item | Controlled item     | Measured range of thickness of the lacquer coat [ $\mu\text{m}$ ] |
|------------------------|---------------------|-------------------------------------------------------------------|
| 1                      | Front cover         | to 150                                                            |
| 2                      | Front left fender   | to 150                                                            |
| 3                      | Left front pillar   | to 150                                                            |
| 4                      | Front left door     | to 150                                                            |
| 5                      | Roof                | to 150                                                            |
| 6                      | Left middle pillar  | to 150                                                            |
| 7                      | Right side sill     | to 150                                                            |
| 8                      | Left rear door      | to 150                                                            |
| 9                      | Rear left fender    | to 150                                                            |
| 10                     | Cover/lid           | to 150                                                            |
| 11                     | Right rear fender   | to 150                                                            |
| 12                     | Right rear door     | to 150                                                            |
| 13                     | Right middle pillar | to 150                                                            |
| 14                     | Right side sill     | to 150                                                            |
| 15                     | Front right door    | to 150                                                            |
| 16                     | Right front pillar  | to 150                                                            |
| 17                     | Front right fender  | to 150                                                            |

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

During the inspection the registration proof of the vehicle was presented and its photo was taken and enclosed to the expertise.

During the inspection the service book of the vehicle was not provided.

**Information concerning the origin of the vehicle**

The vehicle purchased domestically from an authorized representative of the brand.

**Anti-theft protection - immobilizer**

- as a result of the inspection of the vehicle found no malfunctions of the immobilizer in the extent possible to determine during the inspection of the vehicle in the non- workshop conditions.

**Anti-theft protection - other:**

not found

**Additional comments on the car:**

Not applicable.

**Test drive**

Test drive of the vehicle was conducted. Test drive in the full extent is not possible. Comment below:

.

**Checking of the correctness and / or construction of identification / serial numbers of the object:**

Not tested

**Verification of the accuracy of the object data, including year of production, and other.**

Not conducted - adopted according to the documents presented and indicated sources.

- The read odometer status has not been verified with records in electronic equipment of the vehicle.

- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.

- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.

- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.

- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.

- The evaluation has been carried out basing on delivered documentation and organoleptic examination of the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the

page 5/40

assessed object.

- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

---

Comments to the commission - regarding valuation

**Kluczyki**

TAK

2

---

Expert comments - regarding valuation

Widoczne ślady użytkowania pojazdu: drobne rysy, odpryski, wgniecenia, zaplamienia.  
Nie działa jeden pilot zamka centralnego.

Restrictive disclaimer - regarding valuation

- W Ocenie/Raporcie uwzględniono niesprawności, uszkodzenia, braki itp., które były możliwe do stwierdzenia organoleptycznego, w warunkach oględzin (z uwzględnieniem: stanu czystości pojazdu, warunków atmosferycznych, oświetlenia itd.) oraz bez weryfikacji serwisowej, bez dostępu do spodu pojazdu, bez specjalistycznego sprzętu diagnostycznego (w tym bez diagnostyki komputerowej), bez jazdy próbnej wykonanej w warunkach drogowych z obciążeniem.
- W ramach Oceny/Raportu nie weryfikowano odczytanego stanu drogomierza z zapisami w urządzeniach elektronicznych pojazdu.
- Rzeczoznawca nie bierze na siebie odpowiedzialności za wady ukryte (prawne i fizyczne) oraz ewentualne skutki wynikające z dalszego użytkowania przedmiotu oceny, a także za skutki wykorzystania samej oceny.
- Podane przedziały grubości powłoki lakierowej, dotyczą punktów pomiarowych. Nie mogą być traktowane jako gwarancja, że grubość powłoki lakierowej w innych punktach nie wykracza poza te przedziały.
- Zawarte w niniejszej Ocenie/Raporcie informacje (w tym dotyczące wyposażenia) służą jedynie ogólnym celom informacyjnym. Ocena/Raport nie może być zatem traktowana jako oferta w rozumieniu przepisów Kodeksu Cywilnego oraz opisu towaru ani zapewnienia w rozumieniu art. 4 Ustawy z dnia 27 lipca 2002 roku o szczególnych warunkach sprzedaży konsumenckiej.
- Niniejsza Ocena/Raport nie jest szczegółową oceną stanu technicznego.

Ocenę/Raport wykonano w kierunku ujawnienia uszkodzeń nieakceptowanych z punktu widzenia właściwego przewodnika zwrotu pojazdu lub innych ustaleń ze Zleceniodawcą. Tym samym Ocena/Raport może nie ujmować typowych zużyć i uszkodzeń eksploatacyjnych.

PHOTOGRAPHIC DOCUMENTATION



**Photo 1.**  
Przekątna przednia lewa



**Photo 2.**  
Przód

PHOTOGRAPHIC DOCUMENTATION



**Photo 3.**

Przekątna przednia prawa



**Photo 4.**

Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



**Photo 5.**  
Bok prawy z tyłu



**Photo 6.**  
Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



**Photo 7.**

Tył



**Photo 8.**

Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



**Photo 9.**

Bok lewy z tyłu



**Photo 10.**

Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



**Photo 11.**

Próg lewy (widok od przodu)



**Photo 12.**

Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION




**Photo 13.**  
Spód pojazdu przód



**Photo 14.**  
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION



**Photo 15.**

Tarcza hamulcowa przednia prawa



**Photo 16.**


Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION



**Photo 17.**

Tarcza hamulcowa tylna lewa



**Photo 18.**

Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



**Photo 19.**  
Bagażnik



**Photo 20.**  
Komora silnika

PHOTOGRAPHIC DOCUMENTATION



**Photo 21.**

Numer identyfikacyjny



**Photo 22.**

Tabliczka znamionowa

PHOTOGRAPHIC DOCUMENTATION



**Photo 23.**

Zestaw wskaźników - przebieg



**Photo 24.**

Zestaw wskaźników - serwis

PHOTOGRAPHIC DOCUMENTATION



**Photo 25.**

Widok przez otwarte drzwi przednie lewe



**Photo 26.**

Kierownica z lewej strony

PHOTOGRAPHIC DOCUMENTATION



**Photo 27.**

Widok przez otwarte drzwi tylne lewe



**Photo 28.**


Widok z tylnej kanapy na deskę rozd.

PHOTOGRAPHIC DOCUMENTATION



**Photo 29.**

Konsola środkowa



**Photo 30.**

Tunel środkowy

## PHOTOGRAPHIC DOCUMENTATION




**Photo 31.**  
Kierownica (na wprost)



**Photo 32.**  
Dowód rej. Str. 1

PHOTOGRAPHIC DOCUMENTATION**Photo 33.**

Dow. Rej. Str. 2

**Photo 34.**

Książka serwisowa – dane

PHOTOGRAPHIC DOCUMENTATION



**Photo 35.**

Książka serwisowa – ostatni przegląd



**Photo 36.**


Zestaw naprawczy koła

PHOTOGRAPHIC DOCUMENTATION



**Photo 37.**

Kluczyki



**Photo 38.**

Zaślepka ISFOIX - brak

PHOTOGRAPHIC DOCUMENTATION



**Photo 39.**

Pokrywa komory silnika - Rysa/odprysk 1



**Photo 40.**

Pokrywa komory silnika - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 41.**

Zderzak - Rysa/odprysk 1



**Photo 42.**

Felga aluminiowa przednia P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 43.**

Drzwi przednie P - Rysa/odprysk 1



**Photo 44.**

Drzwi tylne P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 45.**

Lusterko zew P - Rysa/odprysk 1



**Photo 46.**

Łotnik tylny P / Ściana boczna P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 47.**

Felga aluminiowa tylna P - Rysa/odprysk 1



**Photo 48.**

Lampa tylna zew P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 49.**

Pokrywy bagażnika - Wgniecenie/odkształcenie 1



**Photo 50.**

Zaślepka tyl haka hol. - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 51.**

Zderzak tylny - Rysa/odprysk 1



**Photo 52.**

Zderzak tylny - Rysa/odprysk 2

PHOTOGRAPHIC DOCUMENTATION



**Photo 53.**

Zderzak tylny() - Rysa/odprysk 3



**Photo 54.**


Błotnik tylny L / Ściana boczna L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 55.**

Błotnik tylny L / Ściana boczna L - Wgniecenie/odkształcenie 2



**Photo 56.**

Drzwi przed L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 57.**

Drzwi przed L - Rysa/odprysk 2



**Photo 58.**

Drzwi tylne L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 59.**

Drzwi tylne L - Wgniecenie/odkształcenie 1



**Photo 60.**

Próg L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 61.**

Błotnik przedni L - zdjęcie poglądowe 1



**Photo 62.**

Błotnik przedni L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 63.**

Felga Aluminiowa przednia L - Rysa/odprysk 1



**Photo 64.**

Podłokietnik środkowy przedni - Inne 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 65.**

Fotel prz. lew. - Inne 1



**Photo 66.**

Fotel prz. praw. - Inne 1

PHOTOGRAPHIC DOCUMENTATION



**Photo 67.**

Kanapa tyl. - Inne 1