

DEKRA's commission No. : PKOL(W)/LODZ/96020/26/10/14
commission/ damage No. : 23/032240
Date of commission: 14-10-2026

DEKRA Poland - Headquarters
02-673 Warszawa, ul. Konstruktorska 12A

Client :

PKO Leasing SA
Świętokrzyska 36
00-116 Warszawa

Expert:

Kacper Sosnowski (WSP)
DEKRA Polska - współpraca O/Warszawa
inż. Józef Orłowski
TU - Włocławek

NOTE:

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

Vehicle data

Group of objects (Eurotax)	cars
EC code (Eurotax)	0154598
Manufacturer	AUDI
Model	R8 19-24
Type / version	R8 V10 RWD Performance
Body type	CPE
Number of doors / seats	2/2
Curb weight [kg]	1618
Gross vehicle weight [kg]	1960
Wheelbase 1/2	2650
Engine type	spark ignition
Pollution reduction system	three-way catalytic converter
Engine capacity [ccm]	5204
Engine Power [hp/kW]	570/419
Gearbox	automatic 7- gear
Registration /record No.	CB220PU
VIN / serial number	WUAZZZFX8P7900882
Date of first registration	08-09-2023
Year of manufacture	2023
Readout [km]	8 713 (read)
Body color / type of coating	red/METALIK

Tyres

axle	Wheel	Manufacturer, type	Size	Measured profile
Front	right	MICHELIN, PILOT SPORT 4S	245/30 20 90Y	5,5 mm
	left	MICHELIN, PILOT SPORT 4S	245/30 20 90Y	5,5 mm
back	right	MICHELIN, PILOT SPORT 4S	305/30 20 103Y	5,0 mm
	left	MICHELIN, PILOT SPORT 4S	305/30 20 103Y	5,0 mm

Standard equipment by Eurotax

- | | |
|--|--|
| 1. Additional gauges, On board computer | 34. Keyless Engine start, Keyless go |
| 2. Alarm | 35. LED Daytime running lights |
| 3. Antilock-Brake-System (ABS) | 36. LED front dim light |
| 4. Automatic climate control | 37. LED rear lights |
| 5. Automatic dimlight activation, Rain sensor, Rear-view mirror autodimming | 38. LED rear lights |
| 6. Automatic limited slip differential | 39. Leather steering wheel, Multi functional steering wheel, Sports steering wheel |
| 7. Bluetooth interface | 40. Leather upholstery |
| 8. Bluetooth interface, CD-player, Driver-information-system, mp3 Player, Radio, USB in | 41. Light Alloy wheels 19" |
| 9. Child seat fixation | 42. Mobile Tire System |
| 10. Colour stripe in windscreen, Windows: other | 43. Other |
| 11. DAB radio | 44. Other |
| 12. Daytime running lights | 45. Other |
| 13. Door lights, Exterior lighting: other, Floor lighting, Interior lights: other accessories, Other | 46. Other |
| 14. Door mirrors autodimming, Door mirrors electrically foldable, Door mirrors heated | 47. Other |
| 15. Door mirrors autodimming, Door mirrors electrically foldable, Door mirrors heated | 48. Park Distance Control front, Park Distance Control rear |
| 16. Driver airbag, Passenger airbag | 49. Podnózek i nakładki na pedały ze stali szlachetnej |
| 17. Driver airbag, Passenger airbag, Side airbag driver, Side airbag driver and passenger | 50. Power windows front |
| 18. Driver seat electrically adjustable, Passenger seat electrically adjustable | 51. Rear spoiler |
| 19. ESP (Electronical Stabilizing Program) | 52. Remote controlled central locking |
| 20. Exterior design: other | 53. Rozszerzony zestaw elementów wnętrza w kolorze czarnym |
| 21. Exterior design: other | 54. Selectable driveline characteristics |
| 22. Exterior design: other | 55. Servotronic |
| 23. Exterior design: other | 56. Soundsystem |
| 24. Exterior design: other | 57. Sport seats front |
| 25. Hamulce tarczowe perforowane i wentylowane z przodu (hamulce 8-tłoczkowe) | 58. Sport suspension |
| 26. Hamulce tarczowe perforowane i wentylowane z tyłu (hamulce 4-tłoczkowe) | 59. Start/Stop system |
| 27. Headlamp wash | 60. Third braking light |
| 28. Heated seat driver, Heated seat passenger | 61. Towbar preparation |
| 29. Hill holder | 62. Traction control |
| 30. Interior decoration: other | 63. Tyre pressure control (RDC) |
| 31. Interior: other | 64. USB in |
| 32. Interior: other | 65. Uni-Lackierung |
| 33. Interior: other | 66. Wheel bolt locks |

Dealer's equipment (selected items)

- | | | |
|---|-------|---|
| 1. Bord communication: other, Navigation system | | - |
| 2. Exterior design: other | | - |
| 3. Exterior design: other | | - |
| 4. Exterior design: other | | - |
| 5. Light Alloy wheels 20" | | - |
| 6. Metallic paint | | - |
| 7. Other | | - |
| 8. Other | | - |

9. Other -
10. Park Distance Control rear, Rear view camera -
11. Soundsystem -

Base value of the vehicle

Base value of the vehicle by Eurotax (net) -

Corrections

First registration

Mileage

Equipment

Tyres

Other

Earlier repairs -
stwierdzone braki i uszkodzenia -
brak badania technicznego -


Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 10-2026 POL) with regard to technical and market parameters affecting the value of the vehicle.

Basic print without information about the vehicle's value - due to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 22-10-2026

DEKRA's expert:
Kacper Sosnowski (WSP)
inż. Józef Orłowski

Document issued electronically valid without signature.

Measurement of thickness of the vehicle lacquer coating


No. of controlled item	Controlled item	Measured range of thickness of the lacquer coat [μm]
1	Front cover	150 - 500
3	Left front pillar	150 - 200
4	Front left door	150 - 1000
5	Roof	150 - 200
7	Right side sill	to 150
9	Rear left fender	150 - 500
10	Cover/lid	to 150
11	Right rear fender	150 - 500
14	Right side sill	to 150
15	Front right door	to 150
16	Right front pillar	150 - 200

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

Presented the following documents of the vehicle:

skan PC

During the inspection the service book was presented and its number is given below:
elektroniczna

Information concerning the origin of the vehicle

The vehicle purchased domestically from an authorized representative of the brand.

Anti-theft protection - immobilizer

- as a result of the inspection of the vehicle found no malfunctions of the immobilizer in the extent possible to determine during the inspection of the vehicle in the non- workshop conditions.

Anti-theft protection - other:

alarm

Additional comments on the car:

Not applicable.

Test drive

Test drive of the vehicle was conducted. Test drive in the full extent is not possible. Comment below:
ograniczenia parkingowe

Checking of the correctness and / or construction of identification / serial numbers of the object:

Not tested

Verification of the accuracy of the object data, including year of production, and other.

Not conducted - adopted according to the documents presented and indicated sources.

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.
- The evaluation has been carried out basing on delivered documentation and organoleptic examination of

the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the assessed object.

- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

Comments to the commission - regarding valuation

Kluczyki

TAK

1

Expert comments - regarding valuation

Aktywna kontrolka ciśnienia w kołach. Przekroczona wymiana oleju od 106 dni. Dostarczono ksero pozwolenia czasowego. Widoczne wady lakiernicze. Lewy reflektor jaśniejszy od prawego. Odpryski na szybie czołowej.

PHOTOGRAPHIC DOCUMENTATION



Photo 1.
Przekątna przednia lewa



Photo 2.
Przód

PHOTOGRAPHIC DOCUMENTATION



Photo 3.

Przekątna przednia prawa



Photo 4.

Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 5.
Bok prawy z tyłu



Photo 6.
Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 7.

Tył



Photo 8.

Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 9.

Bok lewy z tyłu



Photo 10.

Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 11.
Próg lewy (widok od przodu)




Photo 12.
Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



Photo 13.
Spód pojazdu przód



Photo 14.
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION



Photo 15.

Tarcza hamulcowa przednia prawa



Photo 16.

Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 17.

Tarcza hamulcowa tylna lewa



Photo 18.

Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 19.
Bagażnik



Photo 20.
Komora silnika

PHOTOGRAPHIC DOCUMENTATION



Photo 21.
Numer identyfikacyjny



Photo 22.
Tabliczka znamionowa

PHOTOGRAPHIC DOCUMENTATION



Photo 23.

Zestaw wskaźników - przebieg



Photo 24.

Zestaw wskaźników - serwis

PHOTOGRAPHIC DOCUMENTATION



Photo 25.

Widok przez otwarte drzwi przednie lewe



Photo 26.

Kierownica z lewej strony

PHOTOGRAPHIC DOCUMENTATION




Photo 27.

Widok przez otwarte drzwi tylne lewe



Photo 28.

Widok z tylnej kanapy na deskę rozd.

PHOTOGRAPHIC DOCUMENTATION



Photo 29.
Konsola środkowa



Photo 30.
Tunel środkowy

PHOTOGRAPHIC DOCUMENTATION




Photo 31.
Kierownica (na wprost)




Photo 32.
Książka serwisowa – dane

PHOTOGRAPHIC DOCUMENTATION**Photo 33.**

Książka serwisowa – ostatni przegląd

**Photo 34.**

Dow. rej. ksero Str. 1

PHOTOGRAPHIC DOCUMENTATION**Photo 35.**

Dow. Rej. ksero Str. 2

**Photo 36.**

Zestaw naprawczy koła

PHOTOGRAPHIC DOCUMENTATION



Photo 37.

Kluczyki



Photo 38.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 39.

Zdjęcie do protokołu



Photo 40.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 41.

Zdjęcie do protokołu



Photo 42.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION




Photo 43.

Zdjęcie do protokołu



Photo 44.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 45.
Zdjęcie do protokołu




Photo 46.
Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 47.

Zdjęcie do protokołu



Photo 48.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 49.

Zdjęcie do protokołu



Photo 50.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 51.

Zdjęcie do protokołu



Photo 52.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 53.

Zdjęcie do protokołu




Photo 54.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 55.

Zdjęcie do protokołu



Photo 56.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 57.

Zdjęcie do protokołu



Photo 58.

Pokrywa komory silnika - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 59.

Szyba czołowa - zdjęcie poglądowe 1



Photo 60.

Szyba czołowa - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 61.

Zderzak - Rysa/odprysk 1



Photo 62.

Drzwi przednie P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 63.

Śłupek przedni P - Wgniecenie/odkształcenie 1



Photo 64.

Światnik tylny P / Ściana boczna P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 65.

Felga aluminiowa tylna P - Rysa/odprysk 1



Photo 66.

Lampa zespolona tylna P - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 67.

Zderzak tylny - Rysa/odprysk 1



Photo 68.

Zderzak tylny - Rysa/odprysk 2

PHOTOGRAPHIC DOCUMENTATION



Photo 69.

Zderzak tylny cz P - Rysa/odprysk 1



Photo 70.

Lampa zespolona tylna L - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 71.

Opona tylna L - Pęknięcie/rozerwanie 1



Photo 72.

Drzwi przed L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 73.

Słupek przedni L - Wgniecenie/odkształcenie 1



Photo 74.

Słupek środkowy L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 75.

Opona przednia L - Pęknięcie/rozerwanie 1



Photo 76.

Fotel prz. lew. - zdjęcie poglądowe 1

PHOTOGRAPHIC DOCUMENTATION



Photo 77.

Fotel prz. lew. - Inne 1



Photo 78.

Fotel prz. praw. - zdjęcie poglądowe 1

PHOTOGRAPHIC DOCUMENTATION



Photo 79.

Fotel prz. praw. - Inne 1



Photo 80.

Uszczelka drzwi przednich L - zdjęcie poglądowe 1

PHOTOGRAPHIC DOCUMENTATION



Photo 81.

Uszczelka drzwi przednich L - Pęknięcie/rozerwanie 1



Photo 82.

Osłona p/słoneczna prawa - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 83.

Pedały - Inne 1