

DEKRA's commission No. : PKOL(W)/LODZ/19180/25/03/17
commission/ damage No. : Futura
Date of commission: 17-03-2025

DEKRA Poland - Headquarters
02-673 Warszawa, ul. Konstruktorska 12A

Client :

PKO Leasing SA
Świętokrzyska 36
00-116 Warszawa

Expert:

Kacper Sosnowski (NEW)
DEKRA Polska - współpraca O/Warszawa
Andrzej Sosnowski
DEKRA Polska - Centrala

NOTE:

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

Vehicle data

Group of objects (Eurotax)	cars
EC code (Eurotax)	0116295
Manufacturer	BMW
Model	Seria 3 Touring [F31] 15-19
Type / version	320d xDrive Sport Line aut
Body type	KOM
Number of doors / seats	5/5
Curb weight [kg]	1650
Gross vehicle weight [kg]	2225
Wheelbase 1/2	2810
Engine type	Automatic ignition
Pollution reduction system	DPF
Engine capacity [ccm]	1995
Engine Power [hp/kW]	190/140
Gearbox	automatic 8- gear
Registration /record No.	WD1520P
VIN / serial number	WBA8J11050A969207
Date of first registration	13-02-2019
Date of next. tech. test	13-01-2026
Year of manufacture	2019 (year has been verified with the manufacturer's base)
Readout [km]	117 215 (read)
Body color / type of coating	white/double-layered, metallized

Tyres

axle	Wheel	Manufacturer, type	Size	Measured profile
Front	right	FULDA, KRISTALL CONTROL HP2	225/50 17 94H	5,0 mm
	left	FULDA, KRISTALL CONTROL HP2	225/50 17 94H	5,0 mm
back	right	FULDA, KRISTALL CONTROL HP2	225/50 17 94H	5,0 mm
	left	FULDA, KRISTALL CONTROL HP2	225/50 17 94H	5,0 mm

Standard equipment by Eurotax

- | | |
|---|--|
| 1. Additional gauges | 28. Interior lights: other accessories |
| 2. Airbag: other | 29. LED Fog Lamps |
| 3. Alarm | 30. LED front dim light |
| 4. Armrest (s) front | 31. LED rear lights |
| 5. Armrest (s) rear | 32. Leather steering wheel, Sports steering wheel |
| 6. Automatic dimlight activation, Rain sensor | 33. Light alloy wheels from 17" |
| 7. Bluetooth interface, Hands-free system, USB in | 34. Limited slip differential in general |
| 8. Bord entertainment: other accessories | 35. Multi functional steering wheel |
| 9. Central locking | 36. On board computer |
| 10. Child seat fixation | 37. Other |
| 11. Colored glass | 38. Other |
| 12. Cruise control | 39. Park Distance Control rear |
| 13. Driver airbag, Head airbags front, Passenger airbag, Side airbag driver and passenger | 40. Power steering |
| 14. Dualzone automatic climate control | 41. Radio |
| 15. ESP (Electronical Stabilizing Program), Traction control | 42. Rear headrests |
| 16. Electric tailgate | 43. Rear seat-backs foldable in two separate parts |
| 17. Exterior design: other | 44. Selectable driveline characteristics |
| 18. Exterior design: other | 45. Servotronic |
| 19. Exterior design: other | 46. Sport seats front |
| 20. Exterior design: other | 47. Start/Stop system |
| 21. Exterior lighting: other | 48. Steering wheel manually adjustable |
| 22. Extra power outlet | 49. Storage facilities in general |
| 23. Floor mat | 50. Telematic |
| 24. Follow me home | 51. Textile upholstery |
| 25. Follow me home | 52. Uni-Lackierung |
| 26. Free service 4 years or more, more than 60000 km | 53. Vehicle immobilizer |
| 27. Interior lights: other accessories | 54. Wheel bolt locks |

Dealer's equipment (selected items)

- | | |
|--|---|
| 1. CD-player | - |
| 2. Interior lights: other accessories | - |
| 3. LED front dim light | - |
| 4. Metallic paint | - |
| 5. Park Distance Control front, Park Distance Control rear | - |
| 6. Rear-view mirror autodimming | - |
| 7. Roof railing | - |
| 8. Wood finish | - |

Base value of the vehicle

Base value of the vehicle by Eurotax (net) -

CorrectionsFirst registration

Equipment

Tyres

Other

Earlier repairs -
Uszkodzenia, stan -


Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 03-2025 POL) with regard to technical and market parameters affecting the value of the vehicle.

Basic print without information about the vehicle's value - duey to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 24-03-2025

DEKRA's expert:
Kacper Sosnowski (NEW)
Andrzej Sosnowski

Document issued electronically valid without signature.

Measurement of thickness of the vehicle lacquer coating


No. of controlled item	Controlled item	Measured range of thickness of the lacquer coat [μm]
1	Front cover	to 150
2	Front left fender	150 - 300
3	Left front pillar	to 150
4	Front left door	150 - 200
5	Roof	to 150
6	Left middle pillar	to 150
7	Right side sill	to 150
8	Left rear door	to 150
9	Rear left fender	to 150
10	Cover/lid	to 150
11	Right rear fender	to 150
12	Right rear door	to 150
13	Right middle pillar	to 150
14	Right side sill	to 150
15	Front right door	to 150
16	Right front pillar	to 150
17	Front right fender	to 150

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

During the inspection the registration proof of the vehicle was presented and its photo was taken and enclosed to the expertise.

During the inspection the service book was presented and its number is given below:
elektroniczna

Information concerning the origin of the vehicle

Lack of reliable data.

Anti-theft protection - immobilizer

- as a result of the inspection of the vehicle found no malfunctions of the immobilizer in the extent possible to determine during the inspection of the vehicle in the non- workshop conditions.

Anti-theft protection - other:

not found

Additional comments on the car:

Not applicable.

Test drive

Test drive of the vehicle was conducted. Test drive in the full extent is not possible. Comment below:
ograniczenia placowe

Checking of the correctness and / or construction of identification / serial numbers of the object:

Not tested

Verification of the accuracy of the object data, including year of production, and other.

Not conducted - adopted according to the documents presented and indicated sources.

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.
- The evaluation has been carried out basing on delivered documentation and organoleptic examination of

page 5/40

the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the assessed object.

- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

Comments to the commission - regarding valuation

Kluczyki

TAK

2

Expert comments - regarding valuation

Rysy na samochodzie. Aktywna kontrolka ciśnienia w kołach. Odpryski na szybie czołowej.

Rzeczoznawca dokonał oględzin pojazdu w warunkach parkingowych, co mogło ograniczyć pełną ocenę jego stanu technicznego. Dodatkowo, jeżeli jazda próbna została przeprowadzona (informacje w treści raportu), to wykonano ją w warunkach parkingowych, z niewielką prędkością, co może nie odzwierciedlać pełnych warunków eksploatacyjnych. Istnieje możliwość, że w innych okolicznościach ujawnią się dodatkowe uszkodzenia lub usterki, których nie można było wykryć podczas obecnych oględzin. Zalecamy zatem skorzystanie z możliwości oględzin pojazdu we własnym zakresie lub w Autoryzowanej Stacji Obsługi danej marki, co pozwoli na pełniejszą weryfikację stanu technicznego pojazdu przed udziałem w aukcji."

Restrictive disclaimer - regarding valuation

Nie weryfikowano szczegółowo stanu układu napędowego, zawieszenia, kierowniczego, hamulcowego oraz wydechowego. Ocena została wykonana bez użycia podnośnika i specjalistycznego sprzętu diagnostycznego, nie dokonywano demontażu osłon i innych elementów. Ocena określa ogólny stan pojazdu na dzień oględzin w miejscu jego udostępnienia, nie może być zatem traktowana jako kompleksowa ocena stanu technicznego. Specyfikacja wg. programu operacyjnego w zakresie wyposażenia standardowego i dodatkowego nie gwarantuje zgodności ze stanem faktycznym w zakresie możliwym do ustalenia przez rzeczoznawcę podczas oględzin pojazdu.

Pomiar grubości powłoki lakierowej wykonano w miejscach możliwych do ich wykonania pomiary nie gwarantują oryginalności poszczególnych elementów poddanych ocenie.

- W Ocenie/Raporcie uwzględniono niesprawności, uszkodzenia, braki itp., które były możliwe do stwierdzenia organoleptycznego, w warunkach oględzin (z uwzględnieniem: stanu czystości pojazdu, warunków atmosferycznych, oświetlenia itd.) oraz bez weryfikacji serwisowej, bez dostępu do spodu pojazdu, bez specjalistycznego sprzętu diagnostycznego (w tym bez diagnostyki komputerowej), bez jazdy próbnej wykonanej w warunkach drogowych z obciążeniem.
- W ramach Oceny/Raportu nie weryfikowano odczytanego stanu drogomierza z zapisami w urządzeniach elektronicznych pojazdu.
- Rzeczoznawca nie bierze na siebie odpowiedzialności za wady ukryte (prawne i fizyczne) oraz ewentualne skutki wynikające z dalszego użytkowania przedmiotu oceny, a także za skutki wykorzystania samej oceny.
- Podane przedziały grubości powłoki lakierowej, dotyczą punktów pomiarowych. Nie mogą być traktowane jako gwarancja, że grubość powłoki lakierowej w innych punktach nie wykracza poza te przedziały.

- Zawarte w niniejszej Ocenie/Raporcie informacje (w tym dotyczące wyposażenia) służą jedynie ogólnym celom informacyjnym. Ocena/Raport nie może być zatem traktowana jako oferta w rozumieniu przepisów Kodeksu Cywilnego oraz opisu towaru ani zapewnienia w rozumieniu art. 4 Ustawy z dnia 27 lipca 2002 roku o szczególnych warunkach sprzedaży konsumenckiej.
- Niniejsza Ocena/Raport nie jest szczegółową oceną stanu technicznego.

Ocenę/Raport wykonano w kierunku ujawnienia uszkodzeń nieakceptowanych z punktu widzenia właściwego przewodnika zwrotu pojazdu lub innych ustaleń ze Zleceniodawcą. Tym samym Ocena/Raport może nie ujmować typowych zużyć i uszkodzeń eksploatacyjnych.

PHOTOGRAPHIC DOCUMENTATION



Photo 1.

Przekątna przednia lewa



Photo 2.

Przód

PHOTOGRAPHIC DOCUMENTATION



Photo 3.

Przekątna przednia prawa



Photo 4.

Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 5.
Bok prawy z tyłu



Photo 6.
Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 7.

Tył



Photo 8.

Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 9.

Bok lewy z tyłu



Photo 10.

Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 11.
Próg lewy (widok od przodu)



Photo 12.
Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



Photo 13.
Spód pojazdu przód



Photo 14.
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION



Photo 15.

Tarcza hamulcowa przednia prawa



Photo 16.

Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 17.

Tarcza hamulcowa tylna lewa



Photo 18.

Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 19.
Bagażnik



Photo 20.
Koło zapasowe

PHOTOGRAPHIC DOCUMENTATION



Photo 21.
Komora silnika




Photo 22.
Numer identyfikacyjny

PHOTOGRAPHIC DOCUMENTATION



Photo 23.

Tabliczka znamionowa



Photo 24.

Zestaw wskaźników - przebieg

PHOTOGRAPHIC DOCUMENTATION



Photo 25.

Widok przez otwarte drzwi przednie lewe



Photo 26.

Kierownica z lewej strony

PHOTOGRAPHIC DOCUMENTATION



Photo 27.

Widok przez otwarte drzwi tylne lewe



Photo 28.

Widok z tylnej kanapy na deskę rozd.

PHOTOGRAPHIC DOCUMENTATION



Photo 29.

Konsola środkowa



Photo 30.

Tunel środkowy

A photograph of the interior of a BMW 1 Series car. The view is from the driver's perspective, looking towards the dashboard. The steering wheel is black with red stitching and features the BMW logo in the center. Behind the steering wheel is the instrument cluster, which includes a speedometer, a tachometer, and several smaller gauges. To the right of the steering wheel is the infotainment screen, which displays a navigation map and other information. The dashboard and center console are black with silver accents. The overall appearance is clean and well-maintained.

RODZAJ POJAZDU		C.1.1 FUTURA LEASING SPÓŁKA AKCYJNA	
SAMOCHÓD OSOBOWY		C.1.2 190917030	
PRZEDSIĘWZIENIE		C.1.3 01-882 WARSZAWA	
---		STEFANA ŻEROMSKIEGO 77	
JAKI PRODUKT		C.2.1 FUTURA LEASING SPÓŁKA AKCYJNA	
2019		C.2.2 190917030	
OŚCIEŻCZANIE		C.2.3 01-882 WARSZAWA	
---		STEFANA ŻEROMSKIEGO 77	
JAKI WIEŚDZ DOP. NADTAKOŚĆ		C	
12,74 kN		F1 2225 kg F2 2225 kg F3 4025 kg	
WARSZAWA		G 1650 kg J M1	
---		K e1*2007/46*0315*22	
QR		L 2 O1 1800 kg O2 750 kg	
---		P1 1995,00 cm ³ P2 140,00 kW	
---		P3 0 Q ---	
---		S.1 5 S.2 ---	
SERIA DR/BAU 2451012		SERIA DR/BAU 2451012	

WSPÓLNOTA EUROPEJSKA RZECZPOSPOLITA POLSKA Dowód Rejestracyjny	
PREZYDENT M.ST. WARSZAWY DZIELNICA TARGÓWEK UL. KONDRATOWICZA 20 00-983 WARSZAWA	
ORGAN WYDAWCY	
A	WD 1520P
D.1 BMW D.2 3K -8311 -6AM50000	
D	D.3 3200 XDRIVE
E	WBA8J11050A969207
B 13.02.2019 28.05.2024 H	---
SERIA DR/BAU 2451012	

DEKRA Polska Sp. z o.o.
02-673 Warszawa, ul. Konstruktorska 12A
www.dekra.pl

PHOTOGRAPHIC DOCUMENTATION



Photo 33.

Dow. Rej. Str.2 i klucze



Photo 34.

Książka serwisowa – dane

PHOTOGRAPHIC DOCUMENTATION



Photo 35.

Książka serwisowa – ostatni przegląd



Photo 36.

Instrukcje

PHOTOGRAPHIC DOCUMENTATION



Photo 37.

Zdjęcie do protokołu



Photo 38.

Pokrywa komory silnika - zdjęcie poglądowe 1

PHOTOGRAPHIC DOCUMENTATION



Photo 39.

Pokrywa komory silnika - Inne 1




Photo 40.

Szyba czołowa - zdjęcie poglądowe 1

PHOTOGRAPHIC DOCUMENTATION




Photo 41.

Szyba czołowa - Pęknięcie/rozerwanie 1



Photo 42.

Felga aluminiowa przednia P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION




Photo 43.

Drzwi przednie P - Rysa/odprysk 1



Photo 44.

Drzwi tylne P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 45.

Drzwi tylne P - Wgniecenie/odkształcenie 1



Photo 46.

Próg P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 47.

Próg P - Wgniecenie/odkształcenie 1



Photo 48.

Łotnik tylny P / Ściana boczna P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION




Photo 49.

Felga aluminiowa tylna P - Rysa/odprysk 1



Photo 50.

Pokrywy bagażnika - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 51.

Zderzak tylny - Rysa/odprysk 1



Photo 52.

Zderzak tylny - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 53.

Zderzak tylny - Inne 1




Photo 54.

Błotnik tylny L / Ściana boczna L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 55.

Błotnik tylny L / Ściana boczna L - Wgniecenie/odkształcenie 2



Photo 56.

Felga aluminiowa tylna L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 57.

Drzwi przed L - Rysa/odprysk 1



Photo 58.

Drzwi przed L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 59.

Drzwi tylne L - Rysa/odprysk 1



Photo 60.

Felga Aluminiowa przednia L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 61.

Deska rozdzielcza - Rysa/odprysk 1



Photo 62.

Konsola tunelu śr. - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 63.

Fotel prz. lew. - Rysa/odprysk 1



Photo 64.

Fotel prz. lew. - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 65.

Uszczelka drzwi przednich L - Inne 1