

DEKRA's commission No. : PKOL(W)/LODZ/67053/26/07/20
commission/ damage No. : 23/001673
Date of commission: 20-07-2026

DEKRA Poland - Headquarters
02-673 Warszawa, ul. Konstruktorska 12A

Client :

PKO Leasing SA
Świętokrzyska 36
00-116 Warszawa

Expert:

Kacper Sosnowski (WSP)
DEKRA Polska - współpraca O/Warszawa
inż. Józef Orłowski
TU - Włocławek

NOTE:

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

Vehicle data

Group of objects (Eurotax)	jeeps
EC code (Eurotax)	0138279
Manufacturer	MERCEDES-BENZ
Model	GLS [167] 19-23
Type / version	GLS 400 d 4-Matic
Body type	KOM
Number of doors / seats	5/7
Curb weight [kg]	2675
Gross vehicle weight [kg]	3250
Wheelbase 1/2	3135
Engine type	Automatic ignition
Pollution reduction system	KSC
Engine capacity [ccm]	2925
Engine Power [hp/kW]	330/243
Gearbox	automatic 9- gear
Registration /record No.	SB580EY
VIN / serial number	W1N1679231A232798
Date of first registration	05-08-2020
Date of next. tech. test	05-08-2025
Year of manufacture	2020 (year has been verified with the manufacturer's base)
Readout [km]	86 359 (read)
Body color / type of coating	white/METALIK

Tyres

axle	Wheel	Manufacturer, type	Size	Measured profile
Front	right	MICHELIN, PILOT SPORT 4S	285/40 23 111Y	4,0 mm
	left	MICHELIN, PILOT SPORT 4S	285/40 23 111Y	4,0 mm
back	right	MICHELIN, PILOT SPORT 4S	325/35 23 115Y	3,5 mm
	left	MICHELIN, PILOT SPORT 4S	325/35 23 115Y	3,5 mm

Standard equipment by Eurotax

- | | |
|---|--|
| 1. 2 single seats rear | 31. Keyless go |
| 2. Active body control, Hydro pneumatic suspension | 32. LED front dim light |
| 3. Adjustable suspension | 33. Lane control assistant |
| 4. Alarm | 34. Leather steering wheel, Multi functional steering wheel, Sports steering wheel |
| 5. Alarm | 35. Leather upholstery |
| 6. Automated High-beam assist | 36. Light Allow wheels over 21" |
| 7. Automatic antenna/ window-antenna | 37. Luggage compartment cover |
| 8. Automatic climate control | 38. Lumbar adjust driver |
| 9. Bluetooth interface | 39. Mirror: others |
| 10. Bord communication: other | 40. Mobile Tire System |
| 11. Bord communication: other | 41. Navigation system |
| 12. Bord entertainment: other accessories | 42. On board monitor |
| 13. Brake Assist | 43. Other |
| 14. Door mirrors autodimming, Rear-view mirror autodimming | 44. Other |
| 15. Door mirrors electrically foldable | 45. Other |
| 16. Driver airbag, Head airbags front, Passenger airbag, Side airbag driver, Side airbag driver and passenger | 46. Other |
| 17. Driver knee airbag | 47. Other |
| 18. Driver seat electrically adjustable, Passenger seat electrically adjustable | 48. Other |
| 19. Electric tailgate | 49. Other |
| 20. Exterior design: other | 50. Other |
| 21. Floor mat | 51. Park Assistant, Park Distance Control front, Park Distance Control rear |
| 22. Glass tilt/slide sunroof electric | 52. Rear view camera |
| 23. Heat reflecting windows, Tinted rear windows | 53. Traffic sign recognition |
| 24. Heated seat driver, Heated seat passenger | 54. Tyre pressure control (RDC) |
| 25. Hydro pneumatic suspension | 55. Tyre pressure control (RDC) |
| 26. Interior decoration: other | 56. USB in |
| 27. Interior: other | 57. USB in |
| 28. Interior: other | 58. Uni-Lackierung |
| 29. Interior: other | 59. Wood finish |
| 30. Keyless go | |

Dealer's equipment (selected items)

1. 360 view camera, Armrest (s) front, Bord climate: other, Bord entertainment: other accessories, Comfort driver seat, Comfort passenger seat, Distance control, Door: other, Driver seat electrically adjustable, Front seat with massage, Glass tilt/slide sunroof electric, Headrests front, Head-Up Display, Heated seat driver, Heated seat passenger, Memory seat, Passenger seat electrically adjustable, Pre-Crash System, Rear seat heating, Seats: other, Soundsystem -
- Uchwyt na kubki z regulacją temperatury - przód
- Wspomaganie domyknięcia drzwi
- Head-up display
- System nagłośnienia Burmester surround
- Dach panoramiczny
- System multimedialny MBUX - rozszerzony
- Pakiet wspomagania bezpieczeństwa jazdy Plus
- Pakiet parkowania z kamerą 360
- Pakiet Pamięci
- Pakiet Energizing Plus
2. Adaptive light, Automated High-beam assist -
3. Air condition rear, Rear seat heating, Seats: other, Ventilated rear seat -

- Klimatyzacja automatyczna dla pasażerów z tyłu
Fotele tylne z funkcją podgrzewania
Fotele tylne wentylowane
Wielokonturowe siedzenia tylne
4. Bord climate: other -
5. Bord entertainment: other accessories, Head-Up Display -
Head-up display
Asystent wnętrza MBUX
6. Comfort driver seat, Comfort passenger seat, Front seat with massage, Headrests front -
Wielokonturowe siedzenie przednie z funkcją masażu + komfortowe zagłówki
7. DAB radio -
8. Driver seat electrically adjustable, Memory seat -
9. Extra power outlet -
10. Interior: other -
11. Interior: other -
12. Light alloy wheels 23" -
13. Metal finish -
14. On board monitor, Quick charging function -
Tablet MBUX z tyłu
Bezprzewodowe ładowanie telefonu z tyłu
15. Other -
16. Other -
17. Other -
18. Other -
19. Paint: other -
20. Side airbags rear -
21. Towbar removable -
22. Trailer parking assist -
23. Under driving protection -
24. Ventilated front seat -

Additional equipment

1. Folia zabezpieczająca -

Base value of the vehicle

Base value of the vehicle by Eurotax (net) -

Corrections

First registration

Mileage

Equipment

Tyres

Other

stwierdzone braki i uszkodzenia -
brak badania techn. -


Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 07-2026 POL) with regard to technical and market parameters affecting the value of the vehicle.

Basic print without information about the vehicle's value - duey to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 24-07-2026

DEKRA's expert:
Kacper Sosnowski (WSP)
inż. Józef Orłowski

Document issued electronically valid without signature.

Measurement of thickness of the vehicle lacquer coating


No. of controlled item	Controlled item	Measured range of thickness of the lacquer coat [µm]
1	Front cover	150 - 300
2	Left front fender	150 - 300
3	Left front pillar	150 - 300
4	Left front wall	150 - 500
5	Roof	150 - 300
6	Left middle pillar	150 - 300
7	Left side sill	150 - 300
8	Left rear wall	150 - 300
9	Left side wall	150 - 300
10	Cover/tailgate	150 - 300
11	Side right wall	150 - 300
12	Rear right door	150 - 300
13	Middle right pillar	150 - 300
14	Front right door	150 - 300
15	Right side sill	150 - 300
16	Right front pillar	150 - 300
17	Right front fender	150 - 300

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

During the inspection the registration proof of the vehicle was presented and its photo was taken and enclosed to the expertise.

During the inspection the service book was presented and its number is given below:
elektroniczna

Information concerning the origin of the vehicle

The vehicle purchased domestically from an authorized representative of the brand.

Additional comments on the car:

Not applicable.

Test drive

Test drive of the vehicle was conducted. Test drive in the full extent is not possible. Comment below:
ograniczenia parkingowe

Checking of the correctness and / or construction of identification / serial numbers of the object:

Not tested

Verification of the accuracy of the object data, including year of production, and other.

Not conducted - adopted according to the documents presented and indicated sources.

Anti-theft protection

alarm immobilizer

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.
- The evaluation has been carried out basing on delivered documentation and organoleptic examination of the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the assessed object.
- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

Comments to the commission - regarding valuation

Kluczyki

TAK

2

Expert comments - regarding valuation

Brak aktualnych badań technicznych. Pojazd białego koloru oklejony czarną folią, pomiar lakieru wykonany na folii. Lusterka i lampy tylne oklejone folią. Rysy na samochodzie. Odpryski na szybie czołowej.

PHOTOGRAPHIC DOCUMENTATION



Photo 1.
Przekątna przednia lewa



Photo 2.
Przód

PHOTOGRAPHIC DOCUMENTATION



Photo 3.

Przekątna przednia prawa



Photo 4.

Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 5.

Bok prawy z tyłu



Photo 6.

Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 7.

Tył



Photo 8.

Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 9.

Bok lewy z tyłu



Photo 10.

Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 11.

Próg lewy (widok od przodu)



Photo 12.

Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



Photo 13.
Spód pojazdu przód



Photo 14.
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION



Photo 15.

Tarcza hamulcowa przednia prawa



Photo 16.

Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 17.

Tarcza hamulcowa tylna lewa



Photo 18.

Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 19.
Bagażnik



Photo 20.
Komora silnika

PHOTOGRAPHIC DOCUMENTATION




Photo 21.

Numer identyfikacyjny



Photo 22.

Tabliczka znamionowa

PHOTOGRAPHIC DOCUMENTATION



Photo 23.

Zestaw wskaźników - przebieg



Photo 24.

Zestaw wskaźników - serwis

PHOTOGRAPHIC DOCUMENTATION



Photo 25.

Widok przez otwarte drzwi przednie lewe



Photo 26.

Kierownica z lewej strony

PHOTOGRAPHIC DOCUMENTATION



Photo 27.

Widok przez otwarte drzwi tylne lewe



Photo 28.

Widok z tylnej kanapy na deskę rozdz.

PHOTOGRAPHIC DOCUMENTATION



Photo 29.

Konsola środkowa



Photo 30.

Tunel środkowy

PHOTOGRAPHIC DOCUMENTATION



Photo 31.

Kierownica (na wprost)



Photo 32.

Dowód rej. Str. 1

PHOTOGRAPHIC DOCUMENTATION



Photo 33.

Książka serwisowa – dane



Photo 34.

Książka serwisowa – ostatni przegląd

PHOTOGRAPHIC DOCUMENTATION



Photo 35.

Dowód rej. str. 2



Photo 36.

Instrukcje

PHOTOGRAPHIC DOCUMENTATION



Photo 37.
Zestaw naprawczy koła



Photo 38.
Kluczyki

PHOTOGRAPHIC DOCUMENTATION



Photo 39.

Zdjęcie do protokołu



Photo 40.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 41.

Zdjęcie do protokołu



Photo 42.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 43.

Zdjęcie do protokołu



Photo 44.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 45.

Zdjęcie do protokołu



Photo 46.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 47.

Zdjęcie do protokołu



Photo 48.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 49.

Zdjęcie do protokołu



Photo 50.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 51.

Zdjęcie do protokołu



Photo 52.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 53.

Emblemat - Rysa/odprysk 1



Photo 54.

Szyba czołowa - zdjęcie poglądowe 1

PHOTOGRAPHIC DOCUMENTATION




Photo 55.

Szyba czołowa - Pęknięcie/rozerwanie 1



Photo 56.

Zderzak - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 57.

Drzwi przednie P - Wgniecenie/odkształcenie 1



Photo 58.

Szyba tylna - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 59.

Błotnik tylny L / Ściana boczna L - Wgniecenie/odkształcenie 1



Photo 60.

Opona tylna L - Pęknięcie/rozerwanie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 61.

Reflektor L - Rysa/odprysk 1



Photo 62.

Fotel prz. lew. - Rysa/odprysk 1