

DEKRA's commission No. : PKOL(W)/LODZ/90093/25/11/20
commission/ damage No. : 22/035149
Date of commission: 20-11-2025

DEKRA Poland - Headquarters
02-673 Warszawa, ul. Konstruktorska 12A

Client :

PKO Leasing SA
Świętokrzyska 36
00-116 Warszawa

Expert:

Kacper Sosnowski (NEW)
DEKRA Polska - współpraca O/Warszawa
Tomasz Ziemniak (NEW)
DEKRA Polska - współpraca O/Konin

NOTE:

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

Vehicle data

Group of objects (Eurotax)	jeeps
EC code (Eurotax)	0138121
Manufacturer	MERCEDES-BENZ
Model	GLC [253] 19-22
Type / version	AMG GLC 63 S 4-Matic
Body type	KOM
Number of doors / seats	5/5
Curb weight [kg]	2050
Gross vehicle weight [kg]	2580
Wheelbase 1/2	2873
Engine type	spark ignition
Pollution reduction system	GPF
Engine capacity [ccm]	3982
Engine Power [hp/kW]	510/375
Gearbox	automatic 9- gear
Registration /record No.	PY24181
VIN / serial number	WDC2539891F737426
Date of first registration	09-10-2019
Date of next. tech. test	21-10-2026
Year of manufacture	2019 (year has been verified with the manufacturer's base)
Readout [km]	145 111 (read)
Body color / type of coating	white/METALIK

Tyres

axle	Wheel	Manufacturer, type	Size	Measured profile
Front	right	YOKOHAMA, BLUEARTH WINTER V905	265/40 21 105V	4,0 mm
	left	YOKOHAMA, BLUEARTH WINTER V905	265/40 21 105V	4,0 mm
back	right	YOKOHAMA, BLUEARTH WINTER V905	295/35 21 107V	4,0 mm
	left	YOKOHAMA, BLUEARTH WINTER V905	295/35 21 107V	4,0 mm

Standard equipment by Eurotax

- | | |
|--|---|
| 1. Accoustic windows, Heat reflecting windows | 30. LED front dim light |
| 2. Alarm | 31. Leather steering wheel, Sports steering wheel |
| 3. Alarm | 32. Limited slip differential in general |
| 4. Artificial leather upholstery | 33. Luggage compartment cover |
| 5. Automatic climate control | 34. Lumbar adjust driver |
| 6. Bord communication: other, Other | 35. Metal finish |
| 7. Bord entertainment: other accessories | 36. Mobile Tire System |
| 8. Brake Assist | 37. Navigation system |
| 9. Cruise control | 38. On board monitor |
| 10. Door mirrors autodimming, Rear-view mirror autodimming | 39. On board monitor |
| 11. Door mirrors electrically foldable | 40. Other |
| 12. Driver knee airbag | 41. Other |
| 13. Electric tailgate | 42. Other |
| 14. Exterior design: other | 43. Other |
| 15. Exterior design: other | 44. Other |
| 16. Exterior design: other | 45. Other |
| 17. Extra power outlet | 46. Other |
| 18. Floor mat | 47. Other |
| 19. Full Cabin Spoiler | 48. Other |
| 20. Heat reflecting windows, Tinted rear windows | 49. Park Assistant, Park Distance Control front, Park Distance Control rear |
| 21. Heated seat driver, Heated seat passenger | 50. Rain sensor |
| 22. Hydro pneumatic suspension | 51. Rear view camera |
| 23. Hydro pneumatic suspension | 52. Roof railing |
| 24. Interior decoration: other | 53. Selectable driveline characteristics |
| 25. Interior: other | 54. Steering wheel with gear-switches |
| 26. Interior: other | 55. Storage facilities in general |
| 27. Interior: other | 56. USB in |
| 28. Interior: other | 57. Uni-Lackierung |
| 29. Keyless go | |

Dealer's equipment (selected items)

1. 360 view camera, Adaptive light, Automated High-beam assist, Bluetooth interface, Bord communication: other, Bord entertainment: other accessories, Glass tilt/slide sunroof electric, Interior lights: other accessories, Keyless go, LED front dim light, On board monitor, Other, Park Assistant, Park Distance Control front, Park Distance Control rear, Soundsystem -
- Oświetlenie AMBIENTE
- Asystent ograniczeń prędkości
- Adaptacyjny asystent świateł drogowych Plus
- Pakiet integracji smartphone-a
- System nagłośnienia Burmester surround
- Dach panoramiczny
- Lampy MULTIBEAM LED
- System bezprzewodowego ładowania telefonu i podłączenie Bluetooth
- Pakiet parkowania z kamerą 360
- Wyświetlacz IC 12,3 cali
- Pakiet Keyless-GO
2. Automatic climate control -
3. Bord entertainment: other accessories -
4. Ceramic composite brakes -
5. Distance control, Pre-Crash System, Steering: other -
- System PRE-SAFE
- Distronic Plus (system kontroli odległości od poprzedzającego pojazdu)
- Asystent układu kierowniczego
6. Driver seat electrically adjustable, Memory seat -

- 7. Exterior design: other -
- 8. Head-Up Display -
- 9. Interior: other -
- 10. Keyless go -
 Keyless-go - system otwierania i uruchamiania pojazdu bez użycia kluczyka
 HANDS-FREE ACCESS - bezkluczykowy dostęp do samochodu
- 11. Light Allow wheels over 21" -
- 12. Memory seat, Passenger seat electrically adjustable -
- 13. Metal finish -
- 14. Other -
- 15. Other -
- 16. Other -
- 17. Other -
- 18. Other -
- 19. Roof railing -
 Relingi dachowe - czarne
- 20. Side airbags rear -
- 21. Sunblind tailgate window manual -
- 22. Tyre pressure control (RDC) -
- 23. Ventilated front seat -

Base value of the vehicle

Base value of the vehicle by Eurotax (net) -

Corrections

First registration

Mileage

Equipment

Tyres

Other

- Regularity of service review -
- Earlier repairs -
- Korekta z tytułu uszkodzeń pojazdu -


Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 11-2025 POL) with regard to technical and market parameters affecting the value of the vehicle.

Basic print without information about the vehicle's value - due to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 21-11-2025

DEKRA's expert:
Kacper Sosnowski (NEW)
Tomasz Ziemniak (NEW)

Document issued electronically valid without signature.

Measurement of thickness of the vehicle lacquer coating


No. of controlled item	Controlled item	Measured range of thickness of the lacquer coat [μm]
1	Front cover	150 - 500
2	Left front fender	150 - 200
3	Left front pillar	to 150
4	Left front wall	to 150
5	Roof	to 150
6	Left middle pillar	to 150
7	Left side sill	to 150
8	Left rear wall	to 150
9	Left side wall	to 150
10	Cover/tailgate	to 150
11	Side right wall	to 150
12	Rear right door	to 150
13	Middle right pillar	to 150
14	Front right door	to 150
15	Right side sill	to 150
16	Right front pillar	to 150
17	Right front fender	150 - 200

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

During the inspection the registration proof of the vehicle was presented and its photo was taken and enclosed to the expertise.

During the inspection the service book was presented and its number is given below:

Elektroniczna

Information concerning the origin of the vehicle

The vehicle purchased domestically from an authorized representative of the brand.

Additional comments on the car:

Not applicable.

Test drive

The test drive has been conducted on a distance and in time enabling rough estimation of the technical condition of the vehicle.

Checking of the correctness and / or construction of identification / serial numbers of the object:

Not tested

Verification of the accuracy of the object data, including year of production, and other.

Not conducted (with the exception of the year of production) - adopted according to the documents presented and indicated sources.

Anti-theft protection

Immobiliser

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.
- The evaluation has been carried out basing on delivered documentation and organoleptic examination of the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the assessed object.
- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its

page 6/41

availability location.

Comments to the commission - regarding valuation

Kluczyki

TAK

2

Expert comments - regarding valuation

Rysy na samochodzie. Brak płynu zestawu naprawczego. Brak zaślepek w tylnej kanapie. Przegląd B5 wymagany od 84 dni. Pokrywa przednia oklejona folią, pomiar lakieru wykonany na folii. Odpryski na szybie czołowej.

Restrictive disclaimer - regarding valuation

- W Ocenie/Raporcie uwzględniono niesprawności, uszkodzenia, braki itp., które były możliwe do stwierdzenia organoleptycznego, w warunkach oględzin (z uwzględnieniem: stanu czystości pojazdu, warunków atmosferycznych, oświetlenia itd.) oraz bez weryfikacji serwisowej, bez dostępu do spodu pojazdu, bez specjalistycznego sprzętu diagnostycznego (w tym bez diagnostyki komputerowej), bez jazdy próbnej wykonanej w warunkach drogowych z obciążeniem.
- W ramach Oceny/Raportu nie weryfikowano odczytanego stanu drogomierza z zapisami w urządzeniach elektronicznych pojazdu.
- Rzeczoznawca nie bierze na siebie odpowiedzialności za wady ukryte (prawne i fizyczne) oraz ewentualne skutki wynikające z dalszego użytkowania przedmiotu oceny, a także za skutki wykorzystania samej oceny.
- Podane przedziały grubości powłoki lakierowej, dotyczą punktów pomiarowych. Nie mogą być traktowane jako gwarancja, że grubość powłoki lakierowej w innych punktach nie wykracza poza te przedziały.
- Zawarte w niniejszej Ocenie/Raporcie informacje (w tym dotyczące wyposażenia) służą jedynie ogólnym celom informacyjnym. Ocena/Raport nie może być zatem traktowana jako oferta w rozumieniu przepisów Kodeksu Cywilnego oraz opisu towaru ani zapewnienia w rozumieniu art. 4 Ustawy z dnia 27 lipca 2002 roku o szczególnych warunkach sprzedaży konsumenckiej.
- Niniejsza Ocena/Raport nie jest szczegółową oceną stanu technicznego.

Ocenę/Raport wykonano w kierunku ujawnienia uszkodzeń nieakceptowanych z punktu widzenia właściwego przewodnika zwrotu pojazdu lub innych ustaleń ze Zleceniodawcą. Tym samym Ocena/Raport może nie ujmować typowych zużyć i uszkodzeń eksploatacyjnych.

PHOTOGRAPHIC DOCUMENTATION



Photo 1.
Przekątna przednia lewa



Photo 2.
Przód

PHOTOGRAPHIC DOCUMENTATION



Photo 3.

Przekątna przednia prawa



Photo 4.

Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 5.
Bok prawy z tyłu



Photo 6.
Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 7.

Tył



Photo 8.

Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 9.

Bok lewy z tyłu



Photo 10.

Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 11.

Próg lewy (widok od przodu)



Photo 12.

Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



Photo 13.
Spód pojazdu przód



Photo 14.
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION



Photo 15.

Tarcza hamulcowa przednia prawa



Photo 16.

Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 17.

Tarcza hamulcowa tylna lewa



Photo 18.

Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 19.
Bagażnik



Photo 20.
Koło zapasowe

PHOTOGRAPHIC DOCUMENTATION



Photo 21.
Komora silnika



Photo 22.
Numer identyfikacyjny

PHOTOGRAPHIC DOCUMENTATION




Photo 23.
Tabliczka znamionowa



Photo 24.
Zestaw wskaźników - przebieg

PHOTOGRAPHIC DOCUMENTATION




Photo 25.

Widok przez otwarte drzwi przednie lewe



Photo 26.

Kierownica z lewej strony

PHOTOGRAPHIC DOCUMENTATION



Photo 27.

Widok przez otwarte drzwi tylne lewe



Photo 28.

Widok z tylnej kanapy na deskę rozdzielczą

PHOTOGRAPHIC DOCUMENTATION



Photo 29.

Konsola środkowa




Photo 30.

Tunel środkowy

PHOTOGRAPHIC DOCUMENTATION



Photo 31.
Kierownica (na wprost)




Photo 32.
Dowód rej. Str. 1

PHOTOGRAPHIC DOCUMENTATION



Photo 33.

Dow. Rej. Str.2 i klucze



Photo 34.

Książka serwisowa – dane

PHOTOGRAPHIC DOCUMENTATION



Photo 35.

Książka serwisowa – ostatni przegląd



Photo 36.

Zestaw naprawczy koła

PHOTOGRAPHIC DOCUMENTATION



Photo 37.
Zdjęcie do protokołu



Photo 38.
Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 39.

Zdjęcie do protokołu



Photo 40.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION




Photo 41.

Zdjęcie do protokołu



Photo 42.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 43.

Zdjęcie do protokołu




Photo 44.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 45.

Zdjęcie do protokołu



Photo 46.

Pokrywa komory silnika - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 47.

Zderzak - Rysa/odprysk 1



Photo 48.

Zderzak - Rysa/odprysk 2

PHOTOGRAPHIC DOCUMENTATION



Photo 49.

Drzwi przednie P - Rysa/odprysk 1



Photo 50.

Drzwi przednie P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 51.

Drzwi tylne P - Rysa/odprysk 1



Photo 52.

Drzwi tylne P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 53.

Słupek przedni P - Rysa/odprysk 1



Photo 54.

Łotnik tylny P / Ściana boczna P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 55.

Felga aluminiowa tylna P - Rysa/odprysk 1



Photo 56.

Lampa przeciwmgielna tylna P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 57.

Listwa krawędzi błotnika tyl P - Wgniecenie/odkształcenie 1



Photo 58.

Błotnik tylny L / Ściana boczna L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 59.

Drzwi przed L - Rysa/odprysk 1



Photo 60.

Próg L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 61.

Felga Aluminiowa przednia L - Rysa/odprysk 1



Photo 62.

Koło kierownicy - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 63.

Kanapa tyl. - Rysa/odprysk 1



Photo 64.

Tapicerka drzwi przednich P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 65.

Tapicerka drzwi przednich P - Wgniecenie/odkształcenie 2



Photo 66.

Tapicerka drzwi tylnych L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 67.

Tapicerka drzwi tylnych P - Rysa/odprysk 1



Photo 68.

Wykładzina pokrywy tylnej - Rysa/odprysk 1