

DEKRA's commission No. : PKOL(W)/LODZ/17567/26/02/26
commission/ damage No. : 23/044125
Date of commission: 26-02-2026

DEKRA Poland - Headquarters
02-673 Warszawa, ul. Konstruktorska 12A

Client :

PKO Leasing SA
Świętokrzyska 36
00-116 Warszawa

Expert:

Kacper Sosnowski (WSP)
DEKRA Polska - współpraca O/Warszawa
Maciej Waldemar Witowski (WSP)
DEKRA Polska - współpraca O/Warszawa

NOTE:

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

Vehicle data

Group of objects (Eurotax)	cars
EC code (Eurotax)	0133740
Manufacturer	BMW
Model	Seria 5 Touring [G31] 17-20
Type / version	530i xDrive GPF M Sport sport-aut
Body type	KOM
Number of doors / seats	5/5
Curb weight [kg]	1770
Gross vehicle weight [kg]	2440
Wheelbase 1/2	2975
Engine type	spark ignition
Pollution reduction system	GPF
Engine capacity [ccm]	1998
Engine Power [hp/kW]	252/185
Gearbox	automatic 8- gear
Registration /record No.	WZ947HC
VIN / serial number	WBAJT51090BU75980
Date of first registration	13-01-2020
Date of next. tech. test	16-01-2027
Year of manufacture	2019 (year has been verified with the manufacturer's base)
Readout [km]	88 341 (read)
Body color / type of coating	white/UNI

Tyres

axle	Wheel	Manufacturer, type	Size	Measured profile
Front	right	NOKIAN, WRA4	245/40 19 98V	4,5 mm
	left	NOKIAN, WRA4	245/40 19 98V	4,5 mm
back	right	PIRELLI, SOTTOZERO 3 WINTER	245/40 19 98V	5,0 mm
	left	PIRELLI, SOTTOZERO 3 WINTER	245/40 19 98V	5,0 mm

Standard equipment by Eurotax

- | | |
|---|---|
| 1. Additional gauges, Navigation system, On board monitor, Other, Touchscreen monitor | 34. Interior decoration: other |
| 2. Aerodynamics package, Exterior design: other | 35. Interior: other |
| 3. Alarm | 36. Interior: other |
| 4. Alcantara upholstery, Textile upholstery | 37. LED Fog Lamps |
| 5. Antilock-Brake-System (ABS) | 38. Leather steering wheel, Sports steering wheel |
| 6. Apple CarPlay | 39. Light Alloy wheels 18" |
| 7. Armrest (s) front | 40. Mobile Tire System |
| 8. Armrest (s) rear | 41. Multi functional steering wheel |
| 9. Automatic climate control | 42. Other |
| 10. Automatic dimlight activation, Rain sensor | 43. Other |
| 11. Bluetooth interface, Hands-free system | 44. Other |
| 12. Bord communication: other | 45. Other |
| 13. Bord communication: other | 46. Other |
| 14. Bord communication: other | 47. Other |
| 15. Bord communication: other | 48. Other |
| 16. Bord entertainment: other accessories | 49. Park Distance Control front, Park Distance Control rear |
| 17. Cargo net | 50. Rear seat-backs foldable in two separate parts |
| 18. Chassis: other | 51. Rear-view mirror autodimming |
| 19. Child seat fixation | 52. Roof railing |
| 20. Collision Warning System | 53. Selectable driveline characteristics |
| 21. Cruise control | 54. Servotronic |
| 22. Door mirrors electrically foldable | 55. Soundsystem |
| 23. Driver airbag, Head airbags front, Passenger airbag, Side airbag driver and passenger | 56. Sport seats front |
| 24. Driver seat electrically adjustable, Passenger seat electrically adjustable | 57. Sport suspension |
| 25. ESP (Electronical Stabilizing Program), Traction control | 58. Sports steering wheel |
| 26. Electric tailgate | 59. Start/Stop system |
| 27. Exterior design: other | 60. Steering wheel manually adjustable |
| 28. Exterior design: other | 61. Telematic |
| 29. Exterior design: other | 62. Telematic |
| 30. Exterior design: other | 63. Tie-down ring |
| 31. Floor mat | 64. Uni-Lackierung |
| 32. Follow me home | 65. Wheel bolt locks |
| 33. Headlamp wash, LED front dim light | 66. Windscreen wash-nozzle heated |

Dealer's equipment (selected items)

- | | |
|---|---|
| 1. Additional gauges, Navigation system, On board monitor, Other, Touchscreen monitor | - |
| 2. Automated High-beam assist | - |
| 3. Blind spot warning, Collision Warning System, Other, Traffic sign recognition | - |
| 4. Bord communication: other | - |
| 5. Cornering Headlights, LED front dim light | - |
| 6. Heated seat driver, Heated seat passenger | - |
| 7. Interior decoration: other | - |
| 8. Keyless entry, Keyless go | - |
| 9. Light Alloy wheels 19", Runflat tyres | - |
| 10. Lumbar adjust driver, Lumbar adjust passenger | - |
| 11. Mobile phone, Wireless device charging | - |
| 12. Other | - |
| 13. Other, Steering: other | - |
| 14. Park Assistant | - |
| Kamera cofania | - |
| Asystent parkowania | - |
| 15. Pre-Crash System | - |

16. Soundsystem -
17. Steering wheel heated -
18. Tinted rear windows -

Base value of the vehicle

Base value of the vehicle by Eurotax (net) -

Corrections

First registration

Mileage

Equipment

Tyres

Other

State of the vehicle -
STWIERDZONE USZKODZENIA STAN POJAZDU -

Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 03-2026 POL) with regard to technical and market parameters affecting the value of the vehicle.

Basic print without information about the vehicle's value - duey to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 16-03-2026

DEKRA's expert:
Kacper Sosnowski (WSP)
Maciej Waldemar Witowski (WSP)

Document issued electronically valid without signature.

Measurement of thickness of the vehicle lacquer coating


No. of controlled item	Controlled item	Measured range of thickness of the lacquer coat [μm]
1	Front cover	to 150
2	Front left fender	to 150
3	Left front pillar	to 150
4	Front left door	to 150
5	Roof	to 150
6	Left middle pillar	to 150
7	Right side sill	to 150
8	Left rear door	to 150
9	Rear left fender	to 150
10	Cover/lid	to 150
11	Right rear fender	to 150
12	Right rear door	to 150
13	Right middle pillar	to 150
14	Right side sill	to 150
15	Front right door	to 150
16	Right front pillar	to 150
17	Front right fender	to 150

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

During the inspection the registration proof of the vehicle was presented and its photo was taken and enclosed to the expertise.

Information concerning the origin of the vehicle

The vehicle purchased domestically from an authorized representative of the brand.

Anti-theft protection - immobilizer

- as a result of the inspection of the vehicle found no malfunctions of the immobilizer in the extent possible to determine during the inspection of the vehicle in the non- workshop conditions.

Anti-theft protection - other:

-other:
fabryczne

Additional comments on the car:

Not applicable.

Test drive

Test drive of the vehicle was conducted. Test drive in the full extent is not possible. Comment below:
warunki parkingowe

Checking of the correctness and / or construction of identification / serial numbers of the object:

Not tested

Verification of the accuracy of the object data, including year of production, and other.

Not conducted - adopted according to the documents presented and indicated sources.

- The read odometer status has not been verified with records in electronic equipment of the vehicle.
- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.
- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.
- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.
- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.
- The evaluation has been carried out basing on delivered documentation and organoleptic examination of the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the

page 5/44

assessed object.

- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

Comments to the commission - regarding valuation

Kluczyki

TAK

2

Restrictive disclaimer - regarding valuation

- W Ocenie/Raporcie uwzględniono niesprawności, uszkodzenia, braki itp., które były możliwe do stwierdzenia organoleptycznego, w warunkach oględzin (z uwzględnieniem: stanu czystości pojazdu, warunków atmosferycznych, oświetlenia itd.) oraz bez weryfikacji serwisowej, bez dostępu do spodu pojazdu, bez specjalistycznego sprzętu diagnostycznego (w tym bez diagnostyki komputerowej), bez jazdy próbnej wykonanej w warunkach drogowych z obciążeniem.
- W ramach Oceny/Raportu nie weryfikowano odczytanego stanu drogomierza z zapisami w urządzeniach elektronicznych pojazdu.
- Rzeczoznawca nie bierze na siebie odpowiedzialności za wady ukryte (prawne i fizyczne) oraz ewentualne skutki wynikające z dalszego użytkowania przedmiotu oceny, a także za skutki wykorzystania samej oceny.
- Podane przedziały grubości powłoki lakierowej, dotyczą punktów pomiarowych. Nie mogą być traktowane jako gwarancja, że grubość powłoki lakierowej w innych punktach nie wykracza poza te przedziały.
- Zawarte w niniejszej Ocenie/Raporcie informacje (w tym dotyczące wyposażenia) służą jedynie ogólnym celom informacyjnym. Ocena/Raport nie może być zatem traktowana jako oferta w rozumieniu przepisów Kodeksu Cywilnego oraz opisu towaru ani zapewnienia w rozumieniu art. 4 Ustawy z dnia 27 lipca 2002 roku o szczególnych warunkach sprzedaży konsumenckiej.
- Niniejsza Ocena/Raport nie jest szczegółową oceną stanu technicznego.

Ocenę/Raport wykonano w kierunku ujawnienia uszkodzeń nieakceptowanych z punktu widzenia właściwego przewodnika zwrotu pojazdu lub innych ustaleń ze Zleceniodawcą. Tym samym Ocena/Raport może nie ujmować typowych zużyć i uszkodzeń eksploatacyjnych.

PHOTOGRAPHIC DOCUMENTATION



Photo 1.

Przekątna przednia lewa



Photo 2.

Przód

PHOTOGRAPHIC DOCUMENTATION



Photo 3.

Przekątna przednia prawa



Photo 4.

Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 5.

Bok prawy z tyłu



Photo 6.

Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 7.

Tył



Photo 8.

Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 9.

Bok lewy z tyłu



Photo 10.

Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 11.

Próg lewy (widok od przodu)



Photo 12.

Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



Photo 13.
Spód pojazdu przód



Photo 14.
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION



Photo 15.

Tarcza hamulcowa przednia prawa



Photo 16.

Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 17.

Tarcza hamulcowa tylna lewa



Photo 18.

Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 19.
Bagażnik



Photo 20.
Koło zapasowe

PHOTOGRAPHIC DOCUMENTATION



Photo 21.
Komora silnika




Photo 22.
Numer identyfikacyjny

PHOTOGRAPHIC DOCUMENTATION



Photo 23.

Tabliczka znamionowa



Photo 24.

Zestaw wskaźników - przebieg

PHOTOGRAPHIC DOCUMENTATION



Photo 25.

Widok przez otwarte drzwi przednie lewe



Photo 26.

Kierownica z lewej strony

PHOTOGRAPHIC DOCUMENTATION



Photo 27.

Widok przez otwarte drzwi tylne lewe



Photo 28.

Widok z tylnej kanapy na deskę rozdź.

PHOTOGRAPHIC DOCUMENTATION



Photo 29.

Konsola środkowa




Photo 30.

Tunel środkowy

PHOTOGRAPHIC DOCUMENTATION



Photo 31.

Kierownica (na wprost)



Photo 32.

Dowód rej. Str. 1

PHOTOGRAPHIC DOCUMENTATION



Photo 33.

Dow. Rej. Str.2 i klucze




Photo 34.

Książka serwisowa – dane

PHOTOGRAPHIC DOCUMENTATION



Photo 35.

Książka serwisowa – ostatni przegląd



Photo 36.

Instrukcje

PHOTOGRAPHIC DOCUMENTATION



Photo 37.

Zdjęcie do protokołu



Photo 38.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 39.

Zdjęcie do protokołu



Photo 40.

Kratka/zaślepka halogenu L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 41.

Kratka/zaślepka halogenu P - Rysa/odprysk 1



Photo 42.

Pokrywa komory silnika - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 43.

Szyba czołowa - zdjęcie poglądowe 1



Photo 44.

Szyba czołowa - Pęknięcie/rozerwanie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 45.

Zderzak - Rysa/odprysk 1



Photo 46.

Zderzak - Rysa/odprysk 2

PHOTOGRAPHIC DOCUMENTATION



Photo 47.

Zderzak() - Rysa/odprysk 3



Photo 48.

Zderzak - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION




Photo 49.

Zderzak - Inne 1



Photo 50.

Felga aluminiowa przednia P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 51.

Reflektor P - Rysa/odprysk 1



Photo 52.

Drzwi przednie P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 53.

Drzwi przednie P - Wgniecenie/odkształcenie 1



Photo 54.

Drzwi przednie P - Wgniecenie/odkształcenie 2

PHOTOGRAPHIC DOCUMENTATION



Photo 55.

Drzwi tylne P - Rysa/odprysk 1



Photo 56.

Felga aluminiowa tylna P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION




Photo 57.

Pokrywy bagażnika - Rysa/odprysk 1



Photo 58.

Pokrywy bagażnika - Rysa/odprysk 2

PHOTOGRAPHIC DOCUMENTATION



Photo 59.

Szyba tylna - Rysa/odprysk 1



Photo 60.

Ścianka tylna L / Ścianka boczna L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 61.

Felga aluminiowa tylna L - Rysa/odprysk 1



Photo 62.

Drzwi przed L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 63.

Drzwi tylne L - Rysa/odprysk 1



Photo 64.

Drzwi tylne L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 65.

Lusterko zew L - Rysa/odprysk 1



Photo 66.

Próg L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 67.

Słupek przedni L - Rysa/odprysk 1



Photo 68.

Koło kierownicy - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 69.

Fotel prz. lew. - zdjęcie poglądowe 1




Photo 70.

Fotel prz. lew. - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 71.

Fotel prz. praw. - Inne 1



Photo 72.

Kanapa tyl. - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 73.

Tapicerka drzwi przednich L - Rysa/odprysk 1



Photo 74.

Tapicerka drzwi tylnych L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 75.

Wykładzina podłogi - zdjęcie poglądowe 1




Photo 76.

Wykładzina podłogi - Inne 1