

DEKRA's commission No. : PKOL(W)/LODZ/22344/25/03/26
commission/ damage No. : 23/000978
Date of commission: 26-03-2025

DEKRA Poland - Headquarters
02-673 Warszawa, ul. Konstruktorska 12A

Client :

PKO Leasing SA
Świętokrzyska 36
00-116 Warszawa

Expert:

Kacper Sosnowski (NEW)
DEKRA Polska - współpraca O/Warszawa
Andrzej Sosnowski
DEKRA Polska - Centrala

NOTE:

Due to the use of the document it was removed from it any information relating to the value of the vehicle, the price of equipment, adjustments, etc..

Vehicle data

Group of objects (Eurotax)	cars
EC code (Eurotax)	0148728
Manufacturer	TOYOTA
Model	Camry 21-24
Type / version	Camry 2.5 Hybrid Executive CVT
Body type	sedan
Number of doors / seats	4/5
Curb weight [kg]	1649
Gross vehicle weight [kg]	2100
Wheelbase 1/2	2825
Engine type	spark ignition
Pollution reduction system	three-way catalytic converter
Engine capacity [ccm]	2487
Engine Power [hp/kW]	178/131
Gearbox	automatic
Registration /record No.	WZ203FU
VIN / serial number	JTNB23HK703131723
Date of first registration	27-01-2023
Date of next. tech. test	27-01-2026
Year of manufacture	2022 (year has been verified with the manufacturer's base)
Readout [km]	93 352 (read)
Body color / type of coating	brązowy/double-layered, metallized

Tyres

axle	Wheel	Manufacturer, type	Size	Measured profile
Front	right	DUNLOP, SP SPORT MAXX D50	235/45 18 94Y	3,5 mm
	left	DUNLOP, SP SPORT MAXX D50	235/45 18 94Y	3,5 mm
back	right	DUNLOP, SP SPORT MAXX D50	235/45 18 94Y	4,0 mm
	left	DUNLOP, SP SPORT MAXX D50	235/45 18 94Y	4,5 mm

Standard equipment by Eurotax

- | | |
|---|---|
| <ol style="list-style-type: none"> 1. Adaptive Cruise Control 2. Android Auto, Apple CarPlay 3. Antilock-Brake-System (ABS) 4. Armrest (s) rear 5. Automated High-beam assist 6. Automatic Emergency Call 7. Automatic antenna/ window-antenna 8. Automatic climate control 9. Automatic dimlight activation 10. Blind spot warning 11. Bluetooth interface 12. Bord climate: other 13. Bord communication: other 14. CD-player, Radio 15. Child lock manually 16. Child seat fixation 17. Collision Warning System 18. DAB radio 19. Diminished spare wheel 20. Distribution of braking force electronically 21. Door mirror(s) electrically adjustable in general, Door mirrors heated 22. Door mirrors electrically foldable 23. Driver airbag, Passenger airbag 24. Driver knee airbag 25. Driver seat electrically adjustable 26. ESP (Electronical Stabilizing Program) 27. Electric parking brake 28. Electric tailgate 29. Exterior design: other 30. Exterior design: other 31. Exterior design: other 32. Exterior lighting: other 33. Extra power outlet 34. Floor mat 35. Fog lamps 36. Head airbags front 37. Headlamp wash 38. Heated seat driver, Heated seat passenger 39. Hill holder 40. Interior decoration: other 41. Interior decoration: other 42. Interior decoration: other 43. Keyless go 44. Keyless go 45. LED Daytime running lights | <ol style="list-style-type: none"> 46. LED front dim light 47. LED rear lights 48. Lane control assistant 49. Lane control assistant 50. Leather gearshifter/switch, Leather steering wheel 51. Leather upholstery 52. Light Alloy wheels 18" 53. Lumbar adjust driver electric 54. Lumbar adjust passenger electric 55. Multi functional steering wheel 56. Navigation system 57. On board computer 58. On board monitor 59. Other 60. Other 61. Other 62. Other 63. Other 64. Park Distance Control front, Park Distance Control rear 65. Passenger seat electrically adjustable 66. Power assisted brakes 67. Power steering, Pre-Crash System 68. Power windows front, Power windows rear 69. Pre-Crash System 70. Radio 71. Rain sensor 72. Rear Cross Traffic Alert 73. Rear bench foldable in two separate parts 74. Rear view camera 75. Rear-view mirror autodimming 76. Remote controlled central locking 77. Selectable driveline characteristics 78. Side airbag driver and passenger 79. Side indicators 80. Steering wheel heated 81. Steering wheel with gear-switches 82. Steering: other 83. Tinted rear windows 84. Traction control 85. Traffic sign recognition 86. Tyre pressure control (RDC) 87. USB in 88. USB in 89. Uni-Lackierung 90. Vehicle immobilizer |
|---|---|

Dealer's equipment (selected items)

1. Metallic paint

Base value of the vehicle

Base value of the vehicle by Eurotax (gross) -

CorrectionsFirst registrationMileageEquipmentTyresOther

Regularity of service review -

Uszkodzenia, stan -

Above figure was estimated on the basis of price quotations of used cars on the Polish market Eurotax (database number 04-2025 POL) with regard to technical and market parameters affecting the value of the vehicle.

Basic print without information about the vehicle's value - duey to use of the document any information relating to the value of the vehicle, the price of equipment, adjustments, etc.. were removed

Date: 01-04-2025

DEKRA's expert:
Kacper Sosnowski (NEW)
Andrzej Sosnowski**Document issued electronically valid without signature.**

Measurement of thickness of the vehicle lacquer coating


No. of controlled item	Controlled item	Measured range of thickness of the lacquer coat [μm]
1	Front cover	150 - 500
2	Front left fender	to 150
3	Left front pillar	150 - 500
4	Front left door	to 150
5	Roof	150 - 500
6	Left middle pillar	to 150
7	Right side sill	to 150
8	Left rear door	to 150
9	Rear left fender	to 150
10	Cover/lid	to 150
11	Right rear fender	to 150
12	Right rear door	to 150
13	Right middle pillar	to 150
14	Right side sill	to 150
15	Front right door	to 150
16	Right front pillar	150 - 500
17	Front right fender	to 150

Description of the technical condition

A detailed description of the technical condition contains in Description of the technical condition attached to following expertise.

General comments - regarding valuation**Vehicle documents**

During the inspection the registration proof of the vehicle was presented and its photo was taken and enclosed to the expertise.

During the inspection the service book was presented and its number is given below:

.

Information concerning the origin of the vehicle

Lack of reliable data.

Anti-theft protection - immobilizer

- as a result of the inspection of the vehicle found no malfunctions of the immobilizer in the extent possible to determine during the inspection of the vehicle in the non- workshop conditions.

Anti-theft protection - other:

not found

Additional comments on the car:

Not applicable.

Test drive

Test drive of the vehicle was conducted. Test drive in the full extent is not possible. Comment below:
ograniczenia placowe

Checking of the correctness and / or construction of identification / serial numbers of the object:

Not tested

Verification of the accuracy of the object data, including year of production, and other.

Not conducted - adopted according to the documents presented and indicated sources.

- The read odometer status has not been verified with records in electronic equipment of the vehicle.

- This expertise is used exclusively to estimate the market value of the item pricing and can not be used for any purpose other than those mentioned above.

- An expert assumes no responsibility for hidden defects (legal and physical) and the possible consequences arising from the continuing use of the subject of valuation, and for the consequences of using the same valuation.

- The above pricing is not an expertise of the technical condition of the subject of valuation and as such can not be considered, in particular, can not be treated as a guarantee for the sales subject of the valuation for estimated value.

- This evaluation may not be published as whole in any document without consent of its executors and without their consent as to the form and contents of such publication.

- The evaluation has been carried out basing on delivered documentation and organoleptic examination of

page 5/41

the assessed object. No diagnostic examination has been carried out, nor any workshop verification of the assessed object.

- This expertise has been issued basing on inspection of the assessed object in conditions ruling in its availability location.

Comments to the commission - regarding valuation

Kluczyki

TAK

2

Expert comments - regarding valuation

Rysy na samochodzie. Odpryski na szybie czołowej. Nieprzyjemny zapach w samochodzie. Pomiar lakieru wykonany na folii, elementy-pokrywa przednia słupki przedni lewy/prawy, dach.

Rzeczoznawca dokonał oględzin pojazdu w warunkach parkingowych, co mogło ograniczyć pełną ocenę jego stanu technicznego. Dodatkowo, jeżeli jazda próbna została przeprowadzona (informacje w treści raportu), to wykonano ją w warunkach parkingowych, z niewielką prędkością, co może nie odzwierciedlać pełnych warunków eksploatacyjnych. Istnieje możliwość, że w innych okolicznościach ujawnią się dodatkowe uszkodzenia lub usterki, których nie można było wykryć podczas obecnych oględzin. Zalecamy zatem skorzystanie z możliwości oględzin pojazdu we własnym zakresie lub w Autoryzowanej Stacji Obsługi danej marki, co pozwoli na pełniejszą weryfikację stanu technicznego pojazdu przed udziałem w aukcji."

Restrictive disclaimer - regarding valuation

Nie weryfikowano szczegółowo stanu układu napędowego, zawieszenia, kierowniczego, hamulcowego oraz wydechowego. Ocena została wykonana bez użycia podnośnika i specjalistycznego sprzętu diagnostycznego, nie dokonywano demontażu osłon i innych elementów. Ocena określa ogólny stan pojazdu na dzień oględzin w miejscu jego udostępnienia, nie może być zatem traktowana jako kompleksowa ocena stanu technicznego. Specyfikacja wg. programu operacyjnego w zakresie wyposażenia standardowego i dodatkowego nie gwarantuje zgodności ze stanem faktycznym w zakresie możliwym do ustalenia przez rzeczoznawcę podczas oględzin pojazdu.

Pomiar grubości powłoki lakierowej wykonano w miejscach możliwych do ich wykonania pomiary nie gwarantują oryginalności poszczególnych elementów poddanych ocenie.

- W Ocenie/Raporcie uwzględniono niesprawności, uszkodzenia, braki itp., które były możliwe do stwierdzenia organoleptycznego, w warunkach oględzin (z uwzględnieniem: stanu czystości pojazdu, warunków atmosferycznych, oświetlenia itd.) oraz bez weryfikacji serwisowej, bez dostępu do spodu pojazdu, bez specjalistycznego sprzętu diagnostycznego (w tym bez diagnostyki komputerowej), bez jazdy próbnej wykonanej w warunkach drogowych z obciążeniem.
- W ramach Oceny/Raportu nie weryfikowano odczytanego stanu drogomierza z zapisami w urządzeniach elektronicznych pojazdu.
- Rzeczoznawca nie bierze na siebie odpowiedzialności za wady ukryte (prawne i fizyczne) oraz ewentualne skutki wynikające z dalszego użytkowania przedmiotu oceny, a także za skutki wykorzystania samej oceny.
- Podane przedziały grubości powłoki lakierowej, dotyczą punktów pomiarowych. Nie mogą być traktowane jako gwarancja, że grubość powłoki lakierowej w innych punktach nie wykracza poza te przedziały.

- Zawarte w niniejszej Ocenie/Raporcie informacje (w tym dotyczące wyposażenia) służą jedynie ogólnym celom informacyjnym. Ocena/Raport nie może być zatem traktowana jako oferta w rozumieniu przepisów Kodeksu Cywilnego oraz opisu towaru ani zapewnienia w rozumieniu art. 4 Ustawy z dnia 27 lipca 2002 roku o szczególnych warunkach sprzedaży konsumenckiej.
- Niniejsza Ocena/Raport nie jest szczegółową oceną stanu technicznego.

Ocenę/Raport wykonano w kierunku ujawnienia uszkodzeń nieakceptowanych z punktu widzenia właściwego przewodnika zwrotu pojazdu lub innych ustaleń ze Zleceniodawcą. Tym samym Ocena/Raport może nie ujmować typowych zużyć i uszkodzeń eksploatacyjnych.

PHOTOGRAPHIC DOCUMENTATION



Photo 1.

Przekątna przednia lewa



Photo 2.

Przód

PHOTOGRAPHIC DOCUMENTATION



Photo 3.

Przekątna przednia prawa



Photo 4.

Bok prawy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 5.

Bok prawy z tyłu



Photo 6.

Przekątna tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 7.

Tył



Photo 8.

Przekątna tylna lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 9.

Bok lewy z tyłu



Photo 10.

Bok lewy z przodu

PHOTOGRAPHIC DOCUMENTATION



Photo 11.

Próg lewy (widok od przodu)



Photo 12.

Próg prawy (widok od przodu)

PHOTOGRAPHIC DOCUMENTATION



Photo 13.
Spód pojazdu przód




Photo 14.
Spód pojazdu tył

PHOTOGRAPHIC DOCUMENTATION



Photo 15.

Tarcza hamulcowa przednia prawa



Photo 16.

Tarcza hamulcowa tylna prawa

PHOTOGRAPHIC DOCUMENTATION



Photo 17.

Tarcza hamulcowa tylna lewa



Photo 18.

Tarcza hamulcowa przednia lewa

PHOTOGRAPHIC DOCUMENTATION



Photo 19.
Bagażnik



Photo 20.
Koło zapasowe

PHOTOGRAPHIC DOCUMENTATION



Photo 21.
Komora silnika




Photo 22.
Numer identyfikacyjny

PHOTOGRAPHIC DOCUMENTATION



Photo 23.

Tabliczka znamionowa



Photo 24.

Zestaw wskaźników - przebieg

PHOTOGRAPHIC DOCUMENTATION



Photo 25.

Widok przez otwarte drzwi przednie lewe



Photo 26.

Kierownica z lewej strony

PHOTOGRAPHIC DOCUMENTATION



Photo 27.

Widok przez otwarte drzwi tylne lewe



Photo 28.

Widok z tylnej kanapy na deskę rozdź.

PHOTOGRAPHIC DOCUMENTATION



Photo 29.
Konsola środkowa



Photo 30.
Tunel środkowy

PHOTOGRAPHIC DOCUMENTATION**Photo 31.**


Kierownica (na wprost)

**Photo 32.**


Dowód rej. Str. 1

PHOTOGRAPHIC DOCUMENTATION**Photo 33.**


Dow. Rej. Str.2 i klucze

**Photo 34.**

Książka serwisowa – dane

PHOTOGRAPHIC DOCUMENTATION**Photo 35.**

Książka serwisowa – ostatni przegląd

**Photo 36.**

Instrukcje

PHOTOGRAPHIC DOCUMENTATION



Photo 37.

Zdjęcie do protokołu



Photo 38.

Zdjęcie do protokołu

PHOTOGRAPHIC DOCUMENTATION



Photo 39.

Zderzak - Rysa/odprysk 1



Photo 40.

Łotnik przedni P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 41.

Drzwi przednie P - Rysa/odprysk 1



Photo 42.

Drzwi tylne P - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 43.

Drzwi tylne P - Wgniecenie/odkształcenie 1



Photo 44.

Łotnik tylny P / Ściana boczna P - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 45.

Zderzak tylny - Rysa/odprysk 1



Photo 46.

Dach - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 47.

Błotnik tylny L / Ściana boczna L - Wgniecenie/odkształcenie 1



Photo 48.

Drzwi przed L - Rysa/odprysk 1

PHOTOGRAPHIC DOCUMENTATION



Photo 49.

Drzwi tylne L - Rysa/odprysk 1




Photo 50.

Drzwi tylne L - Wgniecenie/odkształcenie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 51.

Felga Aluminiowa przednia L - Rysa/odprysk 1



Photo 52.

Opona przednia L - Pęknięcie/rozerwanie 1

PHOTOGRAPHIC DOCUMENTATION



Photo 53.

Gałka dźwigni zmiany biegów - Rysa/odprysk 1



Photo 54.

Podłokietnik środkowy przedni - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 55.

Fotel prz. lew. - Inne 1



Photo 56.

Fotel prz. lew. - Inne 2

PHOTOGRAPHIC DOCUMENTATION



Photo 57.

Fotel prz. praw. - Inne 1



Photo 58.

Tapicerka drzwi przednich L - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 59.

Tapicerka drzwi tylnych P - Inne 1



Photo 60.

Podsufitka - zdjęcie poglądowe 1

PHOTOGRAPHIC DOCUMENTATION




Photo 61.

Podsufitka - zdjęcie poglądowe 2



Photo 62.

Podsufitka - Inne 1

PHOTOGRAPHIC DOCUMENTATION




Photo 63.

Podsufitka - Inne 2




Photo 64.

Podsufitka() - Inne 3

PHOTOGRAPHIC DOCUMENTATION



Photo 65.

Wykładzina(y) słupka przedniego L - Inne 1



Photo 66.

Wykładzina(y) słupka przedniego P - Inne 1

PHOTOGRAPHIC DOCUMENTATION



Photo 67.

Wykładzina(y) słupka tylnego L - Inne 1



Photo 68.

Listwy progowe lew. - Inne 1